

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9245K -**AAD1712-179***Not Authored
21 Sep 2017*

Vehicle No.:

SHD9245K - CANDY

Chassis No.:

KL1LA69RJBB057198

Vehicle Make:

CHEVROLET

Vehicle Model:

EPICA 2.0

Date of Accident :

18.12.2017

Third Party Insurer :

AXA

PART			LIST		
1	1	Rear Bumper	\$	<i>Bz</i> 1,202.00	—
2	1	Rear Bumper Beam	\$	<i>Bz</i> 239.94	—
3	1	Rear Bumper Centre Absorber	\$	<i>CMA</i> 260.00	—
4	1	Rear Bumper Side Retainer RH	\$	<i>D.Y</i> 68.76	—
5	1	Rear Bumper Side Retainer LH	\$	<i>Sn</i> 68.76	X
6	1	Rear Bumper Reflectors RH	\$	<i>Sn</i> 119.74	X
7	1	Rear Bumper Reflectors LH	\$	<i>CMA</i> 119.74	—
8	1	Rear Bumper Tow Hook Cover	\$	<i>Sn</i> 93.00	X
9	1	Rear Luggage Floor Panel	\$	<i>R</i> 973.00	X
10	1	Rear Luggage Floor Panel Insulator	\$	<i>Sn</i> 63.50	X
11	1	Rear Luggage Floor Panel Trim Board	\$	<i>Sn</i> 378.00	X
12	1	Rear End Panel Outer	\$	<i>R</i> 623.76	X
13	1	Rear End Panel Inner Trim	\$	<i>Sn</i> 263.84	X
14	1	Bootlid	\$	<i>Bz</i> 973.00	—
15	1	Bootlid inner trim board	\$	<i>Sn</i> 400.00	X
16	1	Bootlid Weatherstrip	<i>172.14</i> \$	<i>Disinc</i> 344.28	<i>508</i>
17	1	Bootlid Lock - Top	\$	<i>Nd</i> 466.56	—
18	1	Bootlid 'CHEVROLET' Badge	\$	<i>Nd</i> 120.62	—
19	1	Bootlid Logo	\$	<i>Nd</i> 138.84	—
20	1	Bootlid 'EPICA LT' Badge	\$	<i>Nd</i> 119.84	—
21	1	Bootlid Reflector Centre	\$	<i>Sn</i> 217.97	X
22	1	Bootlid Reflector RH	\$	<i>Sn</i> 128.40	X
23	1	Bootlid Reflector LH	\$	<i>Sn</i> 128.40	X
24	1	Bootlid Hinge RH	\$	<i>R</i> 120.00	X
25	1	Bootlid Hinge LH	\$	<i>R</i> 120.00	X
26	1	Rear Tail Lamp RH	\$	<i>Sn</i> 479.30	X
27	1	Rear Tail Lamp Panel RH	\$	<i>R</i> 359.00	X
28	1	Rear Tail Lamp LH	\$	<i>Sn</i> 479.30	X
29	1	Rear Tail Lamp Panel LH	\$	<i>R</i> 359.00	X
30	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	<i>R</i> 1,110.00	X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-179**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9245K -

31	1	Rear Fender RH	\$	<i>12</i>	1,145.00	X
32	1	Rear Fender Inner Trim RH	\$	<i>12</i>	418.44	X
33	1	Rear Fender LH	\$	<i>12</i>	1,145.00	X
34	1	Rear Fender Inner Trim LH	\$	<i>12</i>	418.44	X

TOTAL	\$	13,665.43
10%	\$	1,366.54
	\$	12,298.89

Specical Nett

1	1Set	Licence Plate With Holder	\$	<i>12</i>	60.00	X
2	1Set	Bootlid inner trim board Clip	\$	<i>12</i>	40.00	X
3	1Set	Rear Bumper Parking Sensor	\$	<i>12</i>	300.00	✓
4	1Set	Rear Bumper Fastener Clip	\$	<i>12</i>	44.00	✓
5	1Set	Rear Fender Inner Trim Clip LH	\$	<i>12</i>	30.00	X
6	1Set	Rear Fender Inner Trim Clip RH	\$	<i>12</i>	30.00	X
7	1Set	Rear Bumper End Dust Cover Clip	\$	<i>12</i>	30.00	X
8	1	Rear Boot Sticker 'Trans-cab'	\$	<i>12</i>	30.00	✓
9	1	Rear Boot Sticker '6555-3333'	\$	<i>12</i>	30.00	✓
10	1	Rear Exhaust Mounting	\$	<i>12</i>	10.00	X
11	2	Rear Windscreen Sealant	\$	<i>12</i>	80.00	X
12	1	Rear Windscreen Inner Sponge Seal	\$	<i>12</i>	100.00	X
13	1	Spare Tyre	\$	<i>12</i>	180.00	X
14	1	Spare Wheel Rim	\$	<i>12</i>	126.74	X

TOTAL	\$	1,090.74
TOTAL PARTS	\$	13,389.63

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 4,200.00 *500*

To Check Electrical Lighting Concerned.

\$ 170.00 *20*

To Rust-Proofing Of The Affected Areas.

\$ 170.00 *30*

Putty And Spray Painting Of The Affected
Portion.

\$ 4,500.00 *600*

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-179**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9245K -

To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of end panel fittings and conduct water seepage test.	\$	nn 170.00	X
To transfer of luggage floor panel fittings and conduct water seepage test.	\$	nn 170.00	X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	nn 170.00	X
To transfer of boot fittings and conduct water seepage test.	\$	170.00	601
Towing fees	\$	nn 120.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X

	\$	10,780.00
TOTAL	\$	24,169.63

Repair Days~~15 Days~~

3 days

LKK Auto Consultants hence notify the Repairer the following:

- To resurvey the bodywork painting
- To set the bodywork during resurvey
- Parts and materials confirmation
- Third party survey on "Without Prejudice" basis
- No legal liability is accepted
- Surveys are to be resurveyed and is subject to the insurance Company

Acknowledgement:

Signature:

Date: