



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:

Type of Claim : TP

Vehicle No. : SKP9753L

Make & Model : MAZDA 3 4 DR SDN 1.5L SP

Year of Manufacture : 2014

Chassis No. : JM6BM42A8F0150927

Ins Company : III VS FWD S'PORE P. L.

Engine No. : P520234829

Excess : -

Policy No. : -

Date of Accident : 10.12.2017

Time of Accident : 10:20

Suggested Days of Repair : _____

In-house Vehicle Assessor

Repair Estimate

Case Owner : WILLIAM

Signature : _____

Parts (a) Cost / List Price Items \$ 1,311.50

Plus/Less 20% \$ 262.30

Total of Cost / List \$ 1,049.20

(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ -

Total Parts Cost (Appendix A) \$ 1,049.20

Labour (Appendix B) \$ 1,470.00

Total Repair Cost \$ 2,519.20

Contact No
Frt Counter Operation
 63837466 – Patrick Tia
 63837730 - Brenda Ng
 63837890 – Rohani
braddell_cr@sparkcarcare.com

Workshop Operation
 63837656 - Ngo Toh Wee
 63837362 -
 63838115 - William Wang
 63838115 - Andrew Goh
braddell_operation@sparkcarcare.com

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Eric Qian - 8288 0282

Company : Ukk

Survey conducted on : 22/12/17 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 2 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

*After repair photos.
part by part.*

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

Spare Parts

Vehicle No : SKP9753L Case Owner : WILLIAM

Make & Model : MAZDA 3 4 DR SDN 1.5L S Year Manufacture : 2014

Chassis No : JM6BM42A8F0150927 Engine No : P520234829

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear bumper X Repair	1		\$ 1,074.80			
2	Rear bumper splash shield RH ✓ hit	1		\$ 79.20			
3	Rear bumper splash shield rivet ✓ MC	4		\$ 14.00			
4	Rear bumper retainer LH X	1		\$ 36.10			
5	Rear bumper retainer RH X } NN	1		\$ 36.10			
6	RH rear fender air grille X	1		\$ 71.30			
7	0	1					
8	0	1					
9	0	1		93-2 20%: 78.56			
10	0	1					
11	0	1					
12	0	1					
13	0	1					
14	0	0					
15	0	0					
16	0	0					
17	0	0					
18	0	0					
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

Labour

Vehicle No. : SKP9753L Case Owner : WILLIAM
 Make & Model : IAZDA 3 4 DR SDN 1.5L SP Year of Manufacture : 2014

S/No	Labour Description	Estimated Price	Adjusted Price
1	Labour charges to repair and panel beat the RH rear fender and replace damaged parts. (per day \$240.00)	\$600.00	240
2	To transfer reverse sensor to new rear bumper and check wiring functions.	\$120.00	40
3	To putty, apply primer & spray-paint the RH rear fender, rear bumper and affected areas. (per panel \$250.00)	\$750.00	250
604.56			
<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: auto;"> <p>SparkAuto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey the work after spray painting • To disclose damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.