

APP. RES BY

CS/CTI 17024154/Ktd302

SIGNED BY

Kenneth

ASSIGNMENT OFFICER

SIGNED BY

menmen

Printed Name

Chong Boon Sen

CTI

Estimate No. 20/12/17 @ 11:04am

Estimated Cost

Bill to

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No.

EZ1221B

Insured

at Workshop for

Lai Huet (Meng Kee)

Tel. 64538110

of 160 Sin Ming Drive # 04-01/02

Policy No.

DMPCSN3008731703

Claim No.

SNM17D0718C01

Sum Insured

Excess

\$500.00

Make of Veh.

(Client's Record)

D.O.A. 18/12/17

CA / REV

REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time

20/12/17 @

Person Contacted

jenny

Vehs. IN/OUT

Date/Time

Action/Instruction (✓) Estimate

2/12

Revert to menmen

21/12 @ 6:01pm

inform by China Taiping authorize repair.

22/12 @ 9:55 am

email to Jenny. authorize repair.

Part by Part \$5945.58. (Red: 633.59: 9%)

ASS. REC. BY:

REF: C721**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Litche

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: 500/

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 834k

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 38 days Res.: Yes or NoLum Sum: 1.31 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: EZ 1221B Yr Regn: 08 10Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Jetta c.c. 1390Colour: M. Grey A/C: Insured / Std / NI / NASp. Reading: 191148 T/Radio: Insured / Std / NI / NAEng/No: 722C/No: WVWIK 8AM 133943Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: 225/40R18BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 18/12/17 D.O.I. 20/12/17Survey held at ✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR N/S & O/S 151

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21/12 File passed to Catherine

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 91) 15/15 Typist☐ : Final ReportResurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:

220

Transportation:

S + RS. SI

Photos

Others

TOTAL

220Report Format: 60Lump Sum / I.B. (\$) 5945.53

Add Fee:

☐ : Site Insp (\$ )☐ : Interview (\$ )☐ : Tech. Invs (\$ )☐ : Weekend (\$ )

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Dec 2017 <a href="#">Sendback Est</a>	19 Dec 2017 16:25 <b>S\$6,579.17</b>	20 Dec 2017 11:04 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	TAN YEOW LENG PETER, ID: S7048179J, Tel: +6591998822, Email: peter@advancedautowerkz.com								
Vehicle Reg. No.:	EZ1221B	Date of Loss:	18/12/2017 11:00 - :59						
Claim Type:	OD / SNM17D07187C01	Policy/Cover Note No.:	DMPCSN3008731703 (Comprehensive)						
		Excess:	S\$500.00						
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 02/01/2018]								
Driver/Custodian:	TAN YEOW LENG PETER (47 / Male), NRIC: S7048179J, Tel: +6591998822								
Adj Asg. Remarks:	SURVEY REVERT								
<b>ASSOCIATED MAIL RECEIVED</b>									
			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>									
		<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI17024154/Ktd3

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 20-12-2017



Code : CTI

## 1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	EZ 1221B
Policy No.	DMPCSN3008731703	Coverage (\$)	0.00
Claim No.	SNM17D07187C01	Excess (\$)	500.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	20/12/2017

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	18/12/2017	Inspection Date	
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		

## 5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Friday, 22 December, 2017 9:55 AM  
**To:** Jenny Lim  
**Cc:** SUR  
**Subject:** EZ1221B OD CHINA TAI PING

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **EZ1221B (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

**\*Our client reserve their right not to pay if there is no valid approval obtained before repair.**

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Denise Tay (LKKAuto)

---

To: Jasmine Lok Kheng Kwei; Veron Chen (LKKAuto); SUR  
Subject: RE: SDT4450E (our insured GX6914P/ claim ref: M462121)

Dear Jasmine,

Our surveyor has contacted, insured inform that he will get back to us asap

***"WISHES YOU A MERRY CHRISTMAS & HAPPY  
NEW YEAR 2018"***

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jasmine Lok Kheng Kwei [mailto:[jasmine\\_lok@sg.msig-asia.com](mailto:jasmine_lok@sg.msig-asia.com)]  
Sent: Friday, 22 December, 2017 9:48 AM  
To: Veron Chen (LKKAuto) <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
Subject: RE: SDT4450E (our insured GX6914P/ claim ref: M462121)

Dear Denise,

We refer to the email below.

Please advise whether our surveyor has contact insured.

Thank you.

Have a nice day ahead.

Jasmine Lok  
Executive, Claims Services (Motor)  
Direct line +65 6594 2550 | Direct fax +65 6225 7402 | [jasmine\\_lok@sg.msig-asia.com](mailto:jasmine_lok@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msig.com.sg/> | Follow us



on      
A member of  INSURANCE GROUP

From: Veron Chen (LKKAuto) [mailto:[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)]  
Sent: Wednesday, 29 November, 2017 4:43 PM  
To: Catherine Thia <[catherine\\_thia@sg.msig-asia.com](mailto:catherine_thia@sg.msig-asia.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
Cc: Jasmine Lok Kheng Kwei <[jasmine\\_lok@sg.msig-asia.com](mailto:jasmine_lok@sg.msig-asia.com)>; Katherine Wong <[katherine\\_wong@sg.msig-](mailto:katherine_wong@sg.msig-)

## View Received Message

This mail is associated with :

**EZ1221B (SNM17D07187C01)**

OD

Dec 18 2017 11:00AM

[TAN YEOW LENG PETER]

Lai Huat (Meng Kee) Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA\_TAIPING), sent on 21/12/2017 18:01 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (\$6505.57) - EZ1221B - Claim Handler: Chong Boon Sen

Approved:6505.57;Please proceed to authorize repairs UP TO \$5,192.28 BEFORE Excess of \$500.00

### DOCUMENTS SUMMARY

There are no documents.

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 8179J

### Vehicle Details

Vehicle No.: EZ1221B  
Vehicle to be Exported: No  
Intended De-registration Date: 21 Dec 2017  
Vehicle Make: VOLKSWAGEN  
Vehicle Model: JETTA 1.4 TSI AT 1K23Q5 MX  
Primary Colour: Grey  
Manufacturing Year: 2010  
Engine No.: CAV186741  
Chassis No.: WVVZZZ1KZAM133943  
Maximum Power Output: 118.0 kW (158 bhp)  
Open Market Value: \$22,085.00  
Original Registration Date: 24 Aug 2010  
First Registration Date: 24 Aug 2010  
Transfer Count: 1  
Actual ARF Paid: \$22,085.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 23 Aug 2020  
PARF Rebate Amount: \$13,251.00

### Intended COE Rebate Details

COE Expiry Date: 23 Aug 2020  
COE Category: A - Car (1600cc & below)  
COE Period(Years): 10  
QP Paid: \$32,104.00  
COE Rebate Amount: \$8,578.00  
Total Rebate Amount: \$21,829.00

The information contained herein is correct as at 21 Dec 2017

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	19/12/2017 13:06
Date Of Accident	18/12/2017 11:15
Exact Location Of Accident	GOLDEN MILE COMPLEX BUSINESS CAR PARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	EZ1221B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN YEOW LENG PETER
NRIC No	S7048179J
Email Address	PETER@ADVANCEDAUTOWERKZ.COM
Mobile Phone No	(LOCAL) +65-91998822
Alternative Phone No	OTHERS-91998822

### Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	JETTA-1.4 TSI 1623Q5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3008731703
Cover Note Number	

### Driver

Name of Driver	TAN YEOW LENG PETER
NRIC No	S7048179J
Date Of Birth	16/05/1970
Occupation	INDOOR
Date Of Driving Pass	21/11/1987
Driving Experience	30 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91998822
Fax Number	
Contact Number	OTHERS-91998822
Email Address	PETER@ADVANCEDAUTOWERKZ.COM

Email Address

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLL2649K

Vehicle Make/Model/Colour BMW 118I

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### Details of Witness

Name

Phone Number

Email Address





**SINGAPORE  
POLICE FORCE**



T/20171219/2061

Police Station Of Origin:  
Thomson NPP  
25 Sin Ming Road #01-180 SINGAPORE  
570025  
Tel No: 1800-4529999

2 of 4

Report No. T/20171219/2061

## CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
EZ1221B	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	DMPCSN30087317 03	25/02/2017	24/02/2018

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	TAN YEOW LENG PETER		ID No.	S7048179J
Related Vehicle	EZ1221B (Car)		Contact No.	91998822
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL
Driver				
Name	Chua Keng Yang		ID No.	S1438252F
Related Vehicle	SKK7682Y (Car)		Contact No.	96352482
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL

**Brief Details.**

On the 18/12/2017 at 1115hrs, my vehicle (EZ1221B) was parked inside Golden mile complex basement carpark at lots no. 170 beside a pillar. I was inside the vehicle and vehicle was slowly inching forward as the pillar was blocking my view from the oncoming cars. Just before my vehicle can exit from the said lot, there was a car (SKK7682Y) which was coming from my vehicle's left and had collided into my vehicle which caused my vehicle to hit onto the vehicle (SLL2649K) on my right which was parked inside the lot stationery. I came out of my vehicle to make a check. The damages to my vehicle is the front left portion damaged, centre grille came off, right driver door dented, front right fender and right bottom bridge dented. The damages to the oncoming car was the front right portion damaged. The damages to the stationery is the front left fender and bumper dented. We exchange particulars, took picture of the accident and drive off. There is no in-car camera installed. I did not leave any note on the stationery vehicle as the driver was not around. I am lodging report for insurance claim.



**SINGAPORE  
POLICE FORCE**



T/20171219/2061

4 of 4

Report No. T/20171219/2061

Police Station Of Origin:  
Thomson NPP  
25 Sin Ming Road #01-180 SINGAPORE  
570025  
Tel No: 1800-4529999


## CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan.

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E / Sgt 1 CASSIDY TAN GIA LOK	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 19/12/2017 12:45
Officer In Charge Of Case: TP / GIA / Staff Sgt TANG SIEW PING Contact No.: 65476430	Classification Of Case:
Authentication Stamp NP168	Signature: _____ SN 010

  
 Singapore Police Force



中国太平  
CHINA TAIPING

中国太平保险(新加坡)有限公司  
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.  
Co. Reg. No. 200206384E

MX1E  
R SN  
AN0450A  
Cov.Type: C

MOTOR PRIVATE CAR

**CERTIFICATE OF INSURANCE**  
Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)  
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960  
Road Transport Act, 1987 (Malaysia)  
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

ORIGINAL

CERTIFICATE No.	DMPCSN3008731703	Engine No :CAV186741 Chano:WVZZZ1KZAM133943
1. Index Mark and Registration Number of Vehicle	EZ1221B	AUTOSAFE
2. Name of Policy Holder	MR TAN YEOW LENG PETER	
3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment	25 February 2017	Named Drivers Ex Sect. I ..... S\$1,500.00 Additional Ex other than Named Drivers: Ex Sect. I - Age <= 25..... S\$3,000.00 Ex Sect. I - Age >= 26..... S\$500.00 * Age as at date of accident EX ON WINDSCREEN ..... S\$100.00
4. Date of Expiry of Insurance	24 February 2018	
5. Persons or Classes of Persons entitled to drive*	(a) The Policyholder.  (b) Any other person who is driving on the Policyholder's order or with his permission.  Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor vehicle.	
6. Limitations as to use:	Use for social, domestic and pleasure purposes and for the Policyholder's business. The policy does not cover use for hire or reward tuition driving test racing pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.  Excess whichever is applicable for losses occurring outside Singapore (Constructive Total Loss/Theft) will be doubled. One time Waiver of Excess for the first S\$1,000 will apply to the Insured and Named Drivers in the event of Own Damage Claim at our Authorised Workshops for each Policy Year.	

HIRE PURCHASE CO. : HITACHI LEASING (S) PTE LTD AS HP OWNER

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

**I/We hereby Certify** that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Issued By: INXPIRE .N. SOLUTIONS  
Authorised Officer

Authorised Signatory

**REPAIR DETAILS****Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 19 Dec 2017)**Parts:** 143 VOLKSWAGEN JETTA 1.4 TSI 1623Q5 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Lai Huat (Meng Kee) Motor Pte Ltd/EZ1221B/19/12/2017 16:25**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*AC DECAL	0.00	0.00	NK *8.00 F
2	1	NA	*FRONT BUMPER COVER	0.00	0.00	BT *467.00 F
3	1	NA	*FRT BUMPER C-MEMBER	0.00	0.00	BT *254.00 F
4	1	NA	*FRT BUMPER FILLING	0.00	0.00	Dis *29.00 F
5	1	NA	*FRT LOCK CARRIER	0.00	0.00	CRA *446.00 F
6	1	NA	*GRILLE	0.00	0.00	MIS *209.00 F
7	1	NA	*GRILLE TRIM FRAME	0.00	0.00	MIS *371.00 F
8	1	NA	*L/CHROME MLDG-BUMPER	0.00	0.00	CRA *160.00 F
9	1	NA	*L/F AIR GUIDE GRILLE	0.00	0.00	SCA *51.00 F
10	1	NA	*L/F BUMPER GUIDE	0.00	0.00	SCA *12.00 FX
11	1	NA	*L/F BUMPER MOULDING	0.00	0.00	Dis *34.00 F
12	1	NA	*L/F BUMPER MOULDING	0.00	0.00	Dis *28.00 F
13	1	NA	*L/F OUT BUMPER BRKT	0.00	0.00	Dis *14.00 F
14	1	NA	*L/F WING	0.00	0.00	R *340.00 FX
15	1	NA	*LEFT HEADLAMP ASSY	0.00	0.00	CRA *275.00 F
16	1	NA	*R/F DOORSKIN	0.00	0.00	BT *524.00 F
17	1	NA	*R/F RETAIN RAIL FRT	0.00	0.00	SCA *103.00 FX
18	1	NA	*R/F RETAIN RAIL REAR	0.00	0.00	SVC *103.00 FX
19	1	NA	*R/F WING	0.00	0.00	Boe *250.00 F
20	1	NA	*RIGHT HEADLAMP ASSY	0.00	0.00	Mtq *373.00 F
21	1	NA	*WARNING DECAL	0.00	0.00	NK *8.00 F

F=Franchise part.

<b>Sub Total (\$\$)</b>	<b>4,059.00</b>
<b>+ Margin on L,N Items 5.00% (\$\$)</b>	<b>202.95</b>
<b>Total Parts (\$\$)</b>	<b>4,261.95</b>

Lai Huat (Meng Kee) Motor Pte Ltd/EZ1221B/19/12/2017 16:25. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	AIR CON GAS	50.00
2	1	AUDATEX FEE	42.00
3	1	FRONT NUMBER PLATE	40.00
4	1	STONE CHIP COATING	20.00
5	1	SUNDRY PARTS	100.00
Sub Total (S\$)			252.00

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	Total Paint Labour	New	805.00
2	Total Paint Materials	New	280.42
3	Total Panel/Mechanical Labour	New	979.80
Gross Labour Cost (S\$)			2,065.22

Lai Huat (Meng Kee) Motor Pte Ltd/EZ1221B/19/12/2017 16:25. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

51 Ubi Avenue 1, #01-25  
Paya Ubi Industrial Park  
Singapore  
408933

Claim Reference: SNM17D07187C01  
Assessment Number: LHMJ0558  
Version: CHINATAI/4  
Date Calculated: 15/05/2018 06:44

Full Report - V1  
Registration: EZ 1221B  
Printed: 15/05/2018 13:44

## Summary Information

### Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	18/12/2017
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	SNM17D07187C01	Estimated Repair Time:	
Policy Number:	DMPCSN3008731703	Quote Due Date:	
Other Reference:	OD CLAIM	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	



### Vehicle Details

Vehicle	Model Specs
Manufacturer: VOLKSWAGEN	FROM 07/2010 SAFE SECURITY
Model: Jetta	DOOR MIRROR W/MEMORY CLIMATRONIC VALEO
Sub Model: BASE MODEL	INS PANEL COOLER BOX WIPER/RAIN SENSOR
Model Sheet Number: 677 01	REAR ELECT WINDOWS ELEC FOLD DR MIRRORS
Registration: EZ 1221B	AUTO DIPPING MIRROR WDW MOULDING CHROME
Registration Month:	10 SPEAKER FOG LAMPS
Registration Year:	LIGHT SWITCHING AUTO HEIGHT ADJUST SEATS
VIN Number: WVVZZZ1KZAM133943	MULTI FUNC INDICATOR COMFORT SEATS
Odometer: Not Known	LUMBAR SUPPORT OIL LEVEL GAUGE
Colour:	FRONT CENTRE ARMREST SMOKER EQUIPMENT
Engine Number:	ALTERNATOR 110A 7-SPEED DSG
Fuel Level: %	UPHILL TRACTION CONT ILLUM SUN VISORS
	CRUISE CONTROL TYRES 205/55 VR 16
	WHEELS 6.5J X 16 SPARE WHEEL STEEL
	HEAD AIRBAG FRONT SIDE AIRBAG
	TRIM COMFORTLINE 1.4 LTR 118KW
	TWO COAT METALLIC REAR BRAKE 272 X 10

## Vehicle Condition

### Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection: 19/12/2017
Place of Inspection:	
Pre-Accident Damage:	
Tyres Condition:	
Tread Depth LHF:	Tread Depth RHF:
Tread Depth LHR:	Tread Depth RHR:
Damage Areas:	Direction of Impact:



## Addresses

## Cost Summary

Total Labour	\$1,743.40
Total Paint/Material	\$273.08
Total Parts	\$3,677.10
Total of Additional Costs	\$252.00
Repair Cost Exc GST:	\$5,945.58
Overall Discount (0.0%):	- \$0.00
Excess:	-\$500.00
After Deduction -	
Grand Total Exc GST:	\$5,445.58
7 % GST:	\$381.19
Grand Total Inc GST:	\$5,826.77

## Repair Information

### LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR  
Price/Dent = \$46.00/HR

### Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
21 43 19 ZAX	R + R CHARGE AIR COOLER (LOCK CARRIER DETACHED)	2.0	9.20
50 38 55 50	RENEW FRONT LOCK CARRIER (REMOVED) INCLUDES: CONVERT ATTACHED PARTS	5.0	23.00
50 38 19 50	R + R FRONT LOCK CARRIER (BUMPER COVER REMOVED)	13.0	59.80
63 29 55 53	DOES NOT INCLUDE: ADJUST HEADLAMPS RENEW FRONT BUMPER COVER (BUMPER COVER REMOVED)	7.0	32.20
50 55 19 50	INCLUDES: R + R MOULDING, FRONT FOG LAMPS AND SPOILER R + R R/F WING (BUMPER COVER REMOVED)	7.0	32.20
50 55 55 50	INCLUDES: R + R WHEELHOUSE SHELL RENEW RIGHT FRONT WING (REMOVED)	2.0	9.20
94 15 16 00	ADJUST HEADLAMPS	2.0	9.20
92 66 19 00	R + R WASHER NOZZLE	2.0	9.20
94 15 55 50	RENEW L/HEADLAMP (HEADLAMP REMOVED)	1.0	4.60
94 15 55 50	RENEW R/HEADLAMP (HEADLAMP REMOVED)	1.0	4.60
57 11 19 00	R + R L/F DOOR HANDLE INCLUDES: R + R LOCK CYLINDER	2.0	9.20
57 39 19 50	R + R R/F OUTER DOOR SKIN (DOOR HANDLE REMOVED)	5.0	23.00
57 39 55 50	RENEW R/F DOOR SKIN	5.0	23.00

57 11 19 00	(DOOR SKIN REMOVED) R + R R/F DOOR HANDLE	2.0	9.20
	INCLUDES: R + R LOCK CYLINDER		
19 70 19 50	R + R RADIATOR	7.0	32.20
87 50 19 50	R + R CONDENSER	1.0	4.60
	(LOCK CARRIER AND BUMPER REMOVED)		
87 03 17 00	DRAIN + REFILL REFRIGERANT	5.0	23.00
1000	REMOVE + REFIT FAN SHROUD	3.0*	13.80
0391	REPAIR FRONT BUMPER SPOILER	6.0*	27.60
0471	REPAIR BONNET	10.0*	46.00
0741	REPAIR L/F WING	15.0*	69.00
1201	REPAIR L/F SIDE MEMBER CPL	40.0*	184.00
1202	REPAIR R/F SIDE MEMBER CPL	40.0*	184.00
2084	REPAIR R/SIDE FRAME	20.0*	92.00

**LABOUR COST****Total Work Units**

203.0

**Corrosion Protection External Labour**

0.0HRS

0.00

**Corrosion Protection Internal Labour**

0.0HRS

0.00

**Sub Total**

20.3HRS

\$933.80

**Paint Labour**

17.6HRS

\$809.60

**Total Labour**

37.9HRS

\$1,743.40

**PAINT WORK**

Time Basis 10 WU = 1 HR. Price = \$46.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
742	R/F WING NEW PART PAINTING	10.0	
1486	R/F DOORSKIN NEW PART PAINTING	15.0	
283	FRONT BUMPER COVER NEW PART PAINT K1R	9.0	
311	L/F BUMPER MOULDING NEW PART PAINT K1R	3.0	
315	L/F BUMPER MOULDING NEW PART PAINT K1R	3.0	
391	FRONT BUMPER SPOILER REPAIR PAINT PLASTIC	11.0	
471	BONNET REPAIR PAINTING <50%	21.0	
741	L/F WING REPAIR PAINTING <50%	11.0	
2108	R/OUTER SILL PANEL REPAIR PAINTING <50%	11.0	
2240	R/OUTER A-PILLAR REPAIR PAINTING <50%	8.0	
2292	RIGHT B-PILLAR REPAIR PAINTING <50%	9.0	
2398	R/ROOF FRAME REPAIR PAINTING <50%	8.0	
312	R/F BUMPER MOULDING SURFACE PAINT PLAST.	3.0	
316	R/F BUMPER MOULDING SURFACE PAINT PLAST.	3.0	
1201	L/F SIDE MEMBER CPL SURFACE PAINT	4.0	
1202	R/F SIDE MEMBER CPL SURFACE PAINT	4.0	
1485	L/F DOORSKIN SURFACE PAINT	7.0	
1786	R/R DOORSKIN SURFACE PAINT	7.0	

**LABOUR COST - PAINT****TIME(PAINT)**

147.0

**Preparation Main Work Metal**

21.0

**Preparation Comp. Work Plastic**

8.0

**Preparation Work Multi Layer Paint**

0.0

**Total Work Units (10WU/HR)**

176.0

**Total Paintwork Labour**

17.6HRS

\$809.60

**MATERIAL COST - PAINT**

Cost Price

New Part Painting	\$58.83
New Part Painting - Plastic K1R	\$39.36
Surface-/Blend Paint	\$40.09
Surface Paint Plastic	\$2.19
Repair Painting	\$82.37
Repair Painting Plastic	\$19.44
Material-Const Main Work Metal	\$18.10
Material-Const Comp. Work Plastic	\$12.70
Total Excluding Pearlescent Uplift	\$273.08
Pearlescent Uplift @ 0.0%	\$0.00
Total Paint Material Cost	\$273.08

## PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Price (\$)
1000	1	AC DECAL	Renew		8.00*
283	1	FRONT BUMPER COVER	1K0 807 217 AA		467.00*
			GRU		
340	1	FRT BUMPER C-MEMBER	1K5 807 109 F		254.00*
341	1	FRT BUMPER FILLING	1K5 807 248 B		29.00*
930	1	FRT LOCK CARRIER	1K0 805 588 R		446.00*
410	1	GRILLE	1K5 853 653 C 9B9		209.00*
411	1	GRILLE TRIM FRAME	1K5 853 761 A 2ZZ		371.00*
313	1	L/CHROME MLDG-BUMPER	1K0 807 243 A 2ZZ		160.00*
297	1	L/F AIR GUIDE GRILLE	1K0 853 665 K 9B9		51.00*
311	1	L/F BUMPER MOULDING	1K0 807 717 B		34.00*
			GRU		
315	1	L/F BUMPER MOULDING	1K0 853 963		28.00*
319	1	L/F OUT BUMPER BRKT	1K0 807 183		15.00*
561	1	LEFT HEADLAMP ASSY	1K6 941 029 Q		275.00*
1546	2	R/F DOOR 1-PACK ADH	D 169 300 M1		0.00G
1486	1	R/F DOORSKIN	1K5 831 106 F		524.00F
1534	1	R/F RETAIN RAIL FRT	1K5 831 308 J		0.00F
1532	1	R/F RETAIN RAIL REAR	1K5 831 300 J		0.00F
742	1	R/F WING	1K5 821 022 A		250.00*
562	1	RIGHT HEADLAMP ASSY	1K6 941 030 Q		373.00*
1000	1	WARNING DECAL	Renew		8.00*
f: OEM Parts			Saving		\$91.80
g: Original			Sub Total		\$3,502.00
h: Secondhand			Mark Up From Cost	(5 %)	\$175.10
p: Parallel			Total Parts		\$3,677.10
x: Exchange					

THIS ASSESSMENT CONTAINS UNPRICED PARTS  
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

## Extras

Description	Betterment	Price
FRONT NO PLATE SPECIALIST	0%	\$40.00
TOP UP AIRCON GAS SPECIALIST		\$50.00
STONE CHIP SPECIALIST	0%	\$20.00
COATING		
AUDATEX FEE SPECIALIST		\$42.00
SUNDRY PARTS SPECIALIST	0%	\$100.00
Total Extras		\$252.00

**Final Calculation**

<b>Total Parts</b>		<b>\$3,677.10</b>
<b>Labour</b>		
Total Panel/Mechanical	\$933.80	
Total Paintwork	\$809.60	
<b>Total Labour</b>		<b>\$1,743.40</b>
<b>Additional Costs</b>		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$252.00	
<b>Total of Additional Costs</b>		<b>\$252.00</b>
<b>Total Paint/Material Costs</b>		<b>\$273.08</b>
<b>Repair Costs Excludes GST</b>		<b>\$5,945.58</b>
<b>Deductions</b>		
Deduction for Excess ( Fixed )	-\$500.00	
<b>Total Deductions</b>		<b>-\$500.00</b>
<b>Grand Total Excludes GST (After Deduction)</b>		<b>\$5,445.58</b>
GST @ 7 %		<b>\$381.19</b>
<b>Grand Total Includes GST (After Deduction)</b>		<b>\$5,826.77</b>

**Assessment Notes**

**CHINA TAIPING  
INSURANCE (S) PTE LTD  
3 ANSON ROAD  
#15-02 SPRINGLEAF  
TOWER  
079909**

**Claim Reference: SNM17D07187C01  
Assessment Number: LHMJ0558  
Version: LAI HUAT/2  
Date Calculated: 21/12/2017 05:27**

**Full Report - V1  
Registration: EZ 1221B  
Printed: 21/12/2017 13:27**

**Summary Information**

**Claim**

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Mr K.K Lau	Date of Incident:	18/12/2017
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	SNM17D07187C01	Estimated Repair Time:	
Policy Number:	DMPCSN3008731703	Quote Due Date:	
Other Reference:	OD CLAIM	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

**Vehicle Details**

**Vehicle**

Manufacturer:	VOLKSWAGEN
Model:	Jetta
Sub Model:	BASE MODEL
Model Sheet Number:	677 01
Registration:	EZ 1221B
Registration Month:	
Registration Year:	
VIN Number:	WVWZZZ1KZAM133943
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

**Model Specs**

FROM 07/2010	SAFE SECURITY
DOOR MIRROR W/MEMORY	CLIMATRONIC VALEO
INS PANEL COOLER BOX	WIPER/RAIN SENSOR
REAR ELECT WINDOWS	ELEC FOLD DR MIRRORS
AUTO DIPPING MIRROR	WDW MOULDING CHROME
10 SPEAKER	FOG LAMPS
LIGHT SWITCHING AUTO	HEIGHT ADJUST SEATS
MULTI FUNC INDICATOR	COMFORT SEATS
LUMBAR SUPPORT	OIL LEVEL GAUGE
FRONT CENTRE ARMREST	SMOKER EQUIPMENT
ALTERNATOR 110A	7-SPEED DSG
UPHILL TRACTION CONT	ILLUM SUN VISORS
CRUISE CONTROL	TYRES 205/55 VR 16
WHEELS 6.5J X 16	SPARE WHEEL STEEL
HEAD AIRBAG	FRONT SIDE AIRBAG
TRIM COMFORTLINE	1.4 LTR 118KW
TWO COAT METALLIC	REAR BRAKE 272 X 10

**Vehicle Condition**



**Vehicle Status**

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	19/12/2017
Pre-Accident Damage:	
Tyres Condition:	

**CHINA TAIPING INSURANCE (S) PTE LTD****Claim Reference: SNM17D07187C01****Assessment Number: LHMJ0558****Version: LAI HUAT/2****Date Calculated: 21/12/2017 05:27****Full Report - V1****Registration: EZ 1221B****Printed: 21/12/2017 13:27**

Tread Depth LHF:  
Tread Depth LHR:  
Damage Areas:

Tread Depth RHF:  
Tread Depth RHR:  
Direction of Impact:

**Addresses****Cost Summary**

Total Labour	\$1,711.20
Total Paint/Material	\$280.42
Total Parts	\$4,261.95
Total of Additional Costs	\$252.00
Repair Cost Exc GST:	\$6,505.57
Overall Discount (0.0%):	- \$0.00
Excess:	-\$500.00
After Deduction -	
Grand Total Exc GST:	\$6,005.57
7 % GST:	\$420.39
Grand Total Inc GST:	\$6,425.96

**Repair Information****LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR  
Price/Dent = \$46.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
21 43 19 ZAX	R + R CHARGE AIR COOLER (LOCK CARRIER DETACHED)	2.0	9.20
50 38 55 50	RENEW FRONT LOCK CARRIER (REMOVED) INCLUDES: CONVERT ATTACHED PARTS	5.0	23.00
50 38 19 50	R + R FRONT LOCK CARRIER (BUMPER COVER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMPS	13.0	59.80
63 29 55 53	RENEW FRONT BUMPER COVER (BUMPER COVER REMOVED) INCLUDES: R + R MOULDING, FRONT FOG LAMPS AND SPOILER	7.0	32.20
50 55 19 50	R + R L/F WING (BUMPER COVER REMOVED) INCLUDES: R + R WHEELHOUSE SHELL	7.0	32.20
50 55 55 50	RENEW LEFT FRONT WING (REMOVED)	2.0	9.20
50 55 19 50	R + R R/F WING (BUMPER COVER REMOVED) INCLUDES: R + R WHEELHOUSE SHELL	7.0	32.20
50 55 55 50	RENEW RIGHT FRONT WING (REMOVED)	2.0	9.20
94 15 16 00	ADJUST HEADLAMPS	2.0	9.20
92 66 19 00	R + R WASHER NOZZLE	2.0	9.20

# CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: SNM17D07187C01

Assessment Number: LHMJ0558

Version: LAI HUAT/2

Date Calculated: 21/12/2017 05:27

Full Report - V1

Registration: EZ 1221B

Printed: 21/12/2017 13:27

94 15 55 50	RENEW L/HEADLAMP (HEADLAMP REMOVED)	1.0	4.60
94 15 55 50	RENEW R/HEADLAMP (HEADLAMP REMOVED)	1.0	4.60
57 11 19 00	R + R L/F DOOR HANDLE INCLUDES: R + R LOCK CYLINDER	2.0	9.20
57 39 19 50	R + R R/F OUTER DOOR SKIN (DOOR HANDLE REMOVED)	5.0	23.00
57 39 55 50	RENEW R/F DOOR SKIN (DOOR SKIN REMOVED)	5.0	23.00
57 11 19 00	R + R R/F DOOR HANDLE INCLUDES: R + R LOCK CYLINDER	2.0	9.20
19 70 19 50	R + R RADIATOR	7.0	32.20
87 50 19 50	R + R CONDENSER (LOCK CARRIER AND BUMPER REMOVED)	1.0	4.60
87 03 17 00	DRAIN + REFILL REFRIGERANT	5.0	23.00
1000	REMOVE + REFIT FAN SHROUD	3.0*	13.80
0391	REPAIR FRONT BUMPER SPOILER	6.0*	27.60
0471	REPAIR BONNET	10.0*	46.00
1201	REPAIR L/F SIDE MEMBER CPL	40.0*	184.00
1202	REPAIR R/F SIDE MEMBER CPL	40.0*	184.00
2084	REPAIR R/SIDE FRAME	20.0*	92.00

## LABOUR COST

Total Work Units	197.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	19.7HRS	\$906.20
Paint Labour	17.5HRS	\$805.00
Total Labour	37.2HRS	\$1,711.20

## PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$46.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
741	L/F WING NEW PART PAINTING	10.0	
742	R/F WING NEW PART PAINTING	10.0	
1486	R/F DOORSKIN NEW PART PAINTING	15.0	
283	FRONT BUMPER COVER NEW PART PAINT K1R	9.0	
311	L/F BUMPER MOULDING NEW PART PAINT K1R	3.0	
315	L/F BUMPER MOULDING NEW PART PAINT K1R	3.0	
391	FRONT BUMPER SPOILERREPAIR PAINT PLASTIC	11.0	
471	BONNET REPAIR PAINTING <50%	21.0	
2108	R/OUTER SILL PANEL REPAIR PAINTING <50%	11.0	
2240	R/OUTER A-PILLAR REPAIR PAINTING <50%	8.0	
2292	RIGHT B-PILLAR REPAIR PAINTING <50%	9.0	
2398	R/ROOF FRAME REPAIR PAINTING <50%	8.0	
312	R/F BUMPER MOULDING SURFACE PAINT PLAST.	3.0	
316	R/F BUMPER MOULDING SURFACE PAINT PLAST.	3.0	
1201	L/F SIDE MEMBER CPL SURFACE PAINT	4.0	
1202	R/F SIDE MEMBER CPL SURFACE PAINT	4.0	
1485	L/F DOORSKIN SURFACE PAINT	7.0	
1786	R/R DOORSKIN SURFACE PAINT	7.0	

## LABOUR COST - PAINT

# CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: SNM17D07187C01

Assessment Number: LHMJ0558

Version: LAI HUAT/2

Date Calculated: 21/12/2017 05:27

Full Report - V1

Registration: EZ 1221B

Printed: 21/12/2017 13:27

TIME(PAINT)	146.0	
Preparation Main Work Metal	21.0	
Preparation Comp. Work Plastic	8.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	175.0	
Total Paintwork Labour	17.5HRS	\$805.00
MATERIAL COST - PAINT		Cost Price
New Part Painting		\$78.44
New Part Painting - Plastic K1R		\$39.36
Surface-/Blend Paint		\$40.09
Surface Paint Plastic		\$2.19
Repair Painting		\$70.10
Repair Painting Plastic		\$19.44
Material-Const Main Work Metal		\$18.10
Material-Const Comp. Work Plastic		\$12.70
Total Excluding Pearlescent Uplift		\$280.42
Pearlescent Uplift @ 0.0%		\$0.00
Total Paint Material Cost		\$280.42

## PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
1000	1	AC DECAL	Renew		0% 8.00*
283	1	FRONT BUMPER COVER	1K0 807 217 AA		0% 467.00*
			GRU		
340	1	FRT BUMPER C-MEMBER	1K5 807 109 F		0% 254.00*
341	1	FRT BUMPER FILLING	1K5 807 248 B		0% 29.00*
930	1	FRT LOCK CARRIER	1K0 805 588 R		0% 446.00*
410	1	GRILLE	1K5 853 653 C 9B9		0% 209.00*
411	1	GRILLE TRIM FRAME	1K5 853 761 A 2ZZ		0% 371.00*
313	1	L/CHROME MLDG-BUMPER	1K0 807 243 A 2ZZ		0% 160.00*
297	1	L/F AIR GUIDE GRILLE	1K0 853 665 K 9B9		0% 51.00*
329	1	L/F BUMPER GUIDE	1K0 807 889 B		0% 12.00*
311	1	L/F BUMPER MOULDING	1K0 807 717 B		0% 34.00*
			GRU		
315	1	L/F BUMPER MOULDING	1K0 853 963		0% 28.00*
319	1	L/F OUT BUMPER BRKT	1K0 807 183		0% 14.00*
741	1	L/F WING	1K5 821 021 A		0% 340.00*
561	1	LEFT HEADLAMP ASSY	1K6 941 029 Q		0% 275.00*
1546	2	R/F DOOR 1-PACK ADH	D 169 300 M1		0% 0.00F
1486	1	R/F DOORSKIN	1K5 831 106 F		0% 524.00*
1534	1	R/F RETAIN RAIL FRT	1K5 831 308 J		0% 103.00*
1532	1	R/F RETAIN RAIL REAR	1K5 831 300 J		0% 103.00*
742	1	R/F WING	1K5 821 022 A		0% 250.00*
562	1	RIGHT HEADLAMP ASSY	1K6 941 030 Q		0% 373.00*
1000	1	WARNING DECAL	Renew		0% 8.00*
f: OEM Parts			Saving		\$22.60
g: Original			Sub Total		\$4,059.00
h: Secondhand			Mark Up From Cost	(5 %)	\$202.95
p: Parallel			Total Parts		\$4,261.95
x: Exchange					

**THIS ASSESSMENT CONTAINS UNPRICED PARTS**

**NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER**

Extras

**CHINA TAIPING INSURANCE (S) PTE LTD****Claim Reference: SNM17D07187C01****Full Report - V1****Assessment Number: LHMJ0558****Registration: EZ 1221B****Version: LAI HUAT/2****Printed: 21/12/2017 13:27****Date Calculated: 21/12/2017 05:27**

Description		Betterment	Price
FRONT NO PLATE	SPECIALIST	0%	\$40.00
TOP UP AIRCON GAS	SPECIALIST		\$50.00
STONE CHIP	SPECIALIST	0%	\$20.00
COATING			
AUDATEX FEE	SPECIALIST		\$42.00
SUNDRY PARTS	SPECIALIST	0%	\$100.00
		<b>Total Extras</b>	<b>\$252.00</b>

**Final Calculation**

<b>Total Parts</b>		<b>\$4,261.95</b>
<b>Labour</b>		
Total Panel/Mechanical	\$906.20	
Total Paintwork	\$805.00	
<b>Total Labour</b>		<b>\$1,711.20</b>
<b>Additional Costs</b>		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$252.00	
<b>Total of Additional Costs</b>		<b>\$252.00</b>
<b>Total Paint/Material Costs</b>		<b>\$280.42</b>
<b>Repair Costs Excludes GST</b>		<b>\$6,505.57</b>
<b>Deductions</b>		
Deduction for Excess ( Fixed )	-\$500.00	
<b>Total Deductions</b>		<b>-\$500.00</b>
<b>Grand Total Excludes GST (After Deduction)</b>		<b>\$6,005.57</b>
GST @ 7 %		<b>\$420.39</b>
<b>Grand Total Includes GST (After Deduction)</b>		<b>\$6,425.96</b>

**Assessment Notes**

**LAI HUAT (MENG KEE)  
MOTOR PTE LTD  
SIN MING INDUSTRIAL  
ESTATE SECTOR A  
BLK 21 #01-58  
SINGAPORE 575679**

**Claim Reference:**  
**Assessment Number: LHMJ0558**  
**Version: LAI HUAT/1**  
**Date Calculated: 19/12/2017 08:13**

**Full Report - V1**  
**Registration: EZ 1221B**  
**Printed: 19/12/2017 16:13**

### Summary Information

#### Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Jenny Lim	Date of Incident:	18/12/2017
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	DMPCSN3008731703	Quote Due Date:	
Other Reference:	OD CLAIM	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

### Vehicle Details

#### Vehicle

Manufacturer:	VOLKSWAGEN
Model:	Jetta
Sub Model:	BASE MODEL
Model Sheet Number:	677 01
Registration:	EZ 1221B
Registration Month:	
Registration Year:	
VIN Number:	WVWZZZ1KZAM133943
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

#### Model Specs

FROM 07/2010	SAFE SECURITY
DOOR MIRROR W/MEMORY	CLIMATRONIC VALEO
INS PANEL COOLER BOX	WIPER/RAIN SENSOR
REAR ELECT WINDOWS	ELEC FOLD DR MIRRORS
AUTO DIPPING MIRROR	WDW MOULDING CHROME
10 SPEAKER	FOG LAMPS
LIGHT SWITCHING AUTO	HEIGHT ADJUST SEATS
MULTI FUNC INDICATOR	COMFORT SEATS
LUMBAR SUPPORT	OIL LEVEL GAUGE
FRONT CENTRE ARMREST	SMOKER EQUIPMENT
ALTERNATOR 110A	7-SPEED DSG
UPHILL TRACTION CONT	ILLUM SUN VISORS
CRUISE CONTROL	TYRES 205/55 VR 16
WHEELS 6.5J X 16	SPARE WHEEL STEEL
HEAD AIRBAG	FRONT SIDE AIRBAG
TRIM COMFORTLINE	1.4 LTR 118KW
TWO COAT METALLIC	REAR BRAKE 272 X 10

### Vehicle Condition



#### Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	19/12/2017
Pre-Accident Damage:	
Tyres Condition:	

**LAI HUAT (MENG KEE) MOTOR PTE LTD****Claim Reference:****Assessment Number: LHMJ0558****Version: LAI HUAT/1****Date Calculated: 19/12/2017 08:13****Full Report - V1****Registration: EZ 1221B****Printed: 19/12/2017 16:13**

Tread Depth LHF:  
Tread Depth LHR:  
Damage Areas:

Tread Depth RHF:  
Tread Depth RHR:  
Direction of Impact:

**Addresses****Cost Summary**

Total Labour	\$1,784.80
Total Paint/Material	\$280.42
Total Parts	\$4,261.95
Total of Additional Costs	\$252.00
Repair Cost Exc GST:	\$6,579.17
Overall Discount (0.0%):	- \$0.00
Excess:	-\$500.00
After Deduction -	
Grand Total Exc GST:	\$6,079.17
7 % GST:	\$425.54
Grand Total Inc GST:	\$6,504.71

**Repair Information****LABOUR**

**Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR**  
**Price/Dent = \$46.00/HR**

**Repair /****Guide Number Repair Details**

	<b>WU</b>	<b>Cost Price (\$)</b>
21 43 19 ZAX / R + R CHARGE AIR COOLER (LOCK CARRIER DETACHED)	<b>2.0</b>	<b>9.20</b>
50 38 55 50 / RENEW FRONT LOCK CARRIER (REMOVED) INCLUDES: CONVERT ATTACHED PARTS	<b>5.0</b>	<b>23.00</b>
50 38 19 50 / R + R FRONT LOCK CARRIER (BUMPER COVER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMPS	<b>13.0</b>	<b>59.80</b>
63 29 55 53 / RENEW FRONT BUMPER COVER (BUMPER COVER REMOVED) INCLUDES: R + R MOULDING, FRONT FOG LAMPS AND SPOILER	<b>7.0</b>	<b>32.20</b>
50 55 19 50 X R + R L/F WING (BUMPER COVER REMOVED) INCLUDES: R + R WHEELHOUSE SHELL	<b>7.0</b>	<b>32.20</b>
50 55 55 50 / RENEW LEFT FRONT WING (REMOVED)	<b>2.0</b>	<b>9.20</b>
50 55 19 50 ✓ R + R R/F WING (BUMPER COVER REMOVED) INCLUDES: R + R WHEELHOUSE SHELL	<b>7.0</b>	<b>32.20</b>
50 55 55 50 ✓ RENEW RIGHT FRONT WING (REMOVED)	<b>2.0</b>	<b>9.20</b>
94 15 16 00 ✓ ADJUST HEADLAMPS	<b>2.0</b>	<b>9.20</b>
92 66 19 00 ✓ R + R WASHER NOZZLE	<b>2.0</b>	<b>9.20</b>

# LAI HUAT (MENG KEE) MOTOR PTE LTD

**Claim Reference:**

**Assessment Number: LHMJ0558**

**Version: LAI HUAT/1**

**Date Calculated: 19/12/2017 08:13**

**Full Report - V1**

**Registration: EZ 1221B**

**Printed: 19/12/2017 16:13**

94 15 55 50 /	RENEW L/HEADLAMP	1.0	4.60
	(HEADLAMP REMOVED)		
94 15 55 50 /	RENEW R/HEADLAMP	1.0	4.60
	(HEADLAMP REMOVED)		
57 11 19 00 /	R + R L/F DOOR HANDLE	2.0	9.20
	INCLUDES: R + R LOCK CYLINDER		
57 39 19 50 /	R + R R/F OUTER DOOR SKIN	5.0	23.00
	(DOOR HANDLE REMOVED)		
57 39 55 50 /	RENEW R/F DOOR SKIN	5.0	23.00
	(DOOR SKIN REMOVED)		
57 11 19 00 /	R + R R/F DOOR HANDLE	2.0	9.20
	INCLUDES: R + R LOCK CYLINDER		
19 70 19 50 /	R + R RADIATOR	7.0	32.20
87 50 19 50 /	R + R CONDENSER	1.0	4.60
	(LOCK CARRIER AND BUMPER REMOVED)		
87 03 17 00 /	DRAIN + REFILL REFRIGERANT	5.0	23.00
1000 /	REMOVE + REFIT FAN SHROUD	3 5.0*	23.00
0391 /	REPAIR FRONT BUMPER SPOILER	6 10.0*	46.00
0471 /	REPAIR BONNET	10.0*	46.00
1201 /	REPAIR L/F SIDE MEMBER CPL	40.0*	184.00
1202 /	REPAIR R/F SIDE MEMBER CPL	40.0*	184.00
2084 /	REPAIR R/SIDE FRAME	20 30.0*	138.00

## LABOUR COST

<b>Total Work Units</b>	<b>213.0</b>	
<b>Corrosion Protection External Labour</b>	<b>0.0HRS</b>	<b>0.00</b>
<b>Corrosion Protection Internal Labour</b>	<b>0.0HRS</b>	<b>0.00</b>
<b>Sub Total</b>	<b>21.3HRS</b>	<b>\$979.80</b>
<b>Paint Labour</b>	<b>17.5HRS</b>	<b>\$805.00</b>
<b>Total Labour</b>	<b>38.8HRS</b>	<b>\$1,784.80</b>

## PAINT WORK

Guide Number	Description	Time Basis 10 WU = 1 HR. Price = \$46.00/HR	WU	Cost Price (\$)
	- TWO COAT METALLIC			
741	L/F WING NEW PART PAINTING		10.0	
742	R/F WING NEW PART PAINTING		10.0	
1486	R/F DOORSKIN NEW PART PAINTING		15.0	
283	FRONT BUMPER COVER NEW PART PAINT K1R		9.0	
311	L/F BUMPER MOULDING NEW PART PAINT K1R		3.0	
315	L/F BUMPER MOULDING NEW PART PAINT K1R		3.0	
391	FRONT BUMPER SPOILERREPAIR PAINT PLASTIC		11.0	
471	BONNET REPAIR PAINTING <50%		21.0	
2108	R/OUTER SILL PANEL REPAIR PAINTING <50%		11.0	
2240	R/OUTER A-PILLAR REPAIR PAINTING <50%		8.0	
2292	RIGHT B-PILLAR REPAIR PAINTING <50%		9.0	
2398	R/ROOF FRAME REPAIR PAINTING <50%		8.0	
312	R/F BUMPER MOULDING SURFACE PAINT PLAST.		3.0	
316	R/F BUMPER MOULDING SURFACE PAINT PLAST.		3.0	
1201	L/F SIDE MEMBER CPL SURFACE PAINT		4.0	
1202	R/F SIDE MEMBER CPL SURFACE PAINT		4.0	
1485	L/F DOORSKIN SURFACE PAINT		7.0	
1786	R/R DOORSKIN SURFACE PAINT		7.0	

## LABOUR COST - PAINT

# LAI HUAT (MENG KEE) MOTOR PTE LTD

**Claim Reference:**  
**Assessment Number: LHMJ0558**  
**Version: LAI HUAT/1**  
**Date Calculated: 19/12/2017 08:13**

**Full Report - V1**  
**Registration: EZ 1221B**  
**Printed: 19/12/2017 16:13**

<b>TIME(PAINT)</b>	<b>146.0</b>	
Preparation Main Work Metal	<b>21.0</b>	
Preparation Comp. Work Plastic	<b>8.0</b>	
Preparation Work Multi Layer Paint	<b>0.0</b>	
Total Work Units (10WU/HR)	<b>175.0</b>	
Total Paintwork Labour	<b>17.5HRS</b>	<b>\$805.00</b>
<b>MATERIAL COST - PAINT</b>		<b>Cost Price</b>
New Part Painting		<b>\$78.44</b>
New Part Painting - Plastic K1R		<b>\$39.36</b>
Surface-/Blend Paint		<b>\$40.09</b>
Surface Paint Plastic		<b>\$2.19</b>
Repair Painting		<b>\$70.10</b>
Repair Painting Plastic		<b>\$19.44</b>
Material-Const Main Work Metal		<b>\$18.10</b>
Material-Const Comp. Work Plastic		<b>\$12.70</b>
Total Excluding Pearlescent Uplift		<b>\$280.42</b>
Pearlescent Uplift @ 0.0%		<b>\$0.00</b>
Total Paint Material Cost		<b>\$280.42</b>

## PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
1000	1	AC DECAL	Renew		0% 8.00*
283	1	FRONT BUMPER COVER	1K0 807 217 AA		0% 467.00*
			GRU		
340	1	FRT BUMPER C-MEMBER	1K5 807 109 F		0% 254.00*
341	1	FRT BUMPER FILLING	1K5 807 248 B		0% 29.00*
930	1	FRT LOCK CARRIER	1K0 805 588 R		0% 446.00*
410	1	GRILLE	1K5 853 653 C 9B9		0% 209.00*
411	1	GRILLE TRIM FRAME	1K5 853 761 A 2ZZ		0% 371.00*
313	1	L/CHROME MLDG-BUMPER	1K0 807 243 A 2ZZ		0% 160.00*
297	1	L/F AIR GUIDE GRILLE	1K0 853 665 K 9B9		0% 51.00*
329	1	L/F BUMPER GUIDE	1K0 807 889 B		0% 12.00*
311	1	L/F BUMPER MOULDING	1K0 807 717 B		0% 34.00*
			GRU		
315	1	L/F BUMPER MOULDING	1K0 853 963		0% 28.00*
319	1	L/F OUT BUMPER BRKT	1K0 807 183 15		0% 14.00*
741	1	L/F WING	1K5 821 021 A		0% 340.00*
561	1	LEFT HEADLAMP ASSY	1K6 941 029 Q		0% 275.00*
1546	2	R/F DOOR 1-PACK ADH	D 169 300 M1		0% 0.00F
1486	1	R/F DOORSKIN	1K5 831 106 F		0% 524.00*
1534	1	R/F RETAIN RAIL FRT	1K5 831 308 J		0% 103.00*
1532	1	R/F RETAIN RAIL REAR	1K5 831 300 J		0% 103.00*
742	1	R/F WING	1K5 821 022 A		0% 250.00*
562	1	RIGHT HEADLAMP ASSY	1K6 941 030 Q		0% 373.00*
1000	1	WARNING DECAL	Renew		0% 8.00*
f: OEM Parts				Saving	\$22.60
g: Original				Sub Total	\$4,059.00
h: Secondhand				Mark Up From Cost (5 %)	\$202.95
p: Parallel				<b>Total Parts</b>	<b>\$4,261.95</b>
x: Exchange					

**THIS ASSESSMENT CONTAINS UNPRICED PARTS**  
**NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER**

**Extras**

# LAI HUAT (MENG KEE) MOTOR PTE LTD

**Claim Reference:**  
**Assessment Number: LHMJ0558**  
**Version: LAI HUAT/1**  
**Date Calculated: 19/12/2017 08:13**


**Full Report - V1**  
**Registration: EZ 1221B**  
**Printed: 19/12/2017 16:13**

Description	Betterment	Price
FRONT NO PLATE SPECIALIST	0%	\$40.00 ✓
TOP UP AIRCON GAS SPECIALIST		\$50.00 ✓
STONE CHIP SPECIALIST	0%	\$20.00 ✓
COATING		
AUDATEX FEE SPECIALIST		\$42.00 ✓
SUNDRY PARTS SPECIALIST	0%	\$100.00 ✓
<b>Total Extras</b>		<b>\$252.00</b>

## Final Calculation

<b>Total Parts</b>	<b>\$4,261.95</b>
<b>Labour</b>	
Total Panel/Mechanical	\$979.80
Total Paintwork	\$805.00
<b>Total Labour</b>	<b>\$1,784.80</b>
<b>Additional Costs</b>	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$252.00
<b>Total of Additional Costs</b>	<b>\$252.00</b>
<b>Total Paint/Material Costs</b>	<b>\$280.42</b>
<b>Repair Costs Excludes GST</b>	<b>\$6,579.17</b>
<b>Deductions</b>	
Deduction for Excess ( Fixed )	-\$500.00
<b>Total Deductions</b>	<b>-\$500.00</b>
<b>Grand Total Excludes GST (After Deduction)</b>	<b>\$6,079.17</b>
GST @ 7 %	<b>\$425.54</b>
<b>Grand Total Includes GST (After Deduction)</b>	<b>\$6,504.71</b>

## Assessment Notes

  
 Not Authorised  
 1. B.1  
 Recovery B4 panel  
 1st NIS & C/S 1st  
 Ex \$500 9 days  
 Fax 62564315

- UKK Auto Consultants hence notify the Repairer of the following:

  - To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Date:

Kf

**LAI HUAT (MENG KEE)  
MOTOR PTE LTD  
SIN MING INDUSTRIAL  
ESTATE SECTOR A  
BLK 21 #01-58  
SINGAPORE 575679**

**Claim Reference:**  
**Assessment Number: LHMJ0558**  
**Version: LAI HUAT/2**  
**Date Calculated: 11/01/2018 17:18**

**Full Report - V1**  
**Registration: EZ 1221B**  
**Printed: 12/01/2018 01:19**

### Summary Information

#### Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Jenny Lim	Date of Incident:	18/12/2017
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	DMPCSN3008731703	Quote Due Date:	
Other Reference:	OD CLAIM	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

### Vehicle Details

#### Vehicle

Manufacturer:	VOLKSWAGEN
Model:	Jetta
Sub Model:	BASE MODEL
Model Sheet Number:	677 01
Registration:	EZ 1221B
Registration Month:	
Registration Year:	
VIN Number:	WVWZZZ1KZAM133943
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

#### Model Specs

FROM 07/2010	SAFE SECURITY
DOOR MIRROR W/MEMORY	CLIMATRONIC VALEO
INS PANEL COOLER BOX	WIPER/RAIN SENSOR
REAR ELECT WINDOWS	ELEC FOLD DR MIRRORS
AUTO DIPPING MIRROR	WDW MOULDING CHROME
10 SPEAKER	FOG LAMPS
LIGHT SWITCHING AUTO	HEIGHT ADJUST SEATS
MULTI FUNC INDICATOR	COMFORT SEATS
LUMBAR SUPPORT	OIL LEVEL GAUGE
FRONT CENTRE ARMREST	SMOKER EQUIPMENT
ALTERNATOR 110A	7-SPEED DSG
UPHILL TRACTION CONT	ILLUM SUN VISORS
CRUISE CONTROL	TYRES 205/55 VR 16
WHEELS 6.5J X 16	SPARE WHEEL STEEL
HEAD AIRBAG	FRONT SIDE AIRBAG
TRIM COMFORTLINE	1.4 LTR 118KW
TWO COAT METALLIC	REAR BRAKE 272 X 10

### Vehicle Condition

#### Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on
	Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	19/12/2017
Pre-Accident Damage:	
Tyres Condition:	

**LAI HUAT (MENG KEE) MOTOR PTE LTD****Claim Reference:****Full Report - V1****Assessment Number: LHMJ0558****Registration: EZ 1221B****Version: LAI HUAT/2****Printed: 12/01/2018 01:19****Date Calculated: 11/01/2018 17:18**

Tread Depth LHF:



Tread Depth RHF:

Tread Depth LHR:

Tread Depth RHR:

Damage Areas:

Direction of Impact:

**Addresses****Cost Summary**

Total Labour	\$1,743.40
Total Paint/Material	\$273.08
Total Parts	\$3,677.10
Total of Additional Costs	\$252.00
Repair Cost Exc GST:	\$5,945.58
Overall Discount (0.0%):	- \$0.00
Excess:	-\$500.00
After Deduction -	
Grand Total Exc GST:	\$5,445.58
7 % GST:	\$381.19
Grand Total Inc GST:	\$5,826.77

**Repair Information****LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR  
Price/Dent = \$46.00/HR

**Repair /****Guide Number Repair Details**

	WU	Cost Price (\$)
21 43 19 ZAX / R + R CHARGE AIR COOLER (LOCK CARRIER DETACHED)	2.0	9.20
50 38 55 50 RENEW FRONT LOCK CARRIER (REMOVED) INCLUDES: CONVERT ATTACHED PARTS	5.0	23.00
50 38 19 50 R + R FRONT LOCK CARRIER (BUMPER COVER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMPS	13.0	59.80
63 29 55 53 RENEW FRONT BUMPER COVER (BUMPER COVER REMOVED) INCLUDES: R + R MOULDING, FRONT FOG LAMPS AND SPOILER	7.0	32.20
50 55 19 50 ✓ R + R R/F WING (BUMPER COVER REMOVED) INCLUDES: R + R WHEELHOUSE SHELL	7.0	32.20
50 55 55 50 RENEW RIGHT FRONT WING (REMOVED)	2.0	9.20
94 15 16 00 ADJUST HEADLAMPS	2.0	9.20
92 66 19 00 R + R WASHER NOZZLE	2.0	9.20
94 15 55 50 RENEW L/HEADLAMP (HEADLAMP REMOVED)	1.0	4.60
94 15 55 50 RENEW R/HEADLAMP (HEADLAMP REMOVED)	1.0	4.60

# LAI HUAT (MENG KEE) MOTOR PTE LTD

**Claim Reference:**

**Assessment Number: LHMJ0558**

**Version: LAI HUAT/2**

**Date Calculated: 11/01/2018 17:18**

**Full Report - V1**

**Registration: EZ 1221B**

**Printed: 12/01/2018 01:19**

57 11 19 00	R + R L/F DOOR HANDLE	2.0	9.20
	INCLUDES: R + R LOCK CYLINDER		
57 39 19 50	R + R R/F OUTER DOOR SKIN	5.0	23.00
	(DOOR HANDLE REMOVED)		
57 39 55 50	RENEW R/F DOOR SKIN	5.0	23.00
	(DOOR SKIN REMOVED)		
57 11 19 00	R + R R/F DOOR HANDLE	2.0	9.20
	INCLUDES: R + R LOCK CYLINDER		
19 70 19 50	R + R RADIATOR	7.0	32.20
87 50 19 50	R + R CONDENSER	1.0	4.60
	(LOCK CARRIER AND BUMPER REMOVED)		
87 03 17 00	DRAIN + REFILL REFRIGERANT	5.0	23.00
1000	REMOVE + REFIT FAN SHROUD	3.0*	13.80
0391	REPAIR FRONT BUMPER SPOILER	6.0*	27.60
0471	REPAIR BONNET	10.0*	46.00
0741	REPAIR L/F WING	15.0*	69.00
1201	REPAIR L/F SIDE MEMBER CPL	40.0*	184.00
1202	REPAIR R/F SIDE MEMBER CPL	40.0*	184.00
2084	REPAIR R/SIDE FRAME	20.0*	92.00

## LABOUR COST

<b>Total Work Units</b>	<b>203.0</b>	
<b>Corrosion Protection External Labour</b>	<b>0.0HRS</b>	<b>0.00</b>
<b>Corrosion Protection Internal Labour</b>	<b>0.0HRS</b>	<b>0.00</b>
<b>Sub Total</b>	<b>20.3HRS</b>	<b>\$933.80</b>
<b>Paint Labour</b>	<b>17.6HRS</b>	<b>\$809.60</b>
<b>Total Labour</b>	<b>37.9HRS</b>	<b>\$1,743.40</b>

## PAINT WORK

Guide Number	Description	Time Basis 10 WU = 1 HR. Price = \$46.00/HR	WU	Cost Price (\$)
	- TWO COAT METALLIC			
742 /	R/F WING NEW PART PAINTING		10.0	
1486	R/F DOORSKIN NEW PART PAINTING		15.0	
283	FRONT BUMPER COVER NEW PART PAINT K1R		9.0	
311	L/F BUMPER MOULDING NEW PART PAINT K1R		3.0	
315	L/F BUMPER MOULDING NEW PART PAINT K1R		3.0	
391	FRONT BUMPER SPOILER REPAIR PAINT PLASTIC		11.0	
471	BONNET REPAIR PAINTING <50%		21.0	
741 ✓	L/F WING REPAIR PAINTING <50%		11.0	
2108	R/OUTER SILL PANEL REPAIR PAINTING <50%		11.0	
2240	R/OUTER A-PILLAR REPAIR PAINTING <50%		8.0	
2292	RIGHT B-PILLAR REPAIR PAINTING <50%		9.0	
2398	R/ROOF FRAME REPAIR PAINTING <50%		8.0	
312	R/F BUMPER MOULDING SURFACE PAINT PLAST.		3.0	
316	R/F BUMPER MOULDING SURFACE PAINT PLAST.		3.0	
1201	L/F SIDE MEMBER CPL SURFACE PAINT		4.0	
1202	R/F SIDE MEMBER CPL SURFACE PAINT		4.0	
1485	L/F DOORSKIN SURFACE PAINT		7.0	
1786	R/R DOORSKIN SURFACE PAINT		7.0	
<b>LABOUR COST - PAINT</b>				
	<b>TIME(PAINT)</b>		<b>147.0</b>	
	<b>Preparation Main Work Metal</b>		<b>21.0</b>	
	<b>Preparation Comp. Work Plastic</b>		<b>8.0</b>	

# LAI HUAT (MENG KEE) MOTOR PTE LTD

**Claim Reference:**

**Assessment Number: LHMJ0558**

**Version: LAI HUAT/2**

**Date Calculated: 11/01/2018 17:18**

**Full Report - V1**

**Registration: EZ 1221B**

**Printed: 12/01/2018 01:19**

Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	176.0	
Total Paintwork Labour	17.6HRS	\$809.60
<b>MATERIAL COST - PAINT</b>		<b>Cost Price</b>
New Part Painting		\$58.83
New Part Painting - Plastic K1R		\$39.36
Surface-/Blend Paint		\$40.09
Surface Paint Plastic		\$2.19
Repair Painting		\$82.37
Repair Painting Plastic		\$19.44
Material-Const Main Work Metal		\$18.10
Material-Const Comp. Work Plastic		\$12.70
Total Excluding Pearlescent Uplift		\$273.08
Pearlescent Uplift @ 0.0%		\$0.00
<b>Total Paint Material Cost</b>		<b>\$273.08</b>

## PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
1000	1	AC DECAL	Renew		0% 8.00*
283	1	FRONT BUMPER COVER	1K0 807 217 AA		0% 467.00*
			GRU		
340	1	FRT BUMPER C-MEMBER	1K5 807 109 F		0% 254.00*
341	1	FRT BUMPER FILLING	1K5 807 248 B		0% 29.00*
930	1	FRT LOCK CARRIER	1K0 805 588 R		0% 446.00*
410	1	GRILLE	1K5 853 653 C 9B9		0% 209.00*
411	1	GRILLE TRIM FRAME	1K5 853 761 A 2ZZ		0% 371.00*
313	1	L/CHROME MLDG-BUMPER	1K0 807 243 A 2ZZ		0% 160.00*
297	1	L/F AIR GUIDE GRILLE	1K0 853 665 K 9B9		0% 51.00*
311	1	L/F BUMPER MOULDING	1K0 807 717 B		0% 34.00*
			GRU		
315	1	L/F BUMPER MOULDING	1K0 853 963		0% 28.00*
319	1	L/F OUT BUMPER BRKT	1K0 807 183		0% 15.00* ✱
561	1	LEFT HEADLAMP ASSY	1K6 941 029 Q		0% 275.00*
1546	2	R/F DOOR 1-PACK ADH	D 169 300 M1		0% 0.00F
1486	1	R/F DOORSKIN	1K5 831 106 F		0% 524.00F
1534	1	R/F RETAIN RAIL FRT	1K5 831 308 J		0% 0.00F
1532	1	R/F RETAIN RAIL REAR	1K5 831 300 J		0% 0.00F
742	1	R/F WING	1K5 821 022 A		0% 250.00* ✱
562	1	RIGHT HEADLAMP ASSY	1K6 941 030 Q		0% 373.00* ✱
1000	1	WARNING DECAL	Renew		0% 8.00*
f: OEM Parts			Saving		\$91.80
g: Original			Sub Total		\$3,502.00
h: Secondhand			Mark Up From Cost	(5 %)	\$175.10
p: Parallel			<b>Total Parts</b>		<b>\$3,677.10</b>
x: Exchange					

## THIS ASSESSMENT CONTAINS UNPRICED PARTS

### NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

#### Extras

Description	Betterment	Price
FRONT NO PLATE SPECIALIST	0%	\$40.00
TOP UP AIRCON GAS SPECIALIST		\$50.00
STONE CHIP SPECIALIST	0%	\$20.00
COATING		

**LAI HUAT (MENG KEE) MOTOR PTE LTD****Claim Reference:****Assessment Number: LHMJ0558****Version: LAI HUAT/2****Date Calculated: 11/01/2018 17:18****Full Report - V1****Registration: EZ 1221B****Printed: 12/01/2018 01:19**

AUDATEX FEE	SPECIALIST		\$42.00
SUNDRY PARTS	SPECIALIST	0%	\$100.00
<b>Total Extras</b>			<b>\$252.00</b>

**Final Calculation**

<b>Total Parts</b>		<b>\$3,677.10</b>
<b>Labour</b>		
Total Panel/Mechanical	\$933.80	
Total Paintwork	\$809.60	
<b>Total Labour</b>		<b>\$1,743.40</b>
<b>Additional Costs</b>		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$252.00	
<b>Total of Additional Costs</b>		<b>\$252.00</b>
<b>Total Paint/Material Costs</b>		<b>\$273.08</b>
<b>Repair Costs Excludes GST</b>		<b>\$5,945.58</b>
<b>Deductions</b>		
Deduction for Excess ( Fixed )	-\$500.00	
<b>Total Deductions</b>		<b>-\$500.00</b>
<b>Grand Total Excludes GST (After Deduction)</b>		<b>\$5,445.58</b>
GST @ 7 %		<b>\$381.19</b>
<b>Grand Total Includes GST (After Deduction)</b>		<b>\$5,826.77</b>

**Assessment Notes**

# 新中汽配有限公司

## XINZHONG AUTOPARTS LLP

Q : 33 Tyrwhitt Road Singapore 207535  
 Tel : (65) 6291 6051 (5 Lines) Fax : (65) 6291 6052  
 Branch : 25 Kaki Bukit Rd 4 #04-41 Synergy @ KB, Singapore 417800  
 Tel : (65) 3157 2377 Fax : (65) 6702 3855  
 E-mail : info@xinzhongautoparts.com  
 Website : http://www.xinzhongautoparts.com

Tax Invoice No. : CR231525 - 129928  
 Date : 27-12-2017  
 Your Reference No. : 30 DAYS  
 Payment Term : SGD  
 Currency : 1/1  
 Page No. :  
 GST Registration No. : M90361482G

## TAX INVOICE

LKSWAGEN, AUDI, SEAT, SKODA, PORSCHE, BENTLEY, VOLVO, LAND ROVER, JAGUAR & VARIOUS OTHER LEADING EUROPEAN CAR BRANDS.

Customer  
 Lai Huat (Meng Kee) Motor Pte Ltd  
 Sin Ming Autocity  
 160 Sin Ming Drive  
 #04-01, #04-02 & #07-03

Delivery Address  
 Lai Huat (Meng Kee) Motor Pte Ltd  
 Sin Ming Autocity  
 160 Sin Ming Drive  
 #04-01, #04-02 & #07-03  
 ASAP

EM NO.	PART NO.	DESCRIPTION	LOC	QTY	UNIT PRICE	AMOUNT
	1K0807889B+	PIECE	GW B2-G1 -CTN	1 PCS	15.00	15.00 ✓

Remarks: EZ1221  
 Vehicle No. : J3301  
 Chassis No. :  
 Ordered By : Tan  
 Salesperson : 27-12-2017 16:21 PM  
 Time : NORTH-EAST  
 Zone Code :  
 XCF Planner

## Payment Collection

Cash ☐ Cheque ☐ NETS ☐

Amount SGD

Name

Date & Time

## Bank Details:

Bank Name: United Overseas Bank Limited

Account Number:

UOB, Singapore 379 301 364 5 (SGD)

UOB, Singapore 379 900 273 4 (EUR)

UOB, Singapore 379 900 040 5 (USD)

SWIFT UOVBSGSG

SUB-TOTAL	:	15.00
GST	:	1.05
TOTAL	:	16.05

Checked and Received By:

Goods sold are not refundable for cash.  
 Special Indent & Electrical Parts cannot be returned.

For and On Behalf of  
**XINZHONG AUTOPARTS LLP**  
 Co. UEN: T08LL0804C

# 新中汽配有限公司

## XINZHONG AUTOPARTS LLP

HQ : 33 Tyrwhitt Road, Singapore 207585

Tel : (65) 6291 6051 (5 Lines) Fax : (65) 6291 6052

Branch : 25 Kaki Bukit Rd 4 #01-41 Synergy @ KB, Singapore 417800

Tel : (65) 3157 2377 Fax : (65) 6702 3855

E-mail : info@xinzhongautoparts.com

Website : http://www.xinzhongautoparts.com

Tax Invoice No. :  
 Date : CE164187 - 62755  
 Your Reference No. : 27-12-2017  
 Payment Term :  
 Currency :  
 Page No. : SGD

GST Registration No.: M90361482G  
 Sales Order No. : vgs51-22 - 22272  
 GST Registration No.: M90361482G

**TAX INVOICE**

VOLKSWAGEN, AUDI, SEAT, SKODA, PORSCHE, BENTLEY, VOLVO, LAND ROVER, JAGUAR &amp; VARIOUS OTHER LEADING EUROPEAN CAR BRANDS.

## Customer

Lai Huat (Meng Kee) Motor Pte Ltd  
 Sin Ming Autocity  
 160 Sin Ming Drive  
 #04-01, #04-02 & #07-03  
 Singapore 575722

## Delivery Address

Lai Huat (Meng Kee) Motor Pte Ltd  
 Sin Ming Autocity  
 160 Sin Ming Drive  
 #04-01, #04-02 & #07-03  
 Singapore 575722

ITEM NO.	PART NO.	DESCRIPTION	LOC	QTY	UNIT PRICE	AMOUNT
1	701010002A_VA	STICKER	XZ SALE S	① PCS	8.00	8.00
2	5C6010008_VA	STICKER	XZ SALE S	① PCS	8.00	8.00

## Remarks:

Vehicle No. :  
 Chassis No. :  
 Vehicle No. : EZ1221B  
 Ordered By :  
 Vehicle Chassis :  
 Salesperson :  
 Ordered By :  
 Time :  
 Salesperson : Tan  
 Zone Code :  
 Time : 27/12/2017 14:14 PM

## Payment Collection

Cash ☐ Cheque ☐ NETS ☐

Amount SGD

Name ☐ Cheque

Date &amp; Time SGD

SUB-TOTAL : 16.00  
 GST : 1.12  
 TOTAL : 17.12

## Bank Details:

Bank Name: United Overseas Bank Limited

Account Number:

UOB, Singapore 379 301 364 5 (SGD)

UOB, Singapore 379 900 273 4 (EUR)

UOB, Singapore 379 900 040 5 (USD)

SWIFT UOVBSGSG

Checked and Received By

Goods sold are not refundable for cash.

Special Indent &amp; Electrical Parts cannot be returned.

For and On Behalf of

XINZHONG AUTOPARTS LLP

Co. UEN: T08LL0804C

# 新中汽配有限公司 XINZHONG AUTOPARTS LLP

HQ : 33 Tyrwhitt Road, Singapore 207535  
Tel : (65) 6291 6051 (5 Lines) Fax : (65) 6291 6052  
Branch : 25 Kaki Bukit Rd 4 #01-41 Synergy @ KB, Singapore 417800  
Tel : (65) 3157 2377 Fax : (65) 6702 3855  
E-mail : info@xinzhongautoparts.com  
Website : http://www.xinzhongautoparts.com

/OLKSWAGEN, AUDI, SEAT, SKODA, PORSCHE, BENTLEY, VOLVO, LAND ROVER, JAGUAR & VARIOUS OTHER LEADING EU ROPEAN CAR BRANDS.

Tax Invoice No.  
Date  
Your Reference No.  
Payment Term  
Currency  
Page No.

CR230878 - 129281  
22-12-2017

GST Registration No.: M90361482G

**TAX INVOICE**

## Customer

Lai Huat (Meng Kee) Motor Pte Ltd  
Sin Ming Autocity  
160 Sin Ming Drive  
#04-01, #04-02 & #07-03

## Delivery Address

Lai Huat (Meng Kee) Motor Pte Ltd  
Sin Ming Autocity  
160 Sin Ming Drive  
#04-01, #04-02 & #07-03  
Singapore 575722

ITEM NO.	PART NO.	DESCRIPTION	LOC	QTY	UNIT PRICE	AMOUNT
1K5831106F	DOOR PANEL	XZ SALES		1 PCS	524.00	524.00 ✓
1K6941030Q	HEADLAMP RH	XZ SALES		1 PCS	373.00	373.00 ✓
						997.00

## Remarks:

Vehicle No.

Chassis No.

Ordered By

Resperson

ve

Code

E712218

JASON

Tan

22/12/2017

NORTH-EAST

10:21 AM

XG Planner

## Payment Collection

Cash ☐ Cheque ☐ NETS ☐

Amount SGD

Name

Date & Time

## Bank Details:

Bank Name: United Overseas Bank Limited

Account Number:

UOB, Singapore 379 301 364 5 (SGD)

UOB, Singapore 379 900 273 4 (EUR)

UOB, Singapore 379 900 040 5 (USD)

SWIFT UOVBSGSG

SUB-TOTAL

GST

TOTAL

62.7

959.7

Received By

not refundable for cash.

Electrical Parts cannot be returned.

For and On Behalf of  
XINZHONG AUTOPARTS LLP  
Co. UEN: T08LL0804C

CUSTOMER'S CO

# 新中汽配有限公司

## XINZHONG AUTOPARTS LLP

HQ : 33 Tyrwhitt Road Singapore 207535

Tel : (65) 6291 6051 (5 Lines) Fax : (65) 6291 6052

Branch : 25 Kaki Bukit Rd 4 #01-41 Synergy @ KB, Singapore 417800

Tel : (65) 3157 2377 Fax : (65) 6702 3855

E-mail : info@xinzhongautoparts.com

Website : http://www.xinzhongautoparts.com

CR230879 - 129282

Tax Invoice No. 22-12-2017

Date :

Your Reference No. :

Payment Term SGD

Currency 2/2

Page No. :

GST Registration No.: M90361482G

TAX INVOICE

VOLKSWAGEN, AUDI, SEAT, SKODA, PORSCHE, BENTLEY, VOLVO, LAND ROVER, JAGUAR &amp; VARIOUS OTHER LEADING EUROPEAN CAR BRANDS.

## Customer

Lai Huat (Meng Kee) Motor Pte Ltd

Sin Ming Autobody

160 Sin Ming Drive

#04-01, #04-02 &amp; #04-03

## Delivery Address

Lai Huat (Meng Kee) Motor Pte Ltd

Sin Ming Autobody

160 Sin Ming Drive

#04-01, #04-02 &amp; #04-03

Singapore 575722

ITEM NO.	PART NO.	DESCRIPTION	LOC	QTY	UNIT PRICE	AMOUNT
----------	----------	-------------	-----	-----	------------	--------

1K5821022A+

FENDER

GW 31-C1

1 PCS

250.00

250.00 ✓

## Remarks:

Vehicle No. FZ1221B

Chassis No. JASON

Ordered By :

Salesperson Tan

Time 22/12/2017 10:21 AM

Zone Code NORTH-EAST EG Planner

## Payment Collection

Cash ☐ Cheque ☐ NETS ☐

Amount SGD

Name

Date &amp; Time

SUB-TOTAL : 2,574.88

GST : 180.18

TOTAL : 2,754.18

## Bank Details:

Bank Name: United Overseas Bank Limited

Account Number:

UOB, Singapore 379 301 364 5 (SGD)

UOB, Singapore 379 900 273 4 (EUR)

UOB, Singapore 379 900 040 5 (USD)

SWIFT UOVBSGSG

Checked and Received By

Goods sold are not refundable for cash.

Special Indent &amp; Electrical Parts cannot be returned.

For and On Behalf of  
XINZHONG AUTOPARTS LLP

Co. UEN: T08LL0804C

# 新中汽配有限公司

## XINZHONG AUTOPARTS LLP

HQ : 33 Tyrwhitt Road Singapore 207535

Tel : (65) 6291 6051 (5 Lines) Fax : (65) 6291 6052

Branch : 25 Kaki Bukit Rd 4 #01-41 Synergy @ KB, Singapore 417800

Tel : (65) 3157 2377 Fax : (65) 6702 3855

E-mail : info@xinzhongautoparts.com

Website : http://www.xinzhongautoparts.com

CR230879 - 129282  
 Tax Invoice No. 22-12-2017  
 Date :  
 Your Reference No. :  
 Payment Term SGD  
 Currency 1/2  
 Page No. :

GST Registration No.: M90361482G

## TAX INVOICE

VOLKSWAGEN, AUDI, SEAT, SKODA, PORSCHE, BENTLEY, VOLVO, LAND ROVER, JAGUAR &amp; VARIOUS OTHER LEADING EUROPEAN CAR BRANDS.

## Customer

Lai Huat (Meng Kee) Motor Pte Ltd  
 Sin Ming Autocity  
 160 Sin Ming Drive  
 #04-01, #04-02 & #07-03

## Delivery Address

Lai Huat (Meng Kee) Motor Pte Ltd  
 Sin Ming Autocity  
 160 Sin Ming Drive  
 #04-01, #04-02 & #07-03  
 Singapore 575722

ITEM NO.	PART NO.	DESCRIPTION	LOC	QTY	UNIT PRICE	AMOUNT
	1K6941029Q+	HEADLAMP LH	GW B2-J1	1 PCS	275.00	275.00 ✓
	1K0807217AAGRU+	BUMPER	GW A1	1 PCS	467.00	467.00 ✓
	1K0807243A2ZZ+	PROTECTOR CHROME LH	GW B1-F4-A	1 PCS	160.00	160.00 ✓
	1K0853963+	PROTECTOR LH	GW B2-G1-CTN	1 PCS	28.00	28.00 ✓
	1K0853665K9B9+	FOGLAMP GRILLE	GW B2-G1-CTN	1 PCS	51.00	51.00 ✓
	1K5853653C9B9+	GRILLE BASE	GW B1-A3	1 PCS	209.00	209.00 ✓
	1K0805588S+	SUPPORT PANEL	GW B2-K1	1 PCS	446.00	446.00 ✓
	1K5807248B+	FOAM INSERT	GW B2-K7	1 PCS	29.00	29.00 ✓
	1K5807109E+	REINFORCEMENT	GW B1-B4	1 PCS	254.00	254.00 ✓
	1K5853761A2ZZ+	GRILLE CHROME	GW B1-A3	1 PCS	371.00	371.00 ✓
	1K0807717BGRU+	MOLDING LH	GW B2-G1	1 PCS	34.00	34.00 ✓

## Remarks:

Vehicle No. EZ1221B

Chassis No. JASON

Ordered By :

Salesperson Tan

Time 22/12/2017 10:21 AM

Zone Code NORTH-EAST XLS Printer

## Payment Collection

Cash ☐ Cheque ☐ NETS ☐

Amount SGD

Name

Date &amp; Time

SUB-TOTAL : 2,574.00  
 GST : 130.18  
 TOTAL : 2,754.18

## Bank Details:

Bank Name: United Overseas Bank Limited

Account Number:

UOB, Singapore 379 301 364 5 (SGD)

UOB, Singapore 379 900 273 4 (EUR)

UOB, Singapore 379 900 040 5 (USD)

SWIFT UOVBSGSG

Checked and Received By

Goods sold are not refundable for cash.

Special Indent &amp; Electrical Parts cannot be returned.

For and On Behalf of

XINZHONG AUTOPARTS LLP

Co. UEN: T08LL0804C

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Dec 2017 <a href="#">Sendback Est</a>	19 Dec 2017 16:25 <b>\$6,579.17</b>	20 Dec 2017 11:04 <a href="#">Edit Adj Rpt</a>	<b>\$5,945.58</b> <a href="#">Edit Estimates</a>	<b>\$5,945.58</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured: <b>TAN YEOW LENG PETER</b> , ID: S7048179J, Tel: +6591998822, Email: peter@advancedautowerkz.com									
Vehicle Reg. No.: <b>EZ1221B</b>		Date of Loss: 18/12/2017 11:00 - :59 [87 Months and 24 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>OD / SNM17D07187C01</b>		Policy/Cover Note No.: DMPCSN3008731703 (Comprehensive)							
		Excess: \$500.00							
Repairer: <b>Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)</b> 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110									
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... [Final Rpt due 02/01/2018]									
Driver/Custodian: TAN YEOW LENG PETER (47 / Male), NRIC: S7048179J, Tel: +6591998822									
Adj Asg. Remarks: SURVEY REVERT									
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
• CHINA_TAIPING (21/12/2017): Alert - Adj Mandate Approved (\$6505.57) - EZ1221B - Claim Handler: Chong Boon S...									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**EZ1221B (SNM17D07187C01)**  
**OD**  
**Dec 18 2017 11:00AM**  
**[TAN YEOW LENG PETER]**  
**Lai Huat (Meng Kee) Motor Pte Ltd**

<a href="#">Upload Documents</a>		<a href="#">Upload Photos</a>	<a href="#">Compose New Letter</a>	<b>View</b> <a href="#">View in Browser</a> <input type="checkbox"/>	
<b>Assessment Reports</b>				1 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	19/12/17 14:02	<b>Accident Statement</b>		Load HTM	
2	19/12/17 16:25	<b>Repairer Estimates</b>		Load HTM	
		<b>LKK Auto Consultants Pte Ltd (HQ)</b>		<b>Thumbnail</b>	<b>Print</b>
1	21/12/17 13:59	<b>Adjuster Immediate Advice</b>		Load HTM	
<b>Photos/Images</b>				3 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	19/12/17 14:01	<b>Driver NRIC and Driving Licence</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	19/12/17 14:02	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	19/12/17 14:02	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	19/12/17 14:02	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	19/12/17 14:02	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
6	19/12/17 14:02	<b>Chassis Number</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
7	19/12/17 16:21	<b>Front View</b>		Load JPG	<input checked="" type="checkbox"/>
8	19/12/17 16:21	<b>Front View Left</b>		Load JPG	<input checked="" type="checkbox"/>
9	19/12/17 16:21	<b>Front View Right</b>		Load JPG	<input checked="" type="checkbox"/>
10	19/12/17 16:21	<b>Front View Right</b>		Load JPG	<input checked="" type="checkbox"/>
11	19/12/17 16:21	<b>Chassis Number</b>		Load JPG	<input checked="" type="checkbox"/>
		<b>LKK Auto Consultants Pte Ltd (HQ)</b>		<b>Thumbnail</b>	<b>Print</b>
1	15/05/18 14:21	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
2	15/05/18 14:21	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
3	15/05/18 14:21	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
4	15/05/18 14:21	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
5	15/05/18 14:21	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
6	15/05/18 14:21	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
7	15/05/18 14:21	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
8	15/05/18 14:21	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
9	15/05/18 14:21	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
10	15/05/18 14:21	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
11	15/05/18 14:21	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
12	15/05/18 14:21	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
13	15/05/18 14:21	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
14	15/05/18 14:21	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
15	15/05/18 14:21	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
16	15/05/18 14:21	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
17	15/05/18 14:21	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
18	15/05/18 14:21	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
19	15/05/18 14:21	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
20	15/05/18 14:21	General View		<input checked="" type="checkbox"/>
21	15/05/18 14:21	General View		<input checked="" type="checkbox"/>
22	15/05/18 14:21	General View		<input checked="" type="checkbox"/>
23	15/05/18 14:21	General View		<input checked="" type="checkbox"/>
24	15/05/18 14:21	General View		<input checked="" type="checkbox"/>
25	15/05/18 14:21	General View		<input checked="" type="checkbox"/>
26	15/05/18 14:21	General View		<input checked="" type="checkbox"/>
27	15/05/18 14:21	General View		<input checked="" type="checkbox"/>
28	15/05/18 14:37	Reinspection Photo		<input checked="" type="checkbox"/>
29	15/05/18 14:37	Reinspection Photo		<input checked="" type="checkbox"/>
30	15/05/18 14:37	Reinspection Photo		<input checked="" type="checkbox"/>
31	15/05/18 14:37	Reinspection Photo		<input checked="" type="checkbox"/>
32	15/05/18 14:37	Reinspection Photo		<input checked="" type="checkbox"/>
33	15/05/18 14:37	Reinspection Photo		<input checked="" type="checkbox"/>
34	15/05/18 14:37	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	19/12/17 14:01	Sketch Plan [Linked Accident Report Documents]		<input type="checkbox"/>
2	19/12/17 14:01	Police Report [Linked Accident Report Documents]		<input type="checkbox"/>
3	19/12/17 14:01	Insurance Certificate [Linked Accident Report Documents]		<input type="checkbox"/>
4	19/12/17 16:25	E-filed GIA report		<input type="checkbox"/>
5	19/12/17 16:25	Driver's NRIC + Driving License		<input type="checkbox"/>
6	19/12/17 16:25	Certificate of Insurance		<input type="checkbox"/>
7	19/12/17 16:25	Enquire PARF / COE Rebate for Registered Vehicle		<input type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/12/17 16:40	Revised Estimate		<input type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/12/17 14:00	estimate		<input type="checkbox"/>
2	22/05/18 09:11	Parts Invoice		<input type="checkbox"/>

## Linked Accident Report Documents

View

View in Browser

▼

Assessment Reports			1 per page	▼	✓
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	19/12/17 14:02	Accident Statement	1	Load HTM	

Photos/Images

3 per page

▼

✓

No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	19/12/17 14:01	Driver NRIC and Driving Licence	1	Load JPG	✓
2	19/12/17 14:02	Accident Photo	1	Load JPG	✓
3	19/12/17 14:02	Accident Photo	1	Load JPG	✓
4	19/12/17 14:02	Accident Photo	1	Load JPG	✓
5	19/12/17 14:02	Accident Photo	1	Load JPG	✓
6	19/12/17 14:02	Chassis Number	1	Load JPG	✓

Documentation

1 per page

▼

✓

No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	19/12/17 14:01	Sketch Plan	1	Load TIF	
2	19/12/17 14:01	Police Report	1	Load TIF	
3	19/12/17 14:01	Insurance Certificate	1	Load TIF	

Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:** ☐ Repairer ☐ Handling Insurer  
Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

Our File No: CS/CTI17024154/KTD3E2

Date: 22/05/2018

### REFERENCE

Insured/Claimant: TAN YEOW LENG PETER Policy No: DMPCSN3008731703  
Date of Loss: 18/12/2017 Nature of Claim: OD Claim No: SNM17D07187C01

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **EZ1221B**  
Make & Model: VOLKSWAGEN JETTA, 1.4 TSI 1623Q5 (A) Engine No: CAV186741  
Reg. Date: 24/08/2010 (Man. Year: 2010) Chassis No: WWWZZZ1KZAM133943  
Colour: Metallic Grey Odometer: 191148 km  
Engine Capacity: 1390 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18  
Front Left Side: Pirelli 7 mm Rear Left Side: Pirelli 7 mm  
Front Right Side: Pirelli 7 mm Rear Right Side: Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,261.95	3,677.10	584.85	13.72
Miscellaneous Items	252.00	252.00	0.00	0.00
Labour	2,065.22	2,016.48	48.74	2.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,579.17</b>	<b>5,945.58</b>	<b>633.59</b>	<b>9.63</b>
<b>- Excess (S\$)</b>	<b>500.00</b>	<b>500.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>6,079.17</b>	<b>5,445.58</b>	<b>633.59</b>	<b>10.42</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>425.54</b>	<b>381.19</b>	<b>44.35</b>	<b>10.42</b>
<b>Nett Amount (S\$)</b>	<b>6,504.71</b>	<b>5,826.77</b>	<b>677.94</b>	<b>10.42</b>

### INSPECTION

Date of Assignment: 20/12/2017 Present Location: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)  
Date Inspected: 20/12/2017 Inspected At: 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722  
Estimated Period of Repair: 9.0 days

---

**Adjuster:** KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 22 May 2018)  
**Parts:** 143      VOLKSWAGEN JETTA 1.4 TSI 1623Q5 (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for EZ1221B)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*AC DECAL (WCP)	Necessary	8.00 F	*8.00 F
2	1	NA	*FRONT BUMPER COVER (WCP)	Bent	467.00 F	*467.00 F
3	1	NA	*FRT BUMPER C-MEMBER (WCP)	Bent	254.00 F	*254.00 F
4	1	NA	*FRT BUMPER FILLING (WCP)	Distorted	29.00 F	*29.00 F
5	1	NA	*FRT LOCK CARRIER (WCP)	Cracked	446.00 F	*446.00 F
6	1	NA	*GRILLE (WCP)	Missing	209.00 F	*209.00 F
7	1	NA	*GRILLE TRIM FRAME (WCP)	Missing	371.00 F	*371.00 F
8	1	NA	*L/CHROME MLDG-BUMPER (WCP)	Cracked	160.00 F	*160.00 F
9	1	NA	*L/F AIR GUIDE GRILLE (WCP)	Scratched	51.00 F	*51.00 F
10	1	NA	*L/F BUMPER GUIDE (WCP)	Serviceable	12.00 F	*- F
11	1	NA	*L/F BUMPER MOULDING (WCP)	Dented	34.00 F	*34.00 F
12	1	NA	*L/F BUMPER MOULDING (WCP)	Dented	28.00 F	*28.00 F
13	1	NA	*L/F OUT BUMPER BRKT (WCP)	Distorted	14.00 F	*15.00 F
14	1	NA	*L/F WING (WCP)	Repair	340.00 F	*- F
15	1	NA	*LEFT HEADLAMP ASSY (WCP)	Cracked	275.00 F	*275.00 F
16	1	NA	*R/F DOORSKIN (WCP)	Bent	524.00 F	*524.00 F
17	1	NA	*R/F RETAIN RAIL FRT (WCP)	Serviceable	103.00 F	*- F
18	1	NA	*R/F RETAIN RAIL REAR (WCP)	Serviceable	103.00 F	*- F
19	1	NA	*R/F WING (WCP)	Buckled	250.00 F	*250.00 F
20	1	NA	*RIGHT HEADLAMP ASSY (WCP)	MTG Cracked	373.00 F	*373.00 F
21	1	NA	*WARNING DECAL (WCP)	Necessary	8.00 F	*8.00 F

F=Franchise part.

<b>Sub Total (\$\$)</b>	<b>4,059.00</b>	<b>3,502.00</b>
<b>+ Margin on L,N Items 5.00/5.00% (\$\$)</b>	<b>202.95</b>	<b>175.10</b>

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					4,261.95	3,677.10

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	AIR CON GAS (NECESSARY)	50.00	50.00
2	1	AUDATEX FEE	42.00	42.00
3	1	FRONT NUMBER PLATE (MISSING)	40.00	40.00
4	1	STONE CHIP COATING	20.00	20.00
5	1	SUNDRY PARTS (NECESSARY)	100.00	100.00
Sub Total (\$\$)			<b>252.00</b>	<b>252.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	Total Paint Labour	New	805.00	809.60
2	Total Paint Materials	New	280.42	273.08
3	Total Panel/Mechanical Labour	New	979.80	933.80
Gross Labour Cost (\$\$)			<b>2,065.22</b>	<b>2,016.48</b>

Report was unsubmitted during this print-out.
---

&lt; END OF ESTIMATES &gt;