



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
Mr LIM TIEN THENG JEANNE Blk 413 Bedok North Ave 2 #10-156 Singapore 460413 Contact No Mobile: 94319489	Cust No/Name	/Mr Lim Tien Theng Jeanne
	Reg No/Reg Date	SLQ5403G*1F / 14/07/2017
	Date In/Mileage	21/12/2017/ 0
	Chassis No	KNAFX411MH5697733
	Engine No	G4FGGH667939
	Make/Model	KIA/CERATO K3 1.6 A EX
	Colour/Trim	D7U / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	21/12/2017/ 19:04	DS	218 / Marsler	49416

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S MIPNT88088 TO CHECK LIGHTING & WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS				60 80.00
S MIPNT88088 TO REMOVE AND RE-INSTALL REAR CAPERTING AND TRIMMING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS			NN	X 600.00
S MIPNT88088 TO REPLACE REAR BUMPER, REAR BEAM, ETC -REPAIR REAR END PANEL STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS				600 1800.00
S MIPNT98088 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS				420 1260.00
P KS 86611 A7 800 COVER - REAR BUMPER	1.00	668.00	10.00	601.20
M KS 86695 A7 800 COVER - REAR BUMPER	1.00	347.00	10.00	312.30
M KS 86631 A7 800 BEAM - REAR BUMPER	1.00	313.00	10.00	281.70
M KS 86641 A7 800 STAY - REAR BUMPER	1.00	120.00	10.00	108.00
M KS 86642 A7 800 STAY - REAR BUMPER	1.00	120.00	10.00	108.00
M KS 86613 A7 001 LH BRACKET - REAR BU	1.00	29.00	10.00	26.10
M KS 86614 A7 001 RH BRACKET - REAR BU	1.00	29.00	10.00	26.10
P JJMR328954 CLIP, RR BUMPER CLIP	10.00	3.00	10.00	27.00

Z NOTES
ACCIDENT ON 12/12/2017 ALONG COMMONWEALTH AVENUE WEST
OWNER CLAIMING THIRD PARTY
REQUIRED REPLACEMENT CAR
TP : SKC5139E TP INS : EQ

3 Days.
before paint photos.
27/12/17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Confirm & accepted by *Gundap - 82880282*

Parts	1,490.40
Labour	0.00
Standard Menu	0.00
Specialist Job	3,740.00
Others(Lub, etc)	0.00
Sundry	0.00
Total(w/o GST)	5,230.40

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.