

15/5/2010

INS. CASE OWNER:

CC 3 / CTI1702

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :\$

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES/NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHB 5387X



INSRS:

WSP:

Tel:

Liability:

RMKS:

SMRT



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

ELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

SS

5,750

(5 days)

Reduction:

47

%

Email

Call

FINAL SETTLEMENT

Date/Time:

21/02/18

Confirm with:

Cee. Gel

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

27

Email

Call

Repair Cost:

SS

5,750.00

Loss of Rental (LOR):

SS

890.24

8 days

Loss of Use (LOU):

SS

50

x 8 days

Loss of Income (LOI):

SS

4000

50 x 8 days

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

5.00

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

7,045.24

Global Sum SS:

7040/-

Email

Call

FINAL PAYMENT

Date/Time:

Confirm with:

Payee 1:

SS

7,040.00

Name 1:

SMRT TAXIS PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

RECEIVED 25 JAN 2018

RECEIVED 27 FEB 2018

COPY SENT
27/2/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CTI17024272/Syb3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 22-12-2017	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLM 1686D	Veh. Inspected	SHB 5387X	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	22/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	20/12/2017	Inspection Date	21/12/2017	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTII7024272/Syb3

Date: 22.12.2017

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHB5387X


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 21.12.2017 at the premises of M/s SMRT Automotive Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	10,926.33
Revised Estimate Amount	: S\$	6,098.76
"Check" Items Amount	: S\$	882.00
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days


Yours faithfully,

SEBASTIAN YEANG
Licensed Appraiser

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5387X
 Ref. No : TAX/12/17/2121
 Reg. Date : 10/09/2012
 Vehicle Type : TAXI
 Make : CHEVROLET EPICA 2.0 VCDI
 Model : EPICA-2.0
 Name of Driver : TAN CHIN LEONG (CHEN ZHENLONG)
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 20/12/2017 06:00:00 PM
 Accident Reported Date / Time : 21/12/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Sebastian
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024993753
 Special Instruction to ARC, if any :
 DROVE IN / SLM1686D - CHINA TAIPING - LKK
 BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL
 SURVEYOR SEBASTIAN (LKK) & Email : sebastianeang@lkkauto.com HP:90036121
 LUMP SUM REPAIR
 Prepared Date : 21/12/2017 11:58:08 AM



13-40 28/12/17 Pass

Recording Camera

☐
☒ NO

Radio Antenna

☐
☒

1st witness

Date

21-12-17

2nd witness

Date

28/12/17

599592

599656

1 1 1 1
1/4 1/2 3/4 1

1 1 1
1/4 1/2 3/4

Supplementary

to Refer to the Supplementary part 1/1/1

LEE SHENG AUTO PTE LTD

Vehicle Return Date: 28/12/2017

Vehicle Return Time: 11:23

SMRT staff sign:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : KL1LA69RJBB134469

Mileage


0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,183.00	600.00
Total Spray Painting Charges	: 1,674.00	850.00
Total Material Charges	: 4,285.33	4,011.01
Other Charges	: 1,080.00	310.00
TOTAL	: 8,222.33	5,771.01
Lum Sum Total	: 8,200.00	5,750.00
No. of Repair Days	: 7.00	5.00 /
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date	: 21/12/2017 01:09:15 PM	21/12/2017 03:34:37 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 21/12/2017 01:09:15 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1712-0820
Quotation Date : 31/12
Invoice Amount : 0.00

Invoice No :

Invoice Date :

Prepared Date : 12/21/2017 1:09:22 PM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,183.00	600.00 /
Total Labour	1,183.00	600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00 /
TO RESPRAY REAR PANEL	180.00	100.00 /
TO RESPRAY REAR SPARE TYRE PANEL	180.00	100.00 /
TO RESPRAY REAR BOOT LID	378.00	200.00 /
TO RESPRAY TAIL LAMP PANEL RH	180.00	50.00 /
TO RESPRAY REAR FENDER RH	378.00	200.00 /
Total Spray Painting & Panel Beating	1,674.00	850.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40.00 /
TO PROVIDE LABOUR & MATERIAL TO REPLACE SHIELD REAR BUMPER (NET) <i>BN1</i>	140.00 <i>net</i>	140.00 /
TO TRANSFER REAR TAILGATE MECHANISM	120.00	50.00 /
TO REMOVE / REFIT SEAT	120.00	0.00
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30.00 /
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	30.00 /
TO REPLACE SUNDRY PARTS	100.00	20.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	1,080.00	310.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached	
93745100	REAR	6504569	BUMPER RR	1	1,238.00	10.00	1,114.20	Replace	Replace	No	Defun
96941154	REAR	6504571	BEAM RR BUMPER IMPACT	1	1,221.00	10.00	1,098.90	Replace	Replace	No	BT
96873838	REAR		ABSORBER ENGY RR BUMPER	1	70.00	10.00	63.00	Replace	Replace	No	CRK
96633534	REAR		BRACKET RR BUMPER SIDE RH	1	49.00	10.00	44.10	Replace	Replace	No	CRK
	REAR		SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No	DMG
96873820	REAR		COVER TOWING EYE RR	1	21.00	10.00	18.90	Replace	Replace	No	cut
96632015	REAR	6504636	PANEL END REAR	1	255.00	10.00	229.50	Replace	Replace	No	BT
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No	NEC
96515711			PANEL SPARE TYRE	1	2,299.00	100.00	0.00	Replace	Repair	No	R
96636630	REAR	6504631	REAR BOOT LID	1	974.00	10.00	876.60	Replace	Replace	No	BT
96636502	REAR		REAR BOOT HINGE	2	92.00 184	10.00	165.60	Replace	Check	No	NN
96634023	REAR	6504567	EMBLEM REAR	1	44.00	10.00	39.60	Replace	Replace	No	
96634035	REAR	6504564	LETTERING:"CHEVR OLET"	1	29.00	10.00	26.10	Replace	Replace	No	
96634897	REAR	6504565	LETTERING:"EPICA LT"	1	28.00	10.00	25.20	Replace	Replace	No	NEC
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No	
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No	
96851766	REAR	6504583	LAMP BACK UP RH	1	122.00	10.00	109.80	Replace	Check	No	NN
96976171	REAR	6504635	REAR BOOT REFLECTOR	1	165.00	10.00	148.50	Replace	Replace	No	cut
	COMMON		NUMBER PLATE FRAME	0	12.00	0.00	0.00	Replace	Not given	No	NN
96993921	REAR	6504578	TRIM TAIL LID	1	71.00	10.00	63.90	Replace	Replace	No	TN
96636677	REAR	6504634	REAR BOOT LOCK	1	77.00	10.00	69.30	Replace	Replace	No	JM
96327155	REAR		REAR BOOT ACTUATOR LOCK	1	75.00	10.00	67.50	Replace	Check	No	NN
96632854	REAR	6504632	REAR BOOT WEATHERSTRIP	1	49.00	10.00	44.10	Replace	Replace	No	Defun
96637759	REAR	6504579	TRIM REAR END PANEL	1	114.00	10.00	102.60	Replace	Replace	No	CRK
96636426	REAR	6504633	REAR BOOT STRIKER	1	15.00	10.00	13.50	Replace	Replace	No	NEC
			TRIM REAR BOOT, RH	1	125.00	10.00	112.50	Replace	Replace	No	Defun
94503739			CLIP, TRIM	10	1.00 10	10.00	9.00	Replace	Replace	No	NEC
			PANEL TAIL LAMP, RH	1	143.40	10.00	129.06	Replace	Replace	No	CRK
96851764	REAR	6504511	LAMP RR COMBINATION RH	1	415.00	10.00	373.50	Replace	Replace	No	CRK
96632800	REAR	6504638	FENDER RH REAR	1	1,467.00	100.00	0.00	Replace	Repair	No	R
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No	
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No	NEC

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
96632652	REAR	6504619	MOLDING WINDSCREEN REAR	0	45.00	10.00	0.00	Replace	Not given	No X
	COMMON		SEALANT W/SCREEN	0	37.00	0.00	0.00	Replace	Not given	No X
96851765	REAR	6504566	LAMP BACK UP LH	1	151.00	10.00	135.90	Replace	Replace S	No /
TOTAL MATERIALS							5,356.66	5,013.76		
TOTAL MATERIALS(Discounted)							4,285.33	4,011.01		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
96851765	REAR	LAMP BACK UP LH	1	151.00	10.00	135.90	Replace	Replace	No
TOTAL SUPPLEMENTARY MATERIALS						135.90			

13718.20

$$\begin{array}{r}
 5013.76 \\
 - 202 \\
 4011.01 \\
 + 600.00 \\
 + 1160.00 \\
 \hline
 5771.01
 \end{array}$$

L/S \$5750/-

Sebastian.

3/1/18

SMRT Accident Vehicle Repair Estimates

Ching Taiping

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5387X
 Ref. No : TAX/12/17/2121
 Reg. Date : 10/09/2012
 Vehicle Type : TAXI
 Make : CHEVROLET EPICA 2.0 VCDI
 Model : EPICA-2.0
 Name of Driver : TAN CHIN LEONG (CHEN ZHENLONG)
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 20/12/2017 06:00:00 PM
 Accident Reported Date / Time : 21/12/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024093753
 Special Instruction to ARC, if any :
 DROVE IN / SLM1686D - CHINA TAIPING - LKK
 Prepared Date : 21/12/2017 11:58:08 AM



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sebastian .

21/12/2017.

- Lump Sum Repair.

- Question make Item Photo

- Photo After Paint.

90036121

sebastianyang@lkkauto.com.

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : KL1LA69RJBB134469

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,183.00	0.00
Total Spray Painting Charges	: 1,674.00	0.00
Total Material Charges	: 6,989.33	6,989.33
Other Charges	: 1,080.00	0.00
TOTAL	: 10,926.33	0.00
Lum Sum Total	: 10,950.00	0.00
No. of Repair Days	: 7.00	0.00 5 days
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 21/12/2017 01:09:15 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 21/12/2017 01:09:15 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 12/21/2017 1:09:22 PM

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,183.00	0.00 600
Total Labour	1,183.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY REAR PANEL	180.00	0.00 100
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00 100
TO RESPRAY REAR BOOT LID	378.00	0.00 200
TO RESPRAY TAIL LAMP PANEL RH	180.00	0.00 50
TO RESPRAY REAR FENDER RH	378.00	0.00 200
Total Spray Painting & Panel Beating	1,674.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 40
TO PROVIDE LABOUR & MATERIAL TO REPLACE SHIELD REAR BUMPER (NET)	140.00	0.00 ✓
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 50
TO REMOVE / REFIT SEAT	120.00	0.00 X
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00 X
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 30
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 30
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	1,080.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
93745100	REAR	6504569	BUMPER RR	1	1,238.00	10.00	1,114.20	Replace	Replace ✓ Defm	No
96941154	REAR	6504571	BEAM RR BUMPER IMPACT	1	1,221.00	10.00	1,098.90	Replace	Replace ✓ OT	No
96873838	REAR		ABSORBER ENGY RR BUMPER	1	70.00	10.00	63.00	Replace	Replace ?	No
96633534	REAR		BRACKET RR BUMPER SIDE RH	1	49.00	10.00	44.10	Replace	Replace ✓ CRK	No
	REAR		SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace ✓ om	No
96873820	REAR		COVER TOWING EYE RR	1	21.00	10.00	18.90	Replace	Replace ✓ cut	No
96632015	REAR	6504636	PANEL END REAR	1	255.00	10.00	229.50	Replace	Replace ✓ OT	No
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace ✓ NEC	No
96515711			PANEL SPARE TYRE	1	2,299.00	10.00	2,069.10	Replace	Replace R	No
96636630	REAR	6504631	REAR BOOT LID	1	974.00	10.00	876.60	Replace	Replace ✓ Defm	No
96636502	REAR		REAR BOOT HINGE	2	92.00	10.00	165.60	Replace	Replace ?	No
96634023	REAR	6504567	EMBLEM REAR	1	44.00	10.00	39.60	Replace	Replace ✓ NEC	No
96634035	REAR	6504564	LETTERING:"CHEVR OLET"	1	29.00	10.00	26.10	Replace	Replace ✓ NEC	No
96634897	REAR	6504565	LETTERING:"EPICA LT"	1	28.00	10.00	25.20	Replace	Replace ✓ NEC	No
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓ NEC	No
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓ NEC	No
96851766	REAR	6504583	LAMP BACK UP RH	1	122.00	10.00	109.80	Replace	Replace ?	No
96976171	REAR	6504635	REAR BOOT REFLECTOR	1	165.00	10.00	148.50	Replace	Replace ✓ cut	No
	COMMO N		NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace X	No
96993921	REAR	6504578	TRIM TAIL LID	1	71.00	10.00	63.90	Replace	Replace ✓ Defm	No
96636677	REAR	6504634	REAR BOOT LOCK	1	77.00	10.00	69.30	Replace	Replace ✓ Defm	No
96327155	REAR		REAR BOOT ACTUATOR LOCK	1	75.00	10.00	67.50	Replace	Replace ?	No
96632854	REAR	6504632	REAR BOOT WEATHERSTRIP	1	49.00	10.00	44.10	Replace	Replace ✓ Defm	No
96637759	REAR	6504579	TRIM REAR END PANEL	1	114.00	10.00	102.60	Replace	Replace ?	No
96636426	REAR	6504633	REAR BOOT STRIKER	1	15.00	10.00	13.50	Replace	Replace ✓ NEC	No
			TRIM REAR BOOT, RH	1	125.00	10.00	112.50	Replace	Replace ✓ Defm	No
94503739			CLIP,TRIM	10	1.00	10.00	9.00	Replace	Replace ✓ NEC	No
			PANEL TAIL LAMP, RH	1	143.40	10.00	129.06	Replace	Replace ✓ CRK	No
96851764	REAR	6504511	LAMP RR COMBINATION RH	1	415.00	10.00	373.50	Replace	Replace ?	No
96632800	REAR	6504638	FENDER RH REAR	1	1,467.00	10.00	1,320.30	Replace	Replace R	No
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓ NEC	No
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓ NEC	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
96632652	REAR	6504619	MOLDING WINDSCREEN REAR	1	45.00	10.00	40.50	Replace	Replace X	No
	COMMON		SEALANT W/SCREEN	2	37.00	0.00	74.00	Replace	Replace X	No
TOTAL MATERIALS							8,736.66	8,736.66		
TOTAL MATERIALS(Discounted)							6,989.33	6,989.33		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

Shu Pei (LKKAUTO)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Wednesday, 27 December, 2017 2:17 PM
To: Shu Pei (LKKAUTO)
Cc: Jas Khine (LKKAUTO); Thin Thin (LKKAUTO); Admin A
Subject: CTP REF NO. SNM17D07226C02 - Accident Involving SLM1686D (OI : CAI - TBA) and SHB5387X (TP : LKK REF -CC3/CTI17024272/Syb3) on 20.12.2017
Attachments: GIA REPORT SLM1686D.pdf; TayHP_SNM17D07226C02-SLM1686D-LKKDirectSettlementAccidentLtr_CLCR95.621.pdf

WITHOUT PREJUDICE

Dear Sir/Mdm,

We refer to the above matter and your email dated 26 December 2017.

We enclosed herewith a copy of our Insured GIA Report & Letter to our Insured for your attention.

Regards,

Irene Tay

Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389-6192
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: irene.tay@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Tuesday, 26 December, 2017 9:20 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Alfred Toh <alfred.toh@sg.cntaiping.com>; Irene Tay <irene.tay@sg.cntaiping.com>; Jas Khine (LKKAUTO) <jaskhine@lkkauto.com>; Thin Thin (LKKAUTO) <thinthin@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Direct Settlement - Accident Involving SLM1686D (OI : CAI - TBA) and SHB5387X (TP : LKK REF - CC3/CTI17024272/Syb3) on 20.12.2017

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHB 5387X at M/s SMRT Automotive Services Pte Ltd - Woodlands.

Enclosed for your perusal is:

- TP GIA report

- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Jas and she can be contacted at DID: 6841 2928.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.sg.ontaiiping.com
Co. Reg. No. 200208364E

Our Reference: **SNM17D07226/C02/6**

Date : **27 DECEMBER 2017**

via Ordinary & Registered Mail

**SEE KIM SIONG PETER
205 JALAN EUNOS
#10-04 EUNOS MANSION
SINGAPORE 419535**

Dear Sir / Madam

**ACCIDENT INVOLVING SLM1686D AND SHB5387X ON 20 DECEMBER 2017
ALONG PARLIAMENT PLACE**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHB5387X**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : JAS
Ref : CC3/CT117024272/SYB3
Contact No : 6841-2928
via Email : shupeil@lkkauto.com

CC : Agent - (AN0006A) - ALFA CREDIT PTE LTD

F01/LKKDS-2013



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI17024272/Syb3s2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 27-02-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLM 1686D	Veh. Inspected	SHB 5387X
Policy No.	DMPCSN3035061700	Coverage (\$)	0.00
Claim No.	SNM17D07226/C02/6	Excess (\$)	0.00
Assign From		Assign Date	21/12/2017

2. Vehicle Particulars & Condition

Make & Model	CHEVROLET EPICA	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	KL1LA69RJBB134469	Colour	MAROON
Odometer	599591	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55R15	FALKEN	6 mm
L/H Front Tyre	205/55R15	FALKEN	6 mm
R/H Rear Tyre	205/55R15	FALKEN	6 mm
L/H Rear Tyre	205/55R15	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	20/12/2017	Inspection Date	21/12/2017
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5387X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER RR (DISC 10%)	DEFORMED	1,238.00	1,114.20
1	BEAM RR BUMPER IMPACT (DISC 10%)	BENT	1,221.00	1,098.90
1	ABSORBER ENGY RR BUMPER (DISC 10%)	CRACKED	70.00	63.00
1	BRACKET RR BUMPER SIDE RH (DISC 10%)	CRACKED	49.00	44.10
1	COVER TOWING EYE RR (DISC 10%)	CUT	21.00	18.90
1	PANEL END REAR (DISC 10%)	DENTED	255.00	229.50
1	REAR BOOT LID (DISC 10%)	BENT	974.00	876.60
1	EMBLEM REAR (DISC 10%)	NECESSARY	44.00	39.60
1	LETTERING: "CHEVROLET" (DISC 10%)	NECESSARY	29.00	26.10
1	LETTERING: "EPICA LT" (DISC 10%)	NECESSARY	28.00	25.20
1	REAR BOOT REFLECTOR (DISC 10%)	CUT	165.00	148.50
1	TRIM TAIL LID (DISC 10%)	TORN	71.00	63.90
1	REAR BOOT LOCK (DISC 10%)	JAMMED	77.00	69.30
1	REAR BOOT WEATHERSTRIP (DISC 10%)	DEFORMED	49.00	44.10
1	TRIM REAR END PANEL (DISC 10%)	CRACKED	114.00	102.60
1	REAR BOOT STRIKER (DISC 10%)	NECESSARY	15.00	13.50
1	TRIM REAR BOOT, RH (DISC 10%)	DEFORMED	125.00	112.50
10	CLIP, TRIM @ \$1.00 (DISC 10%)	NECESSARY	10.00	9.00
1	PANEL TAIL LAMP, RH (DISC 10%)	CRACKED	143.40	129.06
1	LAMP RR COMBINATION RH (DISC 10%)	CRACKED	415.00	373.50
1	LAMP BACK UP LH (DISC 10%)	CRACKED	151.00	135.90
1	SENSOR REVERSE (SN)	DAMAGED	180.00	180.00
1	SEALANT SIKAFLEX (SN)	NECESSARY	37.00	37.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
2	REAR BOOT HINGE @ \$92.00	NOT NECESSARY	184.00	-
1	LAMP BACK UP RH	NOT NECESSARY	122.00	-
1	NUMBER PLATE FRAME	NOT NECESSARY	12.00	-
1	REAR BOOT ACTUATOR LOCK	NOT NECESSARY	75.00	-

Report Ref No. CC3/CT117024272/Syb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	MOLDING WINDSCREEN REAR	NOT NECESSARY	45.00	-
1	SEALANT W/SCREEN	NOT NECESSARY	37.00	-
1	PANEL SPARE TYRE	TO REPAIR SEE LABOUR	2,299.00	-
1	FENDER RH REAR	TO REPAIR SEE LABOUR	1,467.00	-
1	SHIELD REAR BUMPER (SN)	NECESSARY	140.00	140.00
			9,921.20	5,153.76
	LABOUR			
	PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF PANEL SPARE TYRE AND FENDER RH REAR. SPRAY PAINT.		1,183.00	600.00
	TO CHECK WIRING AND SYSTEM FUNCTION.	NOT NECESSARY	80.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	40.00
	TO TRANSFER REAR TAILGATE MECHANISM.		120.00	50.00
	TO REMOVE / REFIT SEAT.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIX REAR WINDSCREEN.	NOT NECESSARY	120.00	-
	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.		120.00	30.00
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.		120.00	30.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			3,797.00	1,620.00
	GRAND TOTAL		13,718.20	6,773.76
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,750.00

Report Ref No. CC3/CT117024272/Syb3s2

YEANG WAI KEEN

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.