

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG17024353/T1PA3Q2

Date: 20/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100384904

Claimant
Vehicle No : SJT9191Z **Insured Vehicle No :** SKP3760E

Date of Loss: 21/12/2017 Nature of Claim: TP Claim No: 0101719085SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT9191Z		
Make & Model:	MERCEDES-BENZ CLA180, 1.6 COUPE URBAN (R18 LED) (A)	Engine No:	27091031433801
Reg. Date:	22/11/2017 (Man. Year: 2017)	Chassis No:	WDD1173422N575979
Colour:	Blue	Odometer:	921 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,330.36	21,178.21	8,152.15	27.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,128.00	3,090.00	3,038.00	49.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	35,458.36	24,268.21	11,190.15	31.56
+ GST 7.00/7.00% (S\$)	2,482.09	1,698.77	783.32	31.56
Nett Amount (S\$)	37,940.45	25,966.98	11,973.47	31.56
+ Car Rental (20.0 x S\$100.00/day) (S\$)		2,000.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		200.00		
Nett Liability (S\$)		28,174.43		

INSPECTION

Date of Assignment: 26/12/2017

Date Inspected: 27/12/2017 Inspected At:

Accord Auto Services Pte Ltd (Bukit Merah)
BLK 1009 BUKIT MERAH LANE 3,
#01-80
Singapore 159723

Estimated Period of Repair: 10.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	1,290.00 FL	*1,290.00 FL
2	2		*FRONT BONNET HINGE	Bent	196.00 FL	*196.00 FL
3	1		*FRONT BONNET LOCK	Not Necessary	265.94 FL	*- FL
4	1		*FRONT FENDER RH	Bent	699.00 FL	*699.00 FL
5	1		*FRONT FENDER SHIELD RH	Deformed	208.00 FL	*208.00 FL
6	1		*FRONT HEADLAMP LH	Not Necessary	2,700.00 FL	*- FL
7	1		*FRONT HEADLAMP RH	Cracked	2,700.00 FL	*2,700.00 FL
8	1		*FRONT HEADLAMP LOWER BRACKET RH	Necessary	110.00 FL	*110.00 FL
9	1		*FRONT FENDER INNER PANEL RH	Repair	800.00 FL	*- FL
10	1		*FRONT FENDER TOP GARNISH RH	Deformed	75.00 FL	*75.00 FL
11	1		*RH ROOF MOULDING /GARNISH	Not Necessary	728.02 FL	*- FL
12	1		*FRONT REINFORCEMENT	Bent	380.00 FL	*380.00 FL
13	1		*FRONT BUMPER SPONGE	Not Necessary	240.00 FL	*- FL
14	1		*FRONT BUMPER SIDE RETAINER	N/S Not Necessary /O/SDeformed	230.00 FL	*115.00 FL
15	1		*FRONT FOGLAMP GARNISH	N/S Not Necessary/O/SDistorted	250.00 FL	*125.00 FL
16	1		*FRONT BUMPER TOW COVER	Deformed	65.00 FL	*65.00 FL
17	1		*FRONT ABSORBER LH	Not Necessary	695.00 FL	*- FL
18	1		*FRONT ABSORBER RH	Bent	695.00 FL	*695.00 FL
19	1		*FRONT ABSORBER MOUNTING RH	Not Necessary	270.00 FL	*- FL
20	1		*FRONT ABSORBER MOUNTING LH	Not Necessary	270.00 FL	*- FL
21	1		*FRONT ABSORBER STOPPER RH	Not Necessary	80.00 FL	*- FL
22	1		*FRONT ABSORBER STOPPER LH	Not Necessary	80.00 FL	*- FL
23	2		*FRONT ABSORBER DUST COVER LH	Not Necessary	156.00 FL	*- FL
24	2		*FRONT ABSORBER BALL BEARING	Not Necessary	150.00 FL	*- FL
25	1		*FRONT LOWER ARM RH	Bent	580.00 FL	*580.00 FL
26	2		*FRONT STABILIZER BAR WITH BUSH	Not Necessary	395.00 FL	*- FL
27	1		*KNUCKLE ARM RH	Bent	932.18 FL	*932.18 FL
28	1		*LINKAGE RH	Bent	90.00 FL	*90.00 FL
29	1		*WHEEL BEARING RH	Not Necessary	198.20 FL	*- FL
30	1		*CAR PLATE NUMBER WITH HOLDER	Not Necessary	50.00 FS	*- FS
31	2		*FRONT BUMPER SENSOR	Distorted	376.00 FS	*376.00 FS
32	19		*BONNET INSULATOR CLIPS	Necessary	76.00 FS	*76.00 FS
33	10		*FRONT FENDER SHIELD CLIPS	Necessary	40.00 FS	*40.00 FS
34	1		*FRONT BUMPER	Deformed	3,650.00 FS	*3,650.00 FS
35	15		*FRONT BUMPER CLIPS	Necessary	82.50 FS	*82.50 FS
36	1		*FRONT BUMPER LOWER SPOILER (AFTER MARKET)	Cracked	680.00 FS	*680.00 FS
37	1		*FRONT LOWER GRILLE	Not Necessary	105.80 FS	*- FS
38	2		*FRONT LOWER GRILLE SIDE GARNISH	Distorted	170.00 FS	*170.00 FS
39	1		*FRONT GRILLE (AFTER MARKET)	Cut	880.00 FS	*880.00 FS
40	1		*FROM LOGO	Necessary	120.00 FS	*120.00 FS
41	1		*SET FRONT GRILLE CHROME	Cut	220.00 FS	*220.00 FS
42	1		*FRONT LOGO AMG	Not Necessary	135.00 FS	*- FS
43	1		*SET FRONT FOGLAMP TOP GARNISH (AFTER MARKET)	Cracked	260.00 FS	*260.00 FS
44	1		*FRONT TYRE	Not Necessary	320.00 FS	*- FS
45	1		*SET TYRE RIM	Dented	2,800.00 FS	*1,800.00 FS
46	1		*FRONT BEAM	Cracked	655.40 FL	*655.40 FL
47	1		*LOWER COVER/GARNISH	Deformed	85.00 FL	*85.00 FL
48	1		*DRIVE SHAFT RH	Bent	1,940.40 FL	*1,940.40 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
49	1		*HEADLAMP SUPPORT BRACKET RH	Cracked	35.00 FL	*35.00 FL
50	1		*FRONT REINFORCEMENT ARM RH	Bent	168.30 FL	*168.30 FL
51	1		*SPARE TANK	Deformed	180.50 FL	*180.50 FL
52	1		*UNDER ENGINE COVER (FRONT)	Deformed	182.97 FL	*182.97 FL
53	1		*UNDER ENGINE COVER (CENTRE)	Deformed	290.60 FL	*290.60 FL
54	1		*SET UNDER ENGINE COVER SCREW /CLIPS	Necessary	65.00 FS	*65.00 FS
55	1		*FRONT SAFETY BELT RH	Activated	620.00 FL	*620.00 FL
56	1		*REAR SEAT BELT RH	Activated	465.00 FL	*465.00 FL
57	1		*REAR SEAT BELT LH	Activated	465.00 FL	*465.00 FL
58	2		*TRIM	Cracked	72.00 FL	*72.00 FL
59	1		*LOCK FOR SEAT BACKREST LH	Activated	360.00 FL	*360.00 FL
60	1		*LOCK FOR SEAT BACKREST RH	Activated	360.00 FL	*360.00 FL
61	2		*RETAINING CLIP	Necessary	36.00 FL	*36.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 31,474.81 22,595.85
- List Item Discount on L Items 10.00/10.00% (\$\$) 2,144.45 1,417.64

Total Parts (\$\$) 29,330.36 21,178.21

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING TO ALL AFFECTED AREAS	New	1,200.00	1,000.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGES PARTS TO KNOCK ,JACK ,CUT ,WELD AND REALIGN ACCIDENT AFFECTED AREA	New	2,000.00	1,100.00
3	CHECK WIRING SYSTEM & LIGHT	New	100.00	50.00
4	ANTI RUST TREATMENT	New	120.00	40.00
5	TO CHECK & ADJUST WHEEL ALIGNMENT	New	100.00	80.00
6	TO REMOVE /REFIX FRONT BONNET ATTACHMENT	New	200.00	0.00
7	TO CHECK WATER LEAKING	New	120.00	30.00
8	TO REMOVE/REFIX BUMPER SENSOR	New	120.00	30.00
9	TO REMOVE/REFIX FRONT UNDER CARRIAGE	New	250.00	120.00
10	TO REMOVE/REPLACE TYRE & RIM	New	250.00	40.00
11	TO REMOVE/REPLACE OUTER ROOF MOULDING	New	250.00	0.00
12	TO REALIGN & STRAIGHT MAIN CHASSIS FRAME	New	280.00	0.00
13	COMPUTER DIAGNOSTIC	New	350.00	200.00
14	COSMICS COATING 3 LAYERS WITH PAINT CORRECTION POLISH	New	788.00	400.00
Gross Labour Cost (\$\$)			6,128.00	3,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >