

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AXA17024360/KPS3Q2
Date: 11/08/2021REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	GA216355
Claimant Vehicle No :	SKB7907Y	Insured Vehicle No :	SKV4209T
Date of Loss:	22/12/2017	Nature of Claim:	TP
		Claim No:	C0464232

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB7907Y	Engine No:	HIDDEN
Make & Model:	BMW 320I, 2.0 (A)	Chassis No:	WBAPG5600NM22400
Reg. Date:	01/03/2010 (Man. Year: 2010)	Odometer:	175826 km
Colour:	Metallic Black		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Continental 3 mm	Rear Left Side:	Continental 4 mm
Front Right Side:	Continental 3 mm	Rear Right Side:	Continental 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	450.00	340.00	110.00	24.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	450.00	340.00	110.00	24.44
+ GST 7.00/7.00% (S\$)	31.50	23.80	7.70	24.44

Nett Amount (S\$)	481.50	363.80	117.70	24.44
+ Loss of Use (1.0 x S\$80.00/day) (S\$)		80.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		445.80		
Global Sum Settlement (S\$)		440.00		

INSPECTION

Date of Assignment: 22/12/2017

Date Inspected: 28/02/2018

Estimated Period of Repair: 1.0 days

Inspected At:

Alans United Auto Pte Ltd (HQ)
 BLK 7 SIN MING INDUSTRIAL ESTATE #01-76
 Singapore 575642

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 Aug 2021)
Parts: N/A	BMW 320I 2.0 (A) (Model not available in database)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKB7907Y)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE FRONT BUMPER FOR REPAIR ,ADJUST ,ALIGN AND TO REFIX FRONT BUMPER	New	200.00	120.00
2	TO PUTTY AND SPRAY FRONT BUMPER	New	250.00	220.00
			Gross Labour Cost (S\$)	340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >