

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Imm Auth'd	Status
Main	23 Dec 2017 Sendback Est	23 Dec 2017 12:08 S\$4,183.70	26 Dec 2017 14:48 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	HARVEST PRODUCTIONS PTE LTD , Co. Reg. No.: 200807428M, Tel: +6596532609		
Vehicle Reg. No.:	GBE5660L	Date of Loss:	22/12/2017 08:00 - :59
Claim Type:	OD / 542255	Policy/Cover Note No.:	A28878418MKC (Comprehensive) Coverage: 18/01/2017 - 17/01/2018
		Excess:	S\$600.00
Repairer:	Kan Fook Sing Motor Workshop (Defu) No. 61 Defu Lane 12, 539147 Defu Lane - Tel: 67479560		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Joslin Lim - 6643 1327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/12/2017]		
Driver/Custodian:	LIM BOON THYE (55 / Male) , NRIC: S1529817, Tel: +6596532609		
Adj. Asg. Remarks:	Please revert.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17024383/Gtd3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 26-12-2017		
		Code : MSG		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		GBE 5660L	
Policy No. A28878418MKC	Coverage (\$)		0.00	
Claim No. 542255	Excess (\$)		600.00	
Assign From MERIMEN (JOSLIN LIM)	Assign Date		26/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No. HIDDEN	Year of Reg.			
Chassis No.	Colour			
Odometer -	Steering			
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date 22/12/2017	Inspection Date			
Survey held at	KAN FOOK SING MOTOR WORKSHOP 61 DEFU LANE 12 SINGAPORE 539147			
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/12/2017 16:15
Date Of Accident	22/12/2017 08:00
Exact Location Of Accident	JALAN BUKIT MERAH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE5660L
Insured/Policyholder	
Name Of Registered Owner	HARVEST PRODUCTIONS PTE LTD
Co Reg No	200807428M
Email Address	CHANE@HARVESTPRODUCTIONS.SG
Mobile Phone No	(LOCAL) +65-93628752
Alternative Phone No	OFFICE-62977747
Vehicle Particulars	
Manufacturer	TOYOTA
Model	DYNA 3.0 DIESEL TURBO M/T 2WD LORRY
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A28878418 MKC
Cover Note Number	18/01/2017 TO 17/01/2018
Driver	
Name of Driver	LIM BOON THYE
NRIC No	S1529817J
Date Of Birth	05/12/1962
Occupation	OUTDOOR
Date Of Driving Pass	20/12/1982
Driving Experience	35 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96532609
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address APT BLK 240 BUKIT PANJANG RING ROAD #08-125 (S) 670240

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

refer with attach.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJS7783J

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver TAN GIM YONG JIMMY

NRIC/Passport Number S1799105A

Contact Number 84887783

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver) 1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLQ6057R

Vehicle Make/Model/Colour HONDA

Details Of Properties

Vehicle Category

PRIVATE HIRE

Name of Driver

THOMAS TAN LIK JIN

NRIC/Passport Number

S1821507A

Contact Number

97228516

Address

Postcode

Insurance Company Name

Nature Of Damage


No. Of Passenger (Including Driver)

2

A: GBE 5660 L

B: SIS 7783 L

C: SLQ 6057 R



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22/12/2017 @ 0800hrs, I was driving along Jalan Bukit Merah. Suddenly I accidentally hit into the rear of car SIS 7783 L & the impact pushed him forward to hit the rear of front car SLQ 6057 R.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

4:35 pm 22-12-17

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7428M
Vehicle Details	
Vehicle No.:	GBE5660L
Vehicle to be Exported:	No
Intended De-registration Date:	28 Dec 2017
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 3.0 DIESEL TURBO M/T 2WD LORRY
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	1KD2565617
Chassis No.:	KDY2318022209
Maximum Power Output:	-
Open Market Value:	\$29,494.00
Original Registration Date:	13 Jan 2016
First Registration Date:	13 Jan 2016
Transfer Count:	1
Actual ARF Paid:	\$1,475.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 Jan 2026
COE Category:	C - Goods Vehicle & Bus

COE Period(Years):	10
PQP Paid:	\$40,650.00
COE Rebate Amount:	\$32,683.00
Total Rebate Amount:	\$32,683.00

The information contained herein is correct as at 28 Dec 2017

OK



簡福星噴漆工廠 KAN FOOK SING MOTOR WORKSHOP

61 Defu Lane 12, Singapore 539117

Tel: (65) 6747 9980, 6858 2125, 6858 4361

Fax: (65) 6748 1006, 6281 8428

E-mail: kanfs@pacific.net.sg • Website: www.carparts.com.sg

 Insurance Reg. No.: 2246617
 227 No. 2, Tel: 969 0002/017

 INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	A28878418MKC	Date of Loss:	22/12/2017
Vehicle Reg. No.:	GBE5660L	Driveable?	
Driver Age/Info:	55 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HARVEST PRODUCTIONS PTE LTD	Contact No:	+6596532609
Driver:	LIM BOON THYE		
Make/Model:	TOYOTA DYNA 150, 3.0 D (M)	Vehicle Reg. Date:	13/01/2016
Vehicle Colour:	WHITE		
Engine No:	1KD2565617	Chassis No:	KDY2318022209
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Description of Accident/Loss	REFER WITH ATTACH.		
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)		

COST OF CLAIMS	Amount
Parts	2,163.70
Miscellaneous Items	20.00
Labour	1,250.00
Paintwork Labour	750.00
Towing	0.00
Gross Total (S\$)	4,183.70
+ GST 7.00% (S\$)	292.86
Nett Amount (S\$)	4,476.56

This claim is handled by: TAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised: 23 Dec 2017)
Parts: N/A TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Kan Fook Sing Motor Workshop/GBE5660L/23/12/2017 12:08
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT WINDSCREEN RUBBER - MC	0.00	0.00	*95.00 F 90
2	1		*FRONT WIPER PANEL - Bue	0.00	0.00	*90.00 F ✓
3	1		*FRONT PANEL - Bue	0.00	0.00	*310.00 F ✓
4	1		*FRONT PANEL DYNA EMBLEM - MC	0.00	0.00	*28.00 F ✓
5	1		*FRONT PANEL TOP GARNISH (BLACK) - SCR	0.00	0.00	*95.00 F 105
6	1		*FRONT SIDE PANEL TOP GARNISH (BLACK) LH 2 LNN	0.00	0.00	*40.00 F X
7	1		*FRONT SIDE PANEL TOP GARNISH (BLACK) RH 2 LNN	0.00	0.00	*40.00 F X
8	1		*FRONT GRILLE - CRA	0.00	0.00	*140.00 F 185
9	1		*FRONT GRILLE EMBLEM - MC	0.00	0.00	*25.00 F 28
10	1		*FRONT GRILLE SEAL - MC	0.00	0.00	*20.00 F 18
11	1		*FRONT HEADLAMP RH - CRA	0.00	0.00	*320.00 F 300
12	1		*FRONT HEADLAMP LH - CRA	0.00	0.00	*320.00 F 300
13	1		*FRONT HEADLAMP LOWER RUBBER RH - MC	0.00	0.00	*12.00 F 324
14	1		*FRONT HEADLAMP LOWER RUBBER LH - MC	0.00	0.00	*12.00 F 324
15	1		*FRONT BUMPER - BT	0.00	0.00	*250.00 F 260
16	1		*FRONT BUMPER BRACKET RH - BT	0.00	0.00	*85.00 F 3190
17	1		*FRONT BUMPER BRACKET LH - BT	0.00	0.00	*85.00 F 3190

F=Franchise part

Sub Total (S\$)	1,967.00
+ Margin on L,N Items 10.00% (S\$)	196.70
Total Parts (S\$)	2,163.70

Kan Fook Sing Motor Workshop/GBE5660L/23/12/2017 12:08. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT NUMBER PLATE / BT	20.00 ✓
Sub Total (S\$)			20.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	New	700 750.00 ✓
<u>Labour Items</u>			
2	TO CHECK WIRING SYSTEM	New	20 30.00 ✓
3	TO REMOVE/REFIT FRONT WINDSCREEN GLASS	New	100 100.00 ✓
4	TO REMOVE/REFIT DASHBOARD	New	180 240.00 ✓
5	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	700 880.00 ✓
Gross Labour Cost (S\$)			2,000.00

Kan Fook Sing Motor Workshop/GBE5660L/23/12/2017 12:08 Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

6 Days.

part by part.

before paint photos.

Gene Gicaf - 82880282

27/12/17

Not Authorized.

Excess \$ 600

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

簡福星嘢多工廠
KAN FOOK SING MOTOR WORKSHOP
61 DEPU LANE 12
SINGAPORE 539147
TEL: 67479560, 68582126, 68584361
FAX: 67481006, 62818428

MSIG INSURANCE (SINGAPORE) PTE LTD
4 SHENTON WAY #21-01
SGX CENTRE 2
SINGAPORE 068807

INVOICE NO : TEST
DATE : 02-01-2018

VEHICLE NO. : GBE5660L
ACCIDENT DATE : 22-12-2017 08:00
THIRD PARTY REF. : SJS7783J

ATTN: MOTOR CLAIMS DEPT.

INVOICE COST OF REPAIRS TO VEICLE GBE5660L TOYOTA DYNA 3.0 DIESEL TURBO

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	FRONT WINDSCREEN RUBBER	90.00 —
1	FRONT WIPER PANEL	90.00 —
1	FRONT PANEL	310.00 —
1	FRONT PANEL DYNA EMBLEM	28.00 —
1	FRONT PANEL TOP GARNISH (BLACK)	105.00 —
1	FRONT GRILLE	185.00 —
1	FRONT GRILLE EMBLEM	28.00 —
1	FRONT GRILLE SEAL	18.00 —
2	FRONT HEADLAMP @\$300.00	600.00 —
2	FRONT HEADLAMP LOWER RUBBER @\$12.00	24.00 —
1	FRONT BUMPER	260.00 —
2	FRONT BUMPER BRACKET@\$95.00	190.00 —
		1,928.00
	ADD 10 %	192.80
	TOTAL (A)	2,120.80

SPECIAL NETT ITEMS

1	FRONT NUMBER PLATE	20.00 —
	TOTAL (C)	20.00

LABOUR CHARGES

1	TO CHECK WIRING SYSTEM	20.00 —
---	------------------------	---------

簡福星嘜多工廠
 KAN FOOK SING MOTOR WORKSHOP
 81 DEFU LANE 12
 SINGAPORE 539147
 TEL: 67479560, 68582128, 68584361
 FAX: 67481006, 62818428

VEHICLE NO. : GBE5660L
 ACCIDENT DATE : 22-12-2017 08:00
 THIRD PARTY REF. : SJS7783J

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	TO REMOVE/REFIT FRONT WINDSCREEN GLASS	100.00 —
1	TO REMOVE/REFIT DASHBOARD	180.00 —
1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	700.00 —
1	SPRAY PAINTING CHARGES	700.00 —

TOTAL (D)	1,700.00
TOTAL REPAIR COST	3,840.80
G S T	226.85
EXCESS AMOUNT	600.00
INVOICE AMOUNT	3,467.65

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT WINDSCREEN RUBBER / <i>MC</i>				
2	1		*FRONT WIPER PANEL / <i>Buc</i>	0.00	0.00	*95.00F	40
3	1		*FRONT PANEL / <i>Buc</i>	0.00	0.00	*90.00F	—
4	1		*FRONT PANEL DYNA EMBLEM / <i>MC</i>	0.00	0.00	*310.00F	—
5	1		*FRONT PANEL TOP GARNISH (BLACK) / <i>GR</i>	0.00	0.00	*28.00F	—
6	1		*FRONT SIDE PANEL TOP GARNISH (BLACK) LH ?	0.00	0.00	*95.00F	105
7	1		*FRONT SIDE PANEL TOP GARNISH (BLACK) RH ?	0.00	0.00	*40.00F	—
8	1		*FRONT GRILLE / <i>CRA</i>	0.00	0.00	*140.00F	185
9	1		*FRONT GRILLE EMBLEM / <i>MC</i>	0.00	0.00	*25.00F	28
10	1		*FRONT GRILLE SEAL / <i>MC</i>	0.00	0.00	*20.00F	18
11	1		*FRONT HEADLAMP RH / <i>CRA</i>	0.00	0.00	*320.00F	300
12	1		*FRONT HEADLAMP LH / <i>CRA</i>	0.00	0.00	*320.00F	300
13	1		*FRONT HEADLAMP LOWER RUBBER RH / <i>MC</i>	0.00	0.00	*12.00F	—
14	1		*FRONT HEADLAMP LOWER RUBBER LH / <i>MC</i>	0.00	0.00	*12.00F	—
15	1		*FRONT BUMPER / <i>BT</i>	0.00	0.00	*250.00F	260
16	1		*FRONT BUMPER BRACKET RH / <i>BT</i>	0.00	0.00	*85.00F	95
17	1		*FRONT BUMPER BRACKET LH / <i>BT</i>	0.00	0.00	*85.00F	95
F=Franchise part.							
Sub Total (\$\$)						1,967.00	1928
+ Margin on L,N Items 10.00% (\$\$)						196.70	192.80
Total Parts (\$\$)						2,163.70	2120.80

Report

Page 3 of 3

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT NUMBER PLATE / <i>BT</i>	20.00
Sub Total (\$\$)			20.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	New	700 750.00
<u>Labour Items</u>			
2	TO CHECK WIRING SYSTEM	New	20 30.00
3	TO REMOVE/REFIT FRONT WINDSCREEN GLASS	New	100.00
4	TO REMOVE/REFIT DASHBOARD	New	150 240.00
5	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	700 880.00
Gross Labour Cost (\$\$)			2,000.00

Kan Fook Sing Motor Workshop/GBE5660L/23/12/2017 12:08. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

6 Days.

part by part.

before paint photos.

r - - - - -



力善汽車零件私人有限公司 LESUN AUTO PARTS PTE LTD

BLK 3018 UBI ROAD 1 #02-117 SINGAPORE 408710

TEL: 6846 8655 FAX: 6748 3092

A/C TEL: 6291 1886 FAX: 6291 7717

EMAIL: lesun@singnet.com.sg

Co. Reg. No.: 200516381H GST Reg No.: 200516381H

TAX INVOICE

M/S: KAN FOOK SING MOTOR WORKSHOP

61 DEFU LANE 12 (S) 539147

NO: LLI0203461

DATE: 27/12/2017

A/C CODE: LLDKFS7

TERMS: CR

P/O NO: GBE5660L

PAGE:1

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 LT56121-25040	FRT W/S RUBBER	NS-TOP 10	1	90.00	90.00
2 LT55078-37070	FRT WIPER PANEL	U4-D7	1	90.00	90.00
3 LT53928-37011	FRT CENTER GARNISH	NT-2C	1	105.00	105.00
4 LT81130-37463	HEAD LAMP/RH	U4-TC5B	1	300.00	300.00
5 LT81170-37464	HEAD LAMP LH	U4-TC5B	1	300.00	300.00
6 LT52111-37501-B1	FRT BUMPER ASSY	LL1	1	260.00	260.00
7 LT52011-37053	FRT BUMPER ARM/RH	NSG-3C	1	95.00	95.00
8 LT52012-37052	FRT BUMPER ARM/LH	NSG-3G	1	95.00	95.00
9 LT55700-37111	FRT PANEL (37110)	U4-A4	1	310.00	310.00
10 LT81193-37040/60	HEAD LAMP LWR SEAL R/L	IF-24B	2	12.00	24.00
11 LT75311-37130	F.PANEL (DYNA) LABEL	LL1	1	28.00	28.00
12 LT53111-37710-JO	RAD GRILLE ASSY	LL1	1	185.00	185.00
13 LT53119-37080-BO	RAD GRILLE TOP SEAL	LL1	1	18.00	18.00
14 LT75315-37010	FRT PANEL LOGO	IF-10	1	28.00	28.00
TOTAL QUANTITY:			15	TOTAL	SIN 1,928.00
				ADD GST @ 7%	134.96
				GRAND TOTAL	<u>SIN 2,062.96</u>

Print / EDDIE / 27/12/2017 4:21:53 PM

SALESMAN: EDDIE

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & O. E.

GOODS RECEIVED BY



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Dec 2017 Sendback Est	23 Dec 2017 12:08 \$4,183.70	26 Dec 2017 14:48 Edit Adj Rpt	\$43,840.80 Edit Estimates	\$43,840.80 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: HARVEST PRODUCTIONS PTE LTD, Co. Reg. No.: 200807428M									
Vehicle Reg. No.: GBE5660L		Date of Loss: 22/12/2017 08:00 - :59 [23 Months and 9 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 542255		Policy/Cover Note No.: A28878418MKC (Comprehensive) Coverage: 18/01/2017 - 17/01/2018 Excess: \$600.00							
Repairer: Kan Fook Sing Motor Workshop (Defu) No. 61 Defu Lane 12, 539147 Defu Lane - Tel: 67479560									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Joslin Lim - 6643 1327]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 25/01/2018]									
Driver/Custodian: LIM BOON THYE (55 / Male), NRIC: S15298173, Tel: +6596532609									
Adj Asg. Remarks: Please revert.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• MSIG_SG (28/12/2017): Alert - Adj Mandate Approved (\$3883.70) - GBE5660L - Claim Handler: Joslin Lim									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

GBE5660L (542255)
OD
Dec 22 2017 8:00AM
[HARVEST PRODUCTIONS PTE LTD]
Kan Fook Sing Motor Workshop

Upload Documents		Upload Photos	Compose New Letter	View View in Browser v	
Assessment Reports				1 per page v	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail	Print
1	23/12/17 12:08	Repairer Estimates		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/12/17 11:42	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page v	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/12/17 11:44	General View		Load JPG	☒
2	28/12/17 11:44	General View		Load JPG	☒
3	28/12/17 11:44	General View		Load JPG	☒
4	28/12/17 11:44	General View		Load JPG	☒
5	28/12/17 11:44	General View		Load JPG	☒
6	28/12/17 11:44	General View		Load JPG	☒
7	28/12/17 11:44	General View		Load JPG	☒
8	28/12/17 11:44	General View		Load JPG	☒
9	28/12/17 11:44	General View		Load JPG	☒
10	28/12/17 11:44	General View		Load JPG	☒
11	28/12/17 11:44	General View		Load JPG	☒
12	28/12/17 11:44	General View		Load JPG	☒
13	28/12/17 11:44	General View		Load JPG	☒
14	28/12/17 11:44	General View		Load JPG	☒
15	28/12/17 11:44	General View		Load JPG	☒
16	28/12/17 11:44	General View		Load JPG	☒
17	28/12/17 11:44	General View		Load JPG	☒
18	28/12/17 11:44	General View		Load JPG	☒
19	28/12/17 11:44	General View		Load JPG	☒
20	28/12/17 11:44	General View		Load JPG	☒
21	28/12/17 11:44	General View		Load JPG	☒
22	28/12/17 11:44	General View		Load JPG	☒
23	28/12/17 11:44	General View		Load JPG	☒
24	28/12/17 11:44	General View		Load JPG	☒
25	28/12/17 11:44	General View		Load JPG	☒
26	28/12/17 11:44	General View		Load JPG	☒
27	28/12/17 11:44	General View		Load JPG	☒
28	28/12/17 11:44	General View		Load JPG	☒
29	28/12/17 11:44	General View		Load JPG	☒
30	28/12/17 11:44	General View		Load JPG	☒
31	28/12/17 11:44	General View		Load JPG	☒
32	09/04/18 09:34	Photo before Spray		Load JPG	☒
33	09/04/18 09:34	Photo before Spray		Load JPG	☒
34	09/04/18 09:34	Photo before Spray		Load JPG	

Assessment Reports				1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail	Print
			1		☒
35	09/04/18 09:34	Photo before Spray	1	Load JPG	☒
36	09/04/18 09:34	Photo before Spray	1	Load JPG	☒
37	09/04/18 09:34	Photo before Spray	1	Load JPG	☒
38	09/04/18 09:34	Photo before Spray	1	Load JPG	☒
39	09/04/18 09:34	Photo before Spray	1	Load JPG	☒
40	09/04/18 09:34	Photo before Spray	1	Load JPG	☒
41	09/04/18 09:34	Photo before Spray	1	Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail	Print
1	23/12/17 11:54	E-filed GIA report	1	Load PDF	
2	09/04/18 10:47	Repairer's Bill	1	Load PDF	
3	09/04/18 10:47	Signed DV	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/12/17 11:43	Marked estimate	1	Load PDF	
2	09/04/18 09:26	PARTS INVOICE	1	Load PDF	

Linked Accident Report Documents

Assessment Reports				1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail	Print
1	22/12/17 16:57	Accident Statement	1	Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail	Print
1	22/12/17 16:55	Accident Photo	1	Load JPG	☒
2	22/12/17 16:55	Accident Photo	1	Load JPG	☒
3	22/12/17 16:55	Accident Photo	1	Load JPG	☒
4	22/12/17 16:55	Accident Photo	1	Load JPG	☒
5	22/12/17 16:55	Accident Photo	1	Load JPG	☒
6	22/12/17 16:55	Accident Photo	1	Load JPG	☒
7	22/12/17 16:55	Accident Photo	1	Load JPG	☒
8	22/12/17 16:55	Accident Photo	1	Load JPG	☒
9	22/12/17 16:55	Accident Photo	1	Load JPG	☒
10	22/12/17 16:55	Accident Photo	1	Load JPG	☒
11	22/12/17 16:55	Accident Photo	1	Load JPG	☒
12	22/12/17 16:55	Accident Photo	1	Load JPG	☒
13	22/12/17 16:55	Accident Photo	1	Load JPG	☒
14	22/12/17 16:55	Accident Photo	1	Load JPG	☒
15	22/12/17 16:55	Accident Photo	1	Load JPG	☒
16	22/12/17 16:55	Accident Photo	1	Load JPG	☒
17	22/12/17 16:55	Accident Photo	1	Load JPG	☒
18	22/12/17 16:55	Accident Photo	1	Load JPG	☒
19	22/12/17 16:55	Accident Photo	1	Load JPG	☒
20	22/12/17 16:55	Accident Photo	1	Load JPG	☒
21	22/12/17 16:55	Accident Photo	1	Load JPG	☒
22	22/12/17 16:55	Accident Photo	1	Load JPG	☒
23	22/12/17 16:55	Accident Photo	1	Load JPG	☒
Documentation				1 per page	☒

Assessment Reports				1 per page	☐
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail	Print
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail	Print
1	22/12/17 16:57	Accident Sketch Plan		Load TIF	
2	22/12/17 16:57	Accident Sketch Plan		Load TIF	
3	22/12/17 16:57	driver's nric & license		Load TIF	
4	22/12/17 16:57	certificate of insurance		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG17024383/GTD3Q2

Date: 11/04/2018

REFERENCE

Insured/Claimant: HARVEST PRODUCTIONS PTE LTD

Policy No: A28878418MKC

Date of Loss: 22/12/2017

Nature of Claim: OD

Claim No: 542255

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBE5660L

Make & Model: TOYOTA DYNA 150, 3.0 D (M)

Engine No: 1KD2565617

Reg. Date: 13/01/2016 (Man. Year: 2015)

Chassis No: KDY2318022209

Colour: White

Odometer: 50802 km

Engine Capacity: 2982 cc

Market Value/New Car Price: S\$67,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/75 R15

Rear Tyre Size: 185/75 R15

Front Left Side: Koyote 6 mm

Rear Left Side: Koyote 6 mm

Front Right Side: Koyote 6 mm

Rear Right Side: Koyote 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,163.70	2,120.80	42.90	1.98
Miscellaneous Items	20.00	20.00	0.00	0.00
Labour	1,250.00	1,000.00	250.00	20.00
Paintwork Labour	750.00	700.00	50.00	6.67
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,183.70	3,840.80	342.90	8.20
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	4,183.70	3,240.80	942.90	22.54
+ GST 7.00/7.00% (S\$)	292.86	226.86	66.00	22.54
Nett Amount (S\$)	4,476.56	3,467.66	1,008.90	22.54

INSPECTION

Date of Assignment: 26/12/2017 Present Location:

Kan Fook Sing Motor Workshop (Defu)

Date Inspected: 27/12/2017 Inspected At:

Kan Fook Sing Motor Workshop (Defu)

No. 61 Defu Lane 12

Singapore 539147

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 Apr 2018)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE5660L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN RUBBER	Necessary	95.00 F	*90.00 F
2	1		*FRONT WIPER PANEL	Buckled	90.00 F	*90.00 F
3	1		*FRONT PANEL	Buckled	310.00 F	*310.00 F
4	1		*FRONT PANEL DYNA EMBLEM	Necessary	28.00 F	*28.00 F
5	1		*FRONT PANEL TOP GARNISH (BLACK)	Scratched	95.00 F	*105.00 F
6	1		*FRONT SIDE PANEL TOP GARNISH (BLACK) LH	Not Necessary	40.00 F	*- F
7	1		*FRONT SIDE PANEL TOP GARNISH (BLACK) RH	Not Necessary	40.00 F	*- F
8	1		*FRONT GRILLE	Cracked	140.00 F	*185.00 F
9	1		*FRONT GRILLE EMBLEM	Necessary	25.00 F	*28.00 F
10	1		*FRONT GRILLE SEAL	Necessary	20.00 F	*18.00 F
11	1		*FRONT HEADLAMP RH	Cracked	320.00 F	*300.00 F
12	1		*FRONT HEADLAMP LH	Cracked	320.00 F	*300.00 F
13	1		*FRONT HEADLAMP LOWER RUBBER RH	Necessary	12.00 F	*12.00 F
14	1		*FRONT HEADLAMP LOWER RUBBER LH	Necessary	12.00 F	*12.00 F
15	1		*FRONT BUMPER	Bent	250.00 F	*260.00 F
16	1		*FRONT BUMPER BRACKET RH	Bent	85.00 F	*95.00 F
17	1		*FRONT BUMPER BRACKET LH	Bent	85.00 F	*95.00 F

F=Franchise part.

Sub Total (S\$)	1,967.00	1,928.00
+ Margin on L,N Items 10.00/10.00% (S\$)	196.70	192.80
Total Parts (S\$)	2,163.70	2,120.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	FRONT NUMBER PLATE (BENT)	20.00	20.00
Sub Total (\$\$)			20.00	20.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	SPRAYPAINTING CHARGES	New	750.00	700.00
<u>Labour Items</u>				
2	TO CHECK WIRING SYSTEM	New	30.00	20.00
3	TO REMOVE/REFIT FRONT WINDSCREEN GLASS	New	100.00	100.00
4	TO REMOVE/REFIT DASHBOARD	New	240.00	180.00
5	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	880.00	700.00
Gross Labour Cost (\$\$)			2,000.00	1,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >