

SMRT Accident Vehicle Repair Estimates

AIG

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHD6290Z
 Ref. No : TAX/12/17/2130
 Reg. Date : 01/09/2011
 Vehicle Type : TAXI
 Make : CHEVROLET EPICA 2.0 VCDI
 Model : EPICA-2.0
 Name of Driver : LOW AH MENG (LUO YAMING)
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 24/12/2017 08:30:00 PM
 Accident Reported Date / Time : 26/12/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : LKK
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024093783
 Special Instruction to ARC, if any :
 DROVE IN / SLG5827U (AIG) - LKK
 Prepared Date : 26/12/2017 09:10:13 AM



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sebastian

26/12/2017

- Lump Sum Repair
- Question Mark Item Photo
- Photo After Paint.

90036124

sebastianyang@lkauto.com

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : KL1LA69RJBB056432

Mileage :

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates**Quotation from ARC****Adjusted by Surveyor, if applicable**

Total Labour Charges	:	676.00	0.00
Total Spray Painting Charges	:	756.00	0.00
Total Material Charges	:	2,028.96	2,028.96
Other Charges	:	460.00	0.00
TOTAL	:	3,920.96	0.00
Lum Sum Total	:	3,900.00	0.00
No. of Repair Days	:	5.00	0.00
Prepared / Adjusted By	:		3 days
Arc / Surveyor Sign Off Date	:	26/12/2017 03:02:27 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 26/12/2017 03:02:27 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 12/26/2017 3:04:06 PM

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	676.00	0.00 300
Total Labour	676.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT FENDER RH	378.00	0.00 200
Total Spray Painting & Panel Beating	756.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 30
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 X
Total Other Costs	460.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
93744489	FRONT	6504592	BUMPER FRT ASSY	1	1,238.00	10.00	1,114.20	Replace	Replace <i>R</i>	No
96636328	RIGHT	6504581	PANEL FRT FENDER RH	1	606.00	10.00	545.40	Replace	Replace <i>R</i>	No
96633940	RIGHT	6504585	LINER FENDER FRT RH (PROTECTOR)	1	124.00	10.00	111.60	Replace	Replace <i>✓ 1N</i>	No
96644858	FRONT	6504614	LAMP HEAD RH	1	841.00	10.00	756.90	Replace	Replace <i>✓</i>	No
96633984	FRONT		BRACKET FRT BUMPER SIDE RH	1	9.00	10.00	8.10	Replace	Replace <i>✓</i>	No
TOTAL MATERIALS								2,536.20	2,536.20	
TOTAL MATERIALS(Discounted)								2,028.96	2,028.96	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									