2/23/2018 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG17024443/KEB3S2

23/02/2018 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700021023 **Claimant Vehicle** SHD9759U Insured Vehicle No: SJB696M

No:

Date of Loss: 21/12/2017 Nature of Claim: TP Claim No: 9632134291SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD9759U

Make & Model: RENAULT LATITUDE, 2.0 L (A) Engine No: M9R8839C000948 Reg. Date: 31/03/2014 (Man. Year: 2013) Chassis No: VF1ABL15AUC276883

Metallic White/Red Colour: Odometer: 423906 km

Engine Capacity: 1995 cc Market Value/New Car Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16 Front Left Side: Rear Left Side: Falken 8 mm Falken 8 mm Front Right Side: Falken 8 mm Rear Right Side: Falken 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,167.66	2,593.82	23,573.84	90.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,710.00	580.00	7,130.00	92.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,877.66	3,173.82	30,703.84	90.63
Approved Total (Overridden) (S\$)		2,550.00		
(S\$)	33,877.66	2,550.00	31,327.66	92.47
+ GST 7.00/7.00% (S\$)	2,371.44	178.50	2,192.94	92.47
Nett Amount (S\$)	36,249.10	2,728.50	33,520.60	92.47
+ Loss of Use (5.5 x S	\$\$50.00/day) (S\$)	275.00		
+ Car Rental (5.5 x S	5101.46/day) (S\$)	558.03		
+ Doc	/Search Fee (S\$)	7.49		
	Nett Liability (S\$)	3,569.02		

INSPECTION

Date of Assignment: 26/12/2017

Trans-cab Auto Services Pte Ltd Date Inspected: 26/12/2017 Inspected At:

No 2 Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 2.0 days

KENNETH KONG Manager: Adjuster: Asher Sng Rong Yi NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

Кe	Recommended Parts						
No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*BUMPER COVER REAR	Cracked	1,108.46 FL	*1,108.46 FL	
2	1		*BUMPER LOWER REAR	Dented	768.84 FL	*768.84 FL	
3	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL	
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL	
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL	
6	1		*BUMPER REFLECTOR RH	Cracked	43.61 FL	*43.61 FL	
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL	
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL	
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL	
10	1		*BUMPER BEAM REAR	Repair	777.52 FL	*- FL	
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*- FL	
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL	
13	1		*BOOT REAR	Repair	2,872.68 FL	*- FL	
14	1		*BOOT FINISHER	Serviceable	470.06 FL	*- FL	
15	1		*BOOT WEATHERSTRIP	Serviceable	323.05 FL	*- FL	
16	1		*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*- FL	
17	1		*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*- FL	
18	1		*BOOT BADGE RENAULT	Not Necessary	225.36 FL	*- FL	
19	1		*BOOT BADGE KENAGE!	Not Necessary	225.36 FL	*- FL	
20	1		*BOOT SWITCH	Serviceable	168.13 FL	*- FL	
21	1		*BOOT LOCK		202.67 FL	*- FL	
22	1		*BOOT LOCK *BOOT LOCK CATCH	Repair	74.40 FL		
23				Repair			
	2		*LICENCE PLATE LAMP	Serviceable	50.52 FL	*- FL	
24	2		*BOOT RUBBER PLUG	Serviceable	221.81 FL	*-FL	
25	1		*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL	*- FL	
26	1		*FENDER PANEL REAR RH	Repair	3,299.13 FL	*-FL	
27	1		*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL	
28	1		*TAILLAMP RH	Serviceable	552.55 FL	*-FL	
29	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL	
30	1		*TAILLAMP LH	Serviceable	552.55 FL	*-FL	
31	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL	
32	1		*OUTER PANEL REAR (END PANEL)	Repair	1,471.77 FL	*-FL	
33	1		*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	404.56 FL	*- FL	
34	1		*EXHAUST REAR	Repair	7,489.05 FL	*-FL	
35	1		*SET PARKING AID	Shorted	700.00 FS	*700.00 FS	
36	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS	
37	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS	
38	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS	
39	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS	
40	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*-FS	
41	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS	
42	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*-FS	
43	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS	
44	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*-FS	
45	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*-FS	
46	1		*BOOT STICKER TRANS-CAB	Not Necessary	30.00 FS	*-FS	
47	1		*BOOT STICKER 6555-3333	Not Necessary	30.00 FS	*-FS	
48	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*-FS	
49	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS	
50	1		*FENDER INNER TRIM CLIP RH	Not Necessary	28.00 FS	*- FS	
51	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*-FS	
52	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS	
53	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*-FS	
54	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS	
55	1		*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*- FS	
	-				220.00.0	. 3	

No.	Qty	Part No.	Particulars	Condition	on	Repairer's	Amount
56	1		*SPARE TYRE	Servicea	able	330.00 FS	*- FS
57	1		*EXHAUST CAP REAR	Repair		230.49 FL	*-FL
F=Fra	ınchise	part. S=SpcN	ett. L=ListItemDisc.		-		
				Sub '	Total (S\$)	28,835.51	2,785.91
				- List Item Discount on L Items 10.00/10.	.00% (S\$)	2,667.85	192.09
				Total F	Parts (S\$)	26,167.66	2,593.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	3,000.00	270.00
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	2,800.00	250.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR.	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.) New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
9	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
10	TOWING FEES.	New	120.00	0.00
11	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	New	170.00	0.00
12	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	0.00
	Gross Labou	r Cost (S\$)	7,710.00	580.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.