

威利摩多 WEI LEE MOTOR WORKS

LKK Auto Consultants (Pte) Ltd
BLOCK 9, SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

22, Dec 2017

Signature:

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 S 079120

Attn : Motor claim dept-3rd party claim

Claiming against your insured vehicle No: SJD590Z

Accident involving vehicle No: SKC5829Y/SJD590Z

DOA: 19/12/2017 At Multi storey carpark, Parkway Parade

Dear officer incharge

Re: Estimate cost of repair for vehicle No: SKC5829Y

To supply

Description	Qty	Amount
Rear bumper / TN	1	482.00
Rear bumper enforcement/sponge / CNA	1	123.50
Rear bumper retainer, Rh / KL	1	69.80
Rear bumper clip / KL		38.00
Rear bumper foglamp, Rh ?	1	37.20
End panel ?	1	580.60
End panel top garnish ?	1	202.70
Taillamp, Rh ?	1	918.00
Lid X repair	1	618.50
Lid reflector, Rh ?	1	171.60
	Parts	3,241.90
	Parts less 25%	810.47
		2,431.43

Reverse sensor / DM

220.00

To remove damaged parts and attachments.

Repair/reshape dented areas.

Straighten chassis where necessary.

Renew/align all parts into position.

850.00 400

To spray paint.

750.00 500.

4 days.

ump sum repair

After repair photos.

Guo Qiang - 82880282

28/12/17.