



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com

Website: www.nhtmotor.com

Tel: 6747 9241

Fax: 6741 7276

UEN: 201718370K

E'LEGAL CONCEPT

20/12/2017

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

Accident date: 14/05/2017

Estimated repair cost for vehicle no: GBG5785A TOYOTA HIACE 3.0 A '17

| S/N | QTY | ITEMS                                | U/PRICE    | AMOUNT     |
|-----|-----|--------------------------------------|------------|------------|
| 1   | 1   | Front Bumper ✓ chip off / dented     |            | \$591.45   |
| 2   | 8   | Front Bumper Clip ✓ NEC              | \$6.50     | \$52.00    |
| 3   | 1   | Front Bumper Number Plate ✓ CRA      |            | \$50.00    |
| 4   | 1   | Front Bumper Top Beam ?              |            | \$281.10   |
| 5   | 1   | Front Bumper Lower Reinforcement ?   |            | \$278.10   |
| 6   | 1   | Front Grille Assy (Nett) / SCR       |            | \$1,200.00 |
| 7   | 2   | Front Head Lamp ?                    | \$1,712.45 | \$3,424.90 |
| 8   | 1   | Front Support Panel Top Cover ?      |            | \$274.85   |
| 9   | 6   | Front Support Panel Top Cover Clip ? | \$6.50     | \$39.00    |
| 10  | 1   | Front Air-Con Condenser X NN         |            | \$972.10   |

Subtotal:- \$7,163.50

### Labour charges

To check wiring

\$50.00 X

Tuff kote

\$60.00 X

Panel beating


\$500.00 200

Spray painting

\$500.00 X

Subtotal:- \$1,110.00

Total:- \$8,273.50



Wilson 96404178  
LHK Auto Consultant

Parts Subject To Confirmation \$500.00 X

hump Sum Repair

Parts Resurvey

/ Resurvey After

1-2 Days Repair