

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHB 57599

Yr Regn:

12/12/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

CC 1798

Colour

Maroon

A/C: Insured / Std / NI / NA

Sp. Reading

3194

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3F4903575839

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

22/12/2017

D.O.I.

26/12/2017

Survey held at

SMRT.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt, N/S Rear.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

TAX / 12/17 / 2129

LEE.

China Taipei

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Report Format:

Lump Sum / I.B.I.: (\$

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

) \$ + RS. \$

) Photos

) Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CTI17024488/Syb3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 27-12-2017	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKU 7245Z	Veh. Inspected	SHB 5759G	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	27/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/12/2017	Inspection Date	26/12/2017	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

2-1-18 / 12:19

2-1-18 / 16:19

IRT Accident Vehicle Repair Estimates

26-12-17 / 16:19

A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

: SHB5759G
 : TAX/12/17/2129
 Date : 12/12/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : XU HAIBIN
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 22/12/2017 10:55:00 PM
 Accident Reported Date / Time : 23/12/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Sebastian
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle Issued? : No
 Accident Repair Job Card No : 000024093787
 Special Instruction to ARC, if any :
 TOS / SKU7245Z China PIP
 BEFORE PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN
 (LKK) & Email : sebastianyeang@lkkauto.com HP: 90036121
 Prepared Date : 26/12/2017 11:25:39 AM



Recording Camera

☐ ☒

Radio Antenna

☐ ☒

1st witness

Date 26-12-17

2nd witness

Date

Supplementary

to Radio to the Supplementary part 12/17

Qe 3/1/17 12:20 PMS

3194
 1/4 1/2 3/4 3格半
 3257
 1/4 1/2 3/4 3格半

LEE SHENG AUTO PTE LTD

Vehicle Return Date: 03/01/2018

Vehicle Return Time: 11:15

SMRT staff sign: _____

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU903575839

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,521.00	700.00
Total Spray Painting Charges	: 2,628.00	1,400.00
Total Material Charges	: 3,882.42	3,613.62
Other Charges	: 1,640.00	440.00
TOTAL	: 9,671.42	6,153.62
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 9.00	6.00
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sing Off Date	: 26/12/2017 04:03:00 PM	26/12/2017 04:19:26 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 26/12/2017 04:03:00 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : GN-1801-0112 Invoice No :
Quotation Date : 5/1 Invoice Date :
Invoice Amount : Prepared Date :

3613.62
700
+ 1840

6153.62

Sebastian
10/1/18

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	676.00	300.00 /
TO REPAIR LH PORTION	845.00	400.00 /
Total Labour	1,521.00	700.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER RH	378.00	200.00 /
TO RESPRAY ROCKER PANEL MOULDING	360.00	200.00 /
TO RESPRAY FRONT DOOR RH	378.00	200.00 /
TO REPSRAY REAR BUMPER	378.00	200.00 /
TO RESPRAY REAR FENDER LH	378.00	200.00 /
TO RESPRAY REAR DOOR LH	378.00	200.00 /
TO RESPRAY FRONT DOOR LH	378.00	200.00 /
Total Spray Painting & Panel Beating	2,628.00	1,400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	30.00 /
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30.00 /
TO TRANSFER DOOR MECHANISM	360.00	0.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
TO REMOVE AND REFIX UNDERCARRIAGE	250.00	200.00 S /
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60.00 S /
TO CHECK & RESET SYSTEM FUNCTION	350.00	120.00 S /
Total Other Costs	1,640.00	440.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
5380147080			FENDER SUB-ASSY, FR, RH	1	933.10	100.00	0.00	Replace	Repair	No <i>R</i>
7537447140			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	25.00	39.67	Replace	Replace	No <i>✓</i>
5387547070			LINER, FR FENDER, RH	1	196.40	25.00	148.80	Replace	Replace	No <i>✓</i>
4261147450			WHEEL, DISC	1	1,555.10	25.00	1,166.33	Replace	Replace <i>S</i>	No <i>✓</i>
7585047910			MOULDING ASSY, BODY ROCKER PANEL, RH	1	576.00	100.00	0.00	Replace	Repair	No <i>R</i>
6761047780C1			PANEL ASSY, FR DOOR RH	1	725.90	100.00	0.00	Replace	Repair	No <i>R</i>
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace	No <i>✓</i>
6873012120			HINGE ASSY, FRONT DOOR, LOWER RH	1	92.10	0.00	92.10	Replace	Check	No <i>X</i>
6871012151			HINGE ASSY, FRONT DOOR, UPPER RH	1	82.10	25.00	61.58	Replace	Check	No <i>X</i>
6861047040			CHECK ASSY, FRONT DOOR	1	153.50	25.00	115.13	Replace	Check	No <i>X</i>
5215947913			COVER, RR BUMPER ASSY	1	423.90	100.00	0.00	Replace	Repair	No <i>R</i>
5256647930			FILLER, RR BUMPER, LH	1	119.90	100.00	0.00	Replace	Repair	No <i>R</i>
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No <i>✓</i>
3160247130			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	100.00	0.00	Replace	Repair	No <i>R</i>
7586047930			MOULDING ASSY, BODY ROCKER PANEL, LH	1	576.00	100.00	0.00	Replace	Repair	No <i>R</i>
3700447210			PANEL SUB-ASSY, REAR DOOR, LH	1	1,243.90	100.00	0.00	Replace	Repair	No <i>R</i>
3762047830C1			PANEL ASSY, FR DOOR LH	1	725.90	100.00	0.00	Replace	Repair	No <i>R</i>
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace	No <i>✓</i>
1851080815			ABSORBER SET, SHOCK, FRONT RH	1	398.10	25.00	298.57	Replace	Replace <i>S</i>	No <i>✓</i>
1321147010			KNUCKLE, STEERING, RH	1	555.20	25.00	416.40	Replace	Replace <i>S</i>	No <i>✓</i>
1806847010			LOWER ARM SUB-ASSY, FRONT RH	1	631.60	25.00	473.70	Replace	Replace <i>S</i>	No <i>✓</i>
133301915			JOINT ASSY, LWR BALL, RH & LH	1	200.10	25.00	150.07	Replace	Replace <i>S</i>	No <i>✓</i>
504649215			END SET, TIE ROD, RH	1	155.90	25.00	116.92	Replace	Replace <i>S</i>	No <i>✓</i>
88204700			LINK ASSY, FRONT STABILIZER, RH & LH	1	196.70	25.00	147.52	Replace	Replace <i>S</i>	No <i>✓</i>
35504700			HUB & BEARING ASSY, RH & LH	1	554.20	25.00	415.65	Replace	Replace <i>C</i>	No <i>✓</i>
TOTAL MATERIALS								3,882.45	3,613.63	
TOTAL MATERIALS(Discounted)								3,882.42	3,613.62	

Added Spare Parts / Material Usage After Surveyor Signed off

17004.30



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTI17024488/Syb3

Date: 27.12.2017

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHB5759G


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 26.12.2017 at the premises of M/s SMRT Automotive Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	11,604.60
Revised Estimate Amount	: S\$	2,638.47
"Check" Items Amount	: S\$	268.79
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
O/S Front portion & N/S Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

SEBASTIAN YEANG
Licensed Appraiser

SMRT Accident Vehicle Repair Estimates

China Taping

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5759G
 Ref. No : TAX/12/17/2129
 Reg. Date : 12/12/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : XU HAIBIN
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 22/12/2017 10:55:00 PM
 Accident Reported Date / Time : 23/12/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024093787
 Special Instruction to ARC, if any :
 TOS / SKU7245Z
 Prepared Date : 26/12/2017 11:25:39 AM



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

*Sebastian .
 26/12/2017 .*

*- Part by part repair .
 - Photo Before Paint
 - Question Mark Item Photo .
 90036121
 Sebastian.yeang@lkkauto.com .*

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU903575839

Mileage :

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,521.00	0.00
Total Spray Painting Charges	: 2,808.00	0.00
Total Material Charges	: 6,355.60	6,355.60
Other Charges	: 920.00	0.00
TOTAL	: 11,604.60	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 9.00	0.00
Prepared / Adjusted By	:	5 days.
Arc / Surveyor Sign Off Date	: 26/12/2017 04:03:00 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 26/12/2017 04:03:00 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	676.00	0.00 300
TO REPAIR LH PORTION	845.00	0.00 400
Total Labour	1,521.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER RH	378.00	0.00 200
TO RESPRAY RIM	180.00	0.00 50
TO RESPRAY ROCKER PANEL MOULDING	360.00	0.00 200
TO RESPRAY FRONT DOOR RH	378.00	0.00 200
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY REAR FENDER LH	378.00	0.00 200
TO RESPRAY REAR DOOR LH	378.00	0.00 200
TO RESPRAY FRONT DOOR LH	378.00	0.00 200
Total Spray Painting & Panel Beating	2,808.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0.00 30
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 30
TO TRANSFER DOOR MECHANISM	360.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	920.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
5380147080			FENDER SUB-ASSY, FR , RH	1	933.10	25.00	699.82	Replace	Replace <i>R</i>	No
7537447140			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	25.00	39.67	Replace	Replace <i>✓NEG</i>	No
5387547070			LINER, FR FENDER, RH	1	198.40	25.00	148.80	Replace	Replace <i>✓NEG</i>	No
4261147450			WHEEL, DISC	1	1,555.10	25.00	1,166.32	Replace	Replace <i>R</i>	No
7585047910			MOULDING ASSY, BODY ROCKER PANEL , RH	1	576.00	25.00	432.00	Replace	Replace <i>R</i>	No
6761047780C1			PANEL ASSY, FR DOOR RH	1	725.90	25.00	544.42	Replace	Replace <i>R</i>	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace <i>✓NEG</i>	No
6873012120			HINGE ASSY, FRONT DOOR , LOWER RH	1	92.10	0.00	92.10	Replace	Replace <i>?</i>	No
6871012151			HINGE ASSY, FRONT DOOR , UPPER RH	1	82.10	25.00	61.57	Replace	Replace <i>?</i>	No
6861047040			CHECK ASSY, FRONT DOOR	1	153.50	25.00	115.12	Replace	Replace <i>?</i>	No
5215947913			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace <i>R</i>	No
5256647900			FILLER, RR BUMPER , LH	1	119.90	25.00	89.92	Replace	Replace <i>R</i>	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace <i>✓NEG</i>	No
6160247160			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	25.00	618.60	Replace	Replace <i>R</i>	No
7586047900			MOULDING ASSY, BODY ROCKER PANEL , LH	1	576.00	25.00	432.00	Replace	Replace <i>R</i>	No
6700447210			PANEL SUB-ASSY, REAR DOOR , LH	1	1,243.90	25.00	932.92	Replace	Replace <i>R</i>	No
6762047800C1			PANEL ASSY, FR DOOR LH	1	725.90	25.00	544.42	Replace	Replace <i>R</i>	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace <i>✓NEG</i>	No
TOTAL MATERIALS							6,475.65	6,475.60		
TOTAL MATERIALS(Discounted)							6,355.60	6,355.60		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CTI17024488/Syb3s2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 20-03-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKU 7245Z	Veh. Inspected	SHB 5759G	
Policy No.	DMPCSN3125501600	Coverage (\$)	0.00	
Claim No.	SNM17D07311C02/5	Excess (\$)	0.00	
Assign From		Assign Date	26/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU903575839	Colour	MAROON	
Odometer	3194	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65R15	YOKOHAMA	7 mm	
L/H Front Tyre	195/65R15	YOKOHAMA	7 mm	
R/H Rear Tyre	195/65R15	YOKOHAMA	7 mm	
L/H Rear Tyre	195/65R15	YOKOHAMA	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/12/2017	Inspection Date	26/12/2017	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5759G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	EMBLEM, SIDE PANEL (HYBRID) (DISC 25%)	NECESSARY	52.90	39.67
1	LINER, FR FENDER, RH (DISC 25%)	NECESSARY	198.40	148.80
1	WHEEL, DISC (DISC 25%)	DEFORMED	1,555.10	1,166.32
1	ABSORBER SET, SHOCK, FRONT RH (DISC 25%)	BENT	398.10	298.57
1	KNUCKLE, STEERING, RH (DISC 25%)	BENT	555.20	416.40
1	LOWER ARM SUB-ASSY, FRONT RH (DISC 25%)	BENT	631.60	473.70
1	JOINT ASSY, LWR BALL, RH & LH (DISC 25%)	BENT	200.10	150.07
1	END SET, TIE ROD, RH (DISC 25%)	BENT	155.90	116.92
1	LINK ASSY, FRONT STABILIZER, RH & LH (DISC 25%)	BENT	196.70	147.52
1	HUB & BEARING ASSY, RH & LH (DISC 25%)	DAMAGED	554.20	415.65
1	STICKER DECAL SMRT (DOOR) (SN)	NECESSARY	60.00	60.00
2	PIXEL STICKER @ \$60.00 (SN)	NECESSARY	120.00	120.00
1	STICKER DECAL SMRT (DOOR) (SN)	NECESSARY	60.00	60.00
1	HINGE ASSY, FRONT DOOR, LOWER RH	NOT NECESSARY	92.10	-
1	HINGE ASSY, FRONT DOOR, UPPER RH	NOT NECESSARY	82.10	-
1	CHECK ASSY, FRONT DOOR	NOT NECESSARY	153.50	-
1	FENDER SUB-ASSY, FR, RH	TO REPAIR SEE LABOUR	933.10	-
1	MOULDING ASSY, BODY ROCKER PANEL, RH	TO REPAIR SEE LABOUR	576.00	-
1	PANEL ASSY, FR DOOR RH	TO REPAIR SEE LABOUR	725.90	-
1	COVER, RR BUMPER ASSY	TO REPAIR SEE LABOUR	423.90	-
1	FILLER, RR BUMPER, LH	TO REPAIR SEE LABOUR	119.90	-
1	PANEL SUB-ASSY, FENDER REAR LH	TO REPAIR SEE LABOUR	824.80	-
1	MOULDING ASSY, BODY ROCKER PANEL, LH	TO REPAIR SEE LABOUR	576.00	-
1	PANEL SUB-ASSY, REAR DOOR, LH	TO REPAIR SEE LABOUR	1,243.90	-

Report Ref No. CC3/CTI17024488/Syb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	PANEL ASSY, FR DOOR LH	TO REPAIR SEE LABOUR	725.90	-
			11,215.30	3,613.62
	LABOUR			
	PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF FENDER SUB-ASSY, FR, RH; MOULDING ASSY, BODY ROCKER PANEL, RH; PANEL ASSY, FR DOOR RH; COVER, RR BUMPER ASSY; FILLER, RR BUMPER, LH; PANEL SUB-ASSY, FENDER REAR LH; MOULDING ASSY, BODY ROCKER PANEL, LH; PANEL SUB-ASSY, REAR DOOR, LH AND PANEL ASSY, FR DOOR LH.		1,521.00	700.00
	SPRAY PAINT.		2,628.00	1,400.00
	TO CHECK WIRING AND SYSTEM FUNCTION.	NOT NECESSARY	80.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		200.00	30.00
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).		120.00	30.00
	TO TRANSFER DOOR MECHANISM.	NOT NECESSARY	360.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO REMOVE AND REFIX UNDERCARRIAGE.		250.00	200.00
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.		120.00	60.00
	TO CHECK & RESET SYSTEM FUNCTION.		350.00	120.00
			5,789.00	2,540.00
GRAND TOTAL			17,004.30	6,153.62
RECOMMENDED COST OF REPAIRS				6,153.62

Report Ref No. CC3/CT117024488/Syb3s2

YEANG WAI KEEN
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.