

REPAIR ESTIMATE*

VEHICLE NO : SHA 3709U

DATE 27/12/2017 13:26

Jumani

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 562.30
	Front Bumper Grille (RH) ✓			\$ 40.30
	Front Bumper Bracket (RH) ✓			\$ 24.60
	Headlamp (RH) ✓			\$ 1,388.00
	Front Fender (RH) ✓			\$ 619.00
	Front Fender Shield (RH) ✕			\$ 169.80
	Frt Wheel Hub Cap (RH) ✓			\$ 150.70
	SUB TOTAL			\$ 2,954.70
	LESS 20%			\$ 590.94
	DISCOUNTED TOTAL			\$ 2,363.76
	Front Fender Advertisement Logo (RH) ✓			\$ 100.00
				\$ 100.00
	Labour Charge			
	Panel Beating			\$ 560.00 400
	Spray Painting Charge			\$ 400.00 360
	Wiring Charge			\$ 50.00 20
	Tuff Kote			\$ 50.00 20
	Frt Wheel Alignment			\$ 80.00 60
	TOTAL LABOUR			\$ 1,140.00
	ESTIMATE TOTAL			\$ 3,603.76

Kalvin LKK
 27/12/17 1515hrs
 2 Days.
 PIP
 Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.