

**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

A26

VEHICLE NO : SHA 1506B

DATE 27/12/2017 10:57

MAKE :

Lany.

MODEL : HYUNDAI IONIQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>X Repair</i>			
	Rear Bumper Reinforcement ?			
	Rear Bumper Reinforcement Bracket (LH/RH) ?			
	Rear Bumper Sponge ?			
	Rear Bumper Under Cover ?			
	Rear Bumper Garnish ?			
	<b>SUB TOTAL</b>			
	<b>LESS 20%</b>			
	<b>DISCOUNTED TOTAL</b>			
	Rear No.Plate /			\$ 25.00 <b>Nett</b>
	Rear No.Plate Trim Cover /			\$ 30.00 <b>Nett</b>
	Rear Bumper Reverse Sensor X			\$ 135.70 <b>Nett</b>
				<b>\$ 190.70</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>250.00</del> <sup>200</sup>
	Spray Painting Charge			\$ <del>220.00</del> <sup>180</sup>
	Wiring Charge			\$ <del>50.00</del> <sup>X</sup>
	Remove/Refix Reverse Sensor			\$ <del>120.00</del> <sup>20</sup>
	<b>TOTAL LABOUR</b>			<b>\$ 640.00</b>
	<b>ESTIMATE TOTAL</b>			
<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: auto;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>To resurvey before/after spray painting</li> <li>To display damaged part(s) during resurvey</li> <li>Parts prices are subject to confirmation</li> <li>Third party survey is on a "Without Prejudice" basis</li> <li>No illegal modification(s) is allowed</li> <li>Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer Date:</p> </div>				
	<p><i>Kalvin LKK</i></p> <p><i>27/12/17 1115 hrs</i></p> <p><i>2 Pys.</i></p> <p><i>PIP</i></p> <p><i>After Repair photo</i></p>			
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				