



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info | |
|---|---------------------------|-----------------------------------|
| Mr Mohamed Rafi S/O Mouhamadally Blk 502 Hougang Ave 8 #02-606 Singapore 530502 Contact No Mobile: 81218036 | Cust No/Name | /Mr Mohamed Rafi S/O Mouhamadally |
| | Reg No/Reg Date | SKE6760T / 26/03/201 |
| | Date In/Mileage | / 0 |
| | Chassis No | KNAFW611MC5605243 |
| | Engine No | G4FCCH227179 |
| | Make/Model | KIA/KOUP 1.6 A SX SR HB 64 |
| | Colour/Trim | UD Clear White / WK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | |
|--|-------|-------------------|-----|--------------|------------|---------------|---------|
| CSM00081 | Cash | 26/12/2017/ 15:30 | TLC | 442 / CocoLu | 20412 | | |
| Description of Goods / Services | | | | Qty | Unit Price | Disc% | Amount |
| E PNT88000 | | | | | 1100 | | 1650.00 |
| TO RENEW FRT BUMPER, FRT AIRDAM, FRT SUPPORT PANEL, REPAIR BONNET, | | | | | 1050 | | 1680.00 |
| E PNT98000 | | | | | | | 100.00 |
| TO SPRAY PAINT FOR FRT BUMPER, FRT AIRDAM, BONNET | | | | | | | 20.00 |
| M SUNDRY | | | | | | | 200.00 |
| TO SUPPLY FRT & REAR NUMBER PLATE WITH FRAME / Cut | | | | | | | 2750.00 |
| A 54900099 | | | | | | | 2100.00 |
| TO CHECK WIRING & ELECTRICAL SYSTEM | | | | | | | 100.00 |
| A 54900099 | | | | | | | 2750.00 |
| TO CONDUCT DIGNOSTIC CHECK FOR THE CAR SYSTEM | | | | | 1650 | | 2100.00 |
| E PNT88000 | | | | | | | 100.00 |
| TO RENEW REAR BUMPER, REAR AIRDAM, REAR END PANEL, BOOTLID, | | | | | 1680 | | 720.00 |
| E PNT98000 | | | | | | | 80 |
| TO SPRAY PAINT FOR REAR BUMPER, REAR AIRDAM, REAR END PANEL BOOTLID, | | | | | | | 100.00 |
| E PNT88000 | | | | | | | 720.00 |
| TO REMOVE & INSTALL PARKING SENSOR | | | | | | | 80.00 |
| M SUNDRY | | | | | | | 250.00 |
| TO SUPPLY REVERSE CAMERA ? | | | | | | | 30.00 |
| M SUNDRY | | | | | | | 20.00 |
| TO APPLY SEALANT FOR ACCIDENT AREA ? | | | | | | | 100.00 |
| E PNT88000 | | | | | | | 80.00 |
| TO REMOVE & INSTALL REAR COMPARTMENT TRIMS TO FACILITATE REPAIR | | | | | | | 2109.00 |
| M SUNDRY | | | | | | | |
| C&C LOGO / MC | | | | | | | |
| M SUNDRY | | | | | | | |
| Sundry | | | | | | | |
| E PNT88000 | | | | | | | |
| TO REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR ? | | | | | | | |
| M SUNDRY | | | | | | | |
| TO TOP UP AIRCON GAS ? | | | | | | | |
| M CERATO FORTE KOUP UD | | | | | 1.00 | 2109.00 00.00 | 2109.00 |

Confirm & accepted by

Authorized signatory and company stamp

- Customer's Consultant's hence notify
- Repairs of the following:
- Resurvey immediately after spray painting
 - To display damaged part(s) during resurvey
 - Parts price is subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info |
|----------------------------------|--|
| Mr Mohamed Rafi S/O Mouhamadally | Cust No/Name /Mr Mohamed Rafi S/O Mouhamadally |
| Blk 502 Hougang Ave 8 | Reg No/Reg Date SKE6760T / 26/03/201 |
| #02-606 | Date In/Mileage / 0 |
| Singapore 530502 | Chassis No KNAFW611MC5605243 |
| Contact No Mobile: 81218036 | Engine No G4FCCH227179 |
| | Make/Model KIA/KOUP 1.6 A SX SR HB 64 |
| | Colour/Trim UD Clear White / WK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | | |
|---------------------------------|---------------------------------|-------------------|-----|--------------|--------|------------|-------|---------|
| CSM00081 | Cash | 26/12/2017/ 15:30 | TLC | 442 / CocoLu | 20412 | | | |
| Description of Goods / Services | | | | | Qty | Unit Price | Disc% | Amount |
| P | COVER-FR BUMPER | 1.00 ? | | | 1.00 | 735.00 | 00.00 | 735.00 |
| M | MOULDING-FRT BPR LICENSE PLATE | 1.00 | | | 1.00 | 16.00 | 00.00 | 16.00 |
| M | GRILLE ASSY-RADIATOR | 1.00 | | | 1.00 | 244.00 | 00.00 | 244.00 |
| M | ABSORBER-FRONT BUMPER ENERGY | 1.00 | | | 1.00 | 119.00 | 00.00 | 119.00 |
| M | GRILLE ASSY-RADIATOR | 1.00 | | | 1.00 | 241.00 | 00.00 | 241.00 |
| M | RAIL ASSY-FR BUMPER | 1.00 | | | 1.00 | 204.00 | 00.00 | 204.00 |
| M | BRACKET-FR BUMPER UPR SIDE MTG | 1.00 | | | 1.00 | 26.00 | 00.00 | 26.00 |
| M | BRACKET-FR BUMPER UPR SIDE MTG | 1.00 | | | 1.00 | 26.00 | 00.00 | 26.00 |
| M | BRACKET-FR BUMPER SIDE,RH | 1.00 | | | 1.00 | 12.00 | 00.00 | 12.00 |
| M | BRACKET-FR BUMPER SIDE,LH | 1.00 | | | 1.00 | 12.00 | 00.00 | 12.00 |
| M | LAMP ASSY-HEAD,LH | 1.00 | | | 1.00 | 565.00 | 00.00 | 565.00 |
| P | CARRIER ASSY-FRONT END MODULE | 1.00 | | | 1.00 | 438.00 | 00.00 | 438.00 |
| M | COVER-RR BUMPER | 10.00 | | | 10.00 | 607.00 | 00.00 | 6070.00 |
| M | COVER-RR BUMPER,CTR | 1.00 | | | 1.00 | 381.00 | 00.00 | 381.00 |
| M | ABSORBER-REAR BUMPER ENERGY | 1.00 | | | 1.00 | 156.00 | 00.00 | 156.00 |
| M | BRACKET ASSY-RR BUMPER SIDE,RH | 1.00 | | | 1.00 | 23.00 | 00.00 | 23.00 |
| M | BRACKET ASSY-RR BUMPER SIDE,LH | 1.00 | | | 1.00 | 23.00 | 00.00 | 23.00 |
| M | ABSORBER-REAR BUMPER ENERGY | 1.00 | | | 1.00 | 156.00 | 00.00 | 156.00 |
| M | LAMP ASSY-LICENSE PLATE,LH | 1.00 | | | 1.00 | 33.00 | 00.00 | 33.00 |
| M | LAMP ASSY-LICENSE PLATE,RH | 1.00 | | | 1.00 | 33.00 | 00.00 | 33.00 |
| P | SENSOR ASSY-ULTRASONIC BWS,CTR | 2.00 | | | 2.00 | 204.00 | 00.00 | 408.00 |
| P | SENSOR ASSY-ULTRASONIC BWS,SIDE | 2.00 | | | 2.00 | 204.00 | 00.00 | 408.00 |
| M | ANTENNA ASSY-SMARTKEY | 1.00 | | | 1.00 | 79.00 | 00.00 | 79.00 |
| M | RAIL ASSY-REAR BUMPER | 1.00 | | | 1.00 | 559.00 | 00.00 | 559.00 |
| M | LAMP ASSY-REAR COMB OUTSIDE,LH | 1.00 | | | 1.00 | 274.00 | 00.00 | 274.00 |
| M | LAMP ASSY-REAR COMB OUTSIDE,RH | 1.00 | | | 1.00 | 274.00 | 00.00 | 274.00 |
| M | PANEL ASSY-BACK | 1.00 | | | 1.00 | 290.00 | 00.00 | 290.00 |
| M | EMBLEM-KOUP | 1.00 | | | 1.00 | 26.00 | 00.00 | 26.00 |
| M | LOGO ASSY-KIA SUB | 1.00 | | | 1.00 | 41.00 | 00.00 | 41.00 |

Estimate

Guo Qiang @ 1kkanoto.com

Confirm & accepted by

Guo Qiang @ 1kkanoto.com
 9 Days.
 before paint photos.
 Guo Qiang - 82880282
 29/12/17

Nett

23,861.00

7% GST on 23861.00

1670.27

Total Payable

25,531.27

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.