

«

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

General Details

Involving

1 2008 HONDA FIT 1.3 (SJJ5983J)

Date of Loss

December 22, 2017

Time of Loss

18.50

Loss Description

SJJ5983J(INSJ) -> GBF7069B (TP) -> SCH8882R

Comment

Workshop Details

Total Rebate Amount

7328

Nett Loss Amount

\$5,672.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

02/15/2018

Days of work completion *

22



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Vehicle & Driver Details

Vehicle Registration#
SJJ5983J

Registration State
SINGAPORE

Mileage
168933

Purchase Date
mm/dd/yyyy

Registration Date *
09/19/2008

Age of Vehicle
9

CATEGORY	Manufacturing Year
POLICY INFORMATION	2008
ASSESSMENT INFORMATION	2008
CATEGORY	Make
POLICY INFORMATION	HONDA

CATEGORY

Model

POLICY INFORMATION

FIT 1.3

ASSESSMENT INFORMATION

FIT 1.3G A

CATEGORY

Type

POLICY INFORMATION

ASSESSMENT INFORMATION

CATEGORY

Type of Paint

POLICY INFORMATION

ASSESSMENT INFORMATION

CATEGORY

Chassis No

POLICY INFORMATION

GE61107745

ASSESSMENT INFORMATION

GE61107745

CATEGORY

Engine No

POLICY INFORMATION

L13A4120027

ASSESSMENT INFORMATION

L13A4120027

CATEGORY

Engine Capacity

POLICY INFORMATION

ASSESSMENT INFORMATION

1339

POLICY INFORMATION	0
ASSESSMENT INFORMATION	0

CATEGORY Market Value

POLICY INFORMATION	0
ASSESSMENT INFORMATION	13000

Driver Details

CATEGORY Driver Name

FNOL INFORMATION TAN NORMAN

POST SURVEY INFORMATION	
-------------------------	--

CATEGORY Date of Birth

FNOL INFORMATION April 28, 1976

POST SURVEY INFORMATION	mm/dd/yyyy
-------------------------	------------

CATEGORY Age

FNOL INFORMATION 41

POST SURVEY INFORMATION	
-------------------------	--

CATEGORY Occupation

FNOL INFORMATION Unknown

POST SURVEY INFORMATION	
-------------------------	--



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Detailed Assessment

Inspection Date *

12/28/2017



Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

500

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Good

Tyre Condition

Age of Tyres

Front Tyre Size

195/50R15

Front left side

GOODYEAR5mm

Front right side

GOODYEAR5mm

Spare wheel

Rear Tyre Size

195/50R15

Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts
Parts & Labour	Miscellaneous	Summary	AddApproveDeny		
	☐				
					
	1				
	1				
		FRT BONNET			
		Buckled			
		240			
		240			
		Reviewing			
					
	☐				
					
	2				

2

FRT BONNET HINGE

Bent

22

44

Reviewing



3

1

FRT BONNET LOCK

Twisted

75

75

Reviewing



4

1

FRT BONNET LOCK CABLE

Serviceable

0

0

0

0

0

Deny





5

1

FRT GRILLE

Bent

75

75

Reviewing



6

1

FRT GRILLE LOGO

Damaged

20

20

Reviewing



7

1

FRT BUMPER

Damaged

170

170

Reviewing





8

2

FRT BUMPER RETAINER

Bent

10

20

Reviewing



9

10

FRT BUMPER CLIP

Necessary

1.5

15

Reviewing



10

1

FRT BUMPER REINFORCEMENT

Damaged

90

90

Reviewing



11

2

FRT BUMPER BEAM (BELOW HEADLAMP)

Cracked

20

40

Reviewing



12

1

FRT BUMPER TOWING COVER

Damaged

10

10

Reviewing



13

2

HEADLAMP

Cracked

330

660

Reviewing



14

1

HEADLAMP SUPPORT PANEL

Bent

170

170

Reviewing



15

1

AIRCON CONDENSER

Bent

140

140

Reviewing



16

1

RADIATOR

Bent

195

195

Reviewing



17

2

AIRCON CONDENSER TOP BRACKET

Twisted

12

24

Reviewing



18

2

RADIATOR TOP BRACKET

Twisted

12

24

Reviewing



19

1

AIRCON MOTOR COWLING

Cracked

65

65

Reviewing



20

1

AIRCON MOTOR

Damaged

210

210

Reviewing



21

1

AIRCON FAN BLADE

Cracked

35

35

Reviewing



22

1

RADIATOR MOTOR COWLING

Cracked

65

65

Reviewing



23

1

RADIATOR MOTOR

Damaged

210

210

Reviewing





24

1

RADIATOR FAN BLADE

Serviceable

0

0

0

0

0

Deny



25

1

RADIATOR SPARE TANK

Deformed

25

25

Reviewing



26

1

RADIATOR TOP HOSE

Serviceable

0

0

0

0

0

Deny



27

1

AIR CLEANER BOX TOP

Cracked

45

45

Reviewing



28

1

AIR CLEANER BOX LOWER

Serviceable

0

0

0

0

0

Deny



1



29

1

BATTERY TRAY

Serviceable

0

0

0

0

0

Deny



30

1

WASHER TANK

Deformed

85

85

Reviewing





31

1

ENGINE MOUNTING RH

Cracked

100

100

Reviewing



32

1

ENGINE MOUNTING LH

Damaged

100

100

Reviewing



33

1

ENGINE MOUNTING REAR

Damaged

75

75

Reviewing





34

1

TIMMING HOUSING COVER

Cracked

155

155

Reviewing



35

1

FRT FENDER RH

Buckled

110

110

Reviewing



...



36

10

INNER COWLING CLIP

Serviceable

0

0

0

0

0

Deny



37

1

FRT FENDER TOP CORNER GARNISH

Serviceable

0

0

0

0

0

Deny



38

1

4 LIT AUTO OIL

Serviceable

0

0

0

0

0

Deny



Labour

Add

Approve

Deny

☐

1

WIRE CHECKING

20

0

0

Reviewing



2

REMOVE & REFIX AIRCON AND GAS

100

0

0

Reviewing



3

REMOVE & REFIX 1 SET ENGINE MOUNTING

60

0

0

Reviewing



4

REMOVE & REFIX TIMMING HOUSING COVER

20

0

0

Reviewing



5

REMOVE & REFIX ENGINE

0

0

0

Deny



6

LABOUR CHARGE

800

0

0

Reviewing



7

SPRAY PAINTING

800

0

0

Reviewing



Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	
Parts & Labour	Miscellaneous	Summary	Add	Approve	Deny
					
					
		1			
		FRT NUMBER PLATE			
		Reviewing			
		35			
		BENT			
					
					
					
		2			
		RADIATOR COOLANT			
		Reviewing			
		25			
		NECESSARY			
					
					
					

3

FRT BUMPER LOWER GRILLE

Reviewing

45

(TORN)SUPPLEMENTARY ADDED
25/01/2018



4

FRT BONNET STAND CLIPS

Reviewing

3.5

(MISSING)SUPPLEMENTARY ADDED
25/01/2018



5

WASHER TANK MOTOR

Reviewing

35

(DAMAGED)SUPPLEMENTARY
ADDED 25/01/2018



6

2PC WASHER TANK SEAL

Reviewing

12

(NECESSARY))SUPPLEMENTARY
ADDED 25/01/2018



7

FRT RH FENDER INNER COWLING

Reviewing

35

(TORN)SUPPLEMENTARY ADDED
25/01/2018



8

AIRCON SUCTION PIPE

Reviewing

105

(BENT)SUPPLEMENTARY ADDED
25/01/2018



9

AIRCON DISCHARGE PIPE

Reviewing

65

(BENT)SUPPLEMENTARY ADDED
25/01/2018



10

RH ENGINE MOUNTING BRACKET

Reviewing

55

(CRACKED)SUPPLEMENTARY
ADDED 25/01/2018





Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount
\$5,007.50

CATEGORY	Labour
ESTIMATE	\$1,800.00
REVISED AMOUNT	\$1,800.00
CATEGORY	Spare Parts
ESTIMATE	\$3,292.00
REVISED AMOUNT	\$3,292.00
CATEGORY	Miscellaneous
ESTIMATE	\$60.00
REVISED AMOUNT	\$415.50
CATEGORY	Excess
ESTIMATE	-\$500.00
REVISED AMOUNT	-\$500.00

Submit for Review

