SS. REC. BY: REF: CG3/7(S) 7008503/Ctb-(Special Instruction.	
UrVeyor Assignment (Office)	n (7
rom (Person): Phubl July of ICS Date: Time 27-17	2017
estimated Cost: Bill to:	
DD + TED+WS+TP RES / OD RES / EVA / ENV / MV / CS SI /2 86100 Insured: 378 831	567
To inspect Vehicle No:	
at Workshop m/s Pre CISE MUID let:	
	and the state of t
Policy No: Claim No: DMPHI700068H	
Excess:	
Make of Veh: D.O.A.	
Date/Time 02052017 1130pm Person Contacted: Yan Hung Vehicle On OUR	
Date/Time Action/Instruction (x) Estimate	
314 US00 · *	
JA 38517 - 014 Milly 10 13518 (Mark) 100 14	11. 11. 11
Dismoville Port: 0405207	
1001	
1	ted with-the ineura
Submit 12 &S, &Sof without Snalise. (Red: 2950;	33%)
Chia	•
6 days.	

31/1- File page to typist

PRC.	REF: T(S			•
Singly RICHARD	ASSI	GNMENT		
From. Estimated Cost:	Date 03U52017	Veh No: SLG Type: M.Car / M.Cycle / Bu		gn: 2016 17/10 Prime Mover 901
at Workshop m/s of Bk i K4ki Insured: Policy No. Ctaims No. Sum Insured: (Client's Record)	EVALINVIMV SLIT 86200 PCICL ALTO BUICH AVE 6 # 07-314 Excess	Make MAZDA Colour Black Sp.Reading Sp.Reading Eng/No: C/No: Gen. Cond Good/ Fair / Steering Inorder / Jamme	BIANTS A/C T/Radic CC F 7 1 G V Poor / Burnt ed / Leaked / Burnt or	Insured / Std / NI / NA Insured / Std / NI / NA
(DAO Account s done	its N/S O/S	Tyre Size: F: Z	05/60 /16	. 6 mm
Est. Repairs: days Lum Sum: % CA / REV / REP. / 24 HRS	3 Val.: Yes or No ; いいつ Vehicle: IN/OUT	Des. of Damages : Frt		JIC I Rooftop or
Date / Time Action / Instruction			Constant	re affected due to collision
			1-1	12/501]
	reli. Report inal Report	Days Of Repair: Resurvey No. of Trip:		ey Fee. portason
2)	Add Fe	Interview (\$)S }	· · ·
Report Format : PRS Lump Sum / I.B.I: (\$;	Tech Invs (\$ Weakend (\$, . ,	31.2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Intern	ationale Des Experts En Autor	mobile 100 mobile
ECICS LTD	• •	Ref : CS3/ICS17008	3553/tb-1
7 TEMASEK BOULE' #10-01 SUNTEC TO\ SINGAPORE 03898'	VER ONE	Date: 28-12-2017 Code: ICS	
	Policy Particula	ars :- THIRD PARTY CLA	IM
Insured Veh.	SJR 8859Z	Veh. Inspected	SLG 8620D
Policy No.		Coverage (\$)	0.00
Claim No.	DMPH1700068H	Excess (\$)	0.00
Assign From	PHOEBE JAY	Assign Date	27/12/2017
	Vehicle Pa	articulars & Condition	YEARY LOS LAND TO THE REPORT OF
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
	∌ Con∈	ditions of Tyres	MATERIAL STATE OF THE STATE OF
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
	∵∹[Descri]	ption of Damages (21)	
	Gene		· · · · · · · · · · · · · · · · · · ·
Accident Date	28/04/2017	Inspection Date	28/12/2017
Survey held at	PRECISE AUTO SERVICE	mapection Date	20/12/2017
	NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883		
a.	The second second	Remarks	e green and the stable was the company of the stable and
A)THE INSPECTI	ON WAS CONDUCTED ON A"V	VITHOUT PREJUDICE" BAS	IS
	CE TO YOUR INSTRUCTIONS.		

Catherine Chong (LKK Auto)

From:

Phoebe Jay Xie (ECICS, Claims) < Phoebe Jay_Xie@ecics.com.sg>

Sent:

Wednesday, 27 December, 2017 12:01 PM

To:

Catherine Chong (LKK Auto)

Cc:

ECICS Claims; assignments@lkkauto.com

Subject:

RE: ***SPAM*** RE: ACCIDENT INVOLVING MOTOR VEHICLES NO. SLG 8620D AND

SJR 8859Z ON 28.4.17

Attachments:

img-Z27114825-0001.pdf

Dear Catherine.

We received a letter of demand from third party, appreciate if your surveyor can comment on the cost of repair.

Thank you.

Best Regards,

Phoebe Jay Xie

ECICS Limited

DID: +65 6303 0180 FAX: +65 6338 9267

Email: phoebejay xie@ecics.com.sg

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]

Sent: Monday, 15 May, 2017 9:31 AM To: Valerie Yap Jia Pei (ECICS, Operations)

Cc: ECICS Claims; assignments@lkkauto.com; Phoebe Jay Xie (ECICS, Operations / Claims)

Subject: RE: ***SPAM*** RE: ACCIDENT INVOLVING MOTOR VEHICLES NO. SLG 8620D AND SJR 8859Z ON

28.4.17

Dear Valerie.

Noted with thanks.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Valerie Yap Jia Pei (ECICS, Operations) [mailto:Valerie Yap@ecics.com.sg]

Sent: Monday, 15 May, 2017 8:59 AM

To: Catherine Chong (LKK Auto) admin-d@lkkauto.com>

Cc: ECICS Claims < claims@ecics.com.sg >; assignments@lkkauto.com; Phoebe Jay Xie (ECICS, Operations / Claims)

<PhoebeJay Xie@ecics.com.sg>

Subject: RE: ***SPAM*** RE: ACCIDENT INVOLVING MOTOR VEHICLES NO. SLG 8620D AND SJR 8859Z ON 28.4.17

Dear Catherine.

Oref: DMPH1700068H

Thank you.

Kind Regards. Valerie Yap **Operations**

DID: +65 6303 0181 FAX: +65 6338 9267

ECICS LIMITED

Email: valerie yap@ecics.com.sg



From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]

Sent: Saturday, 13 May, 2017 11:46 AM

To: Phoebe Jay Xie (ECICS, Operations / Claims); Valerie Yap Jia Pei (ECICS, Operations)

Cc: ECICS Claims; assignments@lkkauto.com

Subject: RE: ***SPAM*** RE: ACCIDENT INVOLVING MOTOR VEHICLES NO. SLG 8620D AND SJR 8859Z ON

Dear all,

Kindly provide us the claim number.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]

Sent: Tuesday, 2 May, 2017 4:21 PM

To: 'Phoebe Jay Xie (ECICS, Operations / Claims)' < PhoebeJay Xie@ecics.com.sg; 'Hui Ling ' riaz@justice.com.sg;

'Valerie Yap Jia Pei (ECICS, Operations)' < Valerie Yap@ecics.com.sg> Cc: 'ECICS Claims' < claims@ecics.com.sg >; assignments@lkkauto.com

Subject: RE: ***SPAM*** RE: ACCIDENT INVOLVING MOTOR VEHICLES NO. SLG 8620D AND SJR 8859Z ON 28.4.17

Dear Phoebe,

Thank you for your email.

Kindly provide us the workshop detail.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Phoebe Jay Xie (ECICS, Operations / Claims) [mailto:PhoebeJay Xie@ecics.com.sg]

Sent: Tuesday, 2 May, 2017 4:20 PM

To: Hui Ling < riaz@justice.com.sg >; Valerie Yap Jia Pei (ECICS, Operations) < Valerie Yap@ecics.com.sg >; Admin-D

(LKKAuto) admin-d@lkkauto.com">survey@jpknights.com

Cc: ECICS Claims < claims@ecics.com.sg>

Subject: RE: ***SPAM*** RE: ACCIDENT INVOLVING MOTOR VEHICLES NO. SLG 8620D AND SJR 8859Z ON 28.4.17

Dear LKK.

Please survey vehicle

Thank you.

Best Regards.

Phoebe Jay Xie

ECICS Limited

DID: +65 6303 0180 FAX: +65 6338 9267

Email: phoebejay xie@ecics.com.sg



From: Hui Ling [mailto:riaz@justice.com.sg]

Sent: Friday, 28 April, 2017 4:11 PM

To: Phoebe Jay Xie (ECICS, Operations / Claims); Valerie Yap Jia Pei (ECICS, Operations)

Subject: RE: ***SPAM*** RE: ACCIDENT INVOLVING MOTOR VEHICLES NO. SLG 8620D AND SJR 8859Z ON

WITHOUT PREJUDICE

Dear sirs.

We refer to your below email.

On behalf of our client, we disagree with your appointment and nominates as the surveyor.

Please choose one out of the surveyor from the list below:-

- 1. Chang Fuh Keong, Dave
- Ho Joo Loong, Danny 2.
- 3. **Dennis Yap**

- 4. Michael Yap
- Lee Kok Weng 5.
- 6. Winson Goh
- 7. Ong Ah Keng, Kent
- 8. Ong Poh Meng
- 9. Seah Kwang Boon
- 10. Thor Teck Soon, David

Kindly revert within the allotted time pursuant to NIMA protocol.

Best regards,

Hui Ling Riaz LLC

Tel: 6534 0110 Fax: 6534 0220

From: Phoebe Jay Xie (ECICS, Operations / Claims) [mailto:PhoebeJay Xie@ecics.com.sg]

Sent: Friday, 28 April 2017 4:07 PM

To: Hui Ling < riaz@justice.com.sg>; Valerie Yap Jia Pei (ECICS, Operations) < Valerie Yap@ecics.com.sg>

Subject: ***SPAM*** RE: ACCIDENT INVOLVING MOTOR VEHICLES NO. SLG 8620D AND SJR 8859Z ON 28.4.17

Dear Huiling,

Our list of surveyor is:

- Formteam
- Autoprobe
- 3. JP Knights
- LKK
- Raleigh

Please inform us of your choice of surveyor

Thank you.

Best Regards,

Phoebe Jay Xie

ECICS Limited

DID: +65 6303 0180 FAX: +65 6338 9267

Email: phoebejay xie@ecics.com.sg







From: Hui Ling [mailto:riaz@justice.com.sg]

Sent: Friday, 28 April, 2017 3:26 PM

To: Valerie Yap Jia Pei (ECICS, Operations); Phoebe Jay Xie (ECICS, Operations / Claims)

Subject: ACCIDENT INVOLVING MOTOR VEHICLES NO. SLG 8620D AND SJR 8859Z ON 28.4.17

WITHOUT PREJUDICE


Dear sirs.

Please find the enclosed notice of accident for your action.


Thanks.

Best regards, Hui Ling Riaz LLC

Tel: 6534 0110 Fax: 6534 0220



This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.



This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.



This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

PRECISE AUTO SERVICE

NO 1 KAKI BUKIT AVE 6 #02-34/36 AUTOBAY SINGAPORE 417883

TEL: 6745 7367 FAX: 6841 3390

CO. REG. NO.: 35766600C GST REG. NO.: 35766600C

Accident Date: 28-04-17

OUR REF: SLG 8620D/T/17

TAX INVOICE

Sim Sian Thye

Blk 685C Woodlands Dr 73

#12-22

Singapore 733685

Invoice No.: TP1708-019

DATE: 31-08-2017

FINAL BILL ON VEH. NO.: SLG 8620D VEHICLE MODEL: MAZDA BIANTE 5

PART BY PART REPAIR

INCLUDING SUPPLY OF PARTS & LABOUR

PANEL BEATING & SPRAY PAINTING

8,800.00

SUB-TOTAL :

8.800.00

ADD GST 7%

616.00

TOTAL AMOUNT SGD

9,416.00

This is a computer generated document and requires no signature.

CARLINK CONSULTANCY

60 Hillside Drive, Singapore 549009 Fax: 62874788 Tel: 62856178

INVOICE

Sim Sian Thye

C/o 1 Kaki Bukit Ave 6 #02-34/36

Singapore 417883

Invoice No:

CL 11889 TP

Our Ref.

CL 11889 SLG 8620 D

Date:

23rd August 2017

S/N	DESCRIPTION	QTY	UNIT PRICE (\$)	AMOUNT (\$)
	Vehicle No: SLG 8620 D			
	Charges for accident vehicle inspection and appraisal report, transportation, photographs and etc** (photographs - 81 copies)			\$676.00
			Total:	\$676.00

We thank you for the opportunity to serve you and assure you of our best at all times

Automotive Engineer Assessor MIMI, MIRTE, LCGI, I ENG, LAE, CGLI FTC.

Note: Payment by cheque should be crossed and made payable to "CARLINK CONSULTANCY"

CARLINK CONSULTANCY

60 Hillside Drive Singapore 549009 Tel:

62856178

Fax:

62874788

ACCIDENT VEHICLE INSPECTION / ASSESSMENT REPORT

Our Ref: CL 11889 SLG 8620 D

REFERENCE

Date of request

: 3rd May 2017

Requested by

: Sim Sian Thye

C/o 1 Kaki Bukit Ave 6, #02-34/36 Singapore 417883

Type of claim

: Third party

Workshop

: M/S Precise Auto Service

1 Kaki Bukit Ave 6, #02-34/36

Singapore 417883

Date of survey

: 3rd May 2017

Accident date

: 28th April 2017

2 DETAILS OF VEHICLE

Registration No.

: SLG 8620 D

Make & Model

: Mazda Biante 5-Door Wagon 2.0L SP.6EAT

Date of registration

: 17th October 2016

Engine No.

: PE30874803

Chassis No.

: JM6CC1071G0109358

Speedometer reading

: 15051 Km

Transmission

: Automatic

Colour

: Black

3 STATIC CHECK

Steering

: 888 annex(es)

Paintwork

: Good

Footbrake Handbrake

: See annex(es) : see annex(es)

Modification

: Nit General condition : Good

4 TYRE CONDITION

Nearside/Make

Offside/Make

Size

Front tyre Rear tyre

: 6mm/Nancenerg : 6mm/Nancenerg

6mm/Nanoenerg 6mm/Nancenerg : 205/60 R16 : 205/60 R16

5 POINT OF IMPACT

See Annex(es) and Motor Accident Reports

6 REMARK

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not authorised any repair.

MSME17056438 / SME Misor Ple Ltd - Kaki Bulkt ENTRY DATE & TIME: 29/64/2017 69:25

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to apped up the claims process.
- 2 This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to regulate policy ability.
- A. The issue and acceptance of this Form by insurance companies is not an admission of policy hability on the part of the insurance companies
- 5 Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made evadeble upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	29/04/2017 09:25
Date Of Accident	28/04/2017 10:15
Exact Location Of Accident	YIO CHU KANG RD TWDS UPPER THOMSON RD.
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number

Insured/Policyholder

Name Of Registered Owner NRIC No

Email Address

Mobile Phone No

Allemative Phone No Vehicle Particulars

Manufacturer Model

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

Vehicle Category

Insurance Company

Name of Insurance Company

Fleet Policy

Type Of Coverage

Policy Number

Name of Driver

Cover Note Number

Driver

NRIC No Date Of Birth Occupation Date Of Driving Pass

Driving Experience Gender

Mobile Number Fax Number

Contact Number EMail Address

SLG8620D

SIM SIAN THYE

S1794354E

NOEMAIL

(LOCAL) +65-96789854

OFFICE-96789854

MAZDA

BIANTE 5

THIRD PARTY

PRIVATE CAR

MSIG INSURANCE (SINGAPORE) PTE, LTD.

COMPREHENSIVE

NΩ

A28841434 QMY

SIM SIAN THYE

S1794354E

22/02/1967 **INDOOR**

21/07/1987

29 YEARS AND 9 MONTHS

MALE

(LOCAL) +65-96789854

OFFICE-96789854

NOEMAIL

Email Address

DETAILS OF INJURED PERSON 1

Name SIM SIAN THYE

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLG8620D

Were seat belts wom?

Was injured conveyed to hospital by ambulance?

Address

Postcode

	31		
3	tatemant Place Report No	eye Kafer 10	. 0
Poli	ie legart No	1/2014 0478/	400 L
		MARKATO AND	
aration			
	culars are live in every reso	ect.	
	culairs and true of givery possi	ect	
	culars are true in every resp	ect	
	culars are true et every resp	ect	
dectare the follogoing parts	A.		Wilnessed by Reporting Centre
dectare the follogoing parts	A.	driver is not the poscyholder) / Date	Witnessed by Reporting Centre Personnel
sectare the folegoing parts	A.		Wilnessed by Reporting Centre Personnel
sectare the folegoing parts	A.		Witnessed by Reporting Centre Personnel
sectare the foregoing parte	Criver's Signature (F & Time 1) \$704/1		Witnessed by Reporting Centre Personnel
halder's Signature / Date &	Crivers Signature (# 4 Time 1.5/04/1	driver is not the poscyholder) / Date .017- 3_00 pm	
sectare the foregoing parte	Crivers Squature (# 4 Time 1.5/04/1	driver is not the posicyholder) / Date .017	Witnessed by Reporting Centre Personnel
holder's Signature / Date &	Crivers Signature (# 4 Time 1.5/04/1	driver is not the poscyholder) / Date .017- 3_00 pm	





1 of 4

Police Station Of Origin Boon Teck NPP 207 Toa Payon North #01-1231 SINGAPORE 310207 Tel No. 1800-2549999

Report No. T/20170428/2082

DEPORT OF A TRAFFIC ACCIDENT

	ne Report M 017 13:46	Made:	Vide Report No.	Station Diary No. 12
Inform	nt's Partic	ulers .		
	f Informant. N THYE		Address: APT BLK 685C WOODL 733685	ANDS DRIVE 73 #12-22 SINGAPORE
ID Type NRIC N	/ ID No. O / \$17943	54E	Contact No. Home/Office	Mobile: 96789854
National SINGAF	Irty PORE CITIZ	EN.	Email	
Sex Male	Age 50	Date of Birth: 22/02/1967	Type of Informant: Driver	
Race Chinese			Language English	Institution / School Name:
Occupat SWIMM OFFICE	ING POOL	MAINTENANCE	Oriving Licence Informat Class 2B.3,4	tion: Date of Expiry

Type of Accident:	Injury Others	Drink Drive:	Date/Time of Accident 28/04/2017 10:15	Type of Location Straight Road
YIO CHU KAI UPPER THOI				
Weather Clear	T . T . T . T . T . T . T . T . T . T .	Road Surface Dry	R	oad Speed Limit:
Traffic Flow: Dual Carriage	Way	Traffic Control: Not Controlled	· · ·	affic Volume: ght
Type of Collis		Vehicle	4	nyone conveyed by mbulance

Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenge
SJR8859Z	Car	NISSAN	SYLPHY 1.5L 4AT ABS D/AB 2WD 4DR	Blue	Slightly Damaged	0
SLG8620D	Car	MAZDA	BIANTE 5- DOOR WAGON 2.0L	Black	Slightly Damaged	0





Police Station Of Origin Boon Teck NPP 207 Top Payob North #0 7 of 4

207 Toa Payoh North #01-1231 SINGAPORE 310207

Report No. T/20170428/2082

Tel No 1800-2549999

CONTINUATION OF REPORT

Vehicle No. Ins	urance Company	Incuran	a No.		Effective	Expiry Dete
	SIG INSURANCE (SINGAPORE) E LTD					
Details of Perso	n involved					
Any Pedestrian II	nvolved; No					
No of Pedestrian	is Injured: NIL	Use of Ped	estnar	Cross	iing: NA	
Driver						
Name	MOHAMED ALI BIN KOSU MOH	AMED	ID No	-	\$8338157	D
Related Vehicle	SJR8859Z (Car)		Conta	ct No.	NIL	
Hospital/Climic	NIL		Class Drivin Licens Expiry	8	Class: Nit. Date of Ex	•
Date Treatment	NIL	Date Disch	narge	NIL		
No. of Days gran	ted Medical Leave NIL	Degree of	Injury	NIL		
Driver	······································					
Name	SIM SIAN THYE		ID No		S1794354	E
Related Vehicle	SLG8620D (Car)]	Conta	ct No.	96789854	
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL		Class Drivin Licent Expiry	g :e &	Class: 2B, Date of Ex	
Date Treatment	28/04/2017	Date Disch	arge	28/04	/2017	
	ed Medical Leave 05	Degree of		Sligh		

Brief Details

On the 28/04/17 at about 1015hrs, I was travelling along Yio Chu Kang Road going towards Upper Thomson Road in my vehicle bearing registration no SLG8620D. While driving, I observed a few cars to be parked in front of the condo namely Castle Green Condo, before the entrance and exit. As such, I slowed down my car to a stop behind the parked vehicles, before looking at my right side mirror to check if the coast is clear.

However, about 2 to 3 seconds later. I heard a braking sound, and then felt an impact behind me. I then realised that another vehicle bearing registration no. SJR8859Z had collided against the rear of my vehicle. The other driver and I then alighted from our vehicles. I realised that my rear bumper and boot had suffered scratches and dents, and the mudguard of my vehicle is damaged. The other vehicle's bonnet and front bumper was dented and out of place.

The other driver claimed that he is not injured. He does not have any passengers in his vehicle. We then took pictures of each of our vehicles and exchanged particulars before we left the scene. No police or





Police Station Of Origin
Boon Teck NPP
207 Toa Payon North #01-1231 SINGAPORE
310207 CONTINUATION OF REPORT

4 of 4 Report No. T/20170428/2082

Tel No. 1800-2549999

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Re E /	cording The Report.	Signature Of Informant.	e a manager
Sgt MARCUS TEO		J. J.	
Signature Of Interpreter	*.	Date/Time:	
Not applicable		28/04/2017 13:46	
Officer In Charge Of Ca	se ·	Classification Of Case	
TAN SIEW GEK	CONTRACTOR OF THE STATE OF THE	4 fr	
Contact No 65476230			
Authentication Stamp	The second second	jk.	
	A Commission Line Poplar	Lane	

Annex A: Assessement / Adjustment on Spare Parts

ten	Vehicle Parts Description	Condition	Qty	W/shop Est. (\$)	Disc (%)	Adjusted Cost (\$)
	List Items	<u></u>				
1	Rear bumper fascia	Grazed/deformed/cut	1	\$1,114.70	20%	\$891.76
2	Rear bumper side retainer	Necessary	2	\$92.80	20%	\$74.24
3	Rear bumper side attachment	Necessary	2	\$110.20	20%	\$88.16
4	Rear bumper clips	Necessary	10	37.5 5 \$65.00	20%	\$52.00
5	Rear bumper reflector RH	Slack/chipped	1	\$118.50	20%	\$94.80
6	Rear bumper chrome (side)	Grazed/bent	2	\$163.80	20%	\$131.04
7	Rear bumper chrome (center)	Grazed/bent	1	\$123.90	20%	\$99.12
8	Rear bumper dust cover	Grazed	2	\$232.80	20%	\$186.24
9	Rear bumper dust cover clips	Necessary	6	⊋ ≶ \$39.00	20%	\$31.20
10	Tail gate	Buckled	1	\$1,618.70	20%	\$1,294.96
11	Tail gate hinges	Repair	2	\$68.20	100%	\$0.00
12	Tail gate stopper	Necessary	2	\$13.60	20%	\$10.88
i3	Tail gate absorber	Distorted/leaked	2	\$312.40	20%	\$249.92
4	Tail gate tail lamp	Cracked	1	\$1,319.30	20%	\$1,055.44
15	Tall gate tail clips clips	Necessary	6 :	62.5 ³ \$89.40	20%	\$71.52
16	Tail gate lock	Distorted/jammed	1	\$252.00	20%	\$201.60
 7	Tail gate lock striker	Distorted	1	\$27.20	20%	\$21.76
18	Tail gate inner trim board	Cut	1	\$269.80	20%	\$215.84
9	Tail gate inner trim board clips	Necessary	83	%25 \$42.40	20%	\$33.92
20	Tail gate inner handle holder	Deformed/cut	1	\$22.30	20%	\$17.84
21	Tail gate outer keyless sensor	Distorted/faulty	1	\$108.10	20%	\$86.48
2	Tail gate weatherstripe	Deformed/cut	1	\$207.90	20%	\$166.32
23	Tail gate emblem "SKYACATIV"	Necessary	1	\$111.50	20%	\$89.20
24	Rear end panel (outer)	Dented/bent	1	\$288.70	20%	\$230.96
25	Rear end panel top trim	Bent/cut	1	\$116.40	20%	\$93.12
26	Rear end panel top trim clips	Necessary	4	\$21.20	20%	\$16.96
27	Rear end panel (inner)	Dented/bent	1	\$276.80	20%	\$221.44
28	Rear floor panel board	Grazed/cut	1	\$738.50	20%	\$590.80
9	Rear windscreen glass moulding	Necessary	1	\$261.80	20%	\$209.44
.O	Rear windscreen glass inner seal	Necessary	1	\$38.10	20%	\$30.48
31	Rear windscreen glass clips	Necessary	14.	37.5 ¹ \$74.20	20%	\$59.36
32	Rear fender inner trim board RH	Cut	1	\$602.50	20%	\$482.00
33	Rear fender inner trim board clips	Necessary	8	\$29.60	20%	\$23.68
	S/Nett Items	1400030at y	•	₩ £3.00	20%	·
34	Reverse sensor with control unit	Slack/shifted/faulty	1	\$380.00		\$380.00
35	Rear windscreen glass sealant	Necessary	1	\$60.00		\$60.00

Total for Spare Parts : \$9,411.30 \$7,562.48

Annex B: Adjustment on Labour and Spray Painting

SLG 8620 D

Item	Job Description	Workshop Est. (\$)	Adjusted Cost (\$)	
1	Towing	\$80.00	\$60.00	
2	To check wiring system	\$80.00	\$60.00	3 D
3	To tuff coat affected areas	\$180.00	\$120.00	03
4	To remove/refix interior upholstery	\$180.00	\$100.00	60
5	To remove/refix rear windscreen glass	\$180.00	\$120.00	
6	To remove & refix tall gate mechanism	\$200.00	\$100.00	\mathcal{O}
7	To remove/replace/refix rear reverse sensor & reverse camera	\$200.00	\$160.00	70
8	To respray affected areas	\$1,250.00	\$1,200.00	100
9	To renew damaged parts, straighten/repair rear floor panel, rear chassis frame member & aligned all parts	\$1,200.00	\$900.00	800

TOTAL FOR LABOUR & SPRAY PAINTING: \$3,550.00

\$3,550.00 \$2,820.00

6 days

Summary

	Workshop Est. (\$)	Adjusted Cost (\$)
TOTAL FOR SPARE PARTS : TOTAL FOR LABOUR & SPRAY PAINTING :	\$9,411.30 \$3,550.00	\$7,562.48 \$2,820.00
TOTAL REPAIR COSTS:	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	\$10,382.48

CARLINK CONSULTANCY

SLG 8620 D

Annex C: Recommendation

We have inspected thoroughly the actual damages found on the vehicle and our assessment is appended in the Annex(es) attached. The condition and age of the vehicle was considered before we reached our recommendation as to whether the parts need replacement or repair.

M/S Precise Auto Service estimated repair cost is \$\$12,961.30 and we have adjusted it to \$\$10,382.48 on a part by part basis. However, taking into consideration the age of the vehicle and the availability of used/recondition components. We, therefore recommend a contract lump sum repair cost.

The repairer have agreed to undertake the repairs on a contract lump sum of \$\$8,800.00 ,according to acceptable quality and standard. (Repairer discretion to repair parts, to replace with old parts, or to replace with OEM or genuine parts).

The entire repair of the damaged vehicle should be completed within a reasonable period of 7 working days.

We have advised the repairer that the inspection was conducted strictly on a WITHOUT PREJUDICE basis and we have not given any instruction and authorisation to proceed with the repair of the vehicle.

We are reverting the matter to you for your discretion and enclosed is our invoice for service rendered.

Yours falthfully,

CARLINK CONSULTANCY

Automotive Engineer Assessor

MIMI. MIRTE, LCGI, I ENG. LAE, CGLI FTC.



5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Reg. No:	199607198R GST Reg. No. 19-96	00/ 1 9 0-R
2 2 6 3		Affiliated to Federation interr	nationale Dee Experts En Autom	obile
ECI	ICS LTD		Ref : CS3/ICS170085	553/Ctbe2-1
7 TEMASEK BOULEVARD #10-01 SUNTEC TOWER ONE SINGAPORE 038987			Date: 31-01-2018	
<u> </u>			Code: ICS	and the second
1		Policy Particula	ars :- THIRD PARTY CLAII	
<u> </u>	Insured Veh.	SJR 8859Z	Veh. Inspected	SLG 8620D
	Policy No.		Coverage (\$)	0.00
	Claim No.	DMPH1700068H	Excess (\$)	0.00
	Assign From	PHOEBE JAY	Assign Date	27/12/2017
2.		Vehicle P	articulars & Condition	
	Make & Model	MAZDA BIANTE	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JM6CC1071G0109358	Colour	BLACK
	Odometer	15051	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3.	- 1/2 - 1/2	Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	DUNLOP	6 mm
	L/H Front Tyre	205/60 R16	DUNLOP	6 mm
	R/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm
	L/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm
4.		Descri	iption of Damages	
	THE VEHICLE SU	USTAINED DAMAGES AT THE	REAR PORTION.	4 - C - C - C - C - C - C - C - C - C -
5.			eral Information 🖫 🔠	
	Accident Date	28/04/2017	Inspection Date	03/05/2017
	Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883		
5a.	144 (A) (A) (A) (A)		Remarks 💮 💮	
		ON WAS CONDUCTED ON A" CE TO YOUR INSTRUCTIONS		

Estimate Days of Repair:

6 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 8620D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER FASCIA	GRAZED / DEFORMED / CUT	1,114.70	1,114.70
2	REAR BUMPER SIDE RETAINER	NECESSARY	92.80	92.80
2	REAR BUMPER SIDE ATTACHMENT	SERVICEABLE	110.20	-
10	REAR BUMPER CLIPS	NECESSARY	65.00	37.50
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	118.50	-
2	REAR BUMPER CHROME (SIDE)	GRAZED / BENT	163.80	163.80
1	REAR BUMPER CHROME (CENTER)	GRAZED / BENT	123.90	123.90
2	REAR BUMPER DUST COVER	GRAZED	232.80	232.80
6	REAR BUMPER DUST COVER CLIPS	NECESSARY	39.00	25.00
1	TAIL GATE	BUCKLED	1,618.70	1,618.70
2	TAIL GATE HINGES	TO REPAIR SEE LABOUR	68.20	-
2	TAIL GATE STOPPER	NECESSARY	13.60	13.60
2	TAIL GATE ABSORBER	SERVICEABLE	312.40	-
1	TAIL GATE TAIL LAMP	NOT NECESSARY	1,319.30	-
6	TAIL GATE TAIL CLIPS	NECESSARY	89.40	62.50
1	TAIL GATE LOCK	DISTORTED / JAMMED	252.00	252.00
1	TAIL GATE LOCK STRIKER	DISTORTED	27.20	27.20
1	TAIL GATE INNER TRIM BOARD	сит	269.80	269.80
8	TAIL GATE INNER TRIM BOARD CLIPS	NECESSARY	42.40	31.25
1	TAIL GATE INNER HANDLE HOLDER	DEFORMED / CUT	22.30	22.30
1	TAIL GATE OUTER KEYLESS SENSOR	DISTORTED / FAULTY	108.10	108.10
1	TAIL GATE WEATHERSTRIPE	DEFORMED / CUT	207.90	207.90
1	TAIL GATE EMBLEM "SKYACATIV"	NECESSARY	111.50	111.50
1	REAR END PANEL (OUTER)	DENTED / BENT	288.70	288.70
1	REAR END PANEL TOP TRIM	BENT / CUT	116.40	116.40
4	REAR END PANEL TOP TRIM CLIPS	NECESSARY	21.20	21.20
1	REAR END PANEL (INNER)	TO REPAIR SEE LABOUR	276.80	_

Report Ref No. CS3/ICS17008553/Ctbe2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

ty	Description of Parts	⊶ Condition	Estimate By Workshop (\$))	Our Adjusted
1	REAR FLOOR PANEL BOARD	NOT NECESSARY	738.50	MANAGEMENT AND ASSESSMENT OF THE PROPERTY OF T
1	REAR WINDSCREEN GLASS MOULDING	NECESSARY	261.80	261.8
1	REAR WINDSCREEN GLASS INNER SEAL	NECESSARY	38.10	38.1
14	REAR WINDSCREEN GLASS CLIPS	NECESSARY	74.20	37.5
1	REAR FENDER INNER TRIM BOARD RH	сит	602.50	602.5
8	REAR FENDER INNER TRIM BOARD CLIPS	NECESSARY	29.60	29.6
	LESS 20% DISCOUNT		-	-1,182.2
			8,971.30	4,728.9
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR WITH CONTROL UNIT (SN)	SLACK / SHIFTED / FAULTY	380.00	250.0
1	REAR WINDSCREEN GLASS SEALANT (SN)	NECESSARY	60.00	60.0
	•		440.00	310.0
	LABOUR			
	TOWING.		80.00	60.0
	TO CHECK WIRING SYSTEM.		80.00	30.0
	TO TUFF COAT AFFECTED AREAS.		180.00	80.0
	TO REMOVE / REFIX INTERIOR UPHOLSTERY.		180.00	60.0
	TO REMOVE / REFIX REAR WINDSCREEN GLASS.		180.00	120.
	TO REMOVE & REFIX TAIL GATE MECHANISM.		200.00	60.0
	TO REMOVE / REPLACE / REFIX REAR REVERSE SENSOR & REVERSE CAMERA.		200.00	70.0
	TO RESPRAY AFFECTED AREAS.		1,250.00	1,000.
	TO RENEW DAMAGED PARTS, STRAIGHTEN / REPAIR REAR FLOOR PANEL, REAR CHASSIS FRAME MEMBER, ALIGNED ALL PARTS. INCLUSIVE OF THE REPAIR OF TAIL GATE HINGES AND REAR END PANEL (INNER).		1,200.00	800.
			3,550.00	2.280.0
				,
	GRAND TOTAL		12,961.30	7,318.9

RECOMMENDED COST OF LUMP SUM REPAIRS	885000
■ 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
(TO ITS PRE-ACCIDENT CONDITION)	
	The state of the s

Report Ref No. CS3/ICS17008553/Ctbe2-1





Report Ref No. CS3/ICS17008553/Ctbe2-1

1

HO LEONG CHUAN

Automotive Assessor