

INSURER
Merimen

Taufikh

ASSIGNMENT (Office)

First Person:

Chang Boon Sen

of CTI

Date/Time

27/12/17 @ 11:10am

Estimated Cost:

Bill to:

OI / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SGL 4447Y

Insured:

at Workshop m/s

Sng Ah Tee

Tel:

6268 6183

of

Blk 3, Pioneer Rd North, # 01-18

Policy No:

DMPCSN3079351600

Claim No:

20176001956

Sum Insured:

Excess:

-

Make of Veh:

D.O.A.

23/12/17

(Client's Record)

CA REV

/ REP. / REV 24 HRS 'wp'

H.O.D Enforcement:

Date/Time:

10:22am @ 28/12/17

Person Contacted:

Sharon

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SGL 4447Y - CC3/CTI/7024569/K1hs 3 D.O.A: 23/12/17
29/12/17	Revert by merimen 9118 1186
2/1/18	Recd approval from Alfred by merimen
2/1/18	@ 230pm Informed Samantha c/A on LS repair, LS at \$2000+ ex waived

Surveillance Tangfield

REF: CT1

ASSIGNMENT

From _____ Date: 16.10.2017

Estimated Cost: OD WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No. _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 40

(Client's Record)

Make of Veh: _____

Veh No: SGL 444 7 Y Yr Regn: 2007, August

Type: M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Toyota Vios E cc 1497

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 126526 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053HY1305125773

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / Rim / STD A/Rim or

Tyre Size: F: 185/65R15

R: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

X	
N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 28/12/17

Survey held at Sug 4th Tree

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

Bal. or Market Value: \$20K.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Reporter called to ask for PIP. Burnt IA through mcrimen.</u>
	<u>Confirm with Sharon L/c \$1,400.00 @ 6 days</u>
	<u>Red: 41736.63, 57%.</u>
RECEIVED 30 OCT 2018	

Date/Time. File Pass to? Prel. Report

1) typist Final Report

Date/Time. File Return to? _____

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:	<u>220</u>
Transportation:	_____
Photos	_____
Others	_____
TOTAL	<u>220</u>

Add Fee: Site Insp (\$)

Interview (\$)

Tech Invs (\$)

Weekend (\$)

Report Format: OD

Lump Sum / I.B.I. (\$ 1400.00)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17024591/T1rd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 28-12-2017	
		Code : CTI	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SGL 4447Y
Policy No.	DMPCSN3079351600	Coverage (\$)	0.00
Claim No.	20170001956	Excess (\$)	0.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	28/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	23/12/2017	Inspection Date	28/12/2017
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.		
5a. Remarks			
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Dec 2017 Sendback Est	26 Dec 2017 17:53 S\$3,036.63	27 Dec 2017 11:10 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	PANNEERSELVAM S/O RAMASAMY, ID: S69336941, Tel: +6591458638, Email: NOEMAIL		
Vehicle Reg. No.:	SGL4447Y	Date of Loss:	23/12/2017 16:00 - :59
Claim Type:	OD / 20170001956	Policy/Cover Note No.:	DMPCSN3079351600 (Comprehensive)
		Excess:	S\$0.00
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/01/2018]		
Driver/Custodian:	PANNEERSELVAM S/O RAMASAMY (48 / Male), NRIC: S69336941, Tel: +6591458638		
Adj Asg. Remarks:	SURVEY REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

SGL4447Y (SNM17D07291C01)

OD

Dec 23 2017 4:00PM

[PANNEERSELVAM S/O RAMASAMY]

Sng Ah Tee Motor & Panel Service Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 02/01/2018 14:16 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$2000.00) - SGL4447Y - Claim Handler: Chong Boon Sen

Approved:2000.00:Please proceed to authorize repairs at \$2,000.00 (lump sum basis) Excess is WAIVED.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com,assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 29 Dec 2017

Preliminary Advice

Vehicle No	: SGL4447Y	Accident Date	: 23/12/2017
Make	: TOYOTA VIOS	Policy No.	: DMPCSN3079351600
Assignment Date	: 27/12/2017	Excess	: S\$0.00
Date of Inspection	: 28/12/2017	Est. Duration of Repair	: 6.00
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-18 SINGAPORE 628457		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,249.19
Revised Amount	:S\$	1,928.88
Check Items (Estimated)	:S\$	1,107.75
Total	:S\$	3,036.63
Lump Sum Repair (ESTIMATED)	:S\$	2,400.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	20,000.00
COE / PARF Rebate	:S\$	9,489.00
Salvage Value	:S\$	
Margin for Repair	:S\$	10,511.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 03 Jan 2018

Preliminary Advice

Vehicle No	: SGL4447Y	Accident Date	: 23/12/2017
Make	: TOYOTA VIOS	Policy No.	: DMPCSN3079351600
Assignment Date	: 27/12/2017	Excess	: S\$0.00
Date of Inspection	: 28/12/2017	Est. Duration of Repair	: 6.00
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-18 SINGAPORE 628457		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,036.63
Revised Amount	:S\$	1,928.88
Check Items (Estimated)	:S\$	1,107.75
Total	:S\$	3,036.63

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	20,000.00
COE / PARF Rebate	:S\$	9,489.00
Salvage Value	:S\$	
Margin for Repair	:S\$	10,511.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Repairer asking for part by part basis.

639 6192

Print Received Message

This mail is associated with :

SGL4447Y (SNM17D07291C01)

OD

Dec 23 2017 4:00PM

[PANNEERSELVAM S/O RAMASAMY]
Sng Ah Tee Motor & Panel Service Pte Ltd

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 05/01/2018 10:17 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2578.08) - SGL4447Y - Claim Handler: Chong Boon Sen

Approved:2578.08:Please proceed to authorize repairs at \$2578.08. Excess is WAIVED.

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Friday, January 05, 2018 3:28 PM
To: sharon@sngahtee.com
Cc: darren@sngahtee.com; SUR
Subject: SGL 4447Y
Attachments: SGL 4447Y AUTODEX.pdf

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SGL 4447Y (excess \$ waived/-)**. Please note that **repair on Part by Part basis**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3694I
Vehicle Details	
Vehicle No.:	SGL4447Y
Vehicle to be Exported:	No
Intended De-registration Date:	29 Dec 2017
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	1NZX950879
Chassis No.:	MR053HY9305125773
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,717.00
Original Registration Date:	17 Aug 2009
First Registration Date:	17 Aug 2009
Transfer Count:	3
Actual ARF Paid:	\$12,717.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Aug 2019
PARF Rebate Amount:	\$6,994.00
Intended COE Rebate Details	

COE Expiry Date:	16 Aug 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$15,291.00
COE Rebate Amount:	\$2,495.00
Total Rebate Amount:	\$9,489.00

The information contained herein is correct as at 29 Dec 2017

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 36941

Vehicle Details

Vehicle No.: SGL4447Y
Vehicle to be Exported: No
Intended De-registration Date: 31 Dec 2017
Vehicle Make: TOYOTA
Vehicle Model: VIOS E AUTO
Primary Colour: White
Manufacturing Year: 2009
Engine No.: 1NZX950879
Chassis No.: MR053HY9305125773
Maximum Power Output: 80.0 kW (107 bhp)
Open Market Value: \$12,717.00
Original Registration Date: 17 Aug 2009
First Registration Date: 17 Aug 2009
Transfer Count: 3
Actual ARF Paid: \$12,717.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 16 Aug 2019
PARF Rebate Amount: \$6,994.00

Intended COE Rebate Details

COE Expiry Date: 16 Aug 2019
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$15,291.00
COE Rebate Amount: \$2,486.00
Total Rebate Amount: \$9,480.00

The information contained herein is correct as at 26 Dec 2017

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available afterwards.

ACCIDENT STATEMENT

Date Of Report	26/12/2017 09:06
Date Of Accident	23/12/2017 16:00
Exact Location Of Accident	WOODLANDS AVE 12 TOWARDS SLE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGL4447Y
Insured/Policyholder	
Name Of Registered Owner	PANNEERSELVAM S/O RAMASAMY
NRIC No	S6933694I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91458638
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	PANNEERSELVAM S/O RAMASAMY
NRIC No	S6933694I
Date Of Birth	19/09/1969
Occupation	OUTDOOR
Date Of Driving Pass	09/06/1990
Driving Experience	27 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91458638
Fax Number	
Contact Number	OFFICE-NOPHONE
E Mail Address	NOEMAIL

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/12/2017 09:06
Date Of Accident	23/12/2017 16:00
Exact Location Of Accident	WOODLANDS AVE 12 TOWARDS SLE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGL4447Y
Insured/Policyholder	
Name Of Registered Owner	PANNEERSELVAM S/O RAMASAMY
NRIC No	S6933694I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91458638
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	PANNEERSELVAM S/O RAMASAMY
NRIC No	S6933694I
Date Of Birth	19/09/1969
Occupation	OUTDOOR
Date Of Driving Pass	09/06/1990
Driving Experience	27 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91458638
Fax Number	
Contact Number	OFFICE-NOPHONE
EMail Address	NOEMAIL

Address	BLK 553 JURONG WEST ST 42 #11-301
Postcode	640553
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 23/12/2017 AT AROUND 1600HRS, I WAS TRAVELLING ALONG WOODLANDS AVE 12 TOWARDS SLE AND I WAS ON THE MIDDLE LANE. WHILE DRIVING SUDDENLY VEHICLE B BRAKE AND I APPLIED MY BRAKE BUT THE ROAD SURFACE IS WET AND MY VEHICLE SKID FORWARDS A BIT AND SLIGHTLY COLLIDED ONTO VEHICLE B REAR PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC6716T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	SEAH CHING KIONG
NRIC/Passport Number	S1363613C
Contact Number	82806367
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18
Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPCSN3079351600	Date of Loss:	23/12/2017
Vehicle Reg. No.:	SGL4447Y	Driveable?	
Driver Age/Info:	48 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	PANNEERSELVAM S/O RAMASAMY	Contact No:	+6591458638
Driver:	PANNEERSELVAM S/O RAMASAMY		
Make/Model:	TOYOTA VIOS, 1.5 (A)	Vehicle Reg. Date:	17/08/2009
Vehicle Colour:	WHITE	Chassis No:	MR053HY9305125773
Engine No:	1NZX950879		
Odometer:	5 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Description of Accident/Loss	ON 23/12/2017 AT AROUND 1600HRS, I WAS TRAVELLING ALONG WOODLANDS AVE 12 TOWARDS SLE AND I WAS ON THE MIDDLE LANE. WHILE DRIVING SUDDENLY VEHICLE B BRAKE AND I APPLIED MY BRAKE BUT THE ROAD SURFACE IS WET AND MY VEHICLE SKID FORWARDS A BIT AND SLIGHTLY COLLIDED ONTO VEHICLE B REAR PORTION.		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS	Amount
Parts	1,988.25
Miscellaneous Items	0.00
Labour	1,048.38
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,073.38
+ GST 7.00% (S\$)	212.56
Nett Amount (S\$)	3,249.19

This claim is handled by: **JANICE CHANG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Dec 2017)
 Parts: 143 TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/SGL4447Y/26/12/2017 17:53
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*BUMPER REINFORCEMENT /B4	0.00	0.00	115 *120.00 F
2	1	NA	*CONDENSER x nn	0.00	0.00	*350.00 F
3	1	NA	*FRONT BUMPER / de	0.00	0.00	*140.00 F
4	1	NA	*FRONT MANUFACT BADGE /nee	0.00	0.00	*25.00 F
5	1	NA	*FRONT NUMBER PLATE /me	0.00	0.00	*- F
6	1	NA	*FRT BUMPER ABSORBER /de	0.00	0.00	*45.00 F
7	1	NA	*FRT BUMPER CLAMP KIT /nee	0.00	0.00	10 *25.00 F
8	1	NA	*GRILLE /enn	0.00	0.00	75 *70.00 F
9	1	NA	*GRILLE GARNISH x nn	0.00	0.00	*45.00 F
10	1	NA	*INNER FRT PANEL CPL x nn	0.00	0.00	*280.00 F
11	1	NA	*L/F BUMPER BRACKET /nee	0.00	0.00	*25.00 F
12	1	NA	*L/F BUMPER STRUT /de	0.00	0.00	*70.00 F
13	1	NA	*L/UPP RADIATOR BRKT x nn	0.00	0.00	*50.00 F
14	1	NA	*LEFT HEADLAMP ASSY x nn	0.00	0.00	*130.00 F
15	1	NA	*LOWER FRONT GRILLE /de	0.00	0.00	5 *40.00 F
16	1	NA	*R/F BUMPER BRACKET /nee	0.00	0.00	*25.00 F
17	1	NA	*R/F BUMPER STRUT x nn	0.00	0.00	*70.00 F
18	1	NA	*R/UPP RADIATOR BRKT x nn	0.00	0.00	*50.00 F
19	1	NA	*RADIATOR GRILLE TRIM /ent	0.00	0.00	*35.00 F
20	1	NA	*RIGHT HEADLAMP ASSY x nn	0.00	0.00	*130.00 F
21	1	NA	*SPECIALIST AUDATEX FEE	0	0.00	*42.00 FS
22	1	NA	*SPECIALIST FRONT NUMBER PLATE	0	0.00	*35.00 FS
23	1	NA	*SUNDRY PARTS	0	0.00	*100.00 FS

F=Franchise part. S=SpcNett.

Sub Total (S\$)	1,902.00
+ Margin on L,N Items 5.00% (S\$)	86.25
Total Parts (S\$)	1,988.25

Sng Ah Tee Motor & Panel Service Pte Ltd/SGL4447Y/26/12/2017 17:53. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Total Paint Labour	New	450.80 533.60
2	Total Paint Materials	New	141.46 155.98
3	Total Panel/Mechanical Labour	New	271.42 358.80
Gross Labour Cost (\$\$)			1,048.38

Sng Ah Tee Motor & Panel Service Pte Ltd/SGL4447Y/26/12/2017 17:53. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18
Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

(SUPPLEMENTARY)

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPCSN3079351600	Date of Loss:	23/12/2017
Vehicle Reg. No.:	SGL4447Y	Driveable?	
Driver Age/Info:	48 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	PANNEERSELVAM S/O RAMASAMY	Contact No:	+6591458638
Driver:	PANNEERSELVAM S/O RAMASAMY		
Make/Model:	TOYOTA VIOS, 1.5 (A)	Vehicle Reg. Date:	17/08/2009
Vehicle Colour:	WHITE	Chassis No:	MR053HY9305125773
Engine No:	1NZX950879		
Odometer:	5 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Description of Accident/Loss	ON 23/12/2017 AT AROUND 1600HRS, I WAS TRAVELLING ALONG WOODLANDS AVE 12 TOWARDS SLE AND I WAS ON THE MIDDLE LANE. WHILE DRIVING SUDDENLY VEHICLE B BRAKE AND I APPLIED MY BRAKE BUT THE ROAD SURFACE IS WET AND MY VEHICLE SKID FORWARDS A BIT AND SLIGHTLY COLLIDED ONTO VEHICLE B REAR PORTION.		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS	Amount
Parts	36.75
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	36.75
+ GST 7.00% (S\$)	2.57
Nett Amount (S\$)	39.32
+ Previous Estimates (S\$)	3,249.19
Claim Total (S\$)	3,288.51

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 May 2018)

Parts: 143 TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/SGL4447Y/28/05/2018 13:09

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*L/RADIATOR BRACKET <i>bt</i>	0.00	0.00	*35.00 F	
						Sub Total (S\$)	35.00
						+ Margin on L,N Items 5.00% (S\$)	1.75
						Total Parts (S\$)	36.75

F=Franchise part.

Sng Ah Tee Motor & Panel Service Pte Ltd/SGL4447Y/28/05/2018 13:09, Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Aircon gas \$50 / nec.

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Sng Ah Tee Motor & Panel Service Pte Ltd/SGL4447Y/28/05/2018 13:09. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

**SNG AH TEE MOTOR &
 PANEL SERVICE PTE LTD
 3 PIONEER ROAD NORTH
 #01-18
 SINGAPORE 628457**

Claim Reference:
Assessment Number: DS000436
Version: SNGAHTEE/1
Date Calculated: 26/12/2017 09:47

Full Report - V1
Registration: SGL4447Y
Printed: 26/12/2017 17:47

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	DARREN SNG	Date of Incident:	23/12/2017
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	DMPCSN3079351600	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer: TOYOTA
 Model: Vios
 Sub Model: E
 Model Sheet Number: YF3 02
 Registration: SGL4447Y
 Registration Month:
 Registration Year:
 VIN Number:
 Odometer: Not Known
 Colour:
 Engine Number:
 Fuel Level: %

Model Specs

FROM 07/2009 AIR CONDITIONING
 SIDE MOULDINGS 1.5 LTR 80 KW
 EQUIPMENT "E" GRADE TWO COAT METALLIC
 PREPARE OFF VEHICLE

Taiping 97495749
Ex: Nil \$0
Revert 28/12/17 @ 1730.
lump sum.
Resurvey after repair.
6 days.

Vehicle Condition

Vehicle Status

Pre-Accident Condition:
 Steering:
 Brakes Pedal Travel:
 Place of Inspection:
 Pre-Accident Damage:

Severity of Impact:
 Vehicle Status on
 Inspection:
 Date of Inspection: 26/12/2017

Surv @ lkkauto.com.

Tyres Condition:
 Tread Depth LHF:
 Tread Depth LHR:
 Damage Areas:

Tread Depth RHF:
 Tread Depth RHR:
 Direction of Impact:

LKK Auto Consultants hence notify the Repairer of the following:



- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:
Assessment Number: DS000436
Version: SNGAHTEE/1
Date Calculated: 26/12/2017 09:47

Full Report - V1
Registration: SGL4447Y
Printed: 26/12/2017 17:47



Addresses

Cost Summary

Total Labour	\$892.40
Total Paint/Material	\$155.98
Total Parts	\$1,911.25
Total of Additional Costs	\$77.00
Excess:	TBA
Grand Total Exc GST:	\$3,036.63
7 % GST:	\$212.56
Grand Total Inc GST:	\$3,249.19

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR
Price/Dent = \$0.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
B040)	ADJUST HEADLAMPS	2.0	9.20
B140	RENEW FRONT PANEL CPL	9.0	41.40
NO NUMBER	RENEW LEFT FRONT BRACKET	1.0	4.60
NO NUMBER	RENEW RIGHT FRONT BRACKET	1.0	4.60
B010	R + R FRONT BUMPER	5.0	23.00
B020)	RENEW FRONT BUMPER (REMOVED)	4.0	18.40
NO NUMBER	R + R FRONT BUMPER DAMPER	1.0	4.60
B010)	R + R FRONT BUMPER REINFORCEMENT	2.0	9.20
B020)	RENEW FRONT BUMPER REINFORCEMENT	2.0	9.20
B040)	R + R LEFT HEADLAMP (BUMPER REMOVED)	1.0	4.60
B040)	DOES NOT INCLUDE: ADJUST HEADLAMP R + R RIGHT HEADLAMP (BUMPER REMOVED)	1.0	4.60
NO NUMBER	DOES NOT INCLUDE: ADJUST HEADLAMP RENEW FRONT NUMBER PLATE	1.0	4.60
M010	R + R RADIATOR/CONDENSER	14.0	64.40
NO NUMBER	R + R L/LOWER ENGINE PROTECTION	2.0	9.20
NO NUMBER	R + R R/LOWER ENGINE PROTECTION	2.0	9.20
0741	REPAIR L/F WING	10.0*	46.00
0742	REPAIR R/F WING	10.0*	46.00
1213	REPAIR L/R SIDE MEMBER	5.0*	23.00
1214	REPAIR R/R SIDEMEMBER	5.0*	23.00
LABOUR COST			
	Total Work Units	78.0	
	Corrosion Protection External Labour	0.0HRS	0.00

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:
 Assessment Number: DS000436
 Version: SNGAHTEE/1
 Date Calculated: 26/12/2017 09:47

Full Report - V1
 Registration: SGL4447Y
 Printed: 26/12/2017 17:47

Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	7.8HRS	\$358.80
Paint Labour	11.6HRS	\$533.60
Total Labour	19.4HRS	\$892.40

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$46.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
340	BUMPER REINFORCEMENTSURFACE PAINT	6.0	
1009	INNER FRT PANEL CPL SURFACE PAINT	6.0	
281	FRONT BUMPER REPAIR PAINT PLASTIC	16.0	
741	L/F WING REPAIR PAINTING >50%	16.0	
742	R/F WING REPAIR PAINTING >50%	16.0	
293	FRT TOWING EYE COVERSURFACE PAINT PLAST.	3.0	
1213	L/R SIDE MEMBER SURFACE PAINT	5.0	
1214	R/R SIDEMEMBER SURFACE PAINT	5.0	
1000	GRILLE GARNISH NEW PART PAINT	10.0*	
LABOUR COST - PAINT			
	TIME(PAINT)	83.0	
	Preparation Main Work Plastic	8.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	116.0	
	Total Paintwork Labour	11.6HRS	\$533.60
MATERIAL COST - PAINT			Cost Price
	Surface-/Blend Paint		\$32.87
	Surface Paint Plastic		\$0.73
	Repair Painting		\$29.24
	Repair Painting Plastic		\$51.84
	Material-Const Main Work Plastic		\$12.70
	Total Excluding Pearlescent Uplift		\$155.98
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$155.98

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Price Valid: 01/06/2015	Bet.	Price (\$)
257	1	FRONT NUMBER PLATE ✓	KNPL3		0%	mis ✓	0.00F
281	1	FRONT BUMPER ✓	52119 0D996		0%	de ✓	140.00*
317	1	L/F BUMPER BRACKET ✓	53165 0D030		0%	net ✓	25.00*
318	1	R/F BUMPER BRACKET ✓	53164 0D030		0%	net ✓	25.00*
319	1	L/F BUMPER STRUT ✓	52012 52020		0%	de ✓	70.00*
320	1	R/F BUMPER STRUT ✓	52011 52021		0%	net ✓	70.00*
333	1	FRT BUMPER ABSORBER ✓	52617 0D050		0%	de ✓	45.00*
340	1	BUMPER REINFORCEMENT ✓	52021 0D090		0%	bf ✓	120.00* 115
343	1	LOWER FRONT GRILLE ✓	53112 0D120		0%	de ✓	40.00* 35
350	1	FRT BUMPER CLAMP KIT ✓	SEE GUIDE NO. 0351		0%	net ✓	25.00* 10
410	1	GRILLE ✓	53111 0D901		0%	net ✓	70.00* 75
411	1	RADIATOR GRILLE TRIM ✓	53121 0D020		0%	net ✓	35.00*
431	1	FRONT MANUFACT BADGE ✓	75301 0D010		0%	net ✓	25.00*
561	1	LEFT HEADLAMP ASSY ✓	81150 0D310		0%	net ✓	130.00*

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:
Assessment Number: DS000436
Version: SNGAHTEE/1
Date Calculated: 26/12/2017 09:47

Full Report - V1
Registration: SGL4447Y
Printed: 26/12/2017 17:47

562 ✓	1	RIGHT HEADLAMP ASSY	81110 0D310	0%	<i>nn</i>	130.00*
1003	1	L/UPP RADIATOR BRKT	53222 0D010	0%	<i>bt</i>	50.00*
1004	1	R/UPP RADIATOR BRKT	53221 0D010	0%	<i>nn</i>	50.00*
1009	1	INNER FRT PANEL CPL	53201 0D130	0%	<i>nn</i>	280.00*
4465	1	CONDENSER	88460 0D130	0%	<i>nn</i>	350.00*
1000	1	GRILLE GARNISH	Renew	0%	<i>nn</i>	45.00*
f: OEM Parts			Saving			\$18.00
g: Original			Sub Total			\$1,725.00
h: Secondhand			Mark Up From Cost	(5 %)		\$86.25
p: Parallel			Sundry Parts	(Fixed)		\$100.00
x: Exchange			Total Parts			\$1,911.25

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description		Betterment	Price
AUDATEX FEE	SPECIALIST	0%	\$42.00
FRONT NUMBER PLATE	SPECIALIST		\$35.00
<i>ditto on lips</i>			
Total Extras			\$77.00

Final Calculation

Total Parts		\$1,911.25
Labour		
Total Panel/Mechanical	\$358.80	<i>271.40</i>
Total Paintwork	\$533.60	<i>450.80</i>
Total Labour		\$892.40
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$77.00	<i>127</i>
Total of Additional Costs		\$77.00
Total Paint/Material Costs		\$155.98
Grand Total Excludes GST		\$3,036.63
GST @ 7 %		\$212.56
Grand Total Includes GST		\$3,249.19

Assessment Notes

CHINA TAIPING
INSURANCE (S) PTE LTD
3 ANSON ROAD
#15-02 SPRINGLEAF
TOWER
079909

Claim Reference: 20170001956
Assessment Number: DS000436
Version: CHINATAI/2
Date Calculated: 05/01/2018 01:46

Full Report - V1
Registration: SGL4447Y
Printed: 05/01/2018 09:46

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Eddie Sim	Date of Incident:	23/12/2017
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	20170001956	Estimated Repair Time:	
Policy Number:	DMPCSN3079351600	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Vios
Sub Model:	BASE MODEL
Model Sheet Number:	YF3 01
Registration:	SGL4447Y
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FROM 07/2009	AIR CONDITIONING
SIDE MOULDINGS	1.5 LTR 80 KW
EQUIPMENT "E" GRADE	TWO COAT METALLIC
PREPARE OFF VEHICLE	

Vehicle Condition



Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	26/12/2017
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: 20170001956
Assessment Number: DS000436
Version: CHINATAI/2
Date Calculated: 05/01/2018 01:46

Full Report - V1
Registration: SGL4447Y
Printed: 05/01/2018 09:46



Addresses

Cost Summary

Total Labour	\$855.60
Total Paint/Material	\$155.98
Total Parts	\$1,139.50
Total of Additional Costs	\$77.00
Excess:	- \$0.00
Grand Total Exc GST:	\$2,228.08
7 % GST:	\$155.97
Grand Total Inc GST:	\$2,384.05

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR
 Price/Dent = \$0.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
B040)	ADJUST HEADLAMPS	2.0	9.20
NO NUMBER	R + R L/UPPER RADIATOR BRACKET	2.0	9.20
NO NUMBER	R + R R/UPPER RADIATOR BRACKET	2.0	9.20
NO NUMBER	RENEW LEFT FRONT BRACKET	1.0	4.60
NO NUMBER	RENEW RIGHT FRONT BRACKET	1.0	4.60
B010	R + R FRONT BUMPER	5.0	23.00
B020)	RENEW FRONT BUMPER (REMOVED)	4.0	18.40
NO NUMBER	R + R FRONT BUMPER DAMPER	1.0	4.60
B010)	R + R FRONT BUMPER REINFORCEMENT	2.0	9.20
B020)	RENEW FRONT BUMPER REINFORCEMENT	2.0	9.20
B040)	R + R LEFT HEADLAMP (BUMPER REMOVED)	1.0	4.60
B040)	DOES NOT INCLUDE: ADJUST HEADLAMP R + R RIGHT HEADLAMP (BUMPER REMOVED)	1.0	4.60
B040)	DOES NOT INCLUDE: ADJUST HEADLAMP		
NO NUMBER	R + R L/F BUMPER BRACKET	1.0	4.60
NO NUMBER	R + R R/F BUMPER BRACKET	1.0	4.60
NO NUMBER	R + R L/LOWER ENGINE PROTECTION	2.0	9.20
NO NUMBER	R + R R/LOWER ENGINE PROTECTION	2.0	9.20
0741	REPAIR L/F WING	10.0*	46.00
0742	REPAIR R/F WING	5.0*	23.00
1009	REPAIR INNER FRT PANEL CPL	15.0*	69.00
1213	REPAIR L/R SIDE MEMBER	5.0*	23.00
1214	REPAIR R/R SIDEMEMBER	5.0*	23.00
4465	CHECK CONDENSER		
LABOUR COST			
Total Work Units		70.0	

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: 20170001956
Assessment Number: DS000436
Version: CHINATAI/2
Date Calculated: 05/01/2018 01:46

Full Report - V1
Registration: SGL4447Y
Printed: 05/01/2018 09:46

Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	7.0HRS	\$322.00
Paint Labour	11.6HRS	\$533.60
Total Labour	18.6HRS	\$855.60

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$46.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
340	BUMPER REINFORCEMENTSURFACE PAINT	6.0	
281	FRONT BUMPER REPAIR PAINT PLASTIC	16.0	
741	L/F WING REPAIR PAINTING >50%	16.0	
742	R/F WING REPAIR PAINTING >50%	16.0	
293	FRT TOWING EYE COVERSURFACE PAINT PLAST.	3.0	
1009	INNER FRT PANEL CPL SURFACE PAINT	6.0	
1213	L/R SIDE MEMBER SURFACE PAINT	5.0	
1214	R/R SIDEMEMBER SURFACE PAINT	5.0	
1000	GRILLE GARNISH NEW PART PAINT	10.0*	
LABOUR COST - PAINT			
	TIME(PAINT)	83.0	
	Preparation Main Work Plastic	8.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	116.0	
	Total Paintwork Labour	11.6HRS	\$533.60
MATERIAL COST - PAINT			Cost Price
	Surface-/Blend Paint		\$32.87
	Surface Paint Plastic		\$0.73
	Repair Painting		\$29.24
	Repair Painting Plastic		\$51.84
	Material-Const Main Work Plastic		\$12.70
	Total Excluding Pearlescent Uplift		\$155.98
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$155.98

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
281	1	FRONT BUMPER	52119 0D996		0%	140.00*
317	1	L/F BUMPER BRACKET	53165 0D030		0%	25.00F
318	1	R/F BUMPER BRACKET	53164 0D030		0%	25.00*
319	1	L/F BUMPER STRUT	52012 52020		0%	70.00*
320	1	R/F BUMPER STRUT	52011 52021		0%	70.00*
333	1	FRT BUMPER ABSORBER	52617 0D050		0%	45.00*
340	1	BUMPER REINFORCEMENT	52021 0D090		0%	120.00*
341	1	L/BUMPER BRACKET	52536 0D060		0%	25.00*
342	1	R/BUMPER BRACKET	52535 0D060		0%	25.00*
343	1	LOWER FRONT GRILLE	53112 0D120		0%	40.00*
410	1	GRILLE	53111 0D901		0%	70.00*
411	1	RADIATOR GRILLE TRIM	53121 0D020		0%	35.00*
431	1	FRONT MANUFACT BADGE	75301 0D010		0%	25.00*

Price Valid: 01/06/2015

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: 20170001956
Assessment Number: DS000436
Version: CHINATAI/2
Date Calculated: 05/01/2018 01:46

Full Report - V1
Registration: SGL4447Y
Printed: 05/01/2018 09:46

561	1	LEFT HEADLAMP ASSY	81150 0D310	0%	130.00*
1003	1	L/UPP RADIATOR BRKT	53222 0D010	0%	50.00*
1004	1	R/UPP RADIATOR BRKT	53221 0D010	0%	50.00*
1000	1	GRILLE GARNISH	Renew	0%	45.00*
f: OEM Parts		Sub Total			\$990.00
g: Original		Mark Up From Cost		(5 %)	\$49.50
h: Secondhand		Sundry Parts		(Fixed)	\$100.00
p: Parallel		Total Parts			\$1,139.50
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Specialist	Betterment	Price
AUDATEX FEE	SPECIALIST	0%	\$42.00
FRONT NUMBER PLATE	SPECIALIST		\$35.00
Total Extras			\$77.00

Final Calculation

Total Parts	\$1,139.50
Labour	
Total Panel/Mechanical	\$322.00
Total Paintwork	\$533.60
Total Labour	\$855.60
Additional Costs	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$77.00
Total of Additional Costs	\$77.00
Total Paint/Material Costs	\$155.98
Grand Total Excludes GST	\$2,228.08
GST @ 7 %	\$155.97
Grand Total Includes GST	\$2,384.05

Assessment Notes

2,228.08
 ?+ 350.00

 2578.08

**SNG AH TEE MOTOR &
PANEL SERVICE PTE LTD
3 PIONEER ROAD NORTH
#01-18
SINGAPORE 628457**

Claim Reference:
Assessment Number: DS000436
Version: SNGAHTEE/2
Date Calculated: 09/01/2018 07:58

Full Report - V1
Registration: SGL4447Y
Printed: 28/05/2018 11:56

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	DARREN SNG	Date of Incident:	23/12/2017
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	DMPCSN3079351600	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Vios
Sub Model:	E
Model Sheet Number:	YF3 02
Registration:	SGL4447Y
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FROM 07/2009	AIR CONDITIONING
SIDE MOULDINGS	1.5 LTR 80 KW
EQUIPMENT "E" GRADE	TWO COAT METALLIC
PREPARE OFF VEHICLE	

Vehicle Condition



Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	26/12/2017
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:
Assessment Number: DS000436
Version: SNGAHTEE/2
Date Calculated: 09/01/2018 07:58

Full Report - V1
Registration: SGL4447Y
Printed: 28/05/2018 11:56



Addresses

Cost Summary

Total Labour	\$814.20
Total Paint/Material	\$155.98
Total Parts	\$766.75
Total of Additional Costs	\$127.00
Excess:	TBA
Grand Total Exc GST:	\$1,863.93
7 % GST:	\$130.48
Grand Total Inc GST:	\$1,994.41

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR
 Price/Dent = \$0.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
B130	REMOVE AND REFIT L/RADIATOR SHROUD	4.0	18.40
NO NUMBER	RENEW LEFT FRONT BRACKET	1.0	4.60
B010	R + R FRONT BUMPER	5.0	23.00
B020)	RENEW FRONT BUMPER (REMOVED)	4.0	18.40
NO NUMBER	R + R FRONT BUMPER DAMPER	1.0	4.60
B010)	R + R FRONT BUMPER REINFORCEMENT	2.0	9.20
B020)	RENEW FRONT BUMPER REINFORCEMENT	2.0	9.20
NO NUMBER	R + R R/F BUMPER BRACKET	1.0	4.60
NO NUMBER	RENEW FRONT NUMBER PLATE	1.0	4.60
B125	R + R CROSSMEMBER/LOCK CARRIER	2.0	9.20
M010	R + R RADIATOR/CONDENSER	14.0	64.40
NO NUMBER	R + R L/LOWER ENGINE PROTECTION	2.0	9.20
NO NUMBER	R + R R/LOWER ENGINE PROTECTION	2.0	9.20
0741	REPAIR L/F WING	10.0*	46.00
0742	REPAIR R/F WING	10.0*	46.00
1009	REPAIR INNER FRT PANEL CPL	10.0*	46.00
LABOUR COST			
	Total Work Units	71.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	7.1HRS	\$326.60
	Paint Labour	10.6HRS	\$487.60
	Total Labour	17.7HRS	\$814.20

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$46.00/HR

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Full Report - V1

Claim Reference:

Assessment Number: DS000436

Registration: SGL4447Y

Version: SNGAHTEE/2

Printed: 28/05/2018 11:56

Date Calculated: 09/01/2018 07:58

Guide Number Description	WU	Cost Price (\$)
- TWO COAT METALLIC		
- PREPARE OFF VEHICLE		
340 BUMPER REINFORCEMENTSURFACE PAINT	6.0	
281 FRONT BUMPER REPAIR PAINT PLASTIC	16.0	
741 L/F WING REPAIR PAINTING >50%	16.0	
742 R/F WING REPAIR PAINTING >50%	16.0	
293 FRT TOWING EYE COVERSURFACE PAINT PLAST.	3.0	
1009 INNER FRT PANEL CPL SURFACE PAINT	6.0	
1209 L/F S-MEMBER REINF SURFACE PAINT	5.0	
1210 R/F S-MEMBER REINF SURFACE PAINT	5.0	
LABOUR COST - PAINT		
TIME(PAINT)	73.0	
Preparation Main Work Plastic	8.0	
Preparation Main Work Metal	25.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	106.0	
Total Paintwork Labour	10.6HRS	\$487.60
MATERIAL COST - PAINT		Cost Price
Surface-/Blend Paint		\$32.87
Surface Paint Plastic		\$0.73
Repair Painting		\$29.24
Repair Painting Plastic		\$51.84
Material-Const Main Work Plastic		\$12.70
Total Excluding Pearlescent Uplift		\$155.98
Pearlescent Uplift @ 0.0%		\$0.00
Total Paint Material Cost		\$155.98

PARTS

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
257	1	FRONT NUMBER PLATE	KNPL3		0%	0.00F
281	1	FRONT BUMPER	52119 0D996		0%	140.00*
317	1	L/F BUMPER BRACKET	53165 0D030		0%	25.00*
318	1	R/F BUMPER BRACKET	53164 0D030		0%	25.00*
319	1	L/F BUMPER STRUT	52012 52020		0%	70.00*
333	1	FRT BUMPER ABSORBER	52617 0D050		0%	45.00*
340	1	BUMPER REINFORCEMENT	52021 0D090		0%	115.00*
343	1	LOWER FRONT GRILLE	53112 0D120		0%	35.00*
350	1	FRT BUMPER CLAMP KIT	SEE GUIDE NO. 0351		0%	10.00*
410	1	GRILLE	53111 0D901		0%	75.00*
411	1	RADIATOR GRILLE TRIM	53121 0D020		0%	35.00*
431	1	FRONT MANUFACT BADGE	75301 0D010		0%	25.00*
1015	1	L/RADIATOR BRACKET	53203 0D070		0%	35.00*
f: OEM Parts			Saving			\$18.00
g: Original			Sub Total			\$635.00
h: Secondhand			Mark Up From Cost	(5 %)		\$31.75
p: Parallel			Sundry Parts	(Fixed)		\$100.00
x: Exchange			Total Parts			\$766.75

THIS ASSESSMENT CONTAINS UNPRICED PARTS

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
-------------	------------	-------

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Full Report - V1

Registration: SGL4447Y

Printed: 28/05/2018 11:56

Claim Reference:

Assessment Number: DS000436

Version: SNGAHTEE/2

Date Calculated: 09/01/2018 07:58

AUDATEX FEE	SPECIALIST	0%	\$42.00
FRONT NUMBER	SPECIALIST		\$35.00
PLATE			
AIR CON GAS	SPECIALIST	0%	\$50.00
	Total Extras		\$127.00

Final Calculation

Total Parts			\$766.75
Labour			
Total Panel/Mechanical		\$326.60	
Total Paintwork		\$487.60	
Total Labour			\$814.20
Additional Costs			
Corr Prot Materials External		\$0.00	
Corr Prot Materials Internal		\$0.00	
Cost of Specialist		\$127.00	
Total of Additional Costs			\$127.00
Total Paint/Material Costs			\$155.98
Grand Total Excludes GST			\$1,863.93
GST @ 7 %			\$130.48
Grand Total Includes GST			\$1,994.41

Assessment Notes

finalised

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference: 20170001956
Assessment Number: DS000436
Version: LKKAUTOC/7
Date Calculated: 29/10/2018 04:54

Full Report - V1
Registration: SGL4447Y
Printed: 29/10/2018 12:55

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	23/12/2017
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	20170001956	Estimated Repair Time:	
Policy Number:	DMPCSN3079351600	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Vios
Sub Model:	BASE MODEL
Model Sheet Number:	YF3 01
Registration:	SGL4447Y
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FROM 07/2009	AIR CONDITIONING
SIDE MOULDINGS	1.5 LTR 80 KW
EQUIPMENT "E" GRADE	TWO COAT METALLIC
PREPARE OFF VEHICLE	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	26/12/2017
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference: 20170001956

Full Report - V1



Assessment Number: DS000436

Registration: SGL4447Y

Version: LKKAUTOC/7

Printed: 29/10/2018 12:55

Date Calculated: 29/10/2018 04:54



Addresses

Cost Summary

Total Labour	\$722.20
Total Paint/Material	\$141.46
Total Parts	\$766.75
Total of Additional Costs	\$127.00
Excess:	- \$0.00
Grand Total Exc GST:	\$1,757.41
7 % GST:	\$123.02
Grand Total Inc GST:	\$1,880.43

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR
Price/Dent = \$0.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
B130	REMOVE AND REFIT L/RADIATOR SHROUD	4.0	18.40
NO NUMBER	RENEW LEFT FRONT BRACKET	1.0	4.60
NO NUMBER	R + R FRONT BUMPER DAMPER	1.0	4.60
NO NUMBER	R + R R/F BUMPER BRACKET	1.0	4.60
NN	FRONT BUMPER R&R / NEW PARTS	16.0*	73.60
NN	BUMPER REINFORCEMENT R&R / NEW PARTS	6.0*	27.60
0741	REPAIR L/F WING	10.0*	46.00
0742	REPAIR R/F WING	10.0*	46.00
1009	REPAIR INNER FRT PANEL CPL	10.0*	46.00

LABOUR COST

Total Work Units	59.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	5.9HRS	\$271.40
Paint Labour	9.8HRS	\$450.80
Total Labour	15.7HRS	\$722.20

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$46.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
281	FRONT BUMPER REPAIR PAINT PLASTIC	16.0	
293	FRT TOWING EYE COVERSURFACE PAINT PLAST.	3.0*	
340	BUMPER REINFORCEMENTSURFACE PAINT	6.0*	
741	L/F WING SURFACE PAINT	16.0*	
742	R/F WING SURFACE PAINT	16.0*	
1009	INNER FRT PANEL CPL SURFACE PAINT	6.0*	

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference: 20170001956

Full Report - V1

Assessment Number: DS000436

Registration: SGL4447Y

Version: LKKAUTOC/7

Printed: 29/10/2018 12:55

Date Calculated: 29/10/2018 04:54

1209	L/F S-MEMBER REINF SURFACE PAINT	5.0*	
1210	R/F S-MEMBER REINF SURFACE PAINT	5.0*	
LABOUR COST - PAINT			
	TIME(PAINT)	73.0	
	Preparation Main Work Plastic	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	98.0	
	Total Paintwork Labour	9.8HRS	\$450.80
MATERIAL COST - PAINT			
	Surface-/Blend Paint		Cost Price \$51.29
	Surface Paint Plastic		\$0.73
	Repair Painting Plastic		\$51.84
	Material-Const Main Work Plastic		\$28.60
	Material-Const Comp. Work Metal		\$9.00
	Total Excluding Pearlescent Uplift		\$141.46
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$141.46

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
281	1	FRONT BUMPER	52119 0D996		0%	140.00*
317	1	L/F BUMPER BRACKET	53165 0D030		0%	25.00F
318	1	R/F BUMPER BRACKET	53164 0D030		0%	25.00*
319	1	L/F BUMPER STRUT	52012 52020		0%	70.00*
333	1	FRT BUMPER ABSORBER	52617 0D050		0%	45.00*
340	1	BUMPER REINFORCEMENT	52021 0D090		0%	115.00*
343	1	LOWER FRONT GRILLE	53112 0D120		0%	35.00*
350	1	FRT BUMPER CLAMP KIT	SEE GUIDE NO. 0351		0%	10.00*
410	1	GRILLE	53111 0D901		0%	75.00*
411	1	RADIATOR GRILLE TRIM	53121 0D020		0%	35.00*
431	1	FRONT MANUFACT BADGE	75301 0D010		0%	25.00*
1015	1	L/RADIATOR BRACKET	53203 0D070		0%	35.00*
f: OEM Parts		Sub Total				\$635.00
g: Original		Mark Up From Cost		(5 %)		\$31.75
h: Secondhand		Sundry Parts		(Fixed)		\$100.00
p: Parallel		Total Parts				\$766.75
x: Exchange						

Price Valid: 01/06/2015

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
AUDATEX FEE	SPECIALIST 0%	\$42.00
FRONT NUMBER PLATE	SPECIALIST	\$35.00
AIR CON GAS	SPECIALIST 0%	\$50.00
Total Extras		\$127.00

Final Calculation

Total Parts		\$766.75
Labour		
Total Panel/Mechanical	\$271.40	
Total Paintwork	\$450.80	
Total Labour		\$722.20

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference: 20170001956

Full Report - V1

Assessment Number: DS000436

Registration: SGL4447Y

Version: LKKAUTOC/7

Printed: 29/10/2018 12:55

Date Calculated: 29/10/2018 04:54

Additional Costs

Corr Prot Materials External

\$0.00

Corr Prot Materials Internal

\$0.00

Cost of Specialist

\$127.00

Total of Additional Costs

\$127.00

Total Paint/Material Costs

\$141.46

Grand Total Excludes GST

\$1,757.41

GST @ 7 %

\$123.02

Grand Total Includes GST

\$1,880.43

Assessment Notes

Janice Lee (LKKAuto)

From: Sharon Sng <sharon@sngahtee.com>
Sent: Monday, October 29, 2018 4:47 PM
To: Janice Lee (LKKAuto)
Subject: RE: SGL4447Y - FINALISE

Hi Jannice

confirm. thanks.

Best Regards

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



-Please note that all offer/acceptance is made without prejudice.-

From: Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>
Sent: Monday, October 29, 2018 2:13 PM
To: Sharon Sng <sharon@sngahtee.com>
Subject: RE: SGL4447Y - FINALISE

Dear Sharon,

Kindly confirm L/S \$1,400 @ 6 DAYS

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: jannicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Monday, May 28, 2018 2:17 PM
To: Sharon Sng <sharon@sngahtee.com>; SUR <sur@lkkauto.com>
Subject: FW: SGL4447Y - FINALISE

Dear Jannice,

FYNA:CS/CTI17024591/T1rd3

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sharon Sng [<mailto:sharon@sngahtee.com>]

Sent: Monday, 28 May 2018 1:38 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>

Subject: SGL4447Y - FINALISE

Best Regards

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Dec 2017 Sendback Est	26 Dec 2017 17:53 S\$3,036.63	27 Dec 2017 11:10 Edit Adj Rpt	S\$1,400.00 Edit Estimates	S\$1,400.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	28 May 2018 13:09	28 May 2018 13:09 S\$36.75	28 May 2018 13:09			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	PANNEERSELVAM S/O RAMASAMY, ID: S6933694I, Tel: +6591458638, Email: NOEMAIL								
Vehicle Reg. No.:	SGL4447Y	Date of Loss:	23/12/2017 16:00 - :59 [100 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM17D07291C01	Policy/Cover Note No.:	DMPCSN3079351600 (Comprehensive)						
		Excess:	S\$0.00						
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 08/01/2018]								
Driver/Custodian:	PANNEERSELVAM S/O RAMASAMY (48 / Male), NRIC: S6933694I, Tel: +6591458638								
Adj Asg. Remarks:	SURVEY REVERT								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
<ul style="list-style-type: none"> CHINA_TAIPING (05/01/2018): Alert - Adj Mandate Approved (S\$2578.08) - SGL4447Y - Claim Handler: Chong Boon ... CHINA_TAIPING (02/01/2018): Alert - Adj Mandate Approved (S\$2000.00) - SGL4447Y - Claim Handler: Chong Boon ... 									
ALL ASSOCIATED TASKS			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SGL4447Y (SNM17D07291C01)
OD
Dec 23 2017 4:00PM
[PANNEERSELVAM S/O RAMASAMY]
Sng Ah Tee Motor & Panel Service Pte Ltd

Upload Documents Upload Photos Compose New Letter			View	View in Browser <input type="checkbox"/>
Assessment Reports			1 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	26/12/17 15:24	Accident Statement	Load HTM	<input type="checkbox"/>
2	26/12/17 17:53	Repairer Estimates	Load HTM	<input type="checkbox"/>
3	28/05/18 13:09	Repairer Estimates Suppl. #1	Load HTM	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/12/17 15:08	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>
2	03/01/18 14:56	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	26/12/17 15:23	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	26/12/17 15:23	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	26/12/17 15:23	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	26/12/17 15:23	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	26/12/17 15:23	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	26/12/17 15:23	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	26/12/17 15:23	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	26/12/17 15:23	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	26/12/17 15:23	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	26/12/17 15:23	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	26/12/17 15:23	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	26/12/17 15:23	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13	26/12/17 15:23	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
14	26/12/17 15:24	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/01/18 11:44	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	02/01/18 11:44	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	02/01/18 11:44	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	02/01/18 11:44	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	02/01/18 11:44	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	02/01/18 11:44	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	02/01/18 11:44	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	02/01/18 11:44	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	02/01/18 11:44	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	02/01/18 11:44	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	02/01/18 11:44	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
12	02/01/18 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
13	02/01/18 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
14	02/01/18 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
15	02/01/18 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
16	02/01/18 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
17	02/01/18 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
18	02/01/18 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
19	02/01/18 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
20	02/01/18 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
21	02/01/18 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
22	02/01/18 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
23	02/01/18 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
24	02/01/18 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
25	02/01/18 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
26	02/01/18 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
27	02/01/18 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
28	02/01/18 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
29	02/01/18 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
30	02/01/18 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
31	02/01/18 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
32	02/01/18 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
33	02/01/18 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
34	02/01/18 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
35	02/01/18 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
36	02/01/18 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
37	02/01/18 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
38	02/01/18 11:44	General View	 Load JPG	<input checked="" type="checkbox"/>
39	30/10/18 14:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	30/10/18 14:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	30/10/18 14:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	30/10/18 14:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	30/10/18 14:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	30/10/18 14:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	26/12/17 15:24	Sketch Plan <small>[Linked Accident Report Documents]</small>	 Load TIF	
2	26/12/17 15:24	CI,IC,DL <small>[Linked Accident Report Documents]</small>	 Load TIF	
3	26/12/17 17:53	E-filed GIA report	 Load PDF	
4	26/12/17 17:53	IC,DL,CI	 Load TIF	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/01/18 09:41	Revised Estimate	 Load PDF	
2	05/01/18 10:09	Revised Estimate	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/12/17 15:08	SURVEYOR MARKING	 Load PDF	
2	29/12/17 15:08	AUDATEX	 Load PDF	
3	12/01/18 17:17	LETTER TO OI	 Load PDF	

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	26/12/17 15:24	Accident Statement	 Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	26/12/17 15:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	26/12/17 15:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	26/12/17 15:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	26/12/17 15:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	26/12/17 15:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	26/12/17 15:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	26/12/17 15:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	26/12/17 15:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	26/12/17 15:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	26/12/17 15:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	26/12/17 15:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	26/12/17 15:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	26/12/17 15:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	26/12/17 15:24	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	26/12/17 15:24	Sketch Plan	 Load TIF	
2	26/12/17 15:24	CI,IC,DL	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<p>Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT117024591/T1RD3E2

Date: 01/11/2018

REFERENCE

Insured/Claimant: PANNEERSELVAM S/O RAMASAMY Policy No: DMPCSN3079351600

Date of Loss: 23/12/2017

Nature of Claim: OD

Claim No: SNM17D07291C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGL4447Y	Engine No:	1NZX950879
Make & Model:	TOYOTA VIOS, 1.5 (A)	Chassis No:	MR053HY9305125773
Reg. Date:	17/08/2009 (Man. Year: 2009)	Odometer:	126526 km
Colour:	White		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	S\$20,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	2,025.00	893.75	1,131.25	55.86	
Miscellaneous Items	0.00	0.00	0.00		
Labour	1,048.38	863.66	184.72	17.62	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	3,073.38	1,757.41	1,315.97	42.82	
Approved Total (Overridden) (S\$)		1,400.00			
	(S\$)	3,073.38	1,400.00	1,673.38	54.45
	+ GST 7.00/7.00% (S\$)	215.13	98.00	117.13	54.45
	Nett Amount (S\$)	3,288.51	1,498.00	1,790.51	54.45

INSPECTION

Date of Assignment:	27/12/2017 Present Location:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Date Inspected:	28/12/2017 Inspected At:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18 Singapore 628457
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 01 Nov 2018)
Parts: 143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGL4447Y)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*AIR CON GAS	Necessary	-	*50.00 FS
2	1	NA	*BUMPER REINFORCEMENT (WCP)	Bent	120.00 F	*115.00 F
3	1	NA	*CONDENSER (WCP)	Not Necessary	350.00 F	*- F
4	1	NA	*FRONT BUMPER (WCP)	Deformed	140.00 F	*140.00 F
5	1	NA	*FRONT MANUFACT BADGE (WCP)	Necessary	25.00 F	*25.00 F
6	1	NA	*FRONT NUMBER PLATE (WCP)	Missing	0.00 F	*- F
7	1	NA	*FRT BUMPER ABSORBER (WCP)	Deformed	45.00 F	*45.00 F
8	1	NA	*FRT BUMPER CLAMP KIT (WCP)	Necessary	25.00 F	*10.00 F
9	1	NA	*GRILLE (WCP)	Cracked	70.00 F	*75.00 F
10	1	NA	*GRILLE GARNISH (WCP)	Not Necessary	45.00 F	*- F
11	1	NA	*INNER FRT PANEL CPL (WCP)	Not Necessary	280.00 F	*- F
12	1	NA	*L/F BUMPER BRACKET (WCP)	Necessary	25.00 F	*25.00 F
13	1	NA	*L/F BUMPER STRUT (WCP)	Deformed	70.00 F	*70.00 F
14	1	NA	*L/UPP RADIATOR BRKT (WCP)	Not Necessary	50.00 F	*- F
15	1	NA	*LEFT HEADLAMP ASSY (WCP)	Not Necessary	130.00 F	*- F
16	1	NA	*LOWER FRONT GRILLE (WCP)	Deformed	40.00 F	*35.00 F
17	1	NA	*R/F BUMPER BRACKET (WCP)	Necessary	25.00 F	*25.00 F
18	1	NA	*R/F BUMPER STRUT (WCP)	Not Necessary	70.00 F	*- F
19	1	NA	*R/UPP RADIATOR BRKT (WCP)	Not Necessary	50.00 F	*- F
20	1	NA	*RADIATOR GRILLE TRIM (WCP)	Cut	35.00 F	*35.00 F
21	1	NA	*RIGHT HEADLAMP ASSY (WCP)	Not Necessary	130.00 F	*- F
22	1	NA	*SPECIALIST AUDATEX FEE		42.00 FS	*42.00 FS
23	1	NA	*SPECIALIST FRONT NUMBER PLATE		35.00 FS	*35.00 FS
24	1	NA	*SUNDRY PARTS		100.00 FS	*100.00 FS
Supplementary #1						
25	1			Bent	35.00 F	*35.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*L/RADIATOR BRACKET (WCP)			
F=Franchise part. S=SpcNett.						
					Sub Total (S\$)	1,937.00 862.00
				+ Margin on L,N Items 5.00/5.00% (S\$)	88.00	31.75
					Total Parts (S\$)	2,025.00 893.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Total Paint Labour	New	533.60	450.80
2	Total Paint Materials	New	155.98	141.46
3	Total Panel/Mechanical Labour	New	358.80	271.40
			Gross Labour Cost (S\$)	1,048.38
				863.66

Report was unsubmitted during this print-out.

< END OF ESTIMATES >