


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB1336K
Ref. No : BUS/11/17/1035
Reg. Date : 01/01/1900
Vehicle Type : BUS -12M
Make : MAN
Model : MAN
Name of Driver : Yan Chee Kheen
Type of Accident : OTHERS
Date / Time of Accident : 30/11/2017 08:00:00 AM
Accident Reported Date / Time : 01/12/2017 12:00:00 AM
Surveyor is Required? : Yes
Survey by : AIG
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No :
Special Instruction to ARC, if any :
SMB1336K- LEFT REAR SIDE PORTION DAMAGED
SKJ6900E(TP) RIGHT REAR SIDE DAMAGED
Prepared Date : 01/12/2017 10:58:31 AM



Chassis No : Mileage : 0
Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 795.00	0.00
Total Spray Painting Charges	: 616.00	0.00
Total Material Charges	: 0.00	0.00
Other Charges	: 0.00	0.00
TOTAL	: 1,411.00	0.00
Lum Sum Total	: 1,400.00	0.00
No. of Repair Days	: 2.00	0.00 1 day
Prepared / Adjusted By	:	
Arc / Surveyor Sing Off Date	: 27/12/2017 10:47:14 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :
Remarks :

Prepared Date : 27/12/2017 10:46:10 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :
Quotation Date : Invoice Date :
Invoice Amount : Prepared Date :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sebastian.
27/12/2017.
- Lum Sum Repair.
- Photo After Paint.
90036121
sebastiangang@lkkauto.com.

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	795.00	0.00 530
Total Labour	795.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	616.00	0.00 450
Total Spray Painting & Panel Beating	616.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
TOTAL MATERIALS										
TOTAL MATERIALS(Discounted)								0.00	0.00	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									