

ASS. REC. BY:

REF: CS

MSG 17024595/RJvd302

Special Instructions:

Vehicle No:

Rasul

ASSIGNMENT (Office)

FROM (Person):

Lionel Tan

of

MSG

Date/Time:

26/12/17 @ 12:47pm

Estimated Cost:

Bill to:

OD / ~~TH~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJC 8939E

Insured:

SJB 2121S

at Workshop m/s

Uni Automotive

Tel:

6748 279S

of

No. 1 Kaki Bkt Ave 6 # 01-94 Autobay

Policy No:

A28642140@MY

Claim No:

542272

Sum Insured:

Excess:

Make of Veh:

(Client's Record):

D.O.A.

20/12/17

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:19am @ 28/12/17

Person Contacted:

Alvin

Vehicle ☒ IN / ☐ OUT

Date/Time

Action/Instruction (X) Estimate

SJC 8939E - X

SJB 2121S - CS/MSG 17001301 / RV bd 1

D.O.A: 18/01/2017

14/3/18

check with Rasul - OK

14/3/18

Submit LS \$4200 (Red 800, 167)

SINGAPORE

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJC 8939Eat Workshop m/s: UNI AUTOMOTIVEof: Auto Pay #01-94Insured: msuh / PMS

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJC 8939E Yr Regn: 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAZDA 6 cc 1999Colour: BLACK A/C: Insured / Std / NI / NASp. Reading: 243358 T. Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM66H16F180101282Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim orTyre Size: F: 215/50R17

R: _____

BS / DUN / EXNOVA GY FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 20/12/17 D.O.I. 28/12/17Survey held at UNI AUTOMOTIVEDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED

08

14/3/2018

Date/Time. File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time. File Return to?

2)

14/3 - typist

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Photos: _____

Others: _____

Add Fee: ☐ Site Insp. (\$ _____)☐ Interview (\$ _____)☐ Tech. Ins. (\$ _____)☐ Weekend (\$ _____)Report Format: merimenLump Sum / I.B.I. (\$ 4200/2)

PRS & PS

120
50
80
10
260

Survey Department Check List (Case Handler)

Reference No.: CS3 MSG 17024895 R1vd3

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: VERON 14/3/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/20

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rut	Adj Submitted	Ins Auth'd	Status
Main	21 Dec 2017		26 Dec 2017 12:47 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS	[Created by insurer]
Insured:	YEOW MEI ONG, ID: S1310602I
Main Claimant:	TOH LAY HEOK, ID: S1560856J
Vehicle Reg. No.:	SJC8939E
Claim Type:	TP / 542272
Vehicle Reg. No. (Insured):	SJB2121S
Repairer:	Uni Automotive Pte Ltd (HQ) NO. 1 KAKI BUKIT AVE 6 #01-94 AUTOBAY@KAKI BUKIT, 417883 Kaki Bukit - Tel: 67482795
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/12/2017]
Driver/Custodian (Insured):	SHEN RONG DESMOND (), NRIC: S9329858F, Tel: +6598412799

ASSOCIATED MAIL RECEIVED	View All Compose Case Mail
There are no mail for this case.	

ALL ASSOCIATED TASKS <input type="checkbox"/>	View All Search Tasks Create New Task Complete																				
<table style="width: 100%; border-collapse: collapse;"> <tr> <th style="text-align: left;">Due Date</th> <th style="text-align: left;">Priority</th> <th style="text-align: left;">Type</th> <th style="text-align: left;">Task Group</th> <th style="text-align: left;">Subject</th> <th style="text-align: left;">Handler</th> <th style="text-align: left;">Assigned By</th> <th style="text-align: left;">Completed On</th> <th style="text-align: left;">Created On</th> <th style="text-align: left;">Done?</th> </tr> <tr> <td colspan="10">No results.</td> </tr> </table>	Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.										
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?												
No results.																					

Enquire Vehicle & Owner Information (Vehicle No. SJB2121S As At 20 Dec 2017 / 22:10:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: U7-MISC-2017

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: S1310602I

Owner Name: YEOW MEI ONG

Registered Address Type: Private Residential (non-Condo Apt / non-House)

Registered Block/House
No.: 21

Registered Street Name: LIMAU GARDEN

Registered Unit No.: -

Registered Building Name: -

Registered Postal Code: 467880

Current Vehicle Details

Vehicle No.: SJB2121S

Make Description/Model: HONDA / HRV 1.5 LX CVT ABS D/AIRBAG 2WD

Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD



**SINGAPORE
POLICE FORCE**



T/20171221/2141

1 of 4

Police Station Of Origin:
Kampong Kembangan NPP
112 Lengkon Tiga #01-215 SINGAPORE
410112
Tel No: 1800-7489999

Report No. T/20171221/2141

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/12/2017 19:58		Vide Report No.:		Station Diary No.: 50	
Informant's Particulars					
Name of Informant: NG BOON HWA			Address: 40 LENGKONG TUJOH #07-14 SINGAPORE 417393		
ID Type / ID No.: NRIC NO / S1309320B			Contact No.: Home/Office: Mobile: 90696637		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 59	Date of Birth: 31/08/1958	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Odd job person			Driving Licence Information: Class: 3,4,5 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 20/12/2017 22:10	Type of Location: Straight Road
Location: Along Road 1 BEDOK NORTH ROAD heading towards New Upper Changi Rd. Opposite HDB Blk 44 Chai Chee Street				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SJB2121S	Car	HONDA	HRV	Grey	Slightly Damaged	0
SJC8939E	Car	MAZDA	Mazda 6	Brown	Slightly Damaged	1

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SJC8939E		2017-V0081176- VDP-R006	03/03/2017	02/03/2018

Bueg



SINGAPORE POLICE FORCE



T/20171221/2141

Police Station Of Origin:
Kampong Kembangan NPP
112 Lengkok Tiga #01-215 SINGAPORE
410112
Tel No: 1800-7489999

2 of 4

Report No. T/20171221/2141

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	Shen Rong, Desmond	ID No.	S9329858F
Related Vehicle	SJB2121S (Car)	Contact No.	98412799
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	NG BOON HWA	ID No.	S1309320B
Related Vehicle	SJC8939E (Car)	Contact No.	90696637
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3,4,5 Date of Expiry: NIL
Date Treatment	21/12/2017	Date Discharge	21/12/2017
No. of Days granted Medical Leave	07	Degree of Injury	NIL
Passenger			
Name	Toh Lay Heok	ID No.	S1560856J
Related Vehicle	SJC8939E (Car)	Contact No.	94889710
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	21/12/2017	Date Discharge	21/12/2017
No. of Days granted Medical Leave	03	Degree of Injury	NIL

Brief Details.

On 20.12.2017 at about 2210hrs, I was queuing up behind several vehicles in front of me at the first lane of Bedok North Road before the turning right junction of Bedok North Ave 1, opposite HDB Blk 44 Chai Chee Street. The weather is clear and road surface is dry. The traffic condition is moderately heavy. I have a front left passenger who is my wife seated next to me.

My vehicle was stationary and not moving when suddenly, another car; SJB2121S driven by the under-mentioned person collided onto the rear portion of my vehicle. From the impact of the collision, my vehicle did not collide to any vehicle in front of me.

Bill C. C.



**SINGAPORE
POLICE FORCE**



T/20171221/2141

Police Station Of Origin:
Kampong Kembangan NPP
112 Lengkong Tiga #01-215 SINGAPORE
410112
Tel No: 1800-7489999



3 of 4

Report No. T/20171221/2141

CONTINUATION OF REPORT

After the collision, both driver step out of our vehicle to make a check at our damages. After exchanging our particulars and contact numbers, I continue driving my vehicle. There is no eye-witness who had came forward to me. I do not have any In-Car CCTV camera.

On 21.12.2017 at around 1500hrs, I and my said wife proceeded to Changi Hospital as both of us complain of pain due to the impact of the accident. I suffered pain on my neck and lower back area. My wife complain of pain on her neck area. We were treated as out patient that day. I was given 7 days of MC from 21/12/2017 to 27/12/2017. My wife was given 3 days of MC from 21/12/2017 to 23/12/2017.

	SINGAPORE POLICE FORCE	
<hr/>		
SIGNATURE		

Butler q.



**SINGAPORE
POLICE FORCE**



T/20171221/2141

4 of 4

Police Station Of Origin:
Kampong Kembangan NPP
112 Lengkong Tiga #01-215 SINGAPORE
410112
Tel No: 1800-7489999

Report No. T/20171221/2141

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sr Staff Sgt RASHIDI BIN ABU BAKAR

Signature Of Informant:

BW Lee G.

Signature Of Interpreter:

Not applicable

Date/Time:

21/12/2017 19:58

Officer In Charge Of Case:

TP / AEIT /

SSI 2 SITIMARSITA BINTE BOHARI

Contact No.: 65476219

Classification Of Case:

Authentication Stamp
NP158



**SINGAPORE
POLICE FORCE**

CL APPRAISER PTE LTD

47A Edgefield Plains #13-16 Singapore 828714
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

INVOICE

Toh Lay Heok
C/o: Uni Automotive Pte Ltd
No.1 Kaki Bukit Ave 6 #01-94
AutoBay, Singapore 417883

Invoice No: CL/18035

Ref No: UA/12/1703/TP

Date: 15 January 2018

DESCRIPTION

AMOUNT

OUR SERVICE FEE CHARGES:

- SURVEY INSPECTION FOR VEHICLE NO. SJC 8939 E
- RESURVEY INSPECTION
- DIGITAL PHOTOGRAPHS SERVICES
(INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)
- TRANSPORTATION

GRAND TOTAL S\$ 584.00

E & O. E

All cheque payment should be "Crossed" and made payable to "CL APPRAISER PTE LTD"

We shall be grateful if you could forward our payment at your early convenience.



CL Appraiser Pte Ltd

LCL APPRAISER PTE LTD

47A Edgefield Plains #13-16 Singapore 828714
Hp: 90688689 Email: clappraiser@yahoo.com
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Toh Lay Heok Date : 15 January 2018
C/o: Uni Automotive Pte Ltd Our ref : UA/12/1703/TP
No.1 Kaki Bukit Ave 6 #01-94
AutoBay, Singapore 417883

Accident Date : 20 December 2017 Type of Survey : Third Party
Inspection Date : 28 December 2017
Repairer Name : Uni Automotive Pte Ltd
No.1 Kaki Bukit Ave 6 #01-94
AutoBay, Singapore 417883

PARTICULARS OF VEHICLE

Registration No : SJC 8939 E Year / Capacity : 2008 / 1999 cc
Make / Model : Mazda 6 Colour : Purple
Chassis No : JM6GH10F180101282 Mileage : 243358
Engine No : LF20216417

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Good Year	215/50 R17	5 mm	Sport
Front Offside	: Good Year	215/50 R17	5 mm	Sport
Rear Nearside	: Good Year	215/50 R17	5 mm	Sport
Rear Offside	: Good Year	215/50 R17	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 84 copies

REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis
and we have not given authorization and instruction to the repairer to proceed with the repair

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a Lump Sum of \$ 5,000.00 on a contractual basis.

Under normal circumstances, the repair period would be about 6 (Six) working days.

SCL APPRAISER PTE LTD

Vehicle Registration No: SJC 8939 E

Our Ref No: UA/12/1703/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Rear boot lid	Damage	\$ 1,094.10	\$ 1,094.10
1	Rear boot inner trim	Damage	\$ 212.60	\$ 212.60 XNN
1	Rear boot lamp	Damage	\$ 336.00	\$ 336.00 XNN
1	Rear boot lock	Damage	\$ 174.50	\$ 174.50
1	Rear boot lock catch	Necessary	\$ 58.00	\$ 58.00 XSC
1	Rear boot logo	Necessary	\$ 53.70	\$ 53.70
1	Rear boot weatherstrip	Necessary	\$ 140.60	\$ 140.60
1	Rear boot "MAZDA" emblem	Necessary	\$ 26.40	\$ 26.40
1	Rear boot "6" emblem	Necessary	\$ 19.10	\$ 19.10
2	Rear taillamps	Damage	\$ 1,654.00	\$ 1,654.00 827
1	Rear end panel	Damage	\$ 365.40	\$ 365.40 XR
1	Rear end panel inner garnish	Damage	\$ 223.40	\$ 223.40
1	Rear bumper	Damage	\$ 1,078.00	\$ 1,078.00
2	Rear bumper reflectors	Damage	\$ 124.00	\$ 124.00
1	Rear bumper reinforcement	Damage	\$ 423.10	\$ 423.10
2	Rear bumper side retainers	Damage	\$ 89.60	\$ 89.60
1	Rear number plate lamp (1 set)	Damage	\$ 258.30	\$ 258.30
			\$ 6,330.80	\$ 6,330.80
			Less 20%	\$ 1,266.16 \$ 1,266.16
Total Cost - List Items			\$ 5,064.64	\$ 5,064.64

SPECIAL NETT ITEMS

1	Rear boot inner trim clip (1 set)	Necessary	\$ 35.00	\$ 35.00 25
1	Rear bumper clip (1 set)	Necessary	\$ 50.00	\$ 50.00 30
1	Rear reverse sensor (1 set)	Damage	\$ 350.00	\$ 280.00 200
1	Rear number plate with holder	Damage	\$ 50.00	\$ 50.00 40
Total Cost - Special Nett items			\$ 485.00	\$ 415.00

Total cost of parts

\$ 5,549.64 \$ 5,479.64

ECL APPRAISER PTE LTD

Vehicle Registration No: SJC 8939 E

Our Ref No: UA/12/1703/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 5,549.64	\$ 5,479.64

LABOUR

1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00	\$ 50.00 30
2	To remove and refit inner garnishes, inner trim to assist repair.	\$ 150.00	\$ 120.00 60
3	To remove and refit rear reverse sensor.	\$ 120.00	\$ 80.00 50
4	To transfer boot lid mechanism and wiring assembly to assist repair.	\$ 80.00	\$ 60.00
5	To apply undercoating on repaired and replaced panel.	\$ 150.00	\$ 90.00 60
6	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,080.00	\$ 750.00 600
7	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,000.00	\$ 660.00 500

GRAND TOTAL

\$ 8,209.64	\$ 7,289.64
-------------	-------------

C L APPRAISER PTE LTD

Vehicle Registration No: SJC 8939 E

Our Ref No: UA/12/1703/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of : \$ 5,000.00

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K. H.
Automotive Appraiser

5 days

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Dec 2017		26 Dec 2017 12:47 Edit Adj Rpt	S\$4,200.00 Edit Estimates	S\$4,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by Insurer]
Insured:	YEOW MEI ONG, ID: S1310602I	
Main Claimant:	TOH LAY HEOK, ID: S1560856J	
Vehicle Reg. No.:	SJC8939E	Date of Loss: 20/12/2017 22:00 - :59
Claim Type:	TP / 542272	Policy/Cover Note No.: A28642140QMY (Comprehensive) Coverage: 13/11/2017 - 12/11/2018
Vehicle Reg. No. (Insured):	SJB2121S	Policy No. (Claimant):
		Excess: S\$3,500.00
Repairer:	Uni Automotive Pte Ltd (HQ) NO. 1 KAKI BUKIT AVE 6 #01-94 AUTOBAY@KAKI BUKIT, 417883 Kaki Bukit - Tel: 67482795	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 27/12/2017]	
Driver/Custodian (Insured):	SHEN RONG DESMOND (), NRIC: S9329858F, Tel: +6598412799	

ASSOCIATED MAIL RECEIVED	View All Compose Case Mail
<ul style="list-style-type: none"> MSIG_LTPP (06/02/2018): PAPER SURVEY REQUEST - SJC8939E 	

ALL ASSOCIATED TASKS <input type="checkbox"/>										View All Search Tasks Create New Task Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	
No results.										

Claim Documents

***SJC8939E (542272)**

[SJB2121S]

TP

TOH LAY HEOK

Dec 20 2017 10:00PM

[YEOW MEI ONG]

Uni Automotive Pte Ltd

Upload Documents
Upload Photos
Compose New Letter
View View in Browser v

Assessment Reports			1 per page v	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/12/17 12:37	Accident Statement <small>From: SC - Reg. No: SJB2121S, Claimant: YEOW MEI ONG</small>	Load HTM	

Photos/Images			3 per page v	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>
2	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>
3	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>
4	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>
5	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>
6	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>
7	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>
8	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>
9	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>
10	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>
11	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>
12	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>
13	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>
14	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>
15	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>
16	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>
17	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>
18	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>
19	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>
20	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>
21	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>
22	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>
23	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>
24	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>
25	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>
26	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>
27	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>
28	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>
29	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>
30	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>
31	14/03/18 10:57	General View	Load JPG	<input checked="" type="checkbox"/>

32	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
33	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
34	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
35	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
36	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
37	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
38	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
39	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
40	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
41	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
42	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
43	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
44	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
45	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
46	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
47	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
48	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
49	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
50	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
51	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
52	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
53	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
54	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
55	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
56	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
57	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
58	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
59	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
60	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
61	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
62	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
63	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
64	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
65	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
66	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
67	14/03/18 10:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/12/17 12:51	SJC8939E E-FILE, POLICE REPORT, DL, IC & CERT OF INS	1	Load PDF
2	26/12/17 12:51	PRI from Vision Law	1	Load PDF
3	26/12/17 13:04	Survey Disagree on SJE	1	Load PDF
4	06/02/18 14:21	TPD SJC8939E - REPAIR TAX INVOICE	1	Load PDF
5	06/02/18 14:21	TPD SJC8939E - SURVEY REPORT & TAX INVOICE	1	Load PDF
6	06/02/18 14:21	TPD SJC8939E - LTA SEARCH & POLICE REPORT	1	Load PDF
7	06/02/18 14:21	TPD SJC8939E - COLOUR PHOTO	1	Load PDF
8	06/02/18 14:21	TPD SJC8939E - COLOUR PHOTO	1	Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
---------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^
v

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17024595/R1VD3E2

Date: 16/03/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28642140QMY

Claimant Vehicle No : SJC8939E

Insured Vehicle No : SJB2121S

Date of Loss: 20/12/2017

Nature of Claim: TP

Claim No: 542272

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJC8939E

Make & Model: MAZDA 6, 2.0 SDN V (A)

Engine No: LF20216417

Reg. Date: 03/03/2008 (Man. Year: 2008)

Chassis No: JM6GH10F180101282

Colour: Black

Odometer: 243358 km

Engine Capacity: 1999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/50 R17

Rear Tyre Size: 215/50 R17

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,549.64	3,920.44	1,629.20	29.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,660.00	1,360.00	1,300.00	48.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,209.64	5,280.44	2,929.20	35.68
Approved Total (Overridden) (S\$)		4,200.00		
Nett Amount (S\$)	8,209.64	4,200.00	4,009.64	48.84

INSPECTION

Date of Assignment: 26/12/2017

Date Inspected: 28/12/2017 Inspected At:

 Uni Automotive Pte Ltd (HQ)
 NO. 1 KAKI BUKIT AVE 6 #01-94
 AUTOBAY@KAKI BUKIT
 Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Mar 2018)
Parts: 143 MAZDA 6 2.0 SDN V (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJC8939E)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Damaged	1,094.10 FL	*1,094.10 FL
2	1		*REAR BOOT INNER TRIM	Not Necessary	212.60 FL	*- FL
3	1		*REAR BOOT LAMP	Not Necessary	336.00 FL	*- FL
4	1		*REAR BOOT LOCK	Damaged	174.50 FL	*174.50 FL
5	1		*REAR BOOT LOCK CATCH	Serviceable	58.00 FL	*- FL
6	1		*REAR BOOT LOGO	Necessary	53.70 FL	*53.70 FL
7	1		*REAR BOOT WEATHERSTRIP	Necessary	140.60 FL	*140.60 FL
8	1		*REAR BOOT MAZDA EMBLEM	Necessary	26.40 FL	*26.40 FL
9	1		*REAR BOOT 6 EMBLEM	Necessary	19.10 FL	*19.10 FL
10	1		*REAR TAILLAMPS	O/S Damaged	1,654.00 FL	*827.00 FL
11	1		*REAR END PANEL	Repair	365.40 FL	*- FL
12	1		*REAR END PANEL INNER GARNISH	Damaged	223.40 FL	*223.40 FL
13	1		*REAR BUMPER	Damaged	1,078.00 FL	*1,078.00 FL
14	2		*REAR BUMPER REFLECTORS	Damaged	124.00 FL	*124.00 FL
15	1		*REAR BUMPER REINFORCEMENT	Damaged	423.10 FL	*423.10 FL
16	2		*REAR BUMPER SIDE RETAINERS	Damaged	89.60 FL	*89.60 FL
17	1		*SET REAR NUMBER PLATE LAMP	Damaged	258.30 FL	*258.30 FL
18	1		*SET REAR BOOT INNER TRIM CLIP	Necessary	35.00 FS	*25.00 FS
19	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
20	1		*SET REAR REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
21	1		*REAR NUMBER PLATE WITH HOLDER	Damaged	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,815.80	4,826.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,266.16	906.36
Total Parts (\$\$)	5,549.64	3,920.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REFIT, REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES, INNER TRIM TO ASSIST REPAIR	New	150.00	60.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	120.00	50.00
4	TO TRANSFER BOOT LID MECHANISM AND WIRING ASSEMBLY TO ASSIST REPAIR	New	80.00	60.00
5	TO APPLY UNDERCOATING REPAIRED AND REPLACED PANEL	New	150.00	60.00
6	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,080.00	600.00
7	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	500.00
Gross Labour Cost (S\$)			2,660.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >