

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA17024604/KEA3Q2

Date: 24/09/2020

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd	Policy No:	P1405878
Claimant		
Vehicle No : SGE5875A	Insured Vehicle No :	XB7761X
Date of Loss: 23/12/2017	Nature of Claim:	TP
	Claim No:	C0464414

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGE5875A	Engine No:	L15A24801848
Make & Model:	HONDA CITY, 1.5 (M)	Chassis No:	MRHGD85906P010078
Reg. Date:	21/03/2006 (Man. Year: 2006)	Odometer:	230077 km
Colour:	Metallic Blue		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R15	Rear Tyre Size:	195/50 R15
Front Left Side:	Toyo 7 mm	Rear Left Side:	Toyo 7 mm
Front Right Side:	Toyo 7 mm	Rear Right Side:	Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,212.00	3,152.00	60.00	1.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,030.00	1,780.00	250.00	12.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,242.00	4,932.00	310.00	5.91
Approved Total (Overridden) (S\$)		3,950.00		
(S\$)	5,242.00	3,950.00	1,292.00	24.65
+ GST 7.00/7.00% (S\$)	366.94	276.50	90.44	24.65
Nett Amount (S\$)	5,608.94	4,226.50	1,382.44	24.65
+ Loss of Use (6.0 x S\$50.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		4,534.50		
Global Sum Settlement (S\$)		4,500.00		

INSPECTION

Date of Assignment:	27/12/2017	
Date Inspected:	27/12/2017 Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun)
		Blk 1019 #01-374/382, Yishun
		Industrial Park A
		Singapore 768761
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Jun 2019)
Parts:	143	HONDA CITY 1.5 (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGE5875A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (CONSISTENT)	Buckled	446.30 FL	*446.30 FL
2	1		*FRONT BUMPER LH SIDE RETAINER (CONSISTENT)	Distorted	13.20 FL	*13.20 FL
3	6		*FRONT BUMPER CLIPS (CONSISTENT)	Necessary	22.20 FL	*22.20 FL
4	1		*LH HEAD LAMP (CONSISTENT)	Mtg Cracked	448.50 FL	*448.50 FL
5	1		*FRONT LH FENDER (CONSISTENT)	Bent	332.40 FL	*332.40 FL
6	1		*FRONT LH FENDER LAMP (CONSISTENT)	Cracked	30.10 FL	*30.10 FL
7	1		*FRONT LH FENDER INNER SHIELD (CONSISTENT)	Distorted	75.10 FL	*75.10 FL
8	6		*FRONT LH FENDER INNER SHIELD CLIPS (CONSISTENT)	Necessary	22.20 FL	*22.20 FL
9	1		*FRONT LH FENDER TRIANGLE GLASS MOULDING (CONSISTENT)	Necessary	34.10 FL	*34.10 FL
10	1		*FRONT LH MUDFLAP (CONSISTENT)	Dented / Cut	26.50 FL	*26.50 FL
11	1		*FRONT LH DOOR (CONSISTENT)	Bent	669.10 FL	*669.10 FL
12	1		*FRONT LH DOOR PROTECTOR (CONSISTENT)	Dented	62.20 FL	*62.20 FL
13	1		*FRONT LH DOOR STICKER (CONSISTENT)	Necessary	50.10 FL	*50.10 FL
14	1		*FRONT LH DOOR OUTER HANDLE (CONSISTENT)	Dented	87.80 FL	*87.80 FL
15	1		*FRONT LH SIDE MIRROR (CONSISTENT)	Broken	285.80 FL	*285.80 FL
16	1		*REAR LH DOOR PROTECTOR (CONSISTENT)	Necessary	57.50 FL	*57.50 FL
17	1		*FRONT SHOCK ABSORBER (CONSISTENT)	Bent	262.30 FL	*262.30 FL
18	1		*FRONT LH KNUCKLE ARM (CONSISTENT)	Bent	222.30 FL	*222.30 FL
19	1		*FRONT LH WHEEL BEARING (CONSISTENT)	Necessary	119.20 FL	*119.20 FL
20	1		*FRONT LH SPORT RIM (CONSISTENT)	Dented	380.00 FS	*320.00 FS
21	1		*FRONT LH LOWER ARM (CONSISTENT)	Distorted	273.10 FL	*273.10 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,920.00	3,860.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	708.00	708.00
Total Parts (\$\$)	3,212.00	3,152.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING REMOVE AND REFIX FRONT BUMPER ASSY ,FRONT LH FENDER ,HEAD LAMP ,FRONT LH DOOR AND ATTACHMENT .TO KNOCK AND REPAIR FRONT LH WINDSCREEN PILLAR REAR LH DOOR AND REALIGN THE SAME	New	680.00	550.00
2	REMOVE AND REFIX FRONT LH DOOR GLASS	New	60.00	60.00
3	REMOVE AND REFIX FRONT LH FENDER GLASS	New	40.00	40.00
4	PUTTY AND RESPRAY ON FRONT BUMPER ,FRONT LH FENDER ,WINDSCREEN PILLAR ,FRONT AND REAR LH DOOR ,PROTECTORS ,SIDE MIRROR AND ALL AFFECTED AREA	New	950.00	850.00
5	REMOVE AND REFIX FRONT LH UNDER CARRIAGE	New	180.00	160.00
6	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	60.00	60.00
7	RUSTPROOFING	New	60.00	60.00
Gross Labour Cost (\$\$)			2,030.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >