

ASS. REC. BY:

REF: CS/CTI17024612/And3 wk

Special Instruction:

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of CTI

Date/Time: 27/12/17 @ 3:39pm

Estimated Cost:

Bill to:

☒ OD ☐ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐ CS

To Inspect Vehicle No: SJE9136M

Insured:

at Workshop m/s: Auto N Cars Services

Tel: 6555 2909

of Blk 1, Kaki Bkt Ave 6 # 01-04

Policy No: DMHCSN1712371700

Claim No: 20170001929

Sum Insured:

Excess: \$1,000.00

Make of Veh:

D.O.A. 23/12/17

(Client's Record)

CA / ☒ REV ☐ REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9:26am @ 28/12/17

Person Contacted: er/a

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SJE9136M-CS/CTI17009816/Sq302</u> <u>D.O.A: 15/05/2017</u>
<u>29/12/17 @</u>	<u>5:30pm revert to Chong Boon Sen via Meimen (pending car 1)</u>
<u>07/01/18 @</u>	<u>11:52am 2nd revert to Chong Boon Sen via Meimen (repaired car 1 is agreed cost \$700)</u>
<u>16/01/2018 @ 15:52</u>	<u>-authorise by Alfred Toh (need sign undertaking letter)</u>
<u>16/1/2018 @ 4:42pm</u>	<u>email to darla authorise repair and sign under taking</u>
<u>23/5/18 @ 5:53pm</u>	<u>confirmed with Darla LS \$3700, 12 days.</u>


ASSIGNMENT

13/05/08

From: _____ Date: **28/12/17**
 Estimated Cost: _____
☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: **SJE 9136 M**
 at Workshop in: **Auto N Cars**
 of: **31k 1, kaki Bkt Ave 6 # 01-04 Autobay**
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: **\$1,000.00**
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Est. or Market Value: _____
 IDAO Accident Rpt. _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: **12** days Res: Yes or No
 Lum Surp: _____ % 3 Val: Yes or No
 CA / ☒ EV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Van No: **SJE 9136 M** Yr Regn: **2008 May**
 Type: ☒ M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: **Honda Civic** cc: **1799**
 Colour: **Black** A/C: Insured / Std / Nil / NA
 Sp. Reading: _____ T. Radio: Insured / Std / Nil / NA
 Eng. No: _____
 C.No: **JHMF0163085213575**
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / ☒ R / STD A/Rim or
 Tyre Size: F: **225/45R17**
 R: **225/45R17**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Newton**

Front: _____ Rear: _____
 R. Bal: **06** mm R. Bal: **06** mm
 L. Bal: **06** mm L. Bal: **06** mm
 D.O.A. _____ D.O.L: **28/12/17**
 Survey held at: **Auto N Cars**
 Des. of Damages: ☒ Frt / Rear ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date Time Action Instruction

DD Ching
(Red & 70% 89.04, 85%)

MV: 15.6K
PV: 11.6K
Net: 4K

RECEIVED 25 MAY 2018

Date Time File Path to



Prel. Report

15/5 11:55 AM
 Date Time File Path to



Final Report

2

Days Of Repair: **12**

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Fuel: _____

Phone: _____

Other: _____

Total: _____

Total: **220**

Add Fee:



Site Insp: \$



Interview: \$



Tech Insp: \$



Witness: \$

Report Format: **MER-00**Lump Sum: **3700**

220

220

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI17024612/Aqd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 28-12-2017



Code : CTI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SJE 9136M
Policy No.	DMHCSN1712371700	Coverage (\$)	0.00
Claim No.	20170001929	Excess (\$)	1,000.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	28/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	23/12/2017	Inspection Date	28/12/2017
Survey held at	AUTO N CARS SERVICES PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883.		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Dec 2017 Sendback Est	27 Dec 2017 14:54 \$24,689.04	27 Dec 2017 15:39 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	BLUE STAR LIMOUSINE MANAGEMENT PTE LTD , Co. Reg. No.: 201539827C		
Vehicle Reg. No.:	SJE9136M	Date of Loss:	23/12/2017 00:00 - :59
Claim Type:	OD / 20170001929	Policy/Cover Note No.:	DMHCSN1712371700 (Comprehensive)
		Excess:	S\$1,000.00
Repairer:	Auto N Cars Services Pte Ltd (HQ) Blk 1 Kaki Bukit Ave 6 #01-04, AutoBay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 6555 2909		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/01/2018]		
Driver/Custodian:	ALAN TAN JUN RONG (25 / Male), NRIC: S92407791, Tel: +6591258660		
Adj Asg. Remarks:	survey revert		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Darla Balingit <darla@autoncars.com.sg>
Sent: Wednesday, 23 May 2018 5:55 PM
To: Shiau Chan (LKKAuto)
Subject: Re: CHINA TAIPING OUTSTANDING CASES

Dear Shiau,

COR \$3,700 and 12 days confirmed.

Kindly make an offer in merimen

Thank you!

On Wed, May 23, 2018 at 5:25 PM, Shiau Chan (LKKAuto) <siewsc@lkkauto.com> wrote:

Dear Darla,

SJE 9136M – offer Lump Sum \$3,700.00 before excess \$1,000.00 & GST and 14 repair days.

Kindly confirm.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Darla Balingit [mailto:darla@autoncars.com.sg]
Sent: Monday, 7 May 2018 5:38 PM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Ai Phing (LKKAuto) <aiphing@lkkauto.com>; Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Shu Pei (LKKAuto) <shupe@lkkauto.com>
Subject: Fwd: CHINA TAIPING OUTSTANDING CASES

TO: CHINA TAIPING INSURANCE (S) PTE LTD

CLAIM NO: 20170001929

WITHOUT PREJUDICE

LETTER OF UNDERTAKING

FOR THE REPAIR OF VEHICLE NO. SJE9136M

We, the undersigned, confirm that we will undertake to repair the vehicle bearing Registration No SJE9136M to its pre-accident condition, and to the satisfaction of its owner, at a total cost not exceeding LUMP SUM 3,700.00 (before excess) subject to no breach of Terms & Condition of the POLICY, and to the legal requirement of the local Land Transport Authority (LTA).

There should be **no further supplementary** to the repair cost.

The repair job should not be exceeding days to complete the entire repair.

Date

16/3/2016

Date



Workshop Stamp/ Signature

Adrian

Witness by surveyor

View Sent Message

This mail is associated with :

SJE9136M (SNM17D07250C01)

OD

Dec 23 2017 12:00AM

[BLUE STAR LIMOUSINE MANAGEMENT PTE LTD]
Auto N Cars Services Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 16/01/2018 16:48 PM
To boonsen.chong@sg.cntaiping.com; claimsdept@sg.cntaiping.com
Subject SJE9136M (SNM17D07250C01)

Dear Boon Sen,

As per tele conversation with Adrian and you earlier.

The 4 tyres of the said vehicle is in good working condition and the tyres confirm to LTA's regulation.

No illegal modification was observed in the course of survey by the vehicle.

Hope that the above clarifies matter.

Regards,
Denise Tay.

LKK Auto Consultants Pte Ltd

DOCUMENTS SUMMARY

There are no documents.

As spoken, the 4 tyres of the said vehicle is in good working condition and the tyres conform to LTA's regulation.

No illegal modification was observed in the course of surveying the vehicle.

Hope that the above clarifies matters.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 16 January 2018 4:42 PM
To: 'Darla Balingit'
Cc: SUR
Subject: SJE 9136 OD CHINA TAIPING
Attachments: UNDERTAKING LETTER.pdf

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SJE 9136M (Excess \$1000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Please sign the undertaking letter and email/fax back.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SJE9136M (SNM17D07250C01)

OO

Dec 23 2017 12:00AM

[BLUE STAR LIMOUSINE MANAGEMENT PTE LTD]

Auto N Cars Services Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 16/01/2018 15:52 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$3700.00) - SJE9136M - Claim Handler: Chong Boon Sen

Approved:3700.00;PROCEED TO AUTHORIZE REPAIRS NO MORE THAN \$3,700.00 BEFORE Excess of \$1,000.00 UPON RECEIPT OF LTR OF UNDERTAKING from M/s Auto N Cars.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 15 Jan 2018

Preliminary Advice

Vehicle No	: SJE9136M	Accident Date	: 23/12/2017
Make	: HONDA CIVIC	Policy No.	: DMHCSN1712371700
Assignment Date	: 27/12/2017	Excess	: S\$1,000.00
Date of Inspection	: 26/12/2017	Est. Duration of Repair	: 14.00
Inspection At	: AUTO N CARS SERVICES PTE LTD (HQ) BLK 1 KAKI BUKIT AVE 6 #01-04, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,689.04
Revised Amount	:S\$	19,253.27
Check Items (Estimated)	:S\$	2,061.15
Total	:S\$	21,314.42

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	15,600.00
COE / PARF Rebate	:S\$	11,598.00
Salvage Value	:S\$	
Margin for Repair	:S\$	4,002.00

Steering	:	Inorder
Brake	:	Inorder
Tyre Rear	:	6/6 mm
Tyre Front	:	6/6 mm

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : REPAIRER WILL TO UNDERTAKE REPAIR COST AT LUMP SUM \$3,700/-
WE HAVE NOT AUTHORISE REPAIR.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 02 Jan 2018

Preliminary Advice

Vehicle No	: SJE9136M	Accident Date	: 23/12/2017
Make	: HONDA CIVIC	Policy No.	: DMHCSN1712371700
Assignment Date	: 27/12/2017	Excess	: S\$1,000.00
Date of Inspection	: 28/12/2017	Est. Duration of Repair	: 14.00
Inspection At	: AUTO N CARS SERVICES PTE LTD (HQ) BLK 1 KAKI BUKIT AVE 6 #01-04, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front, o/s & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,689.04
Revised Amount	:S\$	19,253.27
Check Items (Estimated)	:S\$	2,061.15
Total	:S\$	21,314.42

Lump Sum Repair	:S\$	3,700.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	15,600.00
COE / PARF Rebate	:S\$	11,598.00
Salvage Value	:S\$	
Margin for Repair	:S\$	4,002.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : REPAIRER WILLING TO UNDERTAKE REPAIR COST AT LUMP SUM \$3,700.00. WE HAVE NOT AUTHORISE REPAIR.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 29 Dec 2017

Preliminary Advice

Vehicle No	: SJE9136M	Accident Date	: 23/12/2017
Make	: HONDA CIVIC	Policy No.	: DMHCSN1712371700
Assignment Date	: 27/12/2017	Excess	: S\$1,000.00
Date of Inspection	: 28/12/2017	Est. Duration of Repair	: 14.00
Inspection At	: AUTO N CARS SERVICES PTE LTD (HQ) BLK 1 KAKI BUKIT AVE 6 #01-04, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front, o/s & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,689.04
Revised Amount	:S\$	19,253.27
Check Items (Estimated)	:S\$	2,061.15
Total	:S\$	21,314.42

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	15,600.00
COE / PARF Rebate	:S\$	11,598.00
Salvage Value	:S\$	
Margin for Repair	:S\$	4,002.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : PENDING REPAIR COST FROM REPAIRER.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 29 Dec 2017

Preliminary Advice

Vehicle No	: SJE9136M	Accident Date	: 23/12/2017
Make	: HONDA CIVIC	Policy No.	: DMHCSN1712371700
Assignment Date	: 27/12/2017	Excess	: S\$1,000.00
Date of Inspection	: 28/12/2017	Est. Duration of Repair	: 14.00
Inspection At	: AUTO N CARS SERVICES PTE LTD (HQ) BLK 1 KAKI BUKIT AVE 6 #01-04, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front, o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,689.04
Revised Amount	:S\$	19,253.27
Check Items (Estimated)	:S\$	2,061.15
Total	:S\$	21,314.42

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	15,600.00
COE / PARF Rebate	:S\$	11,598.00
Salvage Value	:S\$	
Margin for Repair	:S\$	4,002.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : PENDING REPAIR COST FROM REPAIRER.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	9827C
Vehicle Details	
Vehicle No.:	SJE9136M
Vehicle to be Exported:	Yes
Intended De-registration Date:	28 Dec 2017
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.8L A
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	R18A13034144
Chassis No.:	JHMFD16308S215575
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$21,787.00
Original Registration Date:	13 May 2008
First Registration Date:	13 May 2008
Transfer Count:	1
Actual ARF Paid:	\$21,787.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 May 2018
PARF Rebate Amount:	\$10,893.00
Intended COE Rebate Details	
COE Expiry Date:	12 May 2018
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$19,001.00
COE Rebate Amount:	\$705.00
Total Rebate Amount:	\$11,598.00

The information contained herein is correct as at 28 Dec 2017


A-Assurance
Assurance in Insurance
Car Insurance Expiring?
 We get you the cheapest insurance renewal

[Click to get quote](#)

 Username / Email Add
 password
[Connect](#) [Sign Up New Account](#)
[Forgot Password](#)

Civic Price Range Depreciation 2008 Vehicle Type

Used Car Comparison

--- Comparing 3 Vehicles ---

Honda Civic 1.8A VTi-S

Honda Civic 1.8A VTi-S

Honda Civic 1.8A VTi-S



NO IMAGE AV

Use search bar above to be to compare

[Clear All](#)
[Add all to Shortlist](#)
[Back to search result](#)
[Add to Shortlist](#)
[Add to Shortlist](#)
[Add to Shortlist](#)

CAR DETAILS

Price	\$16,800	\$15,000	\$15,800
Instalment	\$2,969	\$3,526	\$2,239
Registration Date	26-May-2008	14-Apr-2008	10-Jun-2008
Manufactured	2008	2008	2008
Mileage	-	170,000 km	-
Transmission	Auto	Auto	Auto
Engine Cap	1,799 cc	1,799 cc	1,799 cc
Road Tax	\$978 /yr	\$978 /yr	\$978 /yr
Power	103.0 kW (138 bhp)	103.0 kW (138 bhp)	103.0 kW (138 bhp)
Curb Weight	1,219 kg	1,219 kg	1,219 kg
Features	Responsive And Reliable 1.8L I-Vtec Engine Mated With Smooth Auto Transmission With Paddleshift, Multi Fuction Steering, ABS, Dual Airbags.	ABS, SRS Airbags.	Powerful 1.8L 16 Valves I-VTEC, 5 Speed Automatic Transmission, Paddle Shift, Dual Airbags, Retractable Side Mirrors.
Accessories	Leather, Original Built In Audio Player With 6 Disc Changer, Reverse Sensors, Solar Film, Fog Lamp, Sports Rims.	Leather Seats, Reverse Sensors, Front And Back Video Recorder.	Original Leather Seats And Sports Rims, Built In Player, Solar Films And Reverse Sensors, Fog Lamps.
Description	Well Maintained, Excellent Choice. Only \$1,680 Down Payment. Up To 90% Flexible Loan. We Provide Lowest Interest Rate In Town. Flexible Loan And High Trade In Are Available. Package With Unrivaled Warranty Complete With Certificate And Test Report. Check Out Our New Offer Now. Meet Our Friendly Consultant For An Non Obligation Advise.	2 Careful Owners, Price Negotiable! High PARF Rebate, Regularly Servicing At Agent, Price Negotiable. Please Call To Arrange A Test Drive.	Best For Short Term Usage, Fujitsu Exhaust With LTA Certificate, Well Maintained And Timed Serviced By Careful Owner, No Repairs Needed, Trade In Welcomed, In House Loan Provided, High Loan With Minimum Drive Away Welcomed! Cal For Viewing/Test Drive Now.
COE	\$19,001	\$19,001	\$15,889
OMV	\$21,092	\$22,417	\$21,609
ARF	\$21,092	\$22,417	\$21,609
Depreciation	-	-	-
No. of Owners	3	2	2
Type of Vehicle	Sedan	Sedan	Sedan
Category	PARF Car	PARF Car, Direct Owner Sale	PARF Car
Availability	Available	Available	Available

SELLER INFORMATION

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/12/2017 11:56
Date Of Accident	23/12/2017 00:30
Exact Location Of Accident	BARTLEY FLYOVER
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJE9136M
Insured/Policyholder	
Name Of Registered Owner	BLUE STAR LIMOUSINE MANAGEMENT PTE LTD
Co Reg No	201539827C
Email Address	VICTOR.ONG@BLUESTARCONCIERGE.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-98229566

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC 1.8L A

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE HIRE
------------------	--------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMHCSN1712371700
Cover Note Number	

Driver

Name of Driver	ALAN TAN JUN RONG
NRIC No	S9240779I
Date Of Birth	03/11/1992
Occupation	OUTDOOR
Date Of Driving Pass	05/07/2012
Driving Experience	5 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91258660
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 902 TAMPINES AVENUE 4 #04-210
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

THE ACCIDENT HAPPENED ON 23/12/2017 AT 12:30AM ALONG BARTLEY FLYOVER. IT WAS RAINING AND ROAD WAS WET WHEN SUDDENLY I LOST CONTROL AND MY VEHICLE SKIDDED CAUSED TO HIT THE FLYOVER RETAINING WALL AND MY VEHICLE SPIN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms) which may be sited outside of Singapore, for one or more of the above Purposes.



Ala L

23/12/17 10:39


Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

A: 53E913GM



Sketch Plan #2 Pg. 1

Describe Circumstances of the Accident

THE ACCIDENT HAPPENED ON 23/12/17 AT 12:30AM ALONG
 BARKLEY FLYOVER. IT WAS RAINING AND ROAD WAS WET WHEN
 AFORENMENT I LOST CONTROL AND MY VEHICLE SKIPPED CAUSED
 TO HIT THE PULVER RETAINING WALL AND SPIN.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &
 Time

Ala Lu 23/12/17 10:39
 Driver's Signature (if driver is not the policyholder) / Date
 & Time

[Signature]
 Witnessed by Reporting Centre
 Personnel

27/12/2017

**AUTO N CARS SERVICES
PTE LTD
AUTOBAY @ BLK 1 #01-04
KAKI BUKIT AVE 6
417883**

**Claim Reference: 078612170D
Assessment Number: ANC00185
Version: AUTONCAR/1
Date Calculated: 27/12/2017 06:23**

**Full Report - V1
Registration: SJE9136M
Printed: 27/12/2017 14:23**

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Darla Belingit	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	OTHER	Repairs Authorised:	TBA
Claim Reference:	078612170D	Estimated Repair Time:	
Policy Number:	DMHCSN1712371700	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	Civic
Sub Model:	GLI
Model Sheet Number:	H34 24
Registration:	SJE9136M
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

4-DOOR	AUTO AIR CON
FOG LAMPS	CTR REAR ARMREST
1.7 LTR 96KW VTEC	FRONT SPOILER

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	27/12/2017
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

AUTO N CARS SERVICES PTE LTD

Claim Reference: 078612170D
Assessment Number: ANC00185
Version: AUTONCAR/1
Date Calculated: 27/12/2017 06:23

Full Report - V1
Registration: SJE9136M
Printed: 27/12/2017 14:23

73111-S5A	(FRONT COWL PANEL TRIM REMOVED) WINDSCREEN R + R INCLUDES: SCREEN WIPER ARM, COWL COVER AND MOULDINGS REMOVE AND REFIT	37.0	170.20
68500-S5A)	RENEW BOOTLID (REMOVED) INCLUDES: R + R INNER TAILLAMPS, NUMBER PLATE, BADGE, NUMBER PLATE LAMPS AND LOCK	9.0	41.40
NO NUMBER	R + R ATTACHED PARTS OF THE R/SIDE PANEL AND REAR END PANEL INCLUDES: R + R BUMPER, TAILLAMPS, BOOTLID, BOOTLID SEAL, REAR SEAT, REAR SCREEN, SEAT BELT AND ALL TRIMS IN THE REPAIR SECTION	72.0	331.20
NO NUMBER	RENEW CPL RIGHT SIDE SECTION AND REAR PANEL	135.0	621.00
77101-S5A	RENEW INSTRUMENT PANEL INCLUDES: R + R INSTRUMENT PANEL AND CONVERT ALL ATTACHED PARTS	41.0	188.60
77960-S5A)	R + R AIRBAG CONTROL UNIT (CENTRE CONSOLE REMOVED)	4.0	18.40
77930-S5A)	R + R L/AIRBAG SENSOR	2.0	9.20
83401-S5A	R + R CENTRE CONSOLE INSERT	3.0	13.80
81450-S5A	R + R LEFT FRONT SEAT BELT INCLUDES: R + R B-PILLAR TRIM	4.0	18.40
81450-S5A	R + R RIGHT FRONT SEAT BELT INCLUDES: R + R B-PILLAR TRIM	4.0	18.40
19010-PLC)	R + R RADIATOR CPL WITH ATTACHED PARTS	6.0	27.60
06770-S5A	R + R DRIVER AIRBAG MODULE	3.0	13.80
44305-S5A)	DETACH + REFIT L/- AND R/DRIVE SHAFT	2.0	9.20
42751-S5A)	FIT AND BALANCE RIGHT FRONT TYRE (WHEEL REMOVED)	5.0	23.00
51210-S5A)	R + R RIGHT FRONT STEERING KNUCKLE INCLUDES: R + R WHEEL, BRAKE DISC, WHEEL HUB AND WHEEL BEARING	12.0	55.20
51601-S5A)	R + R CPL RIGHT FRONT SPRING STRUT (RIGHT STEERING KNUCKLE REMOVED)	2.0	9.20
51605-S5A)	DISS/ASS R/F SUSPENSION STRUT	4.0	18.40
51350-S5A)	R + R R/F LWR CONTR ARM (WHEEL REMOVED)	4.0	18.40
A0112-000	R + R RIGHT REAR WHEEL	2.0	9.20
42751-S5A)	FIT AND BALANCE RIGHT REAR TYRE (WHEEL REMOVED)	5.0	23.00
52370-S5A)	DETACH + REFIT RIGHT REAR CONTROL ARM	2.0	9.20
52370-S5A)	R + R R/RR CONTROL ARM	5.0	23.00
52610-S5A)	DETACH + REFIT RIGHT REAR SHOCK ABSORBER	3.0	13.80
80315-S5A)	R + R CONDENSER/COMPRESSOR PIPE	1.0	4.60
80110-S5A)	R + R AIR CONDITIONING CONDENSER	3.0	13.80
38615-PLC	R + R AIR CONDITIONING SHROUD	6.0	27.60
80311-S5A)	R + R COMPRESSOR-/EVAPORATOR HOSE	2.0	9.20
NO NUMBER	REFILL + VENT AIR CONDITIONING	10.0	46.00
C0104-000	ADJUST FRONT TOE AFTER CHECK	5.0	23.00

AUTO N CARS SERVICES PTE LTD

Claim Reference: 078612170D

Assessment Number: ANC00185

Version: AUTONCAR/1

Date Calculated: 27/12/2017 06:23

Full Report - V1

Registration: SJE9136M

Printed: 27/12/2017 14:23

4481	1	COND/COMPRESSOR HOSE	80315S5A013	0%	175.00*	✓
4465	1	CONDENSER	80110S6DG01	0%	610.00*	✓
7445	1	DRIVER AIRBAG	06770S5AG80ZA	0%	1,220.00*	✓
7405	1	DRIVER AIRBAG SYS	REPLACE	0%	105.00*	✓
1000	1	F/SUPPORT TOP GARN	Renew	0%	120.00*	✓
4489	1	FAN SHROUD	38615PLCN01	0%	120.00*	✓
283	1	FRONT BUMPER	04711S5A407ZZ	0%	280.00*	✓
391	1	FRONT BUMPER SPOILER	08F01S5A601	0%	110.00*	✓
1009	1	FRONT PANEL CPL	60400S5HT00ZZ	0%	418.00*	✓
1416	2	FRONT SCREEN SPACER	91568SX0003	0%	17.44U	✓
1000	1	FRT BONNET INSULATOR	Renew	0%	115.00*	✓
340	1	FRT BUMPER SUPPORT	71130S5A000ZZ	0%	198.00*	✓
1000	1	FRT GRILLE CHROME	Renew	0%	105.00*	✓
1415	6	FRT SCREEN CLIP SET	91520S5A003	0%	10.02U	✓
1419	4	FRT SCREEN CLIP SET	91521S5A003	0%	9.64U	✓
1418	2	FRT SCREEN CLIP SET	91519S5A003	0%	4.82U	✓
1413	1	FRT SCREEN MNTG KIT	USE SINGLE PARTS	0%	0.00	✓
1417	2	FRT SCREEN SUPPORTS	91577S84A01	0%	4.68U	✓
410	1	GRILLE	71121S5A003ZE	0%	95.00*	✓
431	1	GRILLE BADGE	75700S5A000	0%	50.00*	✓
4331	1	INSTRUMENT PANEL	77101S5A010ZC	0%	980.00*	✓
7437	1	L/AIRBAG SENSOR	77940S5AN91	0%	320.00*	✓
475	1	L/BONNET HINGE	60170S5A000ZZ	0%	58.00*	✓
561	1	L/F HEADLAMP CPL	33101S5AQ01	0%	750.00*	✓
317	1	L/F OUT BUMPER BRKT	71198S5A000	0%	25.00*	✓
4661	1	L/F SEAT BELT	81850S5AG01ZD	0%	510.00*	✓
1000	1	L/HEADLAMP BALLAST	Renew	0%	450.00*	✓
2619	1	L/R BUMPER BRACKET	71555S5A000	0%	60.00*	✓
4325	1	PASSENGER AIRBAG	06780S5AE20ZA	0%	1,350.00*	✓
476	1	R/BONNET HINGE	60120S5A000ZZ	0%	58.00*	✓
1394	1	R/COWL PANEL GRILLE	74210S5A000	0%	70.00*	✓
638	1	R/F FOG LAMP	33901S5B003	0%	168.00*	✓
562	1	R/F HEADLAMP CPL	33151S5AQ01	0%	750.00*	✓
318	1	R/F OUT BUMPER BRKT	71193S5A000	0%	25.00*	✓
4662	1	R/F SEAT BELT	81450S5AG01ZD	0%	510.00*	✓
7088	1	R/F SHOCK ABSORBER	51605S5A305	0%	110.00*	✓
7082	1	R/F STEERING KNUCKLE	51210S5AJ00	0%	318.00*	✓
7228	1	R/F TYRE	185/70 R 14 .. H	0%	280.00*	✓
7202	1	R/F WHEEL	42700S6DE01	0%	580.00*	✓
7118	1	R/F WHEEL BEARING	44300S5A008	0%	125.00*	✓
742	1	R/F WING	60211S5A000ZZ	0%	298.00*	✓
1000	1	R/F WING TOP GARNISH	Renew	0%	130.00*	✓
652	1	R/FOG LAMP COVER	33905S6A003	0%	48.00*	✓
1000	1	R/HEADLAMP BALLAST	Renew	0%	450.00*	✓
7054	1	R/LOWER CONTROL ARM	51350S6AA00	0%	150.00*	✓
2620	1	R/R BUMPER BRACKET	71505S5A000	0%	60.00*	✓
9386	1	R/R CONTROL ARM	52370S5AA14	0%	180.00*	✓
3284	1	R/R INNER LAMP CPL	34151S5AA01	0%	310.00*	✓
3282	1	R/R OUTER LAMP CPL	33501S5HT01	0%	350.00*	✓
9566	1	R/R TYRE	185/70 R 14 .. H	0%	280.00*	✓
9552	1	R/R WHEEL	42700S6DE01	0%	580.00*	✓
3482	1	R/R WING	04636S5A405ZZ	0%	680.00*	✓
1000	1	R/R WING AIRVENT	Renew	0%	38.00*	✓
842	1	R/WHEELHOUSE SHELL	74101S5A000	0%	115.00*	✓

AUTO N CARS SERVICES PTE LTD

Claim Reference: 078612170D
Assessment Number: ANC00185
Version: AUTONCAR/1
Date Calculated: 27/12/2017 06:23

Full Report - V1
Registration: SJE9136M
Printed: 27/12/2017 14:23

Assessment Notes

Adrian Ling
L/s 28/12/17
Excess: \$1000
Not Authorised.
1st Pays.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



Co. Reg: 200922097K

AutoBay @ Kaki Bukit Bldg 1 Kaki Bukit Ave 6 #01-04 (S) 417883
• Tel: (65) 6555 2909 • Fax: (65) 6841 7181 • Web: www.autoncars.com.sg

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMHCSN1712371700	Date of Loss:	23/12/2017
Vehicle Reg. No.:	SJE9136M	Driveable?	
Driver Age/Info:	25 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	BLUE STAR LIMOUSINE MANAGEMENT PTE LTD		
Driver:	ALAN TAN JUN RONG		
Make/Model:	HONDA CIVIC, 1.8 L (A)	Vehicle Reg. Date:	13/05/2008
Vehicle Colour:	BLACK	Chassis No:	JHMFD16308S215575
Engine No:	R18A13034144		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Description of Accident/Loss	THE ACCIDENT HAPPENED ON 23/12/2017 AT 12:30AM ALONG BARTLEY FLYOVER. IT WAS RAINING AND ROAD WAS WET WHEN SUDDENLY I LOST CONTROL AND MY VEHICLE SKIDDED CAUSED TO HIT THE FLYOVER RETAINING WALL AND MY VEHICLE SPIN		
Present Location:	AUTO N CARS SERVICES PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	21,306.44
Miscellaneous Items	0.00
Labour	3,382.60
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	24,689.04
+ GST 7.00% (S\$)	1,728.23
Nett Amount (S\$)	26,417.27

This claim is handled by: **DARLA MARIE ENRIQUEZ BALINGIT**

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Dec 2017)
Parts:	143	HONDA CIVIC 1.8 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Auto N Cars Services Pte Ltd/SJE9136M/27/12/2017 14:54	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*AIRBAG CONTROL UNIT	0.00	0	ACT *580.00 F
2	1		*BONNET	0.00	0	DIS *380.00 F
3	1		*BONNET LOCK	0.00	0	PRG *65.00 F
4	1		*BOOTLID	0.00	0	*650.00 F XR
5	1		*COMPR/EVAP TUBE	0.00	0	*158.00 F XHN
6	1		*COND/COMPRESSOR HOSE	0.00	0	BT *175.00 F
7	1		*CONDENSER	0.00	0	BT *610.00 F
8	1		*DRIVER AIRBAG	0.00	0	ACT *1,220.00 F
9	1		*DRIVER AIRBAG SYS	0.00	0	ACT *105.00 F
10	1		*F/SUPPORT TOP GARN	0.00	0	MIS *120.00 F
11	1		*FAN SHROUD	0.00	0	*120.00 F XHN
12	1		*FRONT BUMPER	0.00	0	MIS *280.00 F
13	1		*FRONT BUMPER SPOILER	0.00	0	ALL *110.00 F
14	1		*FRONT PANEL CPL	0.00	0	DIS *418.00 F
15	1		*FRONT SCREEN SPACER	0.00	0	ALL *17.44 F
16	1		*FRT BONNET INSULATOR	0.00	0	*115.00 F /AN
17	1		*FRT BUMPER SUPPORT	0.00	0	*198.00 F XHN
18	1		*FRT GRILLE CHROME	0.00	0	MIS *105.00 F
19	1		*FRT SCREEN CLIP SET	0.00	0	*10.02 F
20	1		*FRT SCREEN CLIP SET	0.00	0	ALL *9.64 F
21	1		*FRT SCREEN CLIP SET	0.00	0	*4.82 F
22	1		*FRT SCREEN MNTG KIT	0.00	0	*- F
23	1		*FRT SCREEN SUPPORTS	0.00	0	ALL *4.68 F
24	1		*GRILLE	0.00	0	MIS *95.00 F
25	1		*GRILLE BADGE	0.00	0	MIS *50.00 F
26	1		*INSTRUMENT PANEL	0.00	0	TN *980.00 F
27	1		*L/AIRBAG SENSOR	0.00	0	ACT *320.00 F
28	1		*L/BONNET HINGE	0.00	0	BT *58.00 F
29	1		*L/F HEADLAMP CPL	0.00	0	*750.00 F XHN
30	1		*L/F OUT BUMPER BRKT	0.00	0	BT *25.00 F
31	1		*L/F SEAT BELT	0.00	0	ACT *510.00 F
32	1		*L/HEADLAMP BALLAST	0.00	0	*450.00 F XHN
33	1		*L/R BUMPER BRACKET	0.00	0	RH BT *60.00 F 70
34	1		*PASSENGER AIRBAG	0.00	0	ACT *1,350.00 F
35	1		*R/BONNET HINGE	0.00	0	BT *58.00 F
36	1		*R/COWL PANEL GRILLE	0.00	0	*70.00 F XHN
37	1		*R/F FOG LAMP	0.00	0	MIS *168.00 F
38	1		*R/F HEADLAMP CPL	0.00	0	CRA *750.00 F
39	1		*R/F OUT BUMPER BRKT	0.00	0	ALL *25.00 F
40	1		*R/F SEAT BELT	0.00	0	ACT *510.00 F
41	1		*R/F SHOCK ABSORBER	0.00	0	*110.00 F XHN
42	1		*R/F STEERING KNUCKLE	0.00	0	*318.00 F XHN
43	1		*R/F TYRE	0.00	0	OUT 150 *280.00 F
44	1		*R/F WHEEL	0.00	0	OUT *580.00 F

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
45	1		*R/F WHEEL BEARING	0.00	0	*125.00 F <i>XNN</i>
46	1		*R/F WING	0.00	0	*298.00 F <i>DTS</i>
47	1		*R/F WING TOP GARNISH	0.00	0	*130.00 F <i>DTS</i>
48	1		*R/FOG LAMP COVER	0.00	0	*48.00 F <i>DTS</i>
49	1		*R/HEADLAMP BALLAST	0.00	0	*450.00 F <i>DMS</i>
50	1		*R/LOWER CONTROL ARM	0.00	0	*150.00 F <i>XNN</i>
51	1		*R/R BUMPER BRACKET	0.00	0	*60.00 F <i>BT</i>
52	1		*R/R CONTROL ARM	0.00	0	*180.00 F <i>XNN</i>
53	1		*R/R INNER LAMP CPL	0.00	0	*310.00 F
54	1		*R/R OUTER LAMP CPL	0.00	0	*350.00 F <i>CRA</i>
55	1		*R/R TYRE	0.00	0	*280.00 F <i>XNN</i>
56	1		*R/R WHEEL	0.00	0	*580.00 F <i>400</i>
57	1		*R/R WING	0.00	0	*680.00 F <i>CUT</i>
58	1		*R/R WING AIRVENT	0.00	0	*38.00 F <i>CRA</i>
59	1		*R/WHEELHOUSE SHELL	0.00	0	*115.00 F <i>XR</i>
60	1		*R/WSCREEN MLDG	0.00	0	*120.00 F <i>REC</i>
61	1		*R/WSCREEN SEALANT	0.00	0	*50.00 F <i>REC</i>
62	1		*RADIATOR	0.00	0	*580.00 F <i>BT</i>
63	1		*RADIATOR FAN	0.00	0	*75.00 F <i>XNN</i>
64	1		*RADIATOR FAN MOTOR	0.00	0	*135.00 F
65	1		*REAR BUMPER	0.00	0	*310.00 F <i>REC</i>
66	1		*REAR PANEL CPL	0.00	0	*398.00 F <i>DTS</i>
67	1		*RR BUMPER PARK SENS	0.00	0	*285.00 F <i>200</i>
68	1		*TIMING BELT	0.00	0	*95.00 F <i>CUT</i>
69	1		*UPP FRT SCREEN SEAL	0.00	0	*25.20 F <i>REC</i>
70	1		*WASHER RESERVOIR	0.00	0	*95.00 F <i>DTS</i>
71	1		*WINDSCREEN	0.00	0	*780.00 F <i>CRA</i>
72	1		*WINDSCREEN REP KIT	0.00	0	*30.00 F
73	1		*WINDSCREEN SEAL	0.00	0	*130.00 F <i>REC</i>
74	1		*WIPER MOTOR	0.00	0	*58.00 F <i>XNN</i>
75	1		*FRT NUMBER PLATE	0	0	*50.00 FS <i>MIS</i>
76	1		*R/ WSCREEN INN SEAL	0	0	*60.00 FS <i>REC</i>
77	2		*F/WSCREEN SEALANT	0	0	*50.00 FS <i>REC</i>
78	1		*IU BRACKET	0	0	*15.00 FS <i>REC</i>
79	1		*F/WSCREEN INN SEAL	0	0	*60.00 FS <i>REC</i>
80	1		*AUDATEX FEE	0	0	*42.00 FS
81	1		*Sundry Parts	0	0	*100.00 FS <i>REC</i>

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	20,309.80
+ Margin on L,N Items 5.00% (\$\$)	996.64
Total Parts (\$\$)	21,306.44

Auto N Cars Services Pte Ltd/SJE9136M/27/12/2017 14:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Total Panel/Mechanical	New	2,235.60
2	Total Paintwork	New	745.20
3	Total Visual Alignment work	New	87.40
4	Total Paint/Material Costs	New	314.40
Gross Labour Cost (\$\$)			3,382.60

Auto N Cars Services Pte Ltd/SJE9136M/27/12/2017 14:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

**CHINA TAIPING
INSURANCE (S) PTE LTD
3 ANSON ROAD
#15-02 SPRINGLEAF
TOWER
079909**

**Claim Reference: 20170001929
Assessment Number: ANC00185
Version: CHINATAI/9
Date Calculated: 25/05/2018 04:35**

**Full Report - V1
Registration: SJE9136M
Printed: 25/05/2018 11:36**

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Mr K.K Lau	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	20170001929	Estimated Repair Time:	
Policy Number:	DMHCSN1712371700	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle	Model Specs
Manufacturer: HONDA	4-DOOR
Model: Civic	FOG LAMPS
Sub Model: GLI	1.7 LTR 96KW VTEC
Model Sheet Number: H34 24	
Registration: SJE9136M	AUTO AIR CON
Registration Month:	CTR REAR ARMREST
Registration Year:	FRONT SPOILER
VIN Number:	
Odometer: Not Known	
Colour:	
Engine Number:	
Fuel Level: %	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection: 27/12/2017
Place of Inspection:	
Pre-Accident Damage:	
Tyres Condition:	
Tread Depth LHF:	Tread Depth RHF:
Tread Depth LHR:	Tread Depth RHR:
Damage Areas:	Direction of Impact:

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: 20170001929

Assessment Number: ANC00185



Version: CHINATAI/9

Date Calculated: 25/05/2018 04:35

Full Report - V1

Registration: SJE9136M

Printed: 25/05/2018 11:36

**Addresses****Cost Summary**

Total Labour	\$2,764.60
Total Paint/Material	\$267.43
Total Parts	\$16,323.34
Total of Additional Costs	\$277.00
Repair Cost Exc GST:	\$19,632.37
Overall Discount (0.0%):	- \$0.00
Excess:	-\$1,000.00
After Deduction -	
Grand Total Exc GST:	\$18,632.37
7 % GST:	\$1,304.27
Grand Total Inc GST:	\$19,936.64

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR

Price/Dent = \$46.00/HR

Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
C0103-000)	FRONT VEHICLE ALIGNMENT W/O ADJUSTMENT	5.0	23.00
C0103-000)	ALIGNMENT W/O ADJUSTMENT REAR VEHICLE	4.0	18.40
33901-S5A	R + R L/F FOGLAMP	3.0	13.80
33901-S5A	R + R R/F FOGLAMP	3.0	13.80
NO NUMBER	R + R FRONT SPOILER	2.0	9.20
71121-S5A)	RENEW RADIATOR GRILLE (REMOVED)	1.0	4.60
60100-S5A)	R + R BONNET	3.0	13.80
60100-S5A)	RENEW BONNET (REMOVED)	3.0	13.80
60120-S5A	R + R LEFT BONNET HINGE	3.0	13.80
	(BONNET REMOVED)		
60120-S5A	R + R RIGHT BONNET HINGE	3.0	13.80
	(BONNET REMOVED)		
76840-S5A)	R + R FRONT WIPER RESERVOIR	3.0	13.80
	(BUMPER REMOVED)		
38100-S04	R + R LOW TONE HORN	2.0	9.20
38150-SX0	R + R HIGH TON HORN	2.0	9.20
60211-S6A	R + R L/F WING	9.0	41.40
	INCLUDES: R + R FRONT BUMPER, HEADLAMP		
	AND WHEELHOUSE COVER		
60211-S6A)	R + R R/F WING	5.0	23.00
	(BUMPER REMOVED)		
	DOES NOT INCLUDE: R + R WHEELHOUSE		
	COVER		
	AND HEADLAMP		
60400-S5A	RENEW FRONT PANEL CPL	25.0	115.00
73111-S5A	WINDSCREEN R + R	37.0	170.20

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: 20170001929
 Assessment Number: ANC00185
 Version: CHINATAI/9
 Date Calculated: 25/05/2018 04:35

Full Report - V1
 Registration: SJE9136M
 Printed: 25/05/2018 11:36

	INCLUDES: SCREEN WIPER ARM, COWL COVER AND MOULDINGS REMOVE AND REFIT		
NO NUMBER	R + R REAR NO-PLATE	1.0	4.60
34151-S5A	R + R R/INNER TAILLAMP	2.0	9.20
74851-S5A	R + R BOOTLID LOCK	2.0	9.20
NO NUMBER	R + R ATTACHED PARTS OF THE R/SIDE PANEL AND REAR END PANEL	72.0	331.20
	INCLUDES: R + R BUMPER, TAILLAMPS, BOOTLID, BOOTLID SEAL, REAR SEAT, REAR SCREEN, SEAT BELT AND ALL TRIMS IN THE REPAIR SECTION		
NO NUMBER	RENEW CPL RIGHT SIDE SECTION AND REAR PANEL	135.0	621.00
77101-S5A	RENEW INSTRUMENT PANEL	41.0	188.60
	INCLUDES: R + R INSTRUMENT PANEL AND CONVERT ALL ATTACHED PARTS		
77960-S5A)	R + R AIRBAG CONTROL UNIT (CENTRE CONSOLE REMOVED)	4.0	18.40
77930-S5A)	R + R L/AIRBAG SENSOR	2.0	9.20
83401-S5A	R + R CENTRE CONSOLE INSERT	3.0	13.80
81450-S5A	R + R LEFT FRONT SEAT BELT	4.0	18.40
	INCLUDES: R + R B-PILLAR TRIM		
81450-S5A	R + R RIGHT FRONT SEAT BELT	4.0	18.40
	INCLUDES: R + R B-PILLAR TRIM		
19010-PLC)	R + R RADIATOR CPL WITH ATTACHED PARTS	6.0	27.60
06770-S5A	R + R DRIVER AIRBAG MODULE	3.0	13.80
A0112-000	R + R RIGHT FRONT WHEEL	2.0	9.20
42751-S5A)	FIT AND BALANCE RIGHT FRONT TYRE (WHEEL REMOVED)	5.0	23.00
A0112-000	R + R RIGHT REAR WHEEL	2.0	9.20
42751-S5A)	FIT AND BALANCE RIGHT REAR TYRE (WHEEL REMOVED)	5.0	23.00
80315-S5A)	R + R CONDENSER/COMPRESSOR PIPE	1.0	4.60
80110-S5A)	R + R AIR CONDITIONING CONDENSER	3.0	13.80
NO NUMBER	REFILL + VENT AIR CONDITIONING	10.0	46.00
C0104-000	ADJUST FRONT TOE AFTER CHECK	5.0	23.00
C0104-000	ADJUST REAR TOE	5.0	23.00
9852	READ OUT FAULT MEM AFTER REP	20.0*	92.00
1118	REPAIR R/F WHEELHOUSE	10.0*	46.00
LABOUR COST			
	Total Work Units	460.0	
	Panel / Mechanical Labour	44.1HRS	\$2,028.60
	Visual Alignment Labour	1.9HRS	\$87.40
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	46.0HRS	\$2,116.00
	Paint Labour	14.1HRS	\$648.60
	Total Labour	60.1HRS	\$2,764.60

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$46.00/HR

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: 20170001929
 Assessment Number: ANC00185
 Version: CHINATAI/9
 Date Calculated: 25/05/2018 04:35

Full Report - V1
 Registration: SJE9136M
 Printed: 25/05/2018 11:36

Guide Number	Description	WU	Cost Price (\$)
471	BONNET NEW PART PAINTING	19.0	
742	R/F WING NEW PART PAINTING	9.0	
1009	FRONT PANEL CPL SURFACE PAINT	6.0	
2711	REAR PANEL CPL NEW PART PAINTING	18.0	
3482	R/R WING NEW PART PAINTING	25.0	
391	FRONT BUMPER SPOILER NEW PART PAINT K1R	6.0	
2583	REAR BUMPER NEW PART PAINT K1R	13.0	
1118	R/F WHEELHOUSE SURFACE PAINT	5.0	
3481	L/R WING SURFACE PAINT	6.0	
3900	BOOTFLOOR SURFACE PAINT	9.0	
4285	PARCEL SHELF PANEL SURFACE PAINT	5.0	
LABOUR COST - PAINT			
	TIME(PAINT)	121.0	
	Preparation Main Work Metal	17.0	
	Preparation Comp. Work Plastic	3.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	141.0	
	Total Paintwork Labour	14.1HRS	\$648.60
MATERIAL COST - PAINT			Cost Price
	New Part Painting		\$110.90
	New Part Painting - Plastic K1R		\$73.29
	Surface-/Blend Paint		\$56.14
	Material-Const Main Work Metal		\$18.10
	Material-Const Comp. Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$267.43
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$267.43

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Price (\$)
283	1	FRONT BUMPER	04711S5A407ZZ		280.00*
317	1	L/F OUT BUMPER BRKT	71198S5A000		25.00*
318	1	R/F OUT BUMPER BRKT	71193S5A000		25.00*
391	1	FRONT BUMPER SPOILER	08F01S5A601		110.00*
410	1	GRILLE	71121S5A003ZE		95.00*
431	1	GRILLE BADGE	75700S5A000		50.00*
471	1	BONNET	60100S5DA90ZZ		380.00*
475	1	L/BONNET HINGE	60170S5A000ZZ		58.00*
476	1	R/BONNET HINGE	60120S5A000ZZ		58.00*
492	1	BONNET LOCK	74120S6A505		65.00*
562	1	R/F HEADLAMP CPL	33151S5AQ01		750.00*
638	1	R/F FOG LAMP	33901S5B003		168.00*
652	1	R/FOG LAMP COVER	33905S6A003		48.00*
742	1	R/F WING	60211S5A000ZZ		298.00*
1009	1	FRONT PANEL CPL	60400S5HT00ZZ		418.00*
1401	1	WINDSCREEN	73111S5AQ00		780.00*
1410	1	WINDSCREEN SEAL	04731S5AJ00		130.00*
1411	1	WINDSCREEN REP KIT	08CRCX016N0		30.00U
1413	1	FRT SCREEN MNTG KIT	USE SINGLE PARTS		0.00
1415	6	FRT SCREEN CLIP SET	91520S5A003		10.02U
1416	2	FRONT SCREEN SPACER	91568SX0003		17.44U

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: 20170001929
 Assessment Number: ANC00185
 Version: CHINATAI/9
 Date Calculated: 25/05/2018 04:35

Full Report - V1
 Registration: SJE9136M
 Printed: 25/05/2018 11:36

1417	2	FRT SCREEN SUPPORTS	91577S84A01	0%	4.68U
1418	2	FRT SCREEN CLIP SET	91519S5A003	0%	4.82U
1419	4	FRT SCREEN CLIP SET	91521S5A003	0%	9.64U
1423	1	UPP FRT SCREEN SEAL	73150S5A013	0%	25.20U
1436	1	WASHER RESERVOIR	76840S5A003	0%	95.00*
2583	1	REAR BUMPER	04715S5AA80ZZ	0%	310.00*
2619	1	L/R BUMPER BRACKET	71555S5A000	0%	30.00*
2620	1	R/R BUMPER BRACKET	71505S5A000	0%	60.00*
2711	1	REAR PANEL CPL	66100S5HT00ZZ	0%	398.00*
3282	1	R/R OUTER LAMP CPL	33501S5HT01	0%	350.00*
3284	1	R/R INNER LAMP CPL	34151S5AA01	0%	310.00*
3482	1	R/R WING	04636S5A405ZZ	0%	680.00*
4325	1	PASSENGER AIRBAG	06780S5AE20ZA	0%	1,350.00*
4331	1	INSTRUMENT PANEL	77101S5A010ZC	0%	980.00*
4465	1	CONDENSER	80110S6DG01	0%	610.00*
4481	1	COND/COMPRESSOR HOSE	80315S5A013	0%	175.00*
4661	1	L/F SEAT BELT	81850S5AG01ZD	0%	510.00*
4662	1	R/F SEAT BELT	81450S5AG01ZD	0%	510.00*
7202	1	R/F WHEEL	42700S6DE01	0%	580.00*
7228	1	R/F TYRE	185/70 R 14 .. H	0%	150.00*
7405	1	DRIVER AIRBAG SYS	REPLACE	0%	105.00*
7437	1	L/AIRBAG SENSOR	77940S5AN91	0%	320.00*
7440	1	AIRBAG CONTROL UNIT	77960S5AG83	0%	580.00*
7445	1	DRIVER AIRBAG	06770S5AG80ZA	0%	1,220.00*
7761	1	RADIATOR	19010PLMA02	0%	580.00*
9552	1	R/R WHEEL	42700S6DE01	0%	400.00*
1000	1	FRT GRILLE CHROME	Renew	0%	105.00*
1000	1	R/HEADLAMP BALLAST	Renew	0%	450.00*
1000	1	R/F WING TOP GARNISH	Renew	0%	130.00*
1000	1	F/SUPPORT TOP GARN	Renew	0%	120.00*
1000	1	TIMING BELT	Renew	0%	95.00*
1000	1	RR BUMPER PARK SENS	Renew	0%	200.00*
1000	1	R/R WING AIRVENT	Renew	0%	38.00*
1000	1	R/WSCREEN SEALANT	Renew	0%	50.00*
1000	1	R/WSCREEN MLDG	Renew	0%	120.00*

f: OEM Parts	Sub Total		\$15,450.80
g: Original	Mark Up From Cost	(5 %)	\$772.54
h: Secondhand	Sundry Parts	(Fixed)	\$100.00
p: Parallel	Total Parts		\$16,323.34
x: Exchange			

THIS ASSESSMENT CONTAINS UNPRICED PARTS
 NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
FRT NUMBER PLATE	SPECIALIST	0%
R/ WSCREEN INN	SPECIALIST	0%
SEAL		
F/WSCREEN SEALANTS	SPECIALIST	0%
IU BRACKET	SPECIALIST	0%
F/WSCREEN INN	SPECIALIST	0%
SEAL		
AUDATEX FEE	SPECIALIST	

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: 20170001929

Assessment Number: ANC00185

Version: CHINATAI/9

Date Calculated: 25/05/2018 04:35

Full Report - V1

Registration: SJE9136M

Printed: 25/05/2018 11:36

	Total Extras	\$277.00
Final Calculation		
Total Parts		\$16,323.34
Labour		
Total Panel/Mechanical	\$2,028.60	
Total Paintwork	\$648.60	
Total Visual Alignment work	\$87.40	
Total Labour		\$2,764.60
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$277.00	
Total of Additional Costs		\$277.00
Total Paint/Material Costs		\$267.43
Repair Costs Excludes GST		\$19,632.37
Deductions		
Deduction for Excess (Fixed)	-\$1,000.00	
Total Deductions		-\$1,000.00
Grand Total Excludes GST (After Deduction)		\$18,632.37
GST @ 7 %		\$1,304.27
Grand Total Includes GST (After Deduction)		\$19,936.64

Assessment Notes

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Dec 2017 Sendback Est	27 Dec 2017 14:54 \$24,689.04	27 Dec 2017 15:39 Edit Adj Rpt	\$3,700.00 Edit Estimates	\$3,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: BLUE STAR LIMOUSINE MANAGEMENT PTE LTD , Co. Reg. No.: 201539827C									
Vehicle Reg. No.: SJE9136M		Date of Loss: 23/12/2017 00:00 - :59 [115 Months and 10 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / SNM17D07250C01		Policy/Cover Note No.: DMHCSN1712371700 (Comprehensive)							
		Excess: \$1,000.00							
Repairer: Auto N Cars Services Pte Ltd (HQ) Blk 1 Kaki Bukit Ave 6 #01-04, AutoBay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 6555 2909									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 08/01/2018]									
Driver/Custodian: ALAN TAN JUN RONG (25 / Male), NRIC: S9240779I, Tel: +6591258660									
Adj Asg. Remarks: survey revert									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- CHINA_TAIPING (16/01/2018): Alert - Adj Mandate Approved (\$3700.00) - SJE9136M - Claim Handler: Chong Boon ... - CHINA_TAIPING (10/01/2018): Alert - Adj Mandate Maintained - SJE9136M - Claim Handler: Chong Boon Sen									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJE9136M (SNM17D07250C01)
 OD
 Dec 23 2017 12:00AM
 [BLUE STAR LIMOUSINE MANAGEMENT PTE LTD]
 Auto N Cars Services Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	☒
No.	Finalized On	Auto N Cars Services Pte Ltd (HQ)		Thumbnail	Print
1	23/12/17 12:04	Accident Statement		Load HTM	
2	27/12/17 14:54	Repairer Estimates		Load HTM	
No.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/12/17 17:20	Adjuster Immediate Advice		Load HTM	
2	02/01/18 11:51	Adjuster Immediate Advice		Load HTM	
3	15/01/18 13:43	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page	☒
No.	Finalized On	Auto N Cars Services Pte Ltd (HQ)		Thumbnail	Print
1	23/12/17 12:03	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
2	23/12/17 12:03	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
3	23/12/17 12:03	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
4	23/12/17 12:03	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
5	23/12/17 12:03	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
6	23/12/17 12:03	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
7	23/12/17 12:03	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
8	23/12/17 12:03	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
9	23/12/17 12:03	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
No.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/05/18 09:30	General View		Load JPG	☒
2	10/05/18 09:30	General View		Load JPG	☒
3	10/05/18 09:30	General View		Load JPG	☒
4	10/05/18 09:30	General View		Load JPG	☒
5	10/05/18 09:30	General View		Load JPG	☒
6	10/05/18 09:30	General View		Load JPG	☒
7	10/05/18 09:30	General View		Load JPG	☒
8	10/05/18 09:30	General View		Load JPG	☒
9	10/05/18 09:30	General View		Load JPG	☒
10	10/05/18 09:30	General View		Load JPG	☒
11	10/05/18 09:30	General View		Load JPG	☒
12	10/05/18 09:30	General View		Load JPG	☒
13	10/05/18 09:30	General View		Load JPG	☒
14	10/05/18 09:30	General View		Load JPG	☒
15	10/05/18 09:30	General View		Load JPG	☒
16	10/05/18 09:30	General View		Load JPG	☒
17	10/05/18 09:30	General View		Load JPG	☒
18	10/05/18 09:30	General View		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Auto N Cars Services Pte Ltd (HQ)	Thumbnail	Print
19	10/05/18 09:30	General View	 Load JPG	☒
20	10/05/18 09:30	General View	 Load JPG	☒
21	10/05/18 09:30	General View	 Load JPG	☒
22	10/05/18 09:30	General View	 Load JPG	☒
23	10/05/18 09:30	General View	 Load JPG	☒
24	10/05/18 09:30	General View	 Load JPG	☒
25	10/05/18 09:30	General View	 Load JPG	☒
26	10/05/18 09:30	General View	 Load JPG	☒
27	10/05/18 09:30	General View	 Load JPG	☒
28	10/05/18 09:30	General View	 Load JPG	☒
29	10/05/18 09:30	General View	 Load JPG	☒
30	10/05/18 09:30	General View	 Load JPG	☒
31	10/05/18 09:30	General View	 Load JPG	☒
32	10/05/18 09:30	General View	 Load JPG	☒
33	10/05/18 09:30	General View	 Load JPG	☒
34	10/05/18 09:30	General View	 Load JPG	☒
35	10/05/18 09:30	General View	 Load JPG	☒
36	10/05/18 09:30	General View	 Load JPG	☒
37	10/05/18 09:30	General View	 Load JPG	☒
38	10/05/18 09:30	General View	 Load JPG	☒
39	10/05/18 09:30	General View	 Load JPG	☒
40	10/05/18 09:30	General View	 Load JPG	☒
41	10/05/18 09:30	General View	 Load JPG	☒
42	10/05/18 09:30	General View	 Load JPG	☒
43	10/05/18 09:30	General View	 Load JPG	☒
44	10/05/18 09:30	General View	 Load JPG	☒
45	10/05/18 09:30	General View	 Load JPG	☒
46	10/05/18 09:30	General View	 Load JPG	☒
47	10/05/18 09:30	General View	 Load JPG	☒
48	10/05/18 09:30	General View	 Load JPG	☒
49	10/05/18 09:30	General View	 Load JPG	☒
50	10/05/18 09:30	General View	 Load JPG	☒
51	10/05/18 09:30	General View	 Load JPG	☒
52	10/05/18 09:30	General View	 Load JPG	☒
53	10/05/18 09:30	General View	 Load JPG	☒
54	10/05/18 09:30	General View	 Load JPG	☒
55	10/05/18 09:30	General View	 Load JPG	☒
56	10/05/18 09:30	General View	 Load JPG	☒
57	10/05/18 09:30	General View	 Load JPG	☒
58	10/05/18 09:30	General View	 Load JPG	☒
59	10/05/18 09:30	General View	 Load JPG	☒
60	10/05/18 09:30	General View	 Load JPG	☒
61	10/05/18 09:30	General View	 Load JPG	☒
62	10/05/18 09:30	General View	 Load JPG	☒
63	10/05/18 09:30	General View	 Load JPG	☒
64	10/05/18 09:30	General View	 Load JPG	☒
65	10/05/18 09:30	General View	 Load JPG	☒
66	10/05/18 09:30	General View	 Load JPG	☒
67	10/05/18 09:30	General View	 Load JPG	☒
68	10/05/18 09:30	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Auto N Cars Services Pte Ltd (HQ)	Thumbnail	Print
69	10/05/18 09:30	General View	Load JPG	☒
70	10/05/18 09:30	General View	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Auto N Cars Services Pte Ltd (HQ)	Thumbnail	Print
1	23/12/17 12:03	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	23/12/17 12:03	Sketch Plan #2 [Linked Accident Report Documents]	Load TIF	
3	23/12/17 12:03	IC & DL [Linked Accident Report Documents]	Load TIF	
4	23/12/17 12:03	INS CERT [Linked Accident Report Documents]	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/12/17 16:56	WORKSHOP ESTIMATE	Load PDF	
2	29/12/17 16:56	REVISED AUDATEX	Load PDF	
3	29/12/17 17:05	INSPECTION PHOTO	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Auto N Cars Services Pte Ltd (HQ)	Thumbnail	Print
1	23/12/17 12:04	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Auto N Cars Services Pte Ltd (HQ)	Thumbnail	Print
1	23/12/17 12:03	Accident Photo	Load JPG	☒
2	23/12/17 12:03	Accident Photo	Load JPG	☒
3	23/12/17 12:03	Accident Photo	Load JPG	☒
4	23/12/17 12:03	Accident Photo	Load JPG	☒
5	23/12/17 12:03	Accident Photo	Load JPG	☒
6	23/12/17 12:03	Accident Photo	Load JPG	☒
7	23/12/17 12:03	Accident Photo	Load JPG	☒
8	23/12/17 12:03	Accident Photo	Load JPG	☒
9	23/12/17 12:03	Accident Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Auto N Cars Services Pte Ltd (HQ)	Thumbnail	Print
1	23/12/17 12:03	Sketch Plan	Load TIF	
2	23/12/17 12:03	Sketch Plan #2	Load TIF	
3	23/12/17 12:03	IC & DL	Load TIF	
4	23/12/17 12:03	INS CERT	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI17024612/AQD3E2

Date: 30/05/2018

REFERENCE

Insured/Claimant: BLUE STAR LIMOUSINE
MANAGEMENT PTE LTD

Policy No: DMHCSN1712371700

Date of Loss: 23/12/2017

Nature of
Claim: ODClaim
No: SNM17D07250C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJE9136M

Make & Model: HONDA CIVIC, 1.8 L (A)

Engine No: R18A13034144

Reg. Date: 13/05/2008 (Man. Year: 2008)

Chassis No: JHMF16308S215575

Colour: Black

Odometer: 0 km

Engine Capacity: 1799 cc

Market Value/New Car Price: S\$15,600.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size:

225/45 R17

Front Left Side: Neuton 6 mm

Rear Left Side:

Neuton 6 mm

Front Right Side: Neuton 6 mm

Rear Right Side:

Neuton 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,306.44	16,600.34	4,706.10	22.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,382.60	3,032.03	350.57	10.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,689.04	19,632.37	5,056.67	20.48
Approved Total (Overridden) (S\$)		3,700.00		
- Excess (S\$)	0.00	1,000.00	-1,000.00	
(S\$)	24,689.04	2,700.00	21,989.04	89.06
+ GST 7.00/7.00% (S\$)	1,728.23	189.00	1,539.23	89.06
Nett Amount (S\$)	26,417.27	2,889.00	23,528.27	89.06

INSPECTION

Date of Assignment: 27/12/2017 Present Location:

Date Inspected: 28/12/2017 Inspected At:

Auto N Cars Services Pte Ltd (HQ)

Blk 1 Kaki Bukit Ave 6 #01-04, AutoBay @

Kaki Bukit

Singapore 417883

Estimated Period of Repair: 12.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 May 2018)
Parts: 143	HONDA CIVIC 1.8 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJE9136M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*AIRBAG CONTROL UNIT (WCP)	Activated	580.00 F	*580.00 F
2	1		*BONNET (WCP)	Distorted	380.00 F	*380.00 F
3	1		*BONNET LOCK (WCP)	Damaged	65.00 F	*65.00 F
4	1		*BOOTLID (WCP)	Repair	650.00 F	*- F
5	1		*COMPR/EVAP TUBE (WCP)	Not Necessary	158.00 F	*- F
6	1		*COND/COMPRESSOR HOSE (WCP)	Bent	175.00 F	*175.00 F
7	1		*CONDENSER (WCP)	Bent	610.00 F	*610.00 F
8	1		*DRIVER AIRBAG (WCP)	Activated	1,220.00 F	*1,220.00 F
9	1		*DRIVER AIRBAG SYS (WCP)	Activated	105.00 F	*105.00 F
10	1		*F/SUPPORT TOP GARN (WCP)	Missing	120.00 F	*120.00 F
11	1		*FAN SHROUD (WCP)	Not Necessary	120.00 F	*- F
12	1		*FRONT BUMPER (WCP)	Missing	280.00 F	*280.00 F
13	1		*FRONT BUMPER SPOILER (WCP)	Necessary	110.00 F	*110.00 F
14	1		*FRONT PANEL CPL (WCP)	Distorted	418.00 F	*418.00 F
15	1		*FRONT SCREEN SPACER (WCP)	Necessary	17.44 F	*17.44 F
16	1		*FRT BONNET INSULATOR (WCP)	Not Necessary	115.00 F	*- F
17	1		*FRT BUMPER SUPPORT (WCP)	Not Necessary	198.00 F	*- F
18	1		*FRT GRILLE CHROME (WCP)	Missing	105.00 F	*105.00 F
19	1		*FRT SCREEN CLIP SET (WCP)	Necessary	10.02 F	*10.02 F
20	1		*FRT SCREEN CLIP SET (WCP)	Necessary	9.64 F	*9.64 F
21	1		*FRT SCREEN CLIP SET (WCP)	Necessary	4.82 F	*4.82 F
22	1		*FRT SCREEN MNTG KIT (NPA)(WCP)	Necessary	0.00 F	*- F
23	1		*FRT SCREEN SUPPORTS (WCP)	Necessary	4.68 F	*4.68 F
24	1			Missing	95.00 F	*95.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*GRILLE (WCP)			
25	1		*GRILLE BADGE (WCP)	Missing	50.00 F	*50.00 F
26	1		*INSTRUMENT PANEL (WCP)	Torn	980.00 F	*980.00 F
27	1		*L/AIRBAG SENSOR (WCP)	Activated	320.00 F	*320.00 F
28	1		*L/BONNET HINGE (WCP)	Bent	58.00 F	*58.00 F
29	1		*L/F HEADLAMP CPL (WCP)	Not Necessary	750.00 F	*- F
30	1		*L/F OUT BUMPER BRKT (WCP)	Bent	25.00 F	*25.00 F
31	1		*L/F SEAT BELT (WCP)	Activated	510.00 F	*510.00 F
32	1		*L/HEADLAMP BALLAST (WCP)	Not Necessary	450.00 F	*- F
33	1		*L/R BUMPER BRACKET (WCP)	O/S Bent	60.00 F	*30.00 F
34	1		*PASSENGER AIRBAG (WCP)	Activated	1,350.00 F	*1,350.00 F
35	1		*R/BONNET HINGE (WCP)	Bent	58.00 F	*58.00 F
36	1		*R/COWL PANEL GRILLE (WCP)	Not Necessary	70.00 F	*- F
37	1		*R/F FOG LAMP (WCP)	Missing	168.00 F	*168.00 F
38	1		*R/F HEADLAMP CPL (WCP)	Cracked	750.00 F	*750.00 F
39	1		*R/F OUT BUMPER BRKT (WCP)	Necessary	25.00 F	*25.00 F
40	1		*R/F SEAT BELT (WCP)	Activated	510.00 F	*510.00 F
41	1		*R/F SHOCK ABSORBER (WCP)	Not Necessary	110.00 F	*- F
42	1		*R/F STEERING KNUCKLE (WCP)	Not Necessary	318.00 F	*- F
43	1		*R/F TYRE (WCP)	Cut	280.00 F	*150.00 F
44	1		*R/F WHEEL (WCP)	Cut	580.00 F	*580.00 F
45	1		*R/F WHEEL BEARING (WCP)	Not Necessary	125.00 F	*- F
46	1		*R/F WING (WCP)	Distorted	298.00 F	*298.00 F
47	1		*R/F WING TOP GARNISH (WCP)	Deformed	130.00 F	*130.00 F
48	1		*R/FOG LAMP COVER (WCP)	Missing	48.00 F	*48.00 F
49	1		*R/HEADLAMP BALLAST (WCP)	Damaged	450.00 F	*450.00 F
50	1		*R/LOWER CONTROL ARM (WCP)	Not Necessary	150.00 F	*- F
51	1		*R/R BUMPER BRACKET (WCP)	Bent	60.00 F	*60.00 F
52	1		*R/R CONTROL ARM (WCP)	Not Necessary	180.00 F	*- F
53	1		*R/R INNER LAMP CPL (WCP)	Cracked	310.00 F	*310.00 F
54	1		*R/R OUTER LAMP CPL (WCP)	Cracked	350.00 F	*350.00 F
55	1		*R/R TYRE (WCP)	Not Necessary	280.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*R/R WHEEL (WCP)	Necessary	580.00 F	*400.00 F
57	1		*R/R WING (WCP)	Cut	680.00 F	*680.00 F
58	1		*R/R WING AIRVENT (WCP)	Cracked	38.00 F	*38.00 F
59	1		*R/WHEELHOUSE SHELL (WCP)	Repair	115.00 F	*- F
60	1		*R/WSCREEN MLDG (WCP)	Necessary	120.00 F	*120.00 F
61	1		*R/WSCREEN SEALANT (WCP)	Necessary	50.00 F	*50.00 F
62	1		*RADIATOR (WCP)	Bent	580.00 F	*580.00 F
63	1		*RADIATOR FAN (WCP)	Not Necessary	75.00 F	*- F
64	1		*RADIATOR FAN MOTOR (WCP)	Not Necessary	135.00 F	*- F
65	1		*REAR BUMPER (WCP)	Missing	310.00 F	*310.00 F
66	1		*REAR PANEL CPL (WCP)	Distorted	398.00 F	*398.00 F
67	1		*RR BUMPER PARK SENS (WCP)	Missing	285.00 F	*200.00 F
68	1		*TIMING BELT (WCP)	Cut	95.00 F	*95.00 F
69	1		*UPP FRT SCREEN SEAL (WCP)	Necessary	25.20 F	*25.20 F
70	1		*WASHER RESERVOIR (WCP)	Distorted	95.00 F	*95.00 F
71	1		*WINDSCREEN (WCP)	Cracked	780.00 F	*780.00 F
72	1		*WINDSCREEN REP KIT (WCP)	Necessary	30.00 F	*30.00 F
73	1		*WINDSCREEN SEAL (WCP)	Necessary	130.00 F	*130.00 F
74	1		*WIPER MOTOR (WCP)	Not Necessary	58.00 F	*- F
75	1		*FRT NUMBER PLATE	Missing	50.00 FS	*50.00 FS
76	1		*R/ WSCREEN INN SEAL	Necessary	60.00 FS	*60.00 FS
77	2		*F/WSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS
78	1		*IU BRACKET	Necessary	15.00 FS	*15.00 FS
79	1		*F/WSCREEN INN SEAL	Necessary	60.00 FS	*60.00 FS
80	1		*AUDATEX FEE		42.00 FS	*42.00 FS
81	1		*Sundry Parts	Necessary	100.00 FS	*100.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	20,309.80	15,827.80
+ Margin on L,N Items 5.00/5.00% (\$\$)	996.64	772.54
Total Parts (\$\$)	21,306.44	16,600.34

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Total Panel/Mechanical	New	2,235.60	2,028.60
2	Total Paintwork	New	745.20	648.60
3	Total Visual Alignment work	New	87.40	87.40
4	Total Paint/Material Costs	New	314.40	267.43
Gross Labour Cost (S\$)			3,382.60	3,032.03

Report was unsubmitted during this print-out.

< END OF ESTIMATES >