

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG17024613/KVD3E2**Date:** 18/09/2018REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28663552AVW
Claimant Vehicle No :	SKP1845H	Insured Vehicle No :	SKX8003H
Date of Loss:	19/12/2017	Nature of Claim:	TP
		Claim No:	541827

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP1845H		
Make & Model:	VOLVO V40, 1.6 V40 CROSS COUNTRY T4 (A)	Engine No:	B4164T1143574
Reg. Date:	29/01/2014 (Man. Year: 2013)	Chassis No:	YV1MV485BE2079920
Colour:	Metallic Pearl White	Odometer:	84059 km
Engine Capacity:	1596 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40Z R18	Rear Tyre Size:	225/40Z R18
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,060.00	28,913.80	-24,853.80	-612.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,850.00	3,923.80	926.20	19.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,910.00	32,837.60	-23,927.60	-268.55
Approved Total (Overridden) (S\$)		21,000.00		
(S\$)	8,910.00	21,000.00	-12,090.00	-135.69
+ GST 7.00/7.00% (S\$)	623.70	1,470.00	-846.30	-135.69
Nett Amount (S\$)	9,533.70	22,470.00	-12,936.30	-135.69

INSPECTION

Date of Assignment:	26/12/2017	Present Location:	K Kim Hin Auto Pte Ltd (HQ)
Date Inspected:	27/12/2017	Inspected At:	K Kim Hin Auto Pte Ltd (HQ)
			160 Sin Ming Drive #02-20, Sin Ming AutoCity
			Singapore 575722
Estimated Period of Repair:	14.0 days		

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

WORKSHOP ESTIMATE : \$34,106.60

THE REPAIRER IS INFORMED ON THE REVISED AMOUNT BUT NOT AGREE WITH OUR RECOMMENDATION.

MARKET VALUE \$87,000.00

LTA REBATE \$66,127.00

NETT VALUE \$20,873.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Aug 2018)

Parts: 144 VOLVO V40 1.6 V40 CROSS COUNTRY T4 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKP1845H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER (WCP)	MTG Cracked	-	*1,400.00 F
2	1	*O/S REAR BUMPER SIDE BRACKET (WCP) (NPA)	Serviceable	-	*- F
3	1	*REAR BUMPER CLIPS (WCP) (NPA)	Not Necessary	-	*- F
4	1	*O/S REAR FENDER (WCP)	Bent	-	*1,750.00 F
5	1	*O/S ROCKER PANEL OUTER GARNISH (WCP) (NPA)	Serviceable	-	*- F
6	1	*O/S REAR DOOR (WCP)	Warped	-	*1,650.00 F
7	1	*O/S REAR DOOR SIDE SEAL (WCP) (NPA)	Serviceable	-	*- F
8	1	*O/S REAR DOOR LOWER SEAL (WCP) (NPA)	Serviceable	-	*- F
9	1	*O/S FRONT DOOR (WCP) (NPA)	Repair	-	*- F
10	1	*O/S FRONT DOOR LOWER SEAL (WCP)	Cut	-	*120.00 F
11	1	*O/S WING MIRROR (WCP) (NPA)	Serviceable	-	*- F
12	1	*O/S WING MIRROR COVER (WCP) (NPA)	Serviceable	-	*- F
13	1	*O/S FRONT FENDER (WCP)	Buckled	-	*890.00 F
14	1	*FRONT BUMPER (WCP)	Buckled	-	*1,400.00 F
15	1	*O/S FRONT BUMPER SIDE BRACKET (WCP)	Distorted	-	*80.00 F
16	1	*FRONT BUMPER CLIPS (WCP)	Necessary	-	*50.00 F
17	1	*O/S HEADLAMP ASSY (WCP)	Cut	-	*1,500.00 F
18	1	*O/S REAR KNUCKLE ARM (WCP)	Bent	-	*700.00 F
19	1	*O/S REAR WHEEL BEARING (WCP)	Necessary	-	*400.00 F
20	1	*O/S REAR LOWER ARM (WCP)	Distorted	-	*235.00 F
21	1	*O/S REAR LOWER CONTROL ARM (WCP)	Distorted	-	*65.00 F
22	1	*O/S REAR UPPER ARM (WCP)	Bent	-	*235.00 F
23	1	*O/S REAR SHOCK ABSORBER (BILSTEIN) (WCP)	Bent	-	*170.00 F
24	1	*O/S REAR SHOCK ABSORBER STOPPER (WCP)	Necessary	-	*45.00 F
25	1	*O/S REAR SHOCK ABSORBER MOUNTING (WCP)	Bent	-	*150.00 F
26	1	*REAR STABILIZER BAR (WCP) (NPA)	Serviceable	-	*- F
27	1	*O/S REAR STABILIZER BAR LINKAGE (WCP)	Distorted	-	*140.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*REAR CROSS MEMBER (WCP) (NPA)	Serviceable	-	*- F
29	1		*O/S FRONT SHOCK ABSORBER (BILSTEIN) (WCP)	Bent	-	*250.00 F
30	1		*O/S FRONT SHOCK ABSORBER MOUNTING (WCP)	Bent	-	*70.00 F
31	1		*O/S FRONT SHOCK ABSORBER MOUNTING BEARING (WCP)	Necessary	-	*42.00 F
32	1		*O/S FRONT SHOCK ABSORBER STOPPER (WCP) (NPA)	Serviceable	-	*- F
33	1		*O/S FRONT SHOCK ABSORBER COVER (WCP) (NPA)	Serviceable	-	*- F
34	1		*O/S FRONT KNUCKLE ARM (WCP)	Bent	-	*900.00 F
35	1		*O/S FRONT WHEEL BEARING (WCP)	Necessary	-	*420.00 F
36	1		*O/S FRONT LOWER ARM (WCP)	Distorted	-	*300.00 F
37	1		*FRONT STABILIZER BAR (WCP) (NPA)	Serviceable	-	*- F
38	1		*O/S FRONT STABILIZER BAR LINKAGE (WCP)	Distorted	-	*150.00 F
39	1		*STEERING RACK PINION (WCP) (NPA)	Repair	-	*- F
40	1		*O/S FRONT TIE ROD (WCP) (NPA)	Serviceable	-	*- F
41	1		*O/S FRONT TIE ROD END (WCP) (NPA)	Serviceable	-	*- F
42	1		*DRIVER SEAT BELT (WCP)	Jammed	-	*1,800.00 F
43	1		*DRIVER SEAT BELT BUCKLE (WCP) (NPA)	Serviceable	-	*- F
44	1		*ROOF TOP PANEL INNER TRIM LINING (WCP)	Torn	-	*1,900.00 F
45	1		*O/S ROOF TOP AIRBAG (WCP)	Burst	-	*2,800.00 F
46	1		*O/S AIRBAG SENSOR (WCP) (NPA)	Necessary	-	*- F
47	1		*AIRBAG CONTROL UNIT (WCP)	Necessary	-	*2,000.00 F
48	1		*O/S REAR FENDER TOP GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
49	1		*O/S REAR FENDER TOP GLASS DAMPING SEAL	Necessary	20.00 FS	*20.00 FS
50	1		*O/S REAR TYRE (NPA)	Serviceable	-	*- FS
51	1		*O/S REAR SPORT RIM	Dented	2,000.00 FS	*2,000.00 FS
52	1		*O/S FRONT TYRE (NPA)	Serviceable	-	*- FS
53	1		*O/S FRONT SPORT RIM	Dented	2,000.00 FS	*2,000.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$)	4,060.00	25,672.00
+ Margin on L,N Items 15.00/15.00% (\$)	0.00	3,241.80
Total Parts (\$)	4,060.00	28,913.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	New	1,500.00	1,200.00
2	TO REMOVE AND REFIT O/S REAR FENDER TOP GLASS AND CONDUCT WATER LEAK TEST.	New	120.00	50.00
3	TO FOCUS HEADLAMPS. TO CHECK WIRING AND LIGHTING OPERATION.	New	50.00	20.00
4	TO REMOVE AND REFIT FRONT SEAT ASSY TRIMBOARD AND CARPET TO FACILITATE REPAIRING WORKS.	New	120.00	120.00
5	TO APPLY UNDERSEALING.	New	120.00	60.00
6	TO REMOVE DOORS FITTINGS.	New	160.00	80.00
7	TO DISMANTLE AND CHECK FRONT UNDER-CARRIAGES. TO REPLACE AFFECTED PORTIONS.	New	240.00	200.00
8	TO CONDUCT FRONT WHEEL ALIGNMENT TEST.	New	120.00	100.00
9	TO DISMANTLE AND CHECK REAR UNDER-CARRIAGES. TO REPLACE AFFECTED PORTIONS.	New	240.00	120.00
10	TO REMOVE AND RENEW AIRBAG SENSORS SEAT BELTS ASSY, TO REWIRING AND RE-SETTING PROGRAM.	New	380.00	653.80
11	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	1,800.00	1,320.00
Gross Labour Cost (S\$)			4,850.00	3,923.80

Report was unsubmitted during this print-out.

< END OF ESTIMATES >