

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDM 4245T

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|---------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | RUBBER VALVE (SN) | NECESSARY | 1.73 | 1.73 |
| 1 | CONTR ARM (SN) | SERVICEABLE | 772.21 | - |
| 1 | WHEEL BEARING HOUSING (SN) | SERVICEABLE | 1,092.25 | - |
| 1 | CONTR ARM JOINT (SN) | SERVICEABLE | 224.79 | - |
| 1 | FENDER LINER (SN) | DEFORMED | 248.08 | 248.08 |
| 1 | WHEEL BEARING (SN) | SERVICEABLE | 815.40 | - |
| 1 | 17" JAMARA RIM ONLY BRIGHT CHROME(SN) | SCRATCHED | 1,404.66 | 1,404.66 |
| 1 | BUMPER SIDE BRACKET LH (SN) | SERVICEABLE | 24.88 | - |
| 1 | BUMPER SIDE BRACKET RH (SN) | NECESSARY | 24.88 | 24.88 |
| 1 | FRT BUMPER (SN) | SCRATCHED | 1,479.91 | 1,479.91 |
| 1 | FOG LAMP GRILLE CHROM RH (SN) | SERVICEABLE | 99.72 | - |
| 1 | RHS BUMPER INNER BRACKET (SN) | NECESSARY | 27.06 | 27.06 |
| 1 | NOZZLE COVER RH (SN) | SCRATCHED | 82.59 | 82.59 |
| 1 | FENDER RH (SN) | BUCKLED | 965.20 | 965.20 |
| 1 | RHS FENDER BRACKET (SN) | NECESSARY | 31.23 | 31.23 |
| 1 | FOG LAMP GRILLE RH (SN) | SERVICEABLE | 172.89 | - |
| 1 | FOG LIGHT RH (SN) | SERVICEABLE | 319.03 | - |
| 1 | NOZZLE RH (SN) | MISSING | 43.65 | 29.10 |
| 1 | NOZZLE CYLINDER RH (SN) | SERVICEABLE | 255.54 | - |
| 1 | HEADLAMP RH (SN) | SCRATCHED | 3,002.55 | 3,002.55 |
| 1 | HOUSING (SN) (ADDITIONAL) | NECESSARY | 9.97 | 9.97 |
| | | | 11,098.22 | 7,306.96 |
| | <u>LABOUR</u> | | | |
| | LABOUR. | | 4,200.00 | 1,680.00 |
| | SPRAY PAINT. | | 3,200.00 | 2,400.00 |
| | PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC. | | 480.00 | 480.00 |
| | ELECT WIRING & MECH COMPO. | | 280.00 | 280.00 |
| | R&R RIM & BALANCE. | | 50.00 | 50.00 |
| | R&R FRT U/CARRIAGE. | NOT NECESSARY | 2,520.00 | - |

Report Ref No. CS/TP17024626/R1vbe2



RECOMMENDED COST OF REPAIRS

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

12,556.96

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|------------------------|-----------|-------------------------------|-------------------|
| | B & P WHEEL ALIGNMENT. | | 360.00 | 360.00 |
| | | | 11,090.00 | 5,250.00 |
| | GRAND TOTAL | | 22,188.22 | 12,556.96 |

Report Ref No. CS/TP17024626/R1vbe2

MKB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

X.S.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.