

INS. CASE OWNER:

Joel

CCG/1EQ17024628 / Kws32

LKK:

IDAC:

ASSIGNMENT

Surveyor:

KENNETH

DOI:

22/12/17

Date / Time:

22/12/17

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : PA 95705

Name of Insured : LOI WEE QUAN

Insured Tel No. : HP: 9026 8556

Excess Sec II : SS D.O.A : 21/12/17

Is driver the owner? YES / NO) Nature of Accident :

Claim No. : DM17H002913-EC

Policy No. : DMBPH216-000117

Make / Model : KING LONG XMQ6118K MMC-88

Place of Accident : ALONG SLE TOWARDS CTE

If NO, Driver Name / Age :

Driver Tel No. :

(V/L) YES / NO)

OI GIA REPORT YES / NO ; TP GIA REPORT YES / NO

Insured Liability : % Final ? Yes / No

YN 8902Y

INSRS:
WSP: Chng Hoe (Driver)
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time

YN 8902Y - X

PA 95705 - CCG/AXN14011705/R161333 DUA: 20/12/17

25/12/17

25/1/18

7/9/18

5/4/19

10/4/19

confirm accident details inform TP claim. agree to settle and aware NCP will be affected. Water and out

File pass to typist type report

Email to EA to seek mandate

email from EQ approve mandate

STAGE DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time: 24/01/18

Sent By: Shirley Hiew

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. : 27

If NO or B 28, Ass. Lia :

Repair Cost:

S\$ 14070.50

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

3120.00 (\$20 x 76 days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

S\$

8.00

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$ 17198.50

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 17198.50

Name 1:

Cheng Hoe Motor Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

ASS. REC. BY:

REF:

EQ1

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

20

days

Res.: _____

Yes or No

Lum Sum: _____

20

%

3 Val.: _____

Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

YN 89034

Yr Regn: _____

08, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

INZU NPR 851451 2999

Colour: _____

white

A/C: Insured / Std / NI / NA

Sp. Reading: _____

75 462

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

JAA NPR 851451-7100 481

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

R: _____

195/85R16 101

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. _____

6

mm

R/Bal. _____

6

6

mm

L/Bal. _____

6

mm

L/Bal. _____

6

6

mm

D.O.A. _____

21/12/17

D.O.A. _____

22/12/17

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/2 After pass to Customer

21 Sep 8 13, 1500h Confirmed Efile

200

(20+6x120)

(20+6x120)

39.1)

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S - RS - SI

Photos

Others

Add Fee: _____



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format: _____

Lump Sum / I.B.I: (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC6/EQI17024628/Kws3

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 28-12-2017



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PA 9570S	Veh. Inspected	YN 8903Y
Policy No.	DMBPHQ16-000117	Coverage (\$)	0.00
Claim No.	DM17HO02913-EC	Excess (\$)	0.00
Assign From		Assign Date	28/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	21/12/2017	Inspection Date	22/12/2017
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

YN8903Y

TP/EG

M/S : EQ INSURANCE CO LTD
 22 GEMMILL LANE
 SINGAPORE 069257

Claim No: ES1791439
 Estimate No: ES1791439
 Date: 22 Dec 2017
 Policy No: 5072900554-02
 Veh Reg No: YN8903Y
 Make/Model: ISUZU NPR85UH5A
 Chassis No: JAANPR85HF7100461
 Engine No: 4JJ11Z6491
 Reg. Date: 18/08/2015

TEL: 62239433
 ATTN: Motor Claim Department
 WS Ref: TP-EQ
 Claim Type: Third Party
 Accident Date: 21/12/2017
 TP Veh Reg No: PA9570S

FAX: 62243903

Not Noted
1/12/17
Passing After Pain

Estimate Repair Cost to Vehicle No : YN8903Y

Pages: 1/2

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>

Cost Plus

1 CABIN REAR PANEL	984.00	1 PCS	984.00	
2 CABIN REAR PANEL INNER GARNISH	88.00	1 PCS	88.00	
3 CABIN REAR WINDSCREEN RUBBER	65.00	1 PCS	65.00	
4 CABIN RH DOOR REAR PILLAR OUTER	215.00	1 PCS	215.00	
5 AIR FILTER HOUSING	182.00	1 PC	182.00	X
6 AIR-FILTER DUCTING TOP	238.00	1 PC	238.00	
7 AIR-FILTER DUCTING CENTRE	76.00	1 PC	76.00	
8 REAR MUD FLAPS	17.00	2 PCS	34.00	
9 REAR MUD GUARDS	60.00	2 PCS	120.00	
			2,002.00	
	Add 20%		400.40	2,402.40

Special Net

10 TAILGATE	1,600.00	1 PC	1,600.00	
11 TAILGATE SPEED LIMIT STICKER	10.00	2 PCS	20.00	
12 REAR STEP MEMBER	180.00	1 PCS	180.00	
13 'U' BOLTS	60.00	6 PCS	360.00	
14 REAR TRUCK WOODEN CHASSISS MEMBER	1,200.00	2 PCS	2,400.00	
15 REAR TRUCK WOODEN FLOOR BOARD	200.00	8 PCS	1,600.00	
16 REAR TRUCK WOODEN CROSS MEMBER	150.00	8 PCS	1,200.00	
17 REAR WOODEN RAILING	450.00	1 PCS	450.00	
18 REAR TRUCK FRONT GATE	1,500.00	1 PCS	1,500.00	X
19 REAR MUDGUARDS	150.00	2 PCS	300.00	
20 CANVAS	1,200.00	1 PCS	1,200.00	X
21 RH SAFETY BAR	450.00	1 PCS	450.00	X
			11,260.00	11,260.00

YN8903Y
TP/EQ

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : EQ INSURANCE CO LTD
22 GEMMILL LANE
SINGAPORE 069257

TEL: 62239433
ATTN: Motor Claim Department
WS Ref: TP-EQ
Claim Type: Third Party
Accident Date: 21/12/2017
TP Veh Reg No: PA9570S

FAX: 62243903

*Not authorized
like B?
Running After Policy*

Estimate No: ES1791439/WS
Date: >>Dec 2017
Policy No: 5072900554-02
Veh Reg No: YN8903Y
Make/Model: ISUZU NPR85UH5A
Chassis No: JAANPR85HF7100461
Engine No: 4JJ11Z6491
Reg. Date: 18/08/2015

Estimate Repair Cost to Vehicle No :YN8903Y

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 CABIN REAR PANEL	1,188.000	1 PCS	1,188.00	✓
2 CABIN REAR PANEL INNER GARNISH	110.4000	1 PCS	110.40	?
3 CABIN REAR WINDSCREEN RUBBER	81.6000	1 PCS	81.60	✓
4 CABIN RH DOOR REAR PILLAR OUTER	268.8000	1 PCS	268.80	✓
5 AIR FILTER HOUSING	228.0000	1 PC	228.00	?
6 AIR-FILTER DUCTING TOP	298.8000	1 PC	298.80	?
7 AIR-FILTER DUCTING CENTRE	96.0000	1 PC	96.00	?
8 REAR MUD FLAPS	24.0000	2 PCS	48.00	?
9 REAR MUD GUARDS	78.0000	2 PCS	156.00	?
			2,475.60	2,475.60
Special Net				
10 TAILGATE	1,600.000	1 PC	1,600.00	✓
11 TAILGATE SPEED LIMIT STICKER	10.0000	2 PCS	20.00	✓
12 REAR STEP MEMBER	180.0000	1 PCS	180.00	✓
13 'U' BOLTS	60.0000	6 PCS	360.00	✓
14 REAR TRUCK WOODEN CHASSISS MEMBER	1,200.000	2 PCS	2,400.00	✓
15 REAR TRUCK WOODEN FLOOR BOARD	200.0000	8 PCS	1,600.00	✓
16 REAR TRUCK WOODEN CROSS MEMBER	150.0000	8 PCS	1,200.00	✓
17 REAR WOODEN RAILING	450.0000	1 PCS	450.00	✓
18 REAR TRUCK FRONT GATE	1,500.000	1 PCS	1,500.00	?
19 REAR MUDGUARDS	150.0000	2 PCS	300.00	?
20 CANVAS	1,200.000	1 PCS	1,200.00	?
21 RH SAFETY BAR	450.0000	1 PCS	450.00	?
			11,260.00	11,260.00
Labour				
22 TOWING (BILL ATTACHMENT)	80.0000	1 LA	80.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : EQ INSURANCE CO LTD
22 GEMMILL LANE
SINGAPORE 069257

TEL: 62239433 FAX: 62243903
ATTN: Motor Claim Department
WS Ref: TP-EQ
Claim Type: Third Party
Accident Date: 21/12/2017
TP Veh Reg No: PA9570S

Estimate No: ES1791439/WS
Date: 22 Dec 2017
Policy No: 5072900554-02
Veh Reg No: YN8903Y
Make/Model: ISUZU NPR85UH5A
Chassis No: JAANPR85HF7100461
Engine No: 4JJ11Z6491
Reg. Date: 18/08/2015

Estimate Repair Cost to Vehicle No :YN8903Y

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
23 REMOVE AND REFIX REAR CANOPY ASSY, CANVAS, TOOL BOX ASSY, SAFETY BAR, REAR WOODEN TRUCK, MAIN CHASSISS, CROSS MEMBER, FLOOR BOARD, REAR METAL FLOOR BOARD, TAILGATE AND FRONT GATE, 'U' BOLT AND REALIGN REAR TRUCK POSITION.	2,500.000	1 LA	2,500.00	1800
24 REMOVE AND REFIX REAR WINDSCREEN GLASS	60.0000	1 LA	60.00	✓
25 REMOVE AND REFIX SEAT, CARPET, TOP ROOF LINING, SAFETY BELT, ETC (TO REMOVE CABIN REAR PANEL)	120.0000	1 LA	120.00	✓
26 REMOVE AND REFIX AIR-FILTER ASSY, TO CUTTING, WELDING AND RENEW CABIN REAR PANEL, KNOCK AND REPAIR CABIN REAR PANEL REINFORCEMENT, STRAIGHTEN REPAIR CABIN MOUNTING BRACKET AND DOOR REAR PILLAR OUER, MAIN CHASSISS AND REALIGN CABIN POSITION, INCLUDING REMO	2,300.000	1 LA	2,300.00	2000
27 PUTTY AND RESPRAY ON CABIN REAR PANEL (INNER OUTER)TOP ROOF LINING, DOOR REAR PILLAR, TAILGATE, FRONT GATE, REAR WOODEN RAILING AND ALL AFFECTED AREA.	1,800.000	1 LA	1,800.00	1400
28 REMOVE AND REFIX REAR WARNING LIGHTS, CHECK WIRING AND RESET SYSTEM	100.0000	1 LA	100.00	60
			6,960.00	6,960.00
			Total	S\$ 20,695.60
			Add GST @ 7%	1,448.69
			Total Amount Payable	S\$ 22,144.29

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

20622.40
21499.20

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

84PP1

IN 8903Y

TP-EQ

M/S : EQ INSURANCE CO LTD
22 GEMMILL LANE
SINGAPORE 069257

TEL: 62239433 FAX: 62243903
ATTN: Motor Claim Department
WS Ref: TP-EQ
Claim Type: Third Party
Accident Date: 21/12/2017
TP Veh Reg No: PA9570S

Claim No: ES1791439
Estimate No: ES1791439/WS
Date: 13 Jan 2018
Policy No: 5072900554-02
Veh Reg No: YN8903Y
Make/Model: ISUZU NPR85UH5A
Chassis No: JAANPR85HF7100461
Engine No: 4JJ11Z6491
Reg. Date: 18/08/2015

Estimate Repair Cost to Vehicle No : YN8903Y

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary 1				
Cost Plus				
1 CYLINDER HEAD COVER	180.00	1 PCS	CM 180.00	—
2 CYLINDER HEAD COVER GASKET	27.00	1 PCS	M 27.00	—
3 CYLINDER HEAD FUEL HOSE RUBBER	7.00	3 PCS	M 21.00	—
4 CYLINDER HEAD MOUNTING RUBBER	5.00	14 PCS	M 70.00	—
5 CYLINDER HEAD COVER SEAL NOZZLE	18.00	4 PCS	M 72.00	—
6 CYLINDER HEAD CAM END	11.00	4 PCS	M 44.00	✓
			414.00	
	Add 20%		82.80	496.80
Labour				
7 REMOVE AND REFIX CYLINDER HEAD COVER, FUEL HOSE RUBBER, MOUNTING RUBBER, SEAL NOZZLE AND RESET ENGINE	0.00	1 LA	380.0000	2501
				380.00

Total	S\$ 876.80
GST Amount	S\$ 61.38
Total Amount payable	S\$ 938.18

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

11572.4



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC6/EQI17024628/Kws3

Date: 24.01.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

PRELIMINARY ADVICE OF VEHICLE NO.

YN 8903Y


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 22.12.2017 at the premises of M/s Cheng Hoe Motor Pte Ltd (Yishun) and have the following to report:-

Workshop Estimate Amount	: S\$	20,695.60
Revised Estimate Amount	: S\$	15,216.40
"Check" Items Amount	: S\$	4,039.20
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 16.0 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

1188.00	110.40	1600.00	1500.00	80.00	700.00
81.60	228.00	20.00	1200.00	1800.00	300.00
268.80	298.80	180.00	450.00	60.00	400.00
48.00	96.00	360.00		120.00	40.00
	156.00	2400.00		2000.00	
		1600.00		1400.00	
		1200.00		60.00	
		450.00			
		300.00		5520.00	

8110.00

889.20

3150.00

1440.00

1586.40

2475.60

1586.40

889.20

0.00

0.00

0.00

1586.40

8110.00

5520.00

15216.40

110.40

228.00

298.80

96.00

156.00

1500.00

1200.00

450.00

4039.20

}

CHECK ITEM

8/10/21 checked 23/1/16

張建福 (機件) 拖車服務
TEO KIAN HOCK (CHEE CHEN) TOWING SERVICES

Mailing Address: 40 Cactus Road, Singapore 809597

Tel: 6858 4067 Fax: 6854 0407

廿四小時服務 24 HOURS SERVICE

Reg. No. 413736/00L

CASH SALE / WORK ORDER

No. 17334

Date: 26.12.17

寶號

Messrs:

CHENG HOE

車號

Vehicle No:

YN 8903 Y

車型

Model No:

14' Van

由

From:

Wood on FS

到

To:

38 Woodlands

時間 (日/夜)

Time (day/night):

其他

Others:

CASH \$:

80.00

CHEQUE:

經手人

Authorised by:



收貨人

Received by:

注意: 本公司對所拖之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

Shirley Hiew (LKK Auto)

From: Elaine Cheong <elaine.cheong@eqinsurance.com.sg>
Sent: Thursday, 25 January 2018 11:19 AM
To: Shirley Hiew (LKK Auto)
Cc: Vivian Lau (LKKAuto); Joy Irene (LKKAuto); Admin A
Subject: RE: Direct Settlement - Accident Involving PA9570S (OI : EQI - DM17HO02913-EC) AND YN8903Y (TP : LKK REF - CC6/EQI17024628/Kws3) on 21/12/2017
Attachments: OI - PA9570S.PDF

Dear Shirley,

Attached a copy of our insured's GIA report for your perusal.

Regards,

Elaine Cheong
Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

www.eqinsurance.com.sg

A Member of Citistate



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Wednesday, January 24, 2018 10:29 AM
To: Elaine Cheong
Cc: Vivian Lau (LKKAuto); Joy Irene (LKKAuto); Admin A
Subject: Direct Settlement - Accident Involving PA9570S (OI : EQI - TBA) AND YN8903Y (TP : LKK REF - CC6/EQI17024628/Kws3) on 21/12/2017

WITHOUT PREJUDICE

Dear Elaine,

We refer to the above matter.

We have inspected TP vehicle YN 8903Y at M/s Cheng Hoe Motor Pte Ltd - Yishun.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vivian and she can be contacted at DID: 6841 8625.

To check availability of the case handler , you may contact the undersigned.

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Pfione: 6366-0055 | email: ShirleyHiew@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC6/EQ117024628/Kwa3s2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 23-04-2019



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PA 9570S	Veh. Inspected	YN 8903Y
Policy No.	DMBPHQ16-000117	Coverage (\$)	0.00
Claim No.	DM17HO02913-EC	Excess (\$)	0.00
Assign From		Assign Date	22/12/2017

2. Vehicle Particulars & Condition

Make & Model	ISUZU NPR85UH5A	c.c	2999
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JAANPR85HF7100461	Colour	WHITE
Odometer	75462	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/85R16	BRIDGESTONE	6 mm
L/H Front Tyre	195/85R16	BRIDGESTONE	6 mm
R/H Rear Tyre	195/85R16 (D)	BRIDGESTONE	6/6 mm
L/H Rear Tyre	195/85R16 (D)	BRIDGESTONE	6/6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/12/2017	Inspection Date	22/12/2017
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	20 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 8903Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	CABIN REAR PANEL (WCP)	BENT	984.00	984.00
1	CABIN REAR PANEL INNER GARNISH (WCP)	DEFORMED	88.00	88.00
1	CABIN REAR WINDSCREEN RUBBER (WCP)	NECESSARY	65.00	65.00
1	CABIN RH DOOR REAR PILLAR OUTER (WCP)	BENT	215.00	215.00
1	AIR FILTER HOUSING (WCP)	SERVICEABLE	182.00	-
1	AIR-FILTER DUCTING TOP (WCP)	DENTED	238.00	238.00
1	AIR-FILTER DUCTING CENTRE (WCP)	DENTED	76.00	76.00
2	REAR MUD FLAPS @ \$17.00 (WCP)	DISTORTED / CUT	34.00	34.00
2	REAR MUD GUARDS @ \$60.00 (WCP)	BUCKLED	120.00	120.00
1	CYLINDER HEAD COVER (WCP) (ADDITIONAL)	CRACKED	180.00	180.00
1	CYLINDER HEAD COVER GASKET (WCP) (ADDITIONAL)	NECESSARY	27.00	27.00
3	CYLINDER HEAD FUEL HOSE RUBBER @ \$7.00 (WCP) (ADDITIONAL)	NECESSARY	21.00	21.00
14	CYLINDER HEAD MOUNTING RUBBER @ \$5.00 (WCP) (ADDITIONAL)	NECESSARY	70.00	70.00
4	CYLINDER HEAD COVER SEAL NOZZLE @ \$18.00 (WCP) (ADDITIONAL)	NECESSARY	72.00	72.00
4	CYLINDER HEAD CAM END @ \$11.00 (WCP) (ADDITIONAL)	NECESSARY	44.00	44.00
	COST PLUS 20%		483.20	446.80
			2,899.20	2,680.80
SPECIAL NETT ITEMS				
1	TAILGATE (SN)	BENT	1,600.00	1,600.00
2	TAILGATE SPEED LIMIT STICKER @ \$10.00 (SN)	NECESSARY	20.00	20.00
1	REAR STEP MEMBER (SN)	CRACKED	180.00	180.00
6	'U' BOLT @ \$60.00 (SN)	BENT	360.00	360.00
2	REAR TRUCK WOODEN CHASSIS MEMBER @ \$1200.00 (SN)	CRACKED	2,400.00	2,400.00
8	REAR TRUCK WOODEN FLOOR BOARD @ \$200.00 (SN)	CRACKED	1,600.00	1,600.00
8	REAR TRUCK WOODEN CROSS MEMBER @ \$150.00 (SN)	CRACKED	1,200.00	1,200.00
1	REAR WOODEN RAILING (SN)	CRACKED	450.00	450.00
1	REAR TRUCK FRONT GATE (SN)	TO REPAIR SEE LABOUR	1,500.00	-

Report Ref No. CC6/EQ117024628/Kwa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR MUDGUARDS @ \$150.00 (SN)	BUCKLED / CUT	300.00	300.00
1	CANVAS (SN)	TO REPAIR SEE LABOUR	1,200.00	-
1	RH SAFETY BAR (SN)	TO REPAIR SEE LABOUR	450.00	-
			11,260.00	8,110.00
	LABOUR			
	TOWING.		80.00	80.00
	REMOVE AND REFIX REAR CANOPY ASSY, CANVAS, TOOL BOX ASSY, SAFETY BAR, REAR WOODEN TRUCK, MAIN CHASSIS, CROSS MEMBER, FLOOR BOARD, REAR METAL FLOOR BOARD, TAILGATE AND FRONT GATE, 'U' BOLT AND REALIGN REAR TRUCK POSITION.		2,500.00	1,800.00
	REMOVE AND REFIX REAR WINDSCREEN GLASS.		60.00	60.00
	REMOVE AND REFIX SEAT, CARPET, TOP ROOF LINING, SAFETY BELT, ETC (TO REMOVE CABIN REAR PANEL)		120.00	120.00
	REMOVE AND REFIX AIR-FILTER ASSY, TO CUTTING, WELDING AND RENEW CABIN REAR PANEL, KNOCK AND REPAIR CABIN REAR PANEL REINFORCEMENT, STRAIGHTEN REPAIR CABIN MOUNTING BRACKET AND DOOR REAR PILLAR OUTER, MAIN CHASSIS AND REALIGN CABIN POSITION, INCLUSIVE OF THE REPAIR OF REAR TRUCK FRONT GATE, CANVAS AND RH SAFETY BAR.		2,300.00	2,000.00
	PUTTY AND RESPRAY ON CABIN REAR PANEL (INNER OUTER) TOP ROOF LINING, DOOR REAR PILLAR, TAILGATE, FRONT GATE, REAR WOODEN RAILING AND ALL AFFECTED AREA.		1,800.00	1,400.00
	REMOVE AND REFIX REAR WIRING LIGHTS, CHECK WIRING AND RESET SYSTEM.		100.00	60.00
	REMOVE AND REFIX CYLINDER HEAD COVER, FUEL HOSE RUBBER, MOUNTING RUBBER, SEAL NOZZLE AND RESET ENGINE.		380.00	250.00
			-	-
			-	-
			-	-
			7,340.00	5,770.00
GRAND TOTAL			21,499.20	16,560.80

Report Ref No. CC6/EQ117024628/Kwa3s2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			13,150.00
---	--	--	-----------

Report Ref No. CC6/EQI17024628/Kwa3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.