



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

General Details

Involving
TPVD HYUNDAI ELANTRA (SKZ2009X)

Date of Loss
December 22, 2017

Time of Loss
9.30

Loss Description
YK5508R (INSD) HIT REAR OF SKZ2009X (TP)

Comment

Workshop Details

Total Rebate Amount

0

Nett Loss Amount
\$0.00

Assigned Workshop
LKK AUTO CONSULTANTS PTE LTD (TP)

Target Date of Completion *

02/18/2018

Days of work completion *

54

« Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Vehicle & Driver Details

Vehicle Registration#
SKZ2009X

Registration State
SINGAPORE

Mileage
29785

Purchase Date
mm/dd/yyyy

Registration Date *
01/13/2016

Age of Vehicle
1

CATEGORY	Manufacturing Year
POLICY INFORMATION	
ASSESSMENT INFORMATION	2015

CATEGORY	Make
POLICY INFORMATION	TPVD HYUNDAI
ASSESSMENT INFORMATION	HYUNDAI

POLICY INFORMATION

ELANTRA

ASSESSMENT INFORMATION

ELANTRA 1.6 AT ABS D/AB 2WD 4DR

CATEGORY

Type

POLICY INFORMATION

ASSESSMENT INFORMATION

CATEGORY

Type of Paint

POLICY INFORMATION

ASSESSMENT INFORMATION

CATEGORY

Chassis No

POLICY INFORMATION

ASSESSMENT INFORMATION

KMHDH41CMGU656804

CATEGORY

Engine No

POLICY INFORMATION

ASSESSMENT INFORMATION

G4FGFU069492

CATEGORY

Engine Capacity

POLICY INFORMATION

ASSESSMENT INFORMATION

1591

CATEGORY

Sum Insured

POLICY INFORMATION

CATEGORY	Market Value
POLICY INFORMATION	
ASSESSMENT INFORMATION	<div>0</div>

Driver Details

CATEGORY	Driver Name
FNOL INFORMATION	KIM CHIONG ONG
POST SURVEY INFORMATION	

CATEGORY	Date of Birth
FNOL INFORMATION	
POST SURVEY INFORMATION	<div>mm/dd/yyyy</div>

CATEGORY	Age
FNOL INFORMATION	0
POST SURVEY INFORMATION	

CATEGORY	Occupation
FNOL INFORMATION	Unknown
POST SURVEY INFORMATION	

CATEGORY	Education Qualification
FNOL INFORMATION	Other
POST SURVEY INFORMATION	

« **Assessment Details**

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Detailed Assessment

Inspection Date *

12/28/2017



Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Fair ▾

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Fair

Tyre Condition

Age of Tyres

Front Tyre Size

195/65R15

Front left side

HANKOOK6mm

Front right side

HANKOOK6mm

Spare wheel

Rear Tyre Size

195/65R15

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORTAXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Ref: CS3/ASM17024635/R1be2

Date: 08-02-2018



Code: ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	YK 5508R	Veh. Inspected	SKZ 2009X
Policy No.		Coverage (\$)	0.00
Claim No.	S7M00615	Excess (\$)	0.00
Assign From	VALE OH	Assign Date	26/12/2017

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI ELANTRA 1.6	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHDH41CMGU656804	Colour	GREY
Odometer	29785 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	HANKOOK	6 mm
L/H Front Tyre	195/65 R15	HANKOOK	6 mm
R/H Rear Tyre	195/65 R15	HANKOOK	6 mm
L/H Rear Tyre	195/65 R15	HANKOOK	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.	
--	--

5. General Information

Accident Date	22/12/2017	Inspect Date / Time	28/12/2017 (02:40 PM)
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

Report Ref No. CS3/ASM17024635/R1be2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

