

ASS. REC. BY:

REF:

AM

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 1.B.1% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHF6891 Yr Regn: 12, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Latitude C.C. 1985

Colour: M. white / R. AC: Insured / Std / NI / NA

Sp. Reading: 384173 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VFI ABL 15 AWC 281180

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Giti 215/60R16

R: Falken

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 28/12/17

Survey held at

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 28/12/17

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/12 Est not ready
29/12 1st call to Customer

1st CONSTRUCTION @ 1,060.68

CHECK REPAIRS @ 822.67

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trlp: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

Report Format :

Lump Sum / I.B.I. (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC3/ASM17024670/Khb3

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 29-12-2017



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLV 1262X	Veh. Inspected	SHF 699H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	29/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	26/12/2017	Inspection Date	28/12/2017
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHF699H - AXA*Not Authored
1-B.1
Refusing B4 claim***AAD1712-263**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF699H - JASMINE

VF1ABL15AUC281180

RENAULT

LATITUDE

26.12.2017

AXA**PART****LIST**

1	1	BUMPER COVER FRT	\$	CM 1,259.42	✓
2	1	BUMPER SPOILER FRT	\$	Sm 181.75	✓
3	1	BUMPER ABSORBER FRT	\$	CM 394.68	✓
4	1	BUMPER RETAINER FRT LH	\$	Sm 151.41	✓
5	1	BUMPER SUPPORT FRT LH	\$	Sm 123.88	✓
6	1	BUMPER RETAINER FRT RH	\$	Sm 150.77	✓
7	1	BUMPER SUPPORT FRT RH	\$	Sm 123.88	✓
8	1	BUMPER UNDERTRAY FRT	\$	Sm 472.83	✓
9	1	BUMPER GRILLE LOWER FRT	\$	Sm 266.80	✓
10	1	BUMPER FOG LAMP GRILLE LH	\$	Sm 207.21	✓
11	1	BUMPER FOG LAMP GRILLE RH	\$	Sm 207.21	✓
12	1	BUMPER BEAM FRT	\$	914.08	?
13	1	TOW COVER FRT	\$	Sm 28.61	} X
14	1	RADAIOR GRILLE	\$	Sm 1,707.78	
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	Sm 225.36	
16	1	RADAIOR GRILLE FRAME	\$	Sm 1,353.75	
17	1	FRAME FULL SUPPORT PANEL	\$	R 615.90	
18	1	FRAME FULL SUPPORT BRACKET	\$	R 89.79	
19	1	FRONT BRACE PANEL	\$	R 177.22	
20	1	HORN	\$	Sm 314.17	} X
21	1	HORN BRACKET	\$	R 40.45	
22	1	HEADLAMP LH	\$	mg-CM 1,184.43	
23	1	HEADLAMP PANEL FRT RH	\$	R 152.15	
24	1	BONNET	\$	R 1,941.63	
25	1	BONNET INSULATOR	\$	Sm 405.73	
26	1	BONNET STRUT LH	\$	Sm 88.61	
27	1	BONNET STRUT RH	\$	Sm 88.61	} X
28	1	BONNET HINGE LH	\$	R 348.31	
29	1	BONNET HINGE RH	\$	R 348.31	
30	1	BONNET LOCK	\$	R 305.48	
31	1	BONNET CABLE	\$	Sm 119.19	
32	1	BONNET CABLE COVER	\$	Sm 161.03	
33	1	BONNET SEAL OUTER	\$	Sm 92.36	
34	1	FENDER PANEL FRT LH	\$	R 783.83	

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-263**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO GST REG NO. 201019626G

SHF699H - AXA

35	1	WHEEL ARCH FRT LH	\$	sin	278.84
36	1	FENDER BRACKET LOWER LH	\$	sin	15.79
37	1	FENDER INSULATOR LH	\$	sin	130.84
38	1	AIR CLEANER LOWER	\$	sin	271.26
39	1	AIR CLEANER HOSE	\$	sin	76.14
40	1	A/C CONDENSER	\$	sin	2,020.37
41	1	A/C CONDENSER GARNISH LH UPPER	\$	sin	39.67
42	1	A/C CONDENSER GARNISH RH UPPER	\$	sin	39.67
43	1	A/C CONDENSER GARNISH LH	\$	sin	58.81
44	1	A/C CONDENSER GARNISH RH	\$	sin	59.60
45	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	sin	208.39
46	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	sin	658.72
47	1	A/C PIPE COMPRESSOR	\$	sin	334.29
48	1	A/C PIPE	\$	sin	658.72
49	1	A/C COMRPRESSOR	\$	sin	2,684.61
50	1	AIR COOLER	\$	sin	792.60
51	1	AIR INTERCOOLER HOSE (LONG)	\$	sin	1,014.13
52	1	AIR INTERCOOLER HOSE (Short)	\$	sin	375.14
53	1	TRANSMISSION COOLER	\$	sin	1,219.30
54	1	TRANSMISSION COOLER PAD	\$	sin	17.96
55	1	RADIATOR	\$	sin	1,202.20
56	2	RADIATOR STUD UPPER	\$	sin	14.41
57	2	RADIATOR BUSH UPPER	\$	sin	50.12
58	2	RADIATOR MTG LOWER	\$	sin	55.85
59	1	RADAITOR FAN COWLING	\$	sin	820.54
60	1	RADIATOR FAN MOTOR LH	\$	sin	967.36
61	1	RADIATOR FAN MOTOR RH	\$	sin	1,479.46
62	1	RADIATOR TANK	\$	sin	324.62
63	1	RADIATOR HOSE UPPER	\$	sin	240.56
64	1	RADIATOR HOSE LOWER	\$	sin	491.18
65	1	RADIATOR TANK HOSE	\$	sin	61.18
66	1	WINDSCREEN FRT	\$	sin	1,364.06
67	1	ROTARY SWITCH	\$	sin	1,253.11

TOTAL	\$	34,306.11
10%	\$	3,430.61
	\$	30,875.50

Specical Nett

1	1SET	RADAITOR GRILLE FRAME CLIP	\$	na	52.00 X
2	1SET	BUMPER CLIP FRT	\$	na	66.00
3	1	BUMPER BRACKET CLIP FRT LH	\$	na	12.00 X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50 X
5	1	BUMPER BRACKET CLIP FRT RH	\$	na	12.00 X
6	1	BUMPER SUPPORT CLIP FRT RH	\$	na	10.50 X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1712-263

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHF699H - AXA

7	1	TOW COVER FRT	\$	Sm	14.50	}	X
8	1SET	RADAIOR GRILLE SCREW	\$	na	16.00		
9	1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00		
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00		
11	2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00		
12	2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00		
13	1SET	WHEELARCH CLIP FRT LH	\$	na	30.50		
14	1	CAP HUB LH FRT	\$	Sm	35.00		
15	1	RIM LH FRT	\$	Sm	385.00		
16	1	TYRE LH FRT	\$	Sm	330.00		
17	1SET	Front licence plate with holder	\$	Sm	80.00	}	X
18	1	DOOR STICKER "6555-3333" LH	\$	na	80.00		
19	1	DOOR STICKER "6555-3333" RH	\$	na	80.00		

TOTAL	\$	1,403.00
TOTAL PARTS	\$	32,278.50

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 4,200.00 ²⁰⁰⁰

Towing Fees.

\$ na 120.00 X

To apply paint protection system (PPS) maintain and enhancement

\$ na 380.00 X

Putty and spray painting of the affected portion.

\$ 4,500.00 ²²⁰⁰

To rust-proofing of the affected areas.

\$ na 170.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ na 380.00 X

To check steering geometry and computer wheel alignment

\$ na 220.00 X

To transfer of tire, rim and on wheel balancing.

\$ na 170.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 ²⁰⁰

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ na 380.00 X

To replace, refix and top up coolant for radiator

\$ na 170.00 X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-263**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHF699H - AXATo vacuum, replace, refix and recharge air
condenser

\$

na 380.00 XTo vacuum, replace, refix and recharge Air
Intercooler

\$

na 170.00 XTo Transfer Of Fender Fittings, Attachments
And Perform Water Seepage Test.

\$

na 170.00 X**TOTAL \$ 11,580.00****Over All Total \$ 43,858.50**

< parts by parts > Repair Days

15 DAYS*2 day,*LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Jan 2018		25 Jan 2018 15:53 Edit Adj Rpt	S\$3,060.68 Edit Estimates	S\$3,060.68 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	NG CHIN CHYE, ID: S0141724Z, Tel: +6598387619		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHF699H	Date of Loss:	26/12/2017 13:00 - :59 [35 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / C0464735	Policy/Cover Note No.:	P2044993 (Comprehensive) Coverage: 22/12/2017 - 21/12/2018
Vehicle Reg. No. (Insured):	SLV1262X	Policy No. (Claimant):	
		Excess:	S\$5,000.00
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Vale Oh - 6880 4897]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 05/02/2018]		
Driver/Custodian (Insured):	NG CHIN CHYE (), NRIC: S0141724Z, Tel: +6598387619		
Adj Asg. Remarks:	TP-ARC PLS OBTAIN VIDEO FOOTAGE AS INSRD REPORTED STATIONARY		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AXA_SG (25/01/2018): New TP Assignment - C0464735/P2044993

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHF699H (C0464735)**
[SLV1262X]
TP
TRANS-CAB SERVICES PTE LTD
Dec 26 2017 1:00PM
[NG CHIN CHYE]
Trans-cab Auto Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser ▼	
Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/05/18 13:53	General View	Load JPG	✓
2	17/05/18 13:53	General View	Load JPG	✓
3	17/05/18 13:53	General View	Load JPG	✓
4	17/05/18 13:53	General View	Load JPG	✓
5	17/05/18 13:53	General View	Load JPG	✓
6	17/05/18 13:53	General View	Load JPG	✓
7	17/05/18 13:53	General View	Load JPG	✓
8	17/05/18 13:53	General View	Load JPG	✓
9	17/05/18 13:53	General View	Load JPG	✓
10	17/05/18 13:53	General View	Load JPG	✓
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/05/18 17:29	EMAIL	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/ASM17024670/KHB3S2

Date: 17/05/2018

REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	P2044993
Claimant Vehicle No :	SHF699H	Insured Vehicle No :	SLV1262X
Date of Loss:	26/12/2017	Nature of Claim:	TP
		Claim No:	C0464735

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHF699H	Engine No:	M9R8839C002450
Make & Model:	RENAULT LATITUDE, 2.0 CVT ABS (A)	Chassis No:	VF1ABL15AUC281180
Reg. Date:	31/12/2014 (Man. Year: 2014)	Odometer:	384173 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 8 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Giti 8 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,278.51	2,620.68	29,657.83	91.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,580.00	440.00	11,140.00	96.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	43,858.51	3,060.68	40,797.83	93.02
+ GST 7.00/7.00% (S\$)	3,070.10	214.25	2,855.85	93.02
Nett Amount (S\$)	46,928.61	3,274.93	43,653.68	93.02

INSPECTION

Date of Assignment:	25/01/2018	
Date Inspected:	28/12/2017	Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

5/17/2018

Adjuster Report

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS \$822.67 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 May 2018)
Parts:	143	RENAULT LATITUDE 2.0 CVT ABS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHF699H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT (CONSISTENT)	Cracked	1,259.42 FL	*1,259.42 FL
2	1		*BUMPER SPOILER FRT (CONSISTENT)	Serviceable	181.75 FL	*- FL
3	1		*BUMPER ABSORBER FRT (CONSISTENT)	Cracked	394.68 FL	*394.68 FL
4	1		*BUMPER RETAINER FRT LH (CONSISTENT)	Serviceable	151.41 FL	*- FL
5	1		*BUMPER SUPPORT FRT LH (CONSISTENT)	Serviceable	123.88 FL	*- FL
6	1		*BUMPER RETAINER FRT RH (CONSISTENT)	Serviceable	150.77 FL	*- FL
7	1		*BUMPER SUPPORT FRT RH (CONSISTENT)	Serviceable	123.88 FL	*- FL
8	1		*BUMPER UNDERTRAY FRT (CONSISTENT)	Serviceable	472.83 FL	*- FL
9	1		*BUMPER GRILLE LOWER FRT (CONSISTENT)	Serviceable	266.80 FL	*- FL
10	1		*BUMPER FOG LAMP GRILLE LH (CONSISTENT)	Serviceable	207.21 FL	*- FL
11	1		*BUMPER FOG LAMP GRILLE RH (CONSISTENT)	Serviceable	207.21 FL	*- FL
12	1		*BUMPER BEAM FRT (CONSISTENT)	*Check	914.08 FL	*- FL
13	1		*TOW COVER FRT (CONSISTENT)	Serviceable	28.61 FL	*- FL
14	1		*RADIATOR GRILLE (CONSISTENT)	Serviceable	1,707.78 FL	*- FL
15	1		*RADIATOR GRILLE BADGE RENAULT (CONSISTENT)	Serviceable	225.36 FL	*- FL
16	1		*RADIATOR GRILLE FRAME (CONSISTENT)	Serviceable	1,353.75 FL	*- FL
17	1		*FRAME FULL SUPPORT PANEL (CONSISTENT)	Repair	615.90 FL	*- FL
18	1		*FRAME FULL SUPPORT BRACKET (CONSISTENT)	Repair	89.79 FL	*- FL
19	1		*FRONT BRACE PANEL (CONSISTENT)	Repair	177.22 FL	*- FL
20	1		*HORN (CONSISTENT)	Serviceable	314.17 FL	*- FL
21	1		*HORN BRACKET (CONSISTENT)	Repair	40.45 FL	*- FL
22	1		*HEADLAMP LH (CONSISTENT)	Mtg Cracked	1,184.43 FL	*1,184.43 FL
23	1		*HEADLAMP PANEL FRT RH (CONSISTENT)	Repair	152.15 FL	*- FL
24	1		*BONNET (CONSISTENT)	Repair	1,941.63 FL	*- FL
25	1		*BONNET INSULATOR (CONSISTENT)	Serviceable	405.73 FL	*- FL
26	1		*BONNET STRUT LH (CONSISTENT)	Serviceable	88.61 FL	*- FL
27	1		*BONNET STRUT RH (CONSISTENT)	Serviceable	88.61 FL	*- FL
28	1		*BONNET HINGE LH (CONSISTENT)	Repair	348.31 FL	*- FL
29	1		*BONNET HINGE RH (CONSISTENT)	Repair	348.31 FL	*- FL
30	1		*BONNET LOCK (CONSISTENT)	Repair	305.48 FL	*- FL
31	1		*BONNET CABLE (CONSISTENT)	Serviceable	119.19 FL	*- FL
32	1		*BONNET CABLE COVER (CONSISTENT)	Serviceable	161.03 FL	*- FL
33	1		*BONNET SEAL OUTER (CONSISTENT)	Serviceable	92.36 FL	*- FL
34	1		*FENDER PANEL FRT LH (CONSISTENT)	Repair	783.83 FL	*- FL
35	1		*WHEELARCH FRT LH (CONSISTENT)	Serviceable	278.84 FL	*- FL
36	1		*FENDER BRACKET LOWER LH (CONSISTENT)	Serviceable	15.79 FL	*- FL
37	1		*FENDER INSULATOR LH (CONSISTENT)	Serviceable	130.84 FL	*- FL
38	1		*AIR CLEANER LOWER (CONSISTENT)	Serviceable	271.26 FL	*- FL
39	1		*AIR CLEANER HOSE (CONSISTENT)	Serviceable	76.14 FL	*- FL
40	1		*A/C CONDENSER (CONSISTENT)	Serviceable	2,020.37 FL	*- FL
41	1		*A/C CONDENSER GARNISH LH UPPER (CONSISTENT)	Serviceable	39.67 FL	*- FL
42	1		*A/C CONDENSER GARNISH RH UPPER (CONSISTENT)	Serviceable	39.67 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*A/C CONDENSER GARNISH LH (CONSISTENT)	Serviceable	58.81 FL	*- FL
44	1		*A/C CONDENSER GARNISH LH (CONSISTENT)	Serviceable	59.60 FL	*- FL
45	1		*A/C PIPE CONDENSER TO COMPRESSOR (CONSISTENT)	Serviceable	208.39 FL	*- FL
46	1		*A/C PIPE CONDENSER TO EXPENSION VALVE (CONSISTENT)	Serviceable	658.72 FL	*- FL
47	1		*A/C PIPE COMPRESSOR (CONSISTENT)	Serviceable	334.29 FL	*- FL
48	1		*A/C PIPE (CONSISTENT)	Serviceable	658.72 FL	*- FL
49	1		*A/C COMPRESSOR (CONSISTENT)	Serviceable	2,684.61 FL	*- FL
50	1		*AIR COOLER (CONSISTENT)	Serviceable	792.60 FL	*- FL
51	1		*AIR INTERCOOLER HOSE (LONG) (CONSISTENT)	Serviceable	1,014.13 FL	*- FL
52	1		*AIR INTERCOOLER HOSE (SHORT) (CONSISTENT)	Serviceable	375.14 FL	*- FL
53	1		*TRANSMISSION COOLER (CONSISTENT)	Serviceable	1,219.30 FL	*- FL
54	1		*TRANSMISSION COOLER PAD (CONSISTENT)	Serviceable	17.96 FL	*- FL
55	1		*RADIATOR (CONSISTENT)	Serviceable	1,202.20 FL	*- FL
56	2		*RADIATOR STUD UPPER (CONSISTENT)	Serviceable	14.41 FL	*- FL
57	2		*RADIATOR BUSH UPPER (CONSISTENT)	Serviceable	50.12 FL	*- FL
58	2		*RADIATOR MTG LOWER (CONSISTENT)	Serviceable	55.85 FL	*- FL
59	1		*RADIATOR FAN COWLING (CONSISTENT)	Serviceable	820.54 FL	*- FL
60	1		*RADIATOR FAN MOTOR LH (CONSISTENT)	Serviceable	967.36 FL	*- FL
61	1		*RADIATOR FAN MOTOR RH (CONSISTENT)	Serviceable	1,479.46 FL	*- FL
62	1		*RADIATOR TANK (CONSISTENT)	Serviceable	324.62 FL	*- FL
63	1		*RADIATOR HOSE UPPER (CONSISTENT)	Serviceable	240.56 FL	*- FL
64	1		*RADIATOR HOSE LOWER (CONSISTENT)	Serviceable	491.18 FL	*- FL
65	1		*RADIATOR TANK HOSE (CONSISTENT)	Serviceable	61.18 FL	*- FL
66	1		*WINDSCREEN FRT (CONSISTENT)	Serviceable	1,364.06 FL	*- FL
67	1		*ROTARY SWITCH (CONSISTENT)	Serviceable	1,253.11 FL	*- FL
68	1		*SET RADIATOR GRILLE FRAME CLIP (CONSISTENT)	Not Necessary	52.00 FS	*- FS
69	1		*SET BUMPER CLIP FRT (CONSISTENT)	Necessary	66.00 FS	*66.00 FS
70	1		*BUMPER BRACKET CLIP FRT LH (CONSISTENT)	Not Necessary	12.00 FS	*- FS
71	1		*BUMPER SUPPORT CLIP FRT LH (CONSISTENT)	Not Necessary	10.50 FS	*- FS
72	1		*BUMPER BRACKET CLIP FRT RH (CONSISTENT)	Not Necessary	12.00 FS	*- FS
73	1		*BUMPER SUPPORT CLIP FRT RH (CONSISTENT)	Not Necessary	10.50 FS	*- FS
74	1		*TOW COVER FRT (CONSISTENT)	Serviceable	14.50 FS	*- FS
75	1		*SET RADIATOR GRILLE SCREW (CONSISTENT)	Not Necessary	16.00 FS	*- FS
76	1		*SET BUMPER GRILLE LOWER CLIP (CONSISTENT)	Not Necessary	69.00 FS	*- FS
77	1		*SET FRAME FULL SUPPORT PANEL CLIP (CONSISTENT)	Not Necessary	70.00 FS	*- FS
78	2		*FRAME FULL SUPPORT PANEL NUT (CONSISTENT)	Not Necessary	20.00 FS	*- FS
79	2		*FRAME FULL SUPPORT PANEL STUD (CONSISTENT)	Not Necessary	30.00 FS	*- FS
80	1		*SET WHEELARCH CLIP FRT LH (CONSISTENT)	Not Necessary	30.50 FS	*- FS
81	1		*CAP HUB LH FRT (CONSISTENT)	Serviceable	35.00 FS	*- FS
82	1		*RIM LH FRT (CONSISTENT)	Serviceable	385.00 FS	*- FS
83	1		*TYRE LH FRT (CONSISTENT)	Serviceable	330.00 FS	*- FS
84	1		*SET FRONT LICENCE PLATE WITH HOLDER (CONSISTENT)	Serviceable	80.00 FS	*- FS
85	1		*DOOR STICKER 6555-3333 LH (CONSISTENT)	Not Necessary	80.00 FS	*- FS
86	1		*DOOR STCIKER 6555-3333RH (CONSISTENT)	Not Necessary	80.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	35,709.12	2,904.53
- List Item Discount on L Items 10.00/10.00% (\$\$)	3,430.61	283.85

Total Parts (\$\$)	32,278.51	2,620.68
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	4,200.00	200.00
2	TOWING FEES.	New	120.00	0.00
3	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	New	380.00	0.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	4,500.00	220.00
5	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	0.00
6	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	New	380.00	0.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	0.00
8	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	New	170.00	0.00
9	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	170.00	20.00
10	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	New	380.00	0.00
11	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR.	New	170.00	0.00
12	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER.	New	380.00	0.00
13	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR INTERCOOLER.	New	170.00	0.00
14	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
Gross Labour Cost (\$\$)			11,580.00	440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >