

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE

First capital insurance ltd

QUOTE NO :

ACCIDENT DATE : 22/12/2017, 10.30am

VRN :

SLE1156J

ATTN: MOTOR CLAIMS DEPT

MODEL :

TOYOTA WISH 1.8 CVT A

TP VRN :

SH8337J

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 Rear bumper / <i>Re</i>	1	\$ 595.90	\$ 595.90 /	
2 Rear bumper clips / <i>MSC</i>	10	\$ 5.50	\$ 55.00 /	
3 Rear bumper retainer outer LH/RH / <i>BT</i>	2	\$ 55.80	\$ 111.60 /	
4 Rear bumper retainer inner LH/RH / <i>BT</i>	2	\$ 95.80	\$ 191.60 /	
5 Reverse sensor <i>X NN</i> S/Nett	1	\$ 250.00	\$ 250.00 <i>X</i>	
6 End panel <i>X BT</i>	1	\$ 485.90	\$ 485.90 /	
7 End panel garnish <i>X NN</i>	1	\$ 285.70	\$ 285.70 <i>X</i>	
8 Spare tyre compartment <i>X NN</i>	1	\$ 650.50	\$ 650.50 <i>X</i>	
9 Tailgate / <i>MSC</i>	1	\$ 1,400.50	\$ 1,400.50 /	
10 Tailgate hinge LH/RH <i>X</i>	2	\$ 65.70	\$ 131.40 <i>X</i>	
11 Tailgate inner trim board <i>X NN</i>	1	\$ 450.80	\$ 450.80 <i>X</i>	
12 Tailgate lock <i>X</i>	1	\$ 425.30	\$ 425.30 <i>X</i>	
13 Tailgate weatherstripe <i>X</i>	1	\$ 320.70	\$ 320.70 <i>X</i>	
14 Tailgate logo "Toyota" / <i>MSC</i>	1	\$ 75.80	\$ 75.80 /	
15 Tailgate logo "Elegance" / <i>MSC</i>	1	\$ 75.80	\$ 75.80 /	
16 Tailgate logo "Valvematic" / <i>MSC</i>	1	\$ 85.70	\$ 85.70 /	
17 Tailgate reflector light LH/RH <i>X NN</i>	2	\$ 195.80	\$ 391.60 <i>X</i>	
18 Taillamp LH/RH <i>X</i>	2	\$ 344.50	\$ 689.00 <i>X</i>	
19 Tailgate windscreen moulding set / <i>MSC</i>	4	\$ 38.50	\$ 154.00 /	
20 Tailgate windscreen sealant / S/Nett <i>MSC</i>	1	\$ 45.00	\$ 45.00 /	
21 Rear number plate with casing <i>X S/Nett NN</i>	1	\$ 45.00	\$ 45.00 <i>X</i>	
22 Rear fender LH <i>X</i> Repair	1	Repair	Repair	
23 Rear fender RH <i>X NN</i> Repair	1	Repair	Repair	
24 Discount 25%	1	(\$1,644.20)	\$ (1,644.20)	
TOTAL			\$ 5,272.60	

2. Labor Charges

1 Panel beat, cut, weld, re-align & replace damaged parts of affected area	<i>1000</i> 700 - 900	\$ 2,500.00
2 Putty, blend and paint affected area	<i>900</i> 700	\$ 2,000.00
3 Check Wiring and ensure proper function	<i>30</i>	\$ 80.00
4 Remove & reinstall bumper sensors	<i>40</i>	\$ 120.00