

ASS. REC. BY:

REF:

CS/FCL170204708/Kabnz

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

CWS Aung Yin Min

of

FCL

Date/Time:

29/12/2017 2.18pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJM 8256 P

Insured:

SHC 7234K

at Workshop m/s

Giong Lee

Tel:

6453 1255

of

160 Sin Ming Drive #02-07

Policy No:

0-15072702MTSH

Claim No:

D17011876MTSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

25-12-2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

29/12/2017 2.29pm

Person Contacted:

Kwae Pin

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJM 8256P - X

SHC 7234K - CS/FCL170204708/Kabnz

DUA: 24/12/17

04/01/18 @ 4.36pm revised to Aung Yin Min by email.

15/3 / 1 Pm @ 90000 Car firm by email (net \$4992.81, 36%)

ASS. REC. BY:

REF: 1021Kenneth**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Sing Lee

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: STN 8256P Yr Regn: 09, 16Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Bmw X1 c.c. 1998Colour: N. Brown A/C: Insured / Std / NI / NASp. Reading: 24733 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAHS72030581061Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: _____

R: 225/50R18BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 25/12/17 D.O.I. 29/12/17

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2/1 File pass to Customer

RECEIVED 15 MAR 2018

Date/Time, File Pass to?

1) 15/3 Amir

Date/Time, File Return to?

2) _____

☐ : Preli. Report☐ : Final ReportDays Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$ 9000)3x15 = 45170 + 45505026341



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17024708/Kqb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 29-12-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 7234K	Veh. Inspected	SJM 8256P
Policy No.		Coverage (\$)	0.00
Claim No.	D17011876MFSH	Excess (\$)	0.00
Assign From	CWS (AUNG YIN MIN)	Assign Date	29/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	25/12/2017	Inspection Date	29/12/2017
Survey held at	160 SIN MING DRIVE #02-07		
Repairer	SIONG LEE MOTOR		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE I, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17011876MFSH

Date: 04 January 2018

Our Ref: CS/FCI17024708/Kqb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJM 8256P .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 29/12/2017 at the premises of M/s SIONG LEE, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>13,992.81</u> .
Revised Estimate Amount	: S\$ <u>10,147.26</u> .
"Check" Items Amount	: S\$ <u>1,749.56</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the front portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	27-12-2017	Our Ref No. D17011876MFSH
Accident Date	25-12-2017	Claim Type. Third Party
Insured Vehicle	SHC7234K	Third Party Vehicle. SJM8256P
Survey Location	160 SING MING DRIVE #02-07 AUTOCITY	
Contact Person.	MR TAN / MS KWEE PIN	
Contact No.	6453 1255/ 0	Fax No. 6552 0692
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SIONG LEE MOTOR	Attention. NIL
Cc : TP Solicitor	CHEONGHOH LAW CORPORATION	TP Solicitor Fax No. NA
Officer Incharge	AUNGYM	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/232383)



PRI Documents



Close



PRI Header Details

Claim No	D17011876MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & CH CORPO
Workshop Name	SIONG LEE MOTOR (Contact Person : MR TAN / MS KWEE PIN)	Survey Location & Contact Details	160 SING MING DRIVE #02-07 AUTOCITY Mobile: 0 , Phone: 6453 1255 , Fax: 6552 06 EmailId: MAIL@CHEONGHOH.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7234K	TP Vehicle No	SJM82!
PRI Recieved Date	28-12-2017 03:50:43 PM	Surveyor Appointed Date	29-12-2017 02:19:00 PM	Surveyor Accept Date	29-12-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	29-12-2017	Upload Survey Report *:	
-----------------------------	----------------------	----------------------	------------	-------------------------	----------------------

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 4 January, 2018 4:36 PM
To: 'Claim Workflow System'; assignments
Cc: AUNGYINMIN@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17011876MFSH/1
Attachments: CSFCI17024708Kqb.pdf

Dear Yin Min,

Enclosed herewith preliminary advice of SJM 8256P.

Wishes you a Happy New Year 2018

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 29 December, 2017 2:25 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: AUNGYINMIN@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011876MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

"Wishes you a Happy New Year 2018"

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Friday, 29 December, 2017 2:18 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; AUNGYINMIN@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17011876MFSH/1

Dear Sir/Mdm,



松 利 摩 哆 SIONG LEE MOTOR

Sin Ming Industrial Estate
Block 12 Sector B #01-73 Singapore 575656
Tel: 6457 0410, 6453 3478 Fax: 6552 0692

Company Reg No: 100838/00J

We specialise in repairing all kinds of vehicles and pre-inspection servicing.
We also undertake accident insurance claims for our customers.

28 December 2017

ATTN: MOTOR CLAIM DEPARTMENT

ATTN: TAY CHEE YEN

H/P: 9468 6918

Dear Sirs / Madam,

Accident Claim for Vehicle No.SJM 8256 P, Involving Vehicle No.SHC 7234 K
Accident on 25 DECEMBER 2017, AT SLIP ROAD OF CORPORATION RISE TO
CORPORATION ROAD.

With reference to the above vehicle. We hereby submit a list of parts required to be changed and append below the charges for changing and repairing ;

NO	SUPPLEMENTARY PARTS REPLACEMENT	QTY	LIST PRICE
1	FRONT BUMPER	1PC	\$ 799.10
2	FRONT BUMPER GRILLE (TOP)	2PCS	\$ 313.20
3	FRONT BUMPER GRILLE (LOWER)	1PC	\$ 156.60
	FRONT BUMPER SIDE GRILLE	2PCS	\$ 264.80
4	FRONT BUMPER LOWER GARNISH	1PC	\$ 190.25
5	FRONT BUMPER LOWER SIDE GARNISH	2PCS	\$ 60.00
6	FRONT BUMPER SPONGE	1PC	\$ 80.80
7	FRONT BUMPER REINFORCEMENT	1PC	\$ 410.95
8	FRONT BUMPER BRACKET	2PCS	\$ 256.80
	FRONT BUMPER CENTER GARNISH	1PC	\$ 293.00
10	FRONT TOWING COVER	1PC	\$ 40.20
11	FRONT FOG LAMP	2PCS	\$ 620.00
12	FRONT CENTER AIR DUCT	1PC	\$ 281.05
13	FRONT SIDE AIR DUCT	1PC	\$ 281.05
14	FRONT CROSS MEMBER	1PC	\$ 290.90
15	HEADLAMP	2PCS	\$ 5,398.30
16	FRONT TOP RUBBER	1PC	\$ 88.10
17	FRONT BONNET	1PC	\$ 1,683.85
18	FRONT BONNET HINGES	2PCS	\$ 210.20
19	FRONT BONNET EMBLEM	1PC	\$ 101.20
	TOTAL LIST PRICE		\$ 11,820.35
	LESS 10%		\$ (1,182.04)
	TOTAL AMOUNT		\$ 10,638.31

29/12/17 (12:10PM)
Not Authored
6/1/18
Recovery After Repairing
5 days

NO	PARTS REPLACEMENT	QTY	SPECIAL NETT PRICE
1	FRONT BUMPER SENSOR 2	4PCS	\$ 1,000.00 <i>Phan</i> 44
2	FRONT NUMBER PLATE	1PC	\$ 40.00 <i>Net</i> ✓
3	FRONT NUMBER PLATE HOLDER	1PC	\$ 67.25 <i>Net</i> ✓
4	FRONT NUMBER PLATE CASING	1PC	\$ 67.25 <i>Net</i> X
	TOTAL SPECIAL NETT PRICE		\$ 1,174.50

	LABOUR :	
1	LABOUR TO SPRAY PAINT	\$ 980.00 <i>600</i>
2	LABOUR TO PANEL BEATING	\$ 950.00 <i>550</i>
3	LABOUR TO FOCUS AND COMPUTER CHECKING	\$ 250.00 <i>120</i>
	TOTAL LABOUR	\$ 2,180.00
	TOTAL AMOUNT	\$ 13,992.81

THANK YOU

FROM:

SIONG LEE MOTOR

Mr Tan Leng Huat



松 利 摩 哆 SIONG LEE MOTOR

Sin Ming Industrial Estate
Block 12 Sector B #01-73 Singapore 575656
Tel: 6457 0410, 6453 3478 Fax: 6552 0692

Company Reg. No: 100838/00J

We specialise in repairing all kinds of vehicles and pre-inspection servicing.
We also undertake accident insurance claims for our customers.

28 December 2017

ATTN: MOTOR CLAIM DEPARTMENT

ATTN: TAY CHEE YEN

H/P: 9468 6918

Dear Sirs / Madam,

**Accident Claim for Vehicle No.SJM 8256 P, Involving Vehicle No.SHC 7234 K
Accident on 25 DECEMBER 2017, AT SLIP ROAD OF CORPORATION RISE TO
CORPORATION ROAD.**

With reference to the above vehicle. We hereby submit a list of parts required to be changed and append below the charges for changing and repairing ;

NO	SUPPLEMENTARY PARTS REPLACEMENT	QTY	LIST PRICE
1	FRONT BUMPER	1PC	\$ 799.10
2	FRONT BUMPER GRILLE (TOP)	2PCS	\$ 313.20
3	FRONT BUMPER GRILLE (LOWER)	1PC	\$ 156.60
	FRONT BUMPER SIDE GRILLE	2PCS	\$ 264.80
4	FRONT BUMPER LOWER GARNISH	1PC	\$ 190.25
5	FRONT BUMPER LOWER SIDE GARNISH	2PCS	\$ 60.00
6	FRONT BUMPER SPONGE	1PC	\$ 80.80
7	FRONT BUMPER REINFORCEMENT	1PC	\$ 410.95
8	FRONT BUMPER BRACKET	2PCS	\$ 256.80
9	FRONT BUMPER CENTER GARNISH	1PC	\$ 293.00
10	FRONT TOWING COVER	1PC	\$ 40.20
11	FRONT FOG LAMP	2PCS	\$ 620.00
12	FRONT CENTER AIR DUCT	1PC	\$ 281.05
13	FRONT SIDE AIR DUCT	1PC	\$ 281.05
14	FRONT CROSS MEMBER	1PC	\$ 290.90
15	HEADLAMP	2PCS	\$ 5,398.30
16	FRONT TOP RUBBER	1PC	\$ 88.10
17	FRONT BONNET	1PC	\$ 1,683.85
18	FRONT BONNET HINGES	2PCS	\$ 210.20
19	FRONT BONNET EMBLEM	1PC	\$ 101.20
	TOTAL LIST PRICE		\$ 11,820.35
	LESS 10%		\$ (1,182.04)
	TOTAL AMOUNT		\$ 10,638.31

*Not Authorised
6/1/18 @ 9000h
Recovery After Repair
5 days*

NO	PARTS REPLACEMENT	QTY	SPECIAL NETT PRICE
1	FRONT BUMPER SENSOR <i>2</i>	<i>4</i> PCS	\$ <i>Shan</i> 1,000.00 <i>44</i>
2	FRONT NUMBER PLATE	1PC	\$ <i>Net</i> 40.00 <i>✓</i>
3	FRONT NUMBER PLATE HOLDER	1PC	\$ <i>Net</i> 67.25 <i>✓</i>
4	FRONT NUMBER PLATE CASING	1PC	\$ <i>Net</i> 67.25 <i>X</i>
	TOTAL SPECIAL NETT PRICE		\$ 1,174.50

	LABOUR :	
1	LABOUR TO SPRAY PAINT	\$ <i>600</i> 980.00
2	LABOUR TO PANEL BEATING	\$ <i>550</i> 950.00
3	LABOUR TO FOCUS AND COMPUTER CHECKING	\$ <i>120</i> 250.00
	TOTAL LABOUR	\$ 2,180.00
	TOTAL AMOUNT	\$ 13,992.81

THANK YOU

FROM:

SIONG LEE MOTOR

Mr Tan Leng Huat

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17024708/Kqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 16-03-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7234K	Veh. Inspected	SJM 8256P	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17011876MFSH	Excess (\$)	0.00	
Assign From	AUNGYM	Assign Date	29/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W X1 (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WBAHS720305E81061	Colour	METALLIC BROWN	
Odometer	24733	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R18	BRIDGESTONE	7 mm	
L/H Front Tyre	225/50 R18	BRIDGESTONE	7 mm	
R/H Rear Tyre	225/50 R18	BRIDGESTONE	7 mm	
L/H Rear Tyre	225/50 R18	BRIDGESTONE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/12/2017	Inspection Date	29/12/2017	
Survey held at	160 SIN MING DRIVE #02-07			
Repairer	SIONG LEE MOTOR			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJM 8256P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	BUCKLED	799.10	799.10
2	FRONT BUMPER GRILLE (TOP)	SCRATCHED / CRACKED	313.20	313.20
1	FRONT BUMPER GRILLE (LOWER)	CRACKED	156.60	156.60
2	FRONT BUMPER SIDE GRILLE	O/S CUT	264.80	132.40
1	FRONT BUMPER LOWER GARNISH	CRACKED	190.25	190.25
2	FRONT BUMPER LOWER SIDE GARNISH	MTG DISTORTED	60.00	60.00
1	FRONT BUMPER SPONGE	CRACKED	80.80	80.80
1	FRONT BUMPER REINFORCEMENT	BENT	410.95	410.95
2	FRONT BUMPER BRACKET	TO REPAIR SEE LABOUR	256.80	-
1	FRONT BUMPER CENTER GARNISH	CRACKED	293.00	293.00
1	FRONT TOWING COVER	DENTED	40.20	40.20
2	FRONT FOG LAMP	MTG CRACKED	620.00	620.00
1	FRONT CENTER AIR DUCT	MTG CRACKED	281.05	281.05
1	FRONT SIDE AIR DUCT	SERVICEABLE	281.05	-
1	FRONT CROSS MEMBER	TO REPAIR SEE LABOUR	290.90	-
2	HEADLAMP	CUT	5,398.30	5,398.30
1	FRONT TOP RUBBER	SERVICEABLE	88.10	-
1	FRONT BONNET	BENT	1,683.85	1,683.85
2	FRONT BONNET HINGES	TO REPAIR SEE LABOUR	210.20	-
1	FRONT BONNET EMBLEM	NECESSARY	101.20	101.20
	LESS 10% DISCOUNT		-1,182.04	-1,056.09
			10,638.31	9,504.81
SPECIAL NETT ITEMS				
4	FRONT BUMPER SENSOR (SN)	SHORTED (2 PCS ONLY)	1,000.00	500.00
1	FRONT NUMBER PLATE (SN)	DENTED	40.00	40.00
1	FRONT NUMBER PLATE HOLDER (SN)	DENTED	67.25	67.25

Report Ref No. CS/FC117024708/Kqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT NUMBER PLATE CASING (SN)	NOT NECESSARY	67.25	-
			1,174.50	607.25
	LABOUR			
	LABOUR TO SPRAY PAINT.		980.00	600.00
	LABOUR TO PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BUMPER BRACKET,FRONT CROSS MEMBER AND FRONT BONNET HINGES.		950.00	550.00
	LABOUR TO FOCUS AND COMPUTER CHECKING.		250.00	120.00
			2,180.00	1,270.00
GRAND TOTAL			13,992.81	11,382.06
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,000.00

Report Ref No. CS/FC117024708/Kqbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.