

The insurer has given adjuster a maximum mandate of S\$25,000.00 to authorize directly on their behalf, but the adjuster has disabled direct offer mode.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG17024724/UQBN2
Date: 02/03/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	P27794111DMA
Claimant Vehicle No :	SGV9956J	Insured Vehicle No :	SJK8981P
Date of Loss:	29/12/2017	Nature of Claim:	TP
		Claim No:	543424

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGV9956J	Engine No:	R18A1705010
Make & Model:	HONDA STREAM, 1.8 (A)	Chassis No:	RN61004450
Reg. Date:	29/06/2007 (Man. Year: 2007)	Odometer:	123912 km
Colour:	White		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65R15	Rear Tyre Size:	205/65R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,863.70	5,407.20	9,456.50	63.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,910.00	2,840.00	2,070.00	42.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,773.70	8,247.20	11,526.50	58.29
Approved Total (Overridden) (S\$)		6,600.00		
(S\$)	19,773.70	6,600.00	13,173.70	66.62
+ GST 7.00/7.00% (S\$)	1,384.16	462.00	922.16	66.62
Nett Amount (S\$)	21,157.86	7,062.00	14,095.86	66.62

INSPECTION

Date of Assignment:	09/01/2018		
Date Inspected:	29/12/2017	Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	8.0 days		

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Mar 2018)
Parts:	M1-MPV	HONDA STREAM 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGV9956J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Not Necessary	1,488.10 F	*- FL
2	1		*REAR WINDSCREEN MOULDING	Not Necessary	48.50 F	*- FL
3	1		*TAILGATE	Badly Dented	903.20 F	*903.20 FL
4	1		*TAILGATE H LOGO	Necessary	35.00 F	*35.00 FL
5	1		*TAILGATE STREAM EMBLEM	Necessary	32.60 F	*32.60 FL
6	1		*TAILGATE OUTER GARNISH	Cracked	184.50 F	*184.50 FL
7	1		*TAILGATE INNER LOCK	Dented	109.50 F	*109.50 FL
8	1		*TAILGATE INNER TRIM BOARD	Deformed/Cracked	341.50 F	*241.50 FL
9	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*39.00 FL
10	1		*TAILGATE INNER TOP SIDE GARNISH	Not Necessary	162.30 F	*- FL
11	2		*TAILGATE DAMPERS	Not Necessary	490.20 F	*- FL
12	1		*TAILGATE REAR WIPER ARM	Not Necessary	235.30 F	*- FL
13	1		*TAILGATE REAR WIPER MOTOR	Not Necessary	488.50 F	*- FL
14	1		*TAILGATE WEATHERSTRIP	Twisted	116.90 F	*116.90 FL
15	1		*REAR BUMPER	Distorted	665.40 F	*588.40 FL
16	2		*REAR BUMPER SIDE RETAINERS	Bent	51.00 F	*51.00 FL
17	2		*REAR BUMPER BRACKETS	Bent	45.00 F	*45.00 FL
18	1		*SET REAR BUMPER CLIPS	Necessary	39.00 F	*39.00 FL
19	1		*REAR END PANEL	Badly Dented	306.10 F	*306.10 FL
20	1		*REAR END PANEL LOWER MEMBER	Badly Dented	182.30 F	*182.30 FL
21	1		*REAR END PANEL TOP GARNISH	Twisted	225.60 F	*184.60 FL
22	1		*REAR FLOOR PANEL	Crumpled/Buckled	912.30 F	*912.30 FL
23	2		*REAR FLOOR PANEL TOP BOARDS	Not Necessary	533.00 F	*- FL
24	1		*REAR FLOOR PANEL INNER TOP GARNISH	Not Necessary	341.10 F	*- FL
25	2		*TAILLAMPS	Cracked	677.60 F	*677.60 FL
26	2		*REAR FENDERS	Repair	1,782.20 F	*- FL
27	2		*REAR FENDER INNER TRIM BOARDS	Deformed/Cracked	790.40 F	*790.40 FL
28	1		*SET REAR FENDER INNER TRIM BOARD CLIPS	Necessary	60.00 F	*60.00 FL
29	2		*REAR FENDER QUARTER GLASS	Not Necessary	1,342.20 F	*- FL
30	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
31	1		*SET REAR REVERSE CAMERA	Shorted	500.00 FS	*380.00 FS
32	1		*REAR LICENCE PLATE W/HOLDER	Bent	50.00 FS	*40.00 FS
33	1		*SET REAR FLOOR PANEL INSULATOR	Necessary	200.00 FS	*120.00 FS
34	1		*REAR QUARTER GLASS SEALANT N/S	Not Necessary	50.00 FS	*- FS
35	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
36	1		*REAR EXHAUST	Repair	689.30 F	*- FL
37	2		*REAR EXHAUST MOUNTINGS	Not Necessary	90.00 F	*- FL
38	1		*REAR SPARE TYRE BRACKET	Bent	285.10 F	*285.10 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	14,863.70	6,564.00
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	1,156.80
Total Parts (S\$)	14,863.70	5,407.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items
There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REPLACING REAR WINDSCREEN	New	150.00	120.00
4	TO DISMANTLE & REPLACING REAR FENDER QUARTER GLASS	New	150.00	-
5	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY	New	150.00	80.00
6	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	60.00
7	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
8	TO DISMANTLE & REFIX PETROL TANK	New	100.00	-
9	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS	New	2,000.00	1,260.00
10	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,080.00
11	TO SPRAY ANTI RUST PROOFING	New	200.00	100.00
Gross Labour Cost (S\$)			4,910.00	2,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >