

22/02/2017

ASS. REC. BY:

REF CS3/MCG17016301/M1V017

Special Instructions

Surveyor  
M1V017

## ASSIGNMENT (Office)

From (Person): Katherine Wong of MSFT Date/Time: 29.12.2017

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKC 5848S Insured: SKV 3983Y

at Workshop m/s AK Workshop Tel: 9339 7780

of Blk 10 Amk Ind Park 2A #04-10

Policy No: 28601854AWW Claim No: 527223

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 22082017

CA / REV / REP. / REV 24 HRS WP H.O.D. Endorsement:

Date/Time: 29/12/2017 10:45am Person Contacted: Matthew Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate	Do Not Finalize
	SKC 5848S - CC6/A1G16002467/R1eg3q2	29012016
	SKV 3983Y - X	
	Dismantle Rd: 24082017	
	After repair: 28082017	

21/1/17 5:50pm Email to Katherine Wong thru M1V017

19/1/18 Submit LS \$4300 (Red 5900, 5790), 5 days

RECEIVED 3 JAN 2018

  
 18/1/18

Surveyor

REF:

mslh

# ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

AK WORKSHOP

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No SKC58485, Yr Regn: MAT 07.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA EDIX. cc 1668.

Colour Silver A/C: Insured / Std / NI / NA

Sp. Reading 148000 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: BE 1103170

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

205/15/15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mm

R/Bal. 8 mm

L/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 22/8/07

D.O.I. 23/8/07 03:14 pm

Survey held at

AK Wksp

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

I-6K

Date/Time: File Pass to?

1) 03-10-2017

Date/Time: File Return to?

2)

☐ : Prell. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS \$

) Photos

) Others

)

TOTAL

180

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech Invs (\$

☐ : Weekend (\$

Report Format : MRS

Lump Sum / I.B.I: (\$



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD			Ref : CS3/MSG17016301/M1vb-1	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 30-12-2017	
			Code : MSG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKV 3983Y	Veh. Inspected	SKC 5848S	
Policy No.	28601854AVW	Coverage (\$)	0.00	
Claim No.	527223	Excess (\$)	0.00	
Assign From	MERIMEN (KATHERINE WONG)	Assign Date	29/12/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	22/08/2017	Inspection Date	30/12/2017	
Survey held at	AK WORKSHOP NO. 10 AMK IND PARK 2A # 04-10 AMK AUTO POINT SINGAPORE 568047			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Aug 2017		23 Aug 2017 10:17 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

<b>Insured:</b>	MDM LIM PECK SER, ID: S1177600J		
<b>Main Claimant:</b>	Khoo Gek Oei, Samuel/Chia S Arul, ID: S8027136J		
<b>Vehicle Reg. No.:</b>	SKC5848S	<b>Date of Loss:</b>	22/08/2017 08:00 - :59
<b>Claim Type:</b>	TP / 527223	<b>Policy/Cover Note No.:</b>	28601854AVW (Comprehensive) Coverage: 13/08/2017 - 12/08/2018
<b>Vehicle Reg. No. (Insured):</b>	SKV3983Y	<b>Policy No. (Claimant):</b>	
	<b>Excess:</b>		
<b>Repairer:</b>	AK WORKSHOP (HQ) 10 Ang Mo Kio Industrial Park 2A, #04-10 AMK Autopoint, S68047 Ang Mo Kio - Tel: 8383 5050 / 9339 7880 / 9321 0855		
<b>Handling Insurer:</b>	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 02/01/2018]		
<b>Driver/Custodian (Insured):</b>	SAMANTHA ANNABELLE NEUBRONNER (), NRIC: S9720771B, Tel: +6596616767		

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG\_SG (28/12/2017): Report Send Back Alerts - SKC5848S (TP)



## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

# Enquire PARF/COE Rebate for Registered Vehicle

## Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 7136J

## Vehicle Details

Vehicle No.: SKC5848S  
Vehicle to be Exported: No  
Intended De-registration Date: 18 Jan 2018  
Vehicle Make: HONDA  
Vehicle Model: EDIX 1.7 A  
Primary Colour: Silver  
Manufacturing Year: 2006  
Engine No.: D17A4053661  
Chassis No.: BE11103170  
Maximum Power Output: 96.0 kW (128 bhp)  
Open Market Value: \$15,838.00  
Original Registration Date: 01 Mar 2007  
First Registration Date: 01 Mar 2007  
Transfer Count: 3  
Actual ARF Paid: \$17,422.00

## Intended PARF Rebate Details

PARF Eligibility: Forfeited  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

## Intended COE Rebate Details

COE Expiry Date: 28 Feb 2027  
COE Category: E - Open Category

COE Period(Years):	10
PQP Paid:	\$52,077.00
COE Rebate Amount:	\$47,458.00
<b>Total Rebate Amount:</b>	<b>\$47,458.00</b>

The information contained herein is correct as at 18 Jan 2018

OK

**CARLINK CONSULTANCY**


60 Hillside Drive  
Singapore 549009

Tel : 62856178

Fax : 62874788

**ACCIDENT VEHICLE INSPECTION / ASSESSMENT REPORT**

Our Ref: CL 11384 SKC 5848 S

<b>1 REFERENCE</b>			
Date of request	: 23rd August 2017		
Requested by	: Khoo Gek Oei, Samuel C/o No. 10 Ang Mo Kio Industrial Park 2A, #04-10 AMK Autopoint Singapore 568047		
Type of claim	: Third party		
Workshop	: M/S AK Workshop No. 10 Ang Mo Kio Industrial Park 2A, #04-10 AMK Autopoint Singapore 568047		
Date of survey	: 23rd August 2017		
Accident date	: 22nd August 2017		
<b>2 DETAILS OF VEHICLE</b>			
Registration No.	: SKC 5848 S		
Make & Model	: Honda Edix 1.7A		
Date of registration	: 1st March 2007		
Engine No.	: D17A4053661		
Chassis No.	: BE11103170		
Speedometer reading	: 148030 Km		
Transmission	: Automatic		
Colour	: Silver		
<b>3 STATIC CHECK</b>			
Steering	: see annex(es)	Paintwork	: Good
Footbrake	: see annex(es)	Modification	: Nil
Handbrake	: see annex(es)	General condition	: Good
<b>4 TYRE CONDITION</b>			
	<u>Nearside/Make</u>	<u>Offside/Make</u>	<u>Size</u>
Front tyre	: 6mm/Michelin	6mm/Michelin	: 205/65 R15
Rear tyre	: 6mm/Michelin	6mm/Michelin	: 205/65 R15
<b>5 POINT OF IMPACT</b>			
See Annex(es) and Motor Accident Reports			
<b>6 REMARK</b>			
This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not authorised any repair.			

## Annex A : Assesement / Adjustment on Spare Parts

SKC 5848 S

Item	Vehicle Parts Description	Condition	Qty	W/shop Est. (\$)	Disc (%)	Adjusted Cost (\$)
List Items						
1	Tail gate assy	Dented/bent	1	\$1,180.60	20%	\$944.48 ✓
2	Tail gate badge	Necessary	1	\$48.90	20%	\$39.12 ✓
3	Tail gate EDIX emblem	Necessary	1	\$56.80	20%	\$45.44 ✓
4	Tail gate outer chrome garnish	Serviceable	1	\$241.10	100%	\$0.00
5	Tail gate outer chrome garnish clips	Necessary	10	\$48.00	20%	\$38.40 X N/N
6	Tail gate "3X2" emblem	Necessary	1	\$51.00	20%	\$40.80 ✓
7	Tail gate absorber	Distorted/leaked	2	\$280.00	20%	\$224.00 X N/N
8	Tail gate weatherstripe	Deformed/cut	1	\$155.40	20%	\$124.32 ✓
9	Tail gate inner trim board	Distorted/cut	1	\$268.50	20%	\$214.80 X N/N
10	Tail gate inner trim board clips	Necessary	10	\$48.00	20%	\$38.40 ✓
11	Tail gate windscreen moulding (bottom)	Necessary	1	\$80.10	20%	\$64.08 ✓
12	Tail gate windscreen moulding (side)	Necessary	2	\$96.00	20%	\$76.80 ✓
13	Tail gate windscreen glass inner seal	Necessary	1	\$29.80	20%	\$23.84 ✓
14	Tail gate windscreen glass clips	Necessary	14	\$77.00	20%	\$61.60 ✓
15	Tail gate lock	Distorted/jammed	1	\$189.80	20%	\$151.84 ✓
16	Tail gate lock striker	Bent	1	\$25.70	20%	\$20.56 X
17	Tail gate number plate lamp	Serviceable	2	\$78.00	100%	\$0.00 X
18	Tail lamp assy L/R	Grazed/cut	2	\$676.80	20%	\$541.44 X N/N
19	Tail lamp sealant L/R	Necessary	2	\$68.00	20%	\$54.40 X
20	Tail lamp clips	Necessary	4	\$21.50	20%	\$17.20 X
21	Rear bumper fascia	Bent/dented/cut	1	\$988.90	20%	\$791.12 ✓
22	Rear bumper side retainer	Necessary	2	\$76.20	20%	\$60.96 ✓
23	Rear bumper side attachment	Necessary	2	\$78.80	20%	\$63.04 ✓
24	Rear bumper clips	Necessary	10	\$36.00	20%	\$28.80 ✓
25	Rear bumper stay bracket	Dented/bent	2	\$121.60	20%	\$97.28 ✓
26	Rear fender RH	Repair	1	\$761.00	100%	\$0.00 ✓
27	Rear fender splash shield RH	Grazed/cut	1	\$18.80	20%	\$15.04 ✓
28	Rear fender splash shield clips RH	Necessary	3	\$10.50	20%	\$8.40 ✓
29	Rear fender LH	Repair	1	\$761.80	100%	\$0.00 ✓
30	Rear fender splash shield LH	Grazed/cut	1	\$18.80	20%	\$15.04 ✓
31	Rear fender splash shield clips LH	Necessary	3	\$10.50	20%	\$8.40 ✓
32	Rear fender air vent RH	Slack/cut	1	\$23.40	20%	\$18.72 X N/N
33	Rear end panel	Dented/bent	1	\$489.90	20%	\$391.92 X
34	Rear end panel top trim	Distorted/cut	1	\$148.60	20%	\$118.88 ✓
35	Rear end panel top trim clips	Necessary	4	\$18.00	20%	\$14.40 ✓
36	End panel retainer bracket L/R	Bent	2	\$160.40	20%	\$128.32 ✓
37	Exhaust silencer	Distorted/dented/rattle	1	\$820.00	20%	\$656.00 X Δ N/N
38	Exhaust silencer mounting	Distorted/cut	2	\$68.80	20%	\$55.04 ✓
39	Spare tyre windnut	Cracked/jammed	1	\$36.20	20%	\$28.96 X
40	Rear knuckle arm RH	Distorted	1	\$327.20	20%	\$261.76 X
41	Rear control arm RH	Bent	1	\$369.20	20%	\$295.36 X
42	Rear upper arm RH	Bent	1	\$123.80	20%	\$99.04 X
43	Rear wheel bearing hup RH	Distorted	1	\$245.20	20%	\$196.16 X N/N
44	Rear absorber RH	Distorted/leaked	1	\$198.00	20%	\$158.40 X
45	Rear anti roll bar link RH	Bent	1	\$70.10	20%	\$56.08 X
46	Rear anti roll bar	Serviceable	1	\$198.40	100%	\$0.00 ✓



SKC 5848 S

Item	Vehicle Parts Description	Condition	Qty	W/shop Est. (\$)	Disc (%)	Adjusted Cost (\$)
<b>S/Nett Items</b>						
47	Rear number plate	Dented/bent	1	\$38.00		<del>\$38.00</del> X
48	Rear number plate holder	Bent/cut	1	\$50.00		<del>\$50.00</del> X
49	Boot compartment water proof sealer	Necessary	1	\$150.00		<del>\$150.00</del> 60
50	Reverse sensor	Cut/faulty	1set	\$380.00		<del>\$380.00</del> 220
51	Rear view camera	Grazed/chipped/faulty	1	\$680.00		<del>\$680.00</del> 250
52	Rear windscreen sealant	Necessary	1	\$80.00		<del>\$80.00</del> —

Total for Spare Parts : \$11,279.10 \$7,666.64

## Annex B : Adjustment on Labour and Spray Painting

SKC 5848 S

Item	Job Description	Workshop Est. (\$)	Adjusted Cost (\$)
1	Anti rust treatment	\$180.00	<del>\$100.00</del> 60
2	To check wiring system & light	\$100.00	<del>\$60.00</del> 30
3	To remove/refix rear windscreen glass to assist in repair	\$150.00	<del>\$120.00</del> 100
4	To remove/refix rear RH fender quarter glass	\$150.00	\$0.00
5	To remove/replace rear RH suspension parts	\$400.00	\$280.00 X
6	To remover/replace rear view camera & test for proper operation	\$200.00	<del>\$100.00</del> 80
7	To remove/replace reverse sensor c/w control unit	\$120.00	<del>\$80.00</del> 60
8	To remove/replace exhaust silencer, mounting & etc,	\$150.00	<del>\$120.00</del> 80
9	To mount vehicle on wheel alignment bench to check & align rear wheel geometry	\$180.00	\$120.00 X
10	To remove & replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	\$2,100.00	<del>\$1,800.00</del> 700
11	To spray painting on rear L/R fender, tailgate, rear bumper, rear end panel, rear floor panel & affected areas	\$2,200.00	<del>\$1,500.00</del> 600
TOTAL FOR LABOUR & SPRAY PAINTING :		\$5,930.00	\$4,280.00

### Summary

	Workshop Est. (\$)	Adjusted Cost (\$)
TOTAL FOR SPARE PARTS :	\$11,279.10	\$7,666.64
TOTAL FOR LABOUR & SPRAY PAINTING :	\$5,930.00	\$4,280.00
TOTAL REPAIR COSTS :	\$17,209.10	\$11,946.64

## CARLINK CONSULTANCY

SKC 5848 S

### Annex C: Recommendation

We have inspected thoroughly the actual damages found on the vehicle and our assessment is appended in the Annex(es) attached. The condition and age of the vehicle was considered before we reached our recommendation as to whether the parts need replacement or repair.

M/S AK Workshop estimated repair cost is **S\$17,209.10** and we have adjusted it to **S\$11,946.64** on a part by part basis. However, taking into consideration the age of the vehicle and the availability of used/recondition components. We, therefore recommend a contract lump sum repair cost.


The repairer have agreed to undertake the repairs on a contract lump sum of **S\$10,200.00**, according to acceptable quality and standard. (Repairer discretion to repair parts, to replace with old parts, or to replace with OEM or genuine parts).

The entire repair of the damaged vehicle should be completed within a reasonable period of 8 working days.

We have advised the repairer that the inspection was conducted strictly on a WITHOUT PREJUDICE basis and we have not given any instruction and authorisation to proceed with the repair of the vehicle.

We are reverting the matter to you for your discretion and enclosed is our invoice for service rendered.

Yours faithfully,  
CARLINK CONSULTANCY

  
PATRICK NG

Automotive Engineer Assessor

MIMI, MIRTE, LCGI, I ENG, LAE, CGLI FTC.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Aug 2017		23 Aug 2017 10:17 <a href="#">Edit Adj Rpt</a>	<b>S\$4,300.00</b> <a href="#">Edit Estimates</a>	<b>S\$4,300.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS** **[Created by Insurer]**

Insured:	MDM LIM PECK SER, ID: S1177600J		
Main Claimant:	Khoo Gek Oei, Samuel/Chia S Arul, ID: S8027136J		
Vehicle Reg. No.:	SKC5848S	Date of Loss:	22/08/2017 08:00 - :59
Claim Type:	TP / 527223	Policy/Cover Note No.:	28601854AVW (Comprehensive) Coverage: 13/08/2017 - 12/08/2018
Vehicle Reg. No. (Insured):	SKV3983Y	Policy No. (Claimant):	
		Excess:	
Repairer:	AK WORKSHOP (HQ) 10 Ang Mo Kio Industrial Park 2A, #04-10 AMK Autopoint, 568047 Ang Mo Kio - Tel: 8383 5050 / 9339 7880 / 9321 0855		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 02/01/2018]		
Driver/Custodian (Insured):	SAMANTHA ANNABELLE NEUBRONNER (), NRIC: S9720771B, Tel: +6596616767		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

- MSIG\_SG (28/12/2017): Report Send Back Alerts - SKC5848S (TP)

**ALL ASSOCIATED TASKS** ☐ [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SKC5848S (527223)**

**[SKV3983Y]**

**TP**

**Khoo Gek Oei, Samuel/Chia S Arul**

**Aug 22 2017 8:00AM**

**[MDM LIM PECK SER]**

**AK WORKSHOP**

Upload Documents			Upload Photos			Compose New Letter			View <span>View in Browser</span>		
Video								1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print		
1	23/08/17 08:30	<b>Video - Accident</b> From:SC - Reg. No: SKV3983Y, Claimant: LIM PECK SER							Load MOV		
2	23/08/17 08:30	<b>Video - Accident</b> From:SC - Reg. No: SKV3983Y, Claimant: LIM PECK SER							Load MOV		
Assessment Reports								1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print		
1	23/08/17 08:30	<b>Accident Statement</b> From:SC - Reg. No: SKV3983Y, Claimant: LIM PECK SER							Load HTM		
Photos/Images								3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	23/08/17 17:49	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
2	23/08/17 17:49	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
3	23/08/17 17:49	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
4	23/08/17 17:49	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
5	23/08/17 17:49	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
6	23/08/17 17:49	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
7	23/08/17 17:49	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
8	23/08/17 17:49	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
9	23/08/17 17:49	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
10	23/08/17 17:49	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
11	23/08/17 17:49	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
12	23/08/17 17:49	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
13	23/08/17 17:49	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
14	23/08/17 17:49	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
15	23/08/17 17:49	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
16	23/08/17 17:49	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
17	23/08/17 17:49	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
18	23/08/17 17:49	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
19	23/08/17 17:49	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
20	23/08/17 17:49	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
21	23/08/17 17:49	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
22	23/08/17 17:49	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
23	24/08/17 16:08	<b>Reinspection Photo</b>							Load JPG	<input checked="" type="checkbox"/>	
24	24/08/17 16:08	<b>Reinspection Photo</b>							Load JPG	<input checked="" type="checkbox"/>	
25	24/08/17 16:08	<b>Reinspection Photo</b>							Load JPG	<input checked="" type="checkbox"/>	
26	24/08/17 16:08	<b>Reinspection Photo</b>							Load JPG	<input checked="" type="checkbox"/>	

27	24/08/17 16:08	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
28	24/08/17 16:08	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
29	24/08/17 16:08	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
30	24/08/17 16:08	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
31	24/08/17 16:08	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
32	24/08/17 16:08	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
33	21/09/17 17:49	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
34	21/09/17 17:49	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
35	21/09/17 17:49	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
36	21/09/17 17:49	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
37	21/09/17 17:49	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	23/08/17 08:30	SKC5848S E file Report From:SC - Reg. No: SKV3983Y, Claimant: LIM PECK SER		Load PDF	
2	23/08/17 08:30	PRI Request		Load PDF	
3	28/12/17 16:15	Survey Report		Load PDF	
4	28/12/17 16:15	Survey Photo 1 of 4		Load PDF	
5	28/12/17 16:15	Survey Photo 2 of 4		Load PDF	
6	28/12/17 16:15	Survey Photo 3 of 4		Load PDF	
7	28/12/17 16:15	Survey Photo 4 of 4		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/01/18 15:55	PHOTO		Load PDF	
2	19/01/18 15:57	Invoice		Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> <div style="text-align: right; margin-top: 5px;"> </div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17016301/M1VBE2-1

Date: 19/01/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28601854AVW

Claimant Vehicle No : SKC5848S

Insured Vehicle No : SKV3983Y

Date of Loss: 22/08/2017

Nature of Claim: TP

Claim No: 527223

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKC5848S

Make &amp; Model: HONDA EDIX, 1.7 (A)

Engine No: D17A4053661

Reg. Date: 01/03/2007 (Man. Year: 2006)

Chassis No: BE11103170

Colour: Silver

Odometer: 148030 km

Engine Capacity: 1668 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R15

Rear Tyre Size: 205/65 R15

Front Left Side: Michelin 8 mm

Rear Left Side: Michelin 8 mm

Front Right Side: Michelin 8 mm

Rear Right Side: Michelin 8 mm

*The above values represent the remaining tyre treads depth*

<u>COST OF CLAIMS</u>	<u>Repairer's</u>	<u>Adjuster's</u>	<u>Difference</u>	<u>Diff %</u>
Parts	11,279.10	3,725.44	7,553.66	66.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,930.00	1,710.00	4,220.00	71.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>17,209.10</b>	<b>5,435.44</b>	<b>11,773.66</b>	<b>68.42</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,300.00</b>		
<b>Nett Amount (\$\$)</b>	<b>17,209.10</b>	<b>4,300.00</b>	<b>12,909.10</b>	<b>75.01</b>

INSPECTION

Date of Assignment: 23/08/2017

Date Inspected: 23/08/2017 Inspected At:

AK WORKSHOP (HQ)  
10 Ang Mo Kio Industrial Park 2A, #04-10  
AMK Autopoint  
Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: MA CHIN FOOK

Manager: CATHERINE CHONG KAI LING

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 19 Jan 2018)  
**Parts:** 144      HONDA EDIX 1.7 (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for SKC5848S)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAIL GATE ASSY	Dented / Bent	1,180.60 F	*1,180.60 FL
2	1	*TAIL GATE BADGE	Necessary	48.90 F	*48.90 FL
3	1	*TAIL GATE EDIX EMBLEM	Necessary	56.80 F	*56.80 FL
4	1	*TAIL GATE OUTER CHROME GARNISH	Serviceable	241.10 F	*- FL
5	10	*TAILGATE OUTER CHROME GARNISH CLIPS	Not Necessary	48.00 F	*- FL
6	1	*TAIL GATE 3X2 EMBLEM	Necessary	51.00 F	*51.00 FL
7	2	*TAIL GATE ABSORBER	Not Necessary	280.00 F	*- FL
8	1	*TAIL GATE WEATHERSTRIP	Deformed / Cut	155.40 F	*155.40 FL
9	1	*TAIL GATE INNER TRIM BOARD	Not Necessary	268.50 F	*- FL
10	10	*TAIL GATE INNER TRIM BOARD CLIPS	Necessary	48.00 F	*48.00 FL
11	1	*TAIL GATE WINDSCREEN MOULDING (BOTTOM)	Necessary	80.10 F	*80.10 FL
12	2	*TAIL GATE WINDSCREEN MOULDING (SIDE)	Necessary	96.00 F	*96.00 FL
13	1	*TAIL GATE WINDSCREEN GLASS INNER SEAL	Necessary	29.80 F	*29.80 FL
14	14	*TAIL GATE WINDSCREEN GLASS CLIPS	Necessary	77.00 F	*77.00 FL
15	1	*TAIL GATE LOCK	Distorted / Jammed	189.80 F	*189.80 FL
16	1	*TAIL GATE LOCK STRIKER	Not Necessary	25.70 F	*- FL
17	2	*TAIL GATE NUMBER PLATE LAMP	Not Necessary	78.00 F	*- FL
18	2	*TAIL LAMP ASSY L/R	Not Necessary	676.80 F	*- FL
19	2	*TAIL LAMP SEALANT L/R	Not Necessary	68.00 F	*- FL
20	4	*TAIL LAMP CLIPS	Necessary	21.50 F	*- FL
21	1	*REAR BUMPER FASCIA	Bent / Dented / Cut	988.90 F	*988.90 FL
22	2	*REAR BUMPER SIDE RETAINER	Necessary	76.20 F	*76.20 FL
23	2	*REAR BUMPER SIDE ATTACHMENT	Necessary	78.80 F	*78.80 FL
24	10	*REAR BUMPER CLIPS	Necessary	36.00 F	*36.00 FL
25	2	*REAR BUMPER STAY BRACKET	Dented / Bent	121.60 F	*121.60 FL
26	1	*REAR FENDER RH	Repair	761.00 F	*- FL
27	1	*REAR FENDER SPLASH SHIELD RH	Grazed / Cut	18.80 F	*18.80 FL
28	3	*REAR FENDER SPLASH SHIELD CLIPS RH	Necessary	10.50 F	*10.50 FL
29	1	*REAR FENDER LH	Repair	761.80 F	*- FL
30	1	*REAR FENDER SPLASH SHIELD LH	Grazed / Cut	18.80 F	*18.80 FL
31	3	*REAR FENDER SPLASH SHIELD CLIPS LH	Necessary	10.50 F	*10.50 FL
32	1	*REAR FENDER AIR VENT RH	Not Necessary	23.40 F	*- FL
33	1	*REAR END PANEL	Not Necessary	489.90 F	*- FL
34	1	*REAR END PANEL TOP TRIM	Distorted / Cut	148.60 F	*148.60 FL
35	4	*REAR END PANEL TOP TRIM CLIPS	Necessary	18.00 F	*18.00 FL
36	2	*END PANEL RETAINER BRACKET L/R	Bent	160.40 F	*160.40 FL
37	1	*EXHAUST SILENCER	Not Necessary	820.00 F	*- FL
38	2	*EXHAUST SILENCER MOUNTING	Distorted / Cut	68.80 F	*68.80 FL
39	1	*SPARE TYRE WINDNUT	Not Necessary	36.20 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR KNUCKLE ARM RH	Not Necessary	327.20 F	*- FL
41	1		*REAR CONTROL ARM RH	Not Necessary	369.20 F	*- FL
42	1		*REAR UPPER ARM RH	Not Necessary	123.80 F	*- FL
43	1		*REAR WHEEL BEARING HUP RH	Not Necessary	245.20 F	*- FL
44	1		*REAR ABSORBER RH	Not Necessary	198.00 F	*- FL
45	1		*REAR ANTI ROLL BAR LINK RH	Not Necessary	70.10 F	*- FL
46	1		*REAR ANTI ROLL BAR	Not Necessary	198.40 F	*- FL
47	1		*REAR NUMBER PLATE	Not Necessary	38.00 FS	*- FS
48	1		*REAR NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
49	1		*BOOT COMPARTMENT WATER PROOF SEALER	Necessary	150.00 FS	*60.00 FS
50	1		*SET REVERSE SENSOR	Cut / Faulty	380.00 FS	*220.00 FS
51	1		*REAR VIEW CAMERA	Grazed/Chipped/Faulty	680.00 FS	*350.00 FS
52	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,279.10</b>	<b>4,479.30</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>	<b>0.00</b>	<b>753.86</b>
<b>Total Parts (\$\$)</b>	<b>11,279.10</b>	<b>3,725.44</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	ANTI RUST TREATMENT	New	180.00	60.00
2	TO CHECK WIRING SYSTEM & LIGHT	New	100.00	30.00
3	TO REMOVE / REFIX REAR WINDSCREEN GLASS TO ASSIST IN REPAIR	New	150.00	100.00
4	TO REMOVE / REFIX REAR RH FENDER QUARTER GLASS	New	150.00	0.00
5	TO REMOVE / REPLACE REAR RH SUSPENSION PARTS	New	400.00	0.00
6	TO REMOVER/REPLACE REAR VIEW CAMERA & TEST FOR PROPER OPERATION	New	200.00	80.00
7	TO REMOVE/ REPLACE REVERSE SENSOR C/W CONTROL UNIT	New	120.00	60.00
8	TO REMOVE, REPLACE EXHAUST SILENCER, MOUNTING & ETC	New	150.00	80.00
9	TO MOUNT VEHICLE ON WHEEL ALIGNMENT BENCH TO CHECK & ALIGN REAR WHEEL GEOMETRY	New	180.00	0.00
10	TO REMOVE & REPLACE ALL THE PARTS MENTIONED ABOVE, KNOCKING AND STRAIGHTEN UP THE NECESSARY AFFECTED AREAS	New	2,100.00	700.00
11	TO SPRAY PAINTING ON REAR L/R FENDER, TAILGATE, REAR BUMPER, REAR END PANEL, REAR FLOOR PANEL & AFFECTED AREAS	New	2,200.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,930.00</b>	<b>1,710.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >