

484 888 888

REF

CS/FCI18000026/Gg/ber

until further notice.

ASSIGNMENT (Office)

Karen Tan

First Capital Insurance

02012018

By: Karen Tan

Signature

OD: ☒ WS / IT RES / OD RES / EVA / INV / MV / CS

To Insured Vehicle No. SUB 1353 Y

Insured SH 6126 P

at Worksite only S Three Automotive Recovery Pte Ltd

Tel. 62841575

of BIK 8 Sin Ming Industrial Estate.

9642 0017

Policy No.

Claim No.

Sum Insured

Excess

Make of VEH

(Client's Record)

D.O.A. 29/12/2017

CA / REV REF. / REV 24 HRS

3/1/2018

H.O.D. Endorsement

Date/Time

Person Contacted

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instructions

Signature

* Note: MV: B 451C (lost); LT: B 95732; NV: B 19268

Xbrl.

REP.

FCI

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD (TP) / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SLB1353Y
at Workshop no: 8 Three
of BLK 8 S/M #01-64
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____
31/12/018
(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.
Bal. or Market Value: \$45K
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 15 days Res: Yes or No
Lum Sum: 20 % 3 Val: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: SLB1353Y Reg: 30 Jun 2010
Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover
Truck / Trailer or
Make: Mini Cooper 1598
Colour: Black A/C Insured / Std / Nil / NA
So. Reading: 126034 T. Radio Insured / Std / Nil / NA
Eng No: _____
C No: WMWZP32040TY78141
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In Order / Jammed / Leaked / Burnt or
Brake: In Order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size F: 205/45R17
R: 11
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front Rear
R/Bal: 6 mm R/Bal: 6 mm
L/Bal: 6 mm L/Bal: 6 mm
D.O.A. 29/12/17 D.O.I. 03-01-18
Survey held at: w/s 3pm
Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision

Date Time Action / Instruction
5/1/18 email preli to Karen.

Guo Qiang.

15: check repair margin
& verify the repair labour cost.

submit us 23/5 \$19k w/s will ask for more with 8/FCI
(area \$ 42407.53, m2)

Date/Time File Pass to: ☐ Preli. Report
23/5 transit ☐ Final Report

Days Of Repair: 15
Resurvey No. of Trip: 2

Survey Fee
Transportation

96x15 = 840
170+840
50
50+50
485

Add Fee: ☐ Site Insp. \$
☐ Material \$
☐ Test \$
☐ Dressing \$

Report Format: TP
Lump Sum: 19000

580
05P
23/5/18
1645

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18000026/Gqb

36 ROBINSON ROAD
#16-01 CITY HOUSES SINGAPORE 068877

Date : 02-01-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 6126P	Veh. Inspected	SLB 1353Y
Policy No.		Coverage (\$)	0.00
Claim No.	D18000077MFSH	Excess (\$)	0.00
Assign From	KARENT	Assign Date	02/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	29/12/2017	Inspection Date	03/01/2018
Survey held at	S THREE AUTOMOTIVE & RECOVERY PTE LTD BLK 8 SIN MING IND EST #01-64/66 SINGAPORE 575643		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

MOTOR SURVEY ASSIGNMENT

Date	29-12-2017	Our Ref No. D18000077MFSH
Accident Date	29-12-2017	Claim Type. Third Party
Insured Vehicle	SH6126P	Third Party Vehicle. SLB1353Y
Survey Location	BLK 8 SIN MING INDUSTRIAL ESTATE #01-64/66	
Contact Person.	MS JOEY / MS MICHELLE	
Contact No.	62841575/ 96620282	Fax No. 64875315
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	S THREE AUTOMOTIVE RECOVERY PTE LTD	Attention. NIL
Cc : TP Solicitor	LIBERTY LAW PRACTICE LLP	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Karen Tan <karentan@msfirstcapital.com.sg>
Sent: Wednesday, 16 May 2018 10:31 AM
To: Shiau Chan (LKKAuto); SUR
Cc: assignments; CWS Motor Claims
Subject: URGENT! REQUEST OF SURVEY REPORT-OUR REF:D18000077MFSH;ACCIDENT INVOLVING SH6126P AND SLB1353Y ON 29-12-2017

Dear Shiau Chan,

We refer to your email dated 15.05.2018.

We have received the third party LOD since Mar'2018 and the 8 weeks' notice is going to be due this week.

Why is there such a delay in finalising the Survey Report?

Kindly let us have the Survey Report by today or latest tomorrow.

Best Regards,

Karen Tan

Motor Claims Dept.

MS First Capital Insurance Ltd | 36 Robinson Road #16-01 City House Singapore 068877 | DID : 6507 3582 | Fax No. : 6507 3849 | Company Regn. No. 195000106C

A Member of  INSURANCE GROUP

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to <http://www.msfirstcapital.com.sg> for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged. If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]
Sent: Tuesday, 15 May, 2018 2:33 PM
To: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Cc: Karen Tan <karentan@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Subject: RE: REQUEST OF SURVEY REPORT-OUR REF:D18000077MFSH;ACCIDENT INVOLVING SH6126P AND SLB1353Y ON 29-12-2017

Dear Karen,

Please be informed that we are in the midst of finalise with repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 15 May 2018 11:48 AM

Ai Phing (LKKAUTO)

From: Ai Phing (LKKAUTO)
Sent: Friday, 5 January, 2018 7:15 PM
To: KARENTAN@FIRST-INSURANCE.COM.SG
Cc: Shiau Chan (LKKAUTO)
Subject: SURVEY ASSESSMENT - D18000077MFSH
Attachments: SLB 1353Y.pdf

Dear Karen,

Enclosed herewith preliminary of SLB 1353Y.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18000077MFSH

Date: 05-01-2018

Our Ref: CS/FCI18000026/Gqb

The Motor Claims Department
First Capital Insurance Ltd

Without Prejudice

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLB 1353Y.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 03-01-2018 at the premises of M/s S THREE AUTOMOTIVE and have the following to report:-

Workshop Estimate Amount	: S\$ <u>62,537.71</u>
Revised Estimate Amount	: S\$ <u>21,886.32</u>
"Check" Items Amount	: S\$ <u>17,257.97</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the front and rear portion.



Yours faithfully

Xing Guo Qiang
Automotive Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 1971D

Vehicle Details

Vehicle No.: SLB1353Y

Vehicle to be Exported: No

Intended De-registration Date: 04 Jan 2018

Vehicle Make: MINI

Vehicle Model: COOPER S 1.6 AT ABS D/AB 2WD 2DR GAS/D

Primary Colour: Black

Manufacturing Year: 2010

Engine No.: B213I722

Chassis No.: WMWZP32040TY78141

Maximum Power Output: 135.0 kW (181 bhp)

Open Market Value: \$29,833.00

Original Registration Date: 30 Jun 2010

First Registration Date: 30 Jun 2010

Transfer Count: 3

Actual ARF Paid: \$29,833.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 29 Jun 2020

PARF Rebate Amount: \$17,899.00

Intended COE Rebate Details

COE Expiry Date: 29 Jun 2020

COE Category: A - Car (1600cc & below)

COE Period(Years):	10
QP Paid:	\$31,510.00
COE Rebate Amount:	\$7,833.00
Total Rebate Amount:	\$25,732.00

The information contained herein is correct as at 04 Jan 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	1971D
Vehicle No.:	SLB1353Y
Vehicle to be Exported:	No
Intended De-registration Date:	03 May 2018
Vehicle Make:	MINI
Vehicle Model:	COOPER S 1.6 AT ABS D/AB 2WD 2DR GAS/D
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	B2131722
Chassis No.:	WMWZP32040TY78141
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$29,833.00
Original Registration Date:	30 Jun 2010
First Registration Date:	30 Jun 2010
Transfer Count:	3
Actual ARF Paid:	\$29,833.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jun 2020
PARF Rebate Amount:	\$17,899.00
COE Expiry Date:	29 Jun 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$31,510.00
COE Rebate Amount:	\$6,792.00
Total Rebate Amount:	\$24,691.00

The information contained herein is correct as at 03 May 2018

MV \$ 43K

OK

$43000 - 24691 = 18309.$

► MINI Cooper Used Vehicle List (9 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
MINI Cooper S 1.6A	\$40,500	\$13,980 /yr	26-Feb-2010	1,598 cc	56,500 km		Availat

Please Call For More Enquiries.

Office No. - -

Suresh Nandwani - 96660390

MINI Cooper S 1.6A JCW	\$44,999	\$15,240 /yr	08-Apr-2010	1,598 cc	98,000 km	99 Motor Trading	Availat
-------------------------------	-----------------	---------------------	--------------------	-----------------	------------------	-------------------------	----------------

Rare MINI JCW, No Gimmicks! Price Negotiable, Low Mileage 98000Km, 100% Beautiful Condition, Low Depreciation, Low Interest Rate, Most Worthy Buy. Call Now For Viewing.

Office No. - 62844922

Bobby Geh - 96365598 | Mr Nah - 81896183 | Ah Wong - 98533943 | Raymond Tang - 81850016

MINI Cooper S Cabriolet 1.6A	\$46,588	\$12,790 /yr	15-Sep-2010	1,598 cc	99,600 km	Cars 88 Pte Ltd	Availat
-------------------------------------	-----------------	---------------------	--------------------	-----------------	------------------	------------------------	----------------

Single Owner Unit! Servicing All Done At Agent With Service Records! Perfect For Short Term Drive! Unique Mustard Yellow With The Signature Union Jack. Powerful And Responsive Drive! Fuel Efficient! A...

Office No. - -

Alex - 92242194

MINI Cooper 1.6A	\$34,900	\$10,320 /yr	16-Sep-2010	1,598 cc	96,632 km	Imperium Car Motor Pte Ltd	Availat
-------------------------	-----------------	---------------------	--------------------	-----------------	------------------	-----------------------------------	----------------

100% Accident Free. Original Paintwork. STA/VICOM Inspection Welcome. No Repairs Needed. Flexible Bank And In House High Loan Available At Low Interest Rate. 6 Months Certified Pre Owned Car Warranty ...

Office No. - 65572663

Melvin Teo - 87870008 | Eugene Lim - 92725924 | Anthony Tay - 84848460

MINI Cooper S 1.6A	\$43,000	\$11,780 /yr	29-Sep-2010	1,598 cc	78,958 km	Autolynx Pte Ltd	Availat
---------------------------	-----------------	---------------------	--------------------	-----------------	------------------	-------------------------	----------------

Good Condition, Good Looking Car, Call For Viewing.

Office No. - 62808291

Ray - 81899085 | Ben - 81892386 | Jason Lau - 96883010 | C K - 87883670

MINI Cooper S 1.6A	\$49,800	\$13,890 /yr	08-Nov-2010	1,598 cc	108,088 km	Hua Yang Credit Pte Ltd	Availat
---------------------------	-----------------	---------------------	--------------------	-----------------	-------------------	--------------------------------	----------------

Face-Lifted Model! Highest Spec In Market! 1 Lady Owner Unit! Full Agent Maintain! Powerful And Responsive Drive! Fuel Efficient! A Car You Should Not Miss! High Trade In And Export Available! Various...

Office No. - 64545111

Alvin Chua - 84488354 | Edison - 82698288

MINI Cooper 1.6A	\$40,800	\$11,560 /yr	12-Nov-2010	1,598 cc	-	Ocean Cars Prestige Pte Ltd	Availat
-------------------------	-----------------	---------------------	--------------------	-----------------	----------	------------------------------------	----------------

10-20% Downpayment. Low Usage, Most Accessories Attached. Blackvue Camera And GPS Comes Along Too! So Unique That You Will Sure Love At 1st Sight. Hurry, Lowest Priced Too.

Office No. - 64633378

Alson - 97497050

MINI Cooper S 1.6A	\$48,500	\$12,990 /yr	03-Dec-2010	1,598 cc	133,000 km		Availat
---------------------------	-----------------	---------------------	--------------------	-----------------	-------------------	--	----------------

Major Servicing And Repairs Including Aircon, Engine Mounting, High Pressure Fuel Pump And All Leaks Done Less Than 10000km. 3 Owner To Be Exact. Sms Or Whatsapp For Viewing.

Office No. - -

Alvin - 96238144

MINI Cooper 1.6A	\$40,000	\$10,940 /yr	29-Dec-2010	1,598 cc	72,500 km	Auto365 Pte Ltd	Availat
-------------------------	-----------------	---------------------	--------------------	-----------------	------------------	------------------------	----------------

Cheapest Cooper In Market! Low Mileage Mini, Car In Excellent Condition, Very Well Maintained Both Interior And Bodywork. Drop By Our Showroom To View It In Pristine Condition Now! Please SMS/Call For...

Office No. - 67416741

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/12/2017 14:20
Date Of Accident	29/12/2017 08:50
Exact Location Of Accident	PASIR RIS ST 21 MSCP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB1353Y
Insured/Policyholder	
Name Of Registered Owner	JULIAH BINTE MOHAMED SAID
NRIC No	S7331971D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92236407
Alternative Phone No	OTHERS-92236407

Vehicle Particulars

Manufacturer	MINI
Model	COOPER
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A000542
Cover Note Number	

Driver

Name of Driver	SITI HAWA BINTE ZULKINIA
NRIC No	S9622727B
Date Of Birth	02/07/1996
Occupation	INDOOR
Date Of Driving Pass	29/06/2015
Driving Experience	2 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-92236407
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 210 PASIR RIS ST 21 #12-328
Postcode	510210
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	PASIR RIS NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 1 PASIR RIS DRIVE 4 , POSTCODE: 519457 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5852999 - FAX NO: 65855261
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SH6126P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time


Driver's Signature
(If driver is not the policyholder)
Date & Time

CITY AUTO PTE LTD
Blk 8 Sin Ming Road
#01-58/60/62, Sun Ming Ind Est
Singapore 575843
Tel: 6453 3444 Fax: 6453 7944
(Claims Section)
Reporting Centre Personnel's Signature
Name:
NRIC/ID No.:

Accident Sketch Plan

SKETCH PLAN

Blk 204A Pasir Ris St 21 NSCP



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My vehicle was parked stationary in the parking lot. When I went down the ramp, TP officers were attending to my car as vehicle SH 6126P had collided into my car and causing damages to my front portion, rear tires and roof were damaged. I had lodge police report for insurance claim purpose.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

CITY AUTO PTE LTD

Blk 8 Sin Ming Road
#01-58/60/62 Sin Ming Ind Est
Singapore 570843
Tel: 6453 1235 Fax: 6453 7944

Reporting Officer's Signature
Name:
NRIC/FIN No.:

Police report



**SINGAPORE
POLICE FORCE**



T/20171229/2013

1 of 3

Police Station Of Origin
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5652999

Report No: T/20171229/2013

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made 29/12/2017 10:02		Vide Report No: G/20171229/0066		Station Diary No.: 19	
Name of Informant: SITI HAWA BINTE ZULKINIA			Address: APT BLK 210 PASIR RIS STREET 21 #12-328 SINGAPORE 510210		
ID Type / ID No.: NRIC NO / S9622727B			Contact No.: Home/Office: Mobile: 81396364		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 21	Date of Birth: 02/07/1986	Type of Informant: Vehicle Owner		
Race: Malay			Language:		Institution / School Name:
Occupation: PASSENGER SERVICE			Driving Licence Information: Class: 3A Date of Expiry:		

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 29/12/2017 08:50	Type of Location: MULTI STORY CAR PARK
Location: Along Road 1 PASIR RIS STREET 21 BLK 204A, MULTI STORY CAR PARK				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

SLB1353Y	Car	MINI	COOPER	White	Seriously Damaged	0
----------	-----	------	--------	-------	----------------------	---

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Police report



**SINGAPORE
POLICE FORCE**



T/20171228/2013

Police Station Of Origin
Pasir Ris N P C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852989

2 of 3
Report No: T/20171228/2013

CONTINUATION OF REPORT

Name	SITI HAWA BINTE ZULKINIA		ID No.	S9822727B
Related Vehicle	NIL		Contact No.	81396364
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3A Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	

Brief Details.

On the above mentioned date and time, I went down to the above mentioned location and discovered that my vehicle was damaged, with the front bumper dislodged, with both rear tires damaged as well. The roof of the car was also damaged. After discovering the damage, the Traffic Police who was at scene passed to me a Case Card with regards to the incident that happened earlier, which involves a taxi driver who had collided with my vehicle. There was a CCTV in my vehicle, and I have downloaded the footage into my thumb drive. The TP Officer advised me to lodge a police report. There were no injuries and I wish to state that the vehicle was parked at Lot 41 on Deck 1B of the said MSCF.

I am lodging this report on behalf of the vehicle owner who is my mother, Julia Bte Mohd Said, 92236487.

Police report



SINGAPORE
POLICE FORCE



1/20171229/ZC13

3 of 3

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

Report No: 1/20171229/2013

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /
Sgt 2 MUHAMMAD FAIZ BIN MUHAMMAD
FAIZAL

Signature Of Interpreter:


Not applicable

Officer In Charge Of Case:

TP / GIT /

Contact No:

Authentication Stamp
NP-108



Signature Of Informant:

Date/Time:

29/12/2017 10:02

Classification Of Case:



S THREE AUTOMOTIVE RECOVERY PTE LTD

Blk 8 Sin Ming Industrial Estate
#01-64/66 Singapore 575643

Tel: (65) 6284 1542. (65) 6284 1575 Fax: (65) 6487 5315
Reg. No: 201325741R

TAX INVOICE

GST Reg. No: 201325741R

PAID
18/11/2016

Name & Address:

ZULKINIA
85339057

Date	17/11/2016
Number:	S3-6711
Vehicle Number	SLB1353Y
Job Sheet	4315
Make and Model	MNI COOPER 96193KM

Payment Method	
Cheque No.	

S/No.	Description	Qty	Amount
1	RESEAL CANOPY GLASS, REMOVE AND REFIT CANOPY GLASS AND REST SSSYTEM		950.00
2	REPLACE CANOPY COVER		58.00
3	REPLACE PIRELLI TYRES 205 45 R17 (\$155X4)		620.00
	REMARKS: DRIVER SIDE HANDLE NOT WORKING WELL Standard Rated (7%)		113.96

Total amount excluding GST

\$1,628.00

Add GST @ 7%

\$113.96



Total amount payable

\$1,741.96

STHREE AUTOMOTIVE RECOVERY PTE LTD

RECEIVED BY

Name



TO :
ATTN : **MOTOR CLAIM DEPT.** T/P VEH. NO. : **SH6126P**

ESTIMATE REPORT 1st QUOTATION
OWNER'S PARTICULAR

NAME : **JULIAH BINTE MOHAMED SAID**
ADDRESS :

JOB NO : _____

CONTACT :

LICENSE NO. : **SLB1353Y** TRANS. :
MAKE / MODEL : **MINI COOPER**
OWNER'S INSURER : **ERGO INSURANCE PTE LTD**
JOB-CODE : **TP** S/A : **MICHELLE**

CHASSIS NO. :

ENGINE NO. :

ACCIDENT DATE : **29-Dec-17**

CLAIM DETAIL

MATERIALS

		QTY	QUO-PRICE	DISC. %	DISC-PRICE	SUR DIS P	REV. PRICE
1	BONNET / <i>Reuc.</i>	1.00	1131.60	10.00	1018.44	Y	
2	BONNET MOULDING / <i>cut</i>	1.00	190.27	10.00	171.24	Y	
3	BONNET AIR GRILLE / <i>3 CRA</i>	1.00	395.00	10.00	355.50	Y	
4	BONNET CATCH RH = <i>BT</i>	1.00	37.55	10.00	33.80	Y	
5	BONNET CATCH LH = <i>BT</i>	1.00	37.55	10.00	33.80	Y	
6	BONNET DAMPER RH = <i>BT</i>	1.00	105.20	10.00	94.68	Y	
7	BONNET DAMPER LH = <i>BT</i>	1.00	105.20	10.00	94.68	Y	
8	BONNET LOCK RH / <i>BT</i>	1.00	253.00	10.00	227.70	Y	
9	BONNET LOCK LH / <i>BT</i>	1.00	253.00	10.00	227.70	Y	
10	BONNET HINGE RH = <i>BT</i>	1.00	137.00	10.00	123.30	Y	
11	BONNET HINGE LH = <i>BT</i>	1.00	137.00	10.00	123.30	Y	
12	BONNET RUBBER / <i>cut</i>	1.00	42.60	10.00	38.34	Y	
13	FRONT GRILLE / <i>CRA</i>	1.00	183.40	10.00	165.06	Y	
14	FRONT GRILL CHROME MOULDING / <i>mis</i>	1.00	158.81	10.00	142.93	Y	
15	FRONT HEADLAMP RH = <i>CRA</i>	1.00	1463.35	10.00	1317.02	Y	
16	FRONT HEADLAMP LH = <i>CRA</i>	1.00	1463.35	10.00	1317.02	Y	
17	FRONT HEADLAMP BULB RH X <i>NN</i>	1.00	679.44	10.00	611.50	Y	
18	FRONT HEADLAMP BULB LH X <i>NN</i>	1.00	679.44	10.00	611.50	Y	
19	FRONT HEADLAMP CONTROL UNIT X <i>NN</i>	1.00	1693.40	10.00	1524.06	Y	
20	FRONT FENDER INNER SHIELD RH = <i>TV</i>	1.00	186.90	10.00	168.21	Y	
21	FRONT FENDER INNER SHIELD LH = <i>TV</i>	1.00	186.90	10.00	168.21	Y	
22	FRONT BUMPER (SPORT) / <i>CRA</i>	1.00	1380.00	10.00	1242.00	Y	
23	FRONT BUMPER CHROME MOULDING / <i>mis</i>	1.00	129.95	10.00	116.96	Y	
24	FRONT BUMPER CENTRE MESH / <i>P's</i>	1.00	107.23	10.00	96.51	Y	
25	FRONT BUMPER LOWER EXTENTION / <i>BT</i>	1.00	222.40	10.00	200.16	Y	
26	FRONT BUMPER SIDE MESH RH = <i>BT</i>	1.00	101.00	10.00	90.90	Y	
27	FRONT BUMPER SIDE MESH LH = <i>BT</i>	1.00	101.00	10.00	90.90	Y	
28	FRONT LAMP LED RH / <i>CRA</i>	1.00	205.42	10.00	184.88	Y	
29	FRONT LAMP LED LH / <i>CRA</i>	1.00	205.42	10.00	184.88	Y	
30	FRONT BUMPER REINFORCEMENT / <i>BT</i>	1.00	532.71	10.00	479.44	Y	
31	FRONT NUMBER PLATE HOLDER / <i>Re</i>	1.00	128.60	10.00	115.74	Y	

32	FRONT BUMPER SPLASH SHIELD RH	miss (After repair take photos)	1.00	285.30	10.00	256.77	Y	
33	FRONT BUMPER SPLASH SHIELD LH		1.00	285.30	10.00	256.77	Y	
34	FRONT SUPPORT PANEL	BT	1.00	905.00	10.00	814.50	Y	
35	AIR CON CONDENSOR	BT	1.00	1062.60	10.00	956.34	Y	
36	RADIATOR ASSY	BT photo.	1.00	1428.50	10.00	1285.65	Y	
37	FRONT SHOCK ABSORBER RH		1.00	285.00	10.00	256.50	Y	
38	FRONT SHOCK ABSORBER LH	X NN	1.00	285.00	10.00	256.50	Y	
39	FRONT SHOCK ABSORBER TOP MOUNTING RH	X NN	1.00	165.40	10.00	148.86	Y	
40	FRONT SHOCK ABSORBER TOP MOUNTING LH	X NN	1.00	165.40	10.00	148.86	Y	
41	FRONT LOWER ARM RH		1.00	341.45	10.00	307.31	Y	
42	FRONT LOWER ARM LH	X NN	1.00	341.45	10.00	307.31	Y	
43	FRONT STABILIZER	X	1.00	253.15	10.00	227.84	Y	
44	BOOT LID	X Repair.	1.00	920.50	10.00	828.45	Y	
45	BOOTLID LOGO	X	1.00	68.55	10.00	61.70	Y	
46	BOOTLID LOGO 'COPPER' EMBLEM	X	1.00	86.52	10.00	77.87	Y	
47	BOOTLID LOGO 'S' EMBLEM	X	1.00	86.52	10.00	77.87	Y	
48	BOOTLID HINGE RH	X	1.00	173.80	10.00	156.42	Y	
49	BOOTLID HINGE LH	X	1.00	173.80	10.00	156.42	Y	
50	BOOTLID NUMBER PLATE GARNISH	X	1.00	155.00	10.00	139.50	Y	
51	INTAKE COOLER	QA	1.00	687.80	10.00	619.02	Y	
52	RADIATOR FAN ASSY	cut	1.00	819.65	10.00	737.69	Y	
53	RADIATOR SPARE TANK	DE	1.00	130.80	10.00	117.72	Y	
54	INTAKE COOLER HOSE	cut	1.00	220.85	10.00	198.77	Y	
55	HEADLAMP NOZZLE RH	cut	1.00	123.10	10.00	110.79	Y	
56	HEADLAMP NOZZLE LH	X	1.00	123.10	10.00	110.79	Y	
57	HEADLAMP NOZZLE COVER RH	X	1.00	32.00	10.00	28.80	Y	
58	HEADLAMP NOZZLE COVER LH	X	1.00	32.00	10.00	28.80	Y	
59	BOOTLID INNER LOCK RH	X	1.00	259.30	10.00	233.37	Y	
60	BOOTLID INNER LOCK LH	X	1.00	259.30	10.00	233.37	Y	
61	BOOTLID RUBBER	X	1.00	283.40	10.00	255.06	Y	
62	REAR BUMPER	cut	1.00	1380.00	10.00	1242.00	Y	
63	REAR BUMPER TWO HOOK COVER	X	1.00	33.15	10.00	29.84	Y	
64	REAR BUMPER REVERSE SENSOR (4PCS)	X	4.00	1436.00	10.00	1292.40	Y	
65	REAR BUMPER GRILLE CENTRE	X	1.00	145.80	10.00	131.22	Y	
66	REAR BUMPER LOWER SIDE GRILLE RH	X	1.00	105.00	10.00	94.50	Y	
67	REAR BUMPER LOWER SIDE GRILLE LH	X	1.00	105.00	10.00	94.50	Y	
68	REAR BUMPER CENTRE MESH	X	1.00	173.10	10.00	155.79	Y	
69	REAR BUMPER INNER SPONGE	X	1.00	158.00	10.00	142.20	Y	
70	REAR BUMPER BEAM	X	1.00	351.80	10.00	316.62	Y	
71	REAR BUMPER REINFORCEMENT	X	1.00	632.21	10.00	568.99	Y	
72	REAR BUMPER AIR COVER RH	X	1.00	102.00	10.00	91.80	Y	
73	REAR BUMPER AIR COVER LH	X	1.00	102.00	10.00	91.80	Y	
74	REAR END PANEL	X	1.00	725.00	10.00	652.50	Y	
75	REAR END AIR VENTS	X	1.00	85.30	10.00	76.77	Y	
76	REAR END PANEL INNER TRIM	X	1.00	269.20	10.00	242.28	Y	

77	REAR EXHAUST SILENCER	R ✓ BT	1.00	1895.00	10.00	1705.50	Y	
78	REAR EXHAUST MOUNTING	R ✓ BT	1.00	194.00	10.00	174.60	Y	
79	REAR EXHAUST UNDERCOVER	R ✓ NN	1.00	106.50	10.00	95.85	Y	
80	REAR EXHAUST HEAD SHIELD	R ✓ BUC	1.00	194.00	10.00	174.60	Y	
81	REAR EXHAUST PIPE CENTRE	R ✓ BT	1.00	910.80	10.00	819.72	Y	
82	ROOFTOP CANOPY CONVERTIBLE	- TN	1.00	4280.00	10.00	3852.00	Y	
83	ROOFTOP CANOPY BRACKET HOUSING ASSY	R ✓ BT	1.00	3000.00	10.00	2700.00	Y	
84	REAR WINDSCREEN GLASS	- SCR	1.00	950.00	10.00	855.00	Y	
85	REAR CANOPY MOULDING	- Cnt	1.00	295.00	10.00	265.50	Y	
86	THIRD BRAKE LAMP	R ✓ Cnt	1.00	286.25	10.00	257.63	Y	
87	REAR SHOCK ABSORBER RH	R ✓ BT	1.00	241.55	10.00	217.40	Y	
88	REAR SHOCK ABSORBER LH	R ✓ BT	1.00	241.55	10.00	217.40	Y	
89	REAR LOWER ARM RH	R ✓ BT	1.00	X 284.42	10.00	255.98	Y	
90	REAR LOWER ARM LH	R ✓ BT	1.00	X 284.42	10.00	255.98	Y	
91	REAR CONTROL ARM RH	R ✓ NN	1.00	297.50	10.00	267.75	Y	
92	REAR CONTROL ARM LH	R ✓ NN	1.00	297.50	10.00	267.75	Y	
93	REAR WHEEL HUP BEARING RH	R ✓ M.C.	1.00	346.55	10.00	311.90	Y	
94	REAR WHEEL HUP BEARING LH	R ✓ M.C.	1.00	346.55	10.00	311.90	Y	
95	REAR TRAILING ARM RH	X ✓ NN	1.00	709.30	10.00	638.37	Y	
96	REAR TRAILING ARM LH	X ✓ NN	1.00	709.30	10.00	638.37	Y	
97	REAR KNUCKLE ARM RH	R ✓ BT	1.00	680.30	10.00	612.27	Y	
98	REAR KNUCKLE ARM LH	R ✓ BT	1.00	680.30	10.00	612.27	Y	
99	FRONT FENDER RH	X Rept - BUC.	1.00	447.90	10.00	403.11	Y	
100	FRONT GARNISH S COVER RH	R ✓ Cnt	1.00	165.00	10.00	148.50	Y	
101	FRONT GARNISH S COVER LH	X ✓ NN	1.00	165.00	10.00	148.50	Y	
102	FRONT FENDER PROTECTOR RH	- Cnt	1.00	157.00	10.00	141.30	Y	
103	FRONT FENDER PROTECTOR LH	- Cnt	1.00	157.00	10.00	141.30	Y	
104	FRONT FENDER INNER SHIELD RH	X ✓ Rept	1.00	186.90	10.00	168.21	Y	
105	FRONT FENDER INNER SHIELD LH	X ✓ Rept	1.00	186.90	10.00	168.21	Y	
106	HEADLAMP INNER GARNISH RH	- Cnt	1.00	176.50	10.00	158.85	Y	
107	HEADLAMP INNER GARNISH LH	R ✓ NN	1.00	176.50	10.00	158.85	Y	
108	FRONT KNUCKLE ARM RH	R ✓ BT	1.00	355.50	10.00	319.95	Y	
109	FRONT KNUCKLE ARM LH	X ✓ NN BT	1.00	355.50	10.00	319.95	Y	
110	FRONT KNUCKLE ARM BEARING RH	R ✓ M.C.	1.00	385.65	10.00	347.09	Y	
111	FRONT KNUCKLE ARM BEARING LH	X	1.00	385.65	10.00	347.09	Y	
112	STEERING RACK & PINION	X	1.00	2300.35	10.00	2070.32	Y	
113	STEERING TIE ROD RH	X ✓ BT NN	1.00	255.80	10.00	230.22	Y	
114	STEERING TIE ROD LH	X	1.00	255.80	10.00	230.22	Y	
115	STEERING TIE ROD END RH	X ✓ BT	1.00	164.90	10.00	148.41	Y	
116	STEERING TIE ROD END LH	X	1.00	164.90	10.00	148.41	Y	
117	ENGINE CROSSMEMBER	X ✓ BT	1.00	1457.90	10.00	1312.11	Y	
118	ENGINE MOUNTING ASSY	X ✓ BT	1.00	667.00	10.00	600.30	Y	

TOTAL (PARTS) :

54675.23

49207.71

SPECIAL NETT ITEM

1	FRONT SPLASH SHIELD CLIPS	- 5 acc	1.00	60.00	0.00	60.00	Y	30
2	FRONT NUMBER PLATE	-	1.00	120.00	0.00	120.00	Y	15
3	REAR NUMBER PLATE	X	1.00	120.00	0.00	120.00	Y	X
4	REAR FENDER INNER SHIELD CLIPS	X { NN	1.00	60.00	0.00	60.00	Y	X
5	REAR END PANEL SEALANT	X	1.00	80.00	0.00	80.00	Y	X
6	FRONT FENDER SHIELD CLIPS RH	-	1.00	80.00	0.00	80.00	Y	30
7	FRONT FENDER SHIELD CLIPS LH	- { NN	1.00	80.00	0.00	80.00	Y	30
8	FRONT FENDER PROTECTOR CIPS	-	1.00	80.00	0.00	80.00	Y	30
9	FRONT SPORT RIM RH	- Cut	1.00	880.00	0.00	880.00	Y	380
10	FRONT SPORT RIM LH	X NN Cut	1.00	880.00	0.00	880.00	Y	X
11	FRONT TYRES 205 45 R17 RH	-	1.00	400.00	0.00	400.00	Y	150
12	REAR WINDSCREEN SEALANT	= P	1.00	50.00	0.00	50.00	Y	30
13	REAR WINDSCREEN PRIMER AND CLEANER	= P	1.00	50.00	0.00	50.00	Y	20

TOTAL (PARTS) :

2940.00

2940.00

LABOUR

1	STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREA		1.00	2800.00	0.00	2800.00	Y	1000
2	SPRAY PAINTING ON ACCIDENT AREA		1.00	2500.00	0.00	2500.00	Y	1400
3	R&R FRONT & REAR SUSPENSION		1.00	800.00	0.00	800.00	Y	500
4	R&R STEERING RACK ASSY W/INSTALLING		1.00	380.00	0.00	380.00	Y	X NN
5	R&R AIR CON CONDENSOR & TOP UP AIR CON GAS		1.00	180.00	0.00	180.00	Y	100
6	R&R INTAKE COOLER W/INSTALLING		1.00	280.00	0.00	280.00	Y	30
7	R&R ENGINE MOUNTING W/INSTALLING		1.00	380.00	0.00	380.00	Y	X NN
8	R&R ROOF TOP CANOPY AND RE-ALIGN		1.00	1200.00	0.00	1200.00	Y	? 600
	TO CENTRE W/RESETTING AND CALIBRATION SYSTEM							
9	R&R REAR WINDSCREEN GLASS CANOPY		1.00	950.00	0.00	950.00	Y	? 200
10	CHECK WIRING SYSTEM		1.00	120.00	0.00	120.00	Y	30
11	BALANCING TYRES		1.00	120.00	0.00	120.00	Y	X NN
12	CONDUCT WHEEL ALIGNMENT		1.00	120.00	0.00	120.00	Y	60
13	CONDUCT CHASSIS ALIGNMENT		1.00	380.00	0.00	380.00	Y	X NN
14	R&R SEAT AND CARPET TO ASSIST REPAIR		1.00	180.00	0.00	180.00	Y	120

TOTAL (LABOUR) :

10390.00

10390.00

TOTAL PARTS & LABOUR

68005.23

62537.71

EXCESS : : S\$

NO. OF DAY :

RE-SURVEY : BEFORE / AFTER PAINTING

PART-BY-PART OR LUMP-SUM : S\$

DATE OF SURVEY 03/01/2018

SURVEY BY : GUN Q: 9p

CONTACT NO :

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

Eng Auto Consultants hence notify the Reparer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

FAX NO :
Acknowledged by Reparer

Signature:

Date:

66407.53

Signature
8/1/18

15 Days -

TO :
ATTN : **MOTOR CLAIM DEPT.** T/P VEH. NO. : **SH6126P**

ESTIMATE REPORT 1st QUOTATION
OWNER'S PARTICULAR
NAME : **JULIAH BINTE MOHAMED SAID**
ADDRESS :
LICENSE NO. : **SLB1353Y** TRANS. :
MAKE / MODEL : **MINI COOPER**
OWNER'S INSURER : **ERGO INSURANCE PTE LTD**
JOB-CODE : **TP** S/A : **MICHELLE**

JOB NO : _____

CONTACT :

CHASSIS NO :

ENGINE NO :

ACCIDENT DATE : **29-Dec-17**

SUPPLYMENTRAY

CLAIM DETAIL

	QTY	QUO-PRICE	DISC. %	DISC-PRICE	SUR DIS	REV. PRICE
1 BONNET FRONT MOUNLDING - <i>CHA</i>	1.00	296.50	10.00	266.85	Y	_____
2 TURBO RESONATOR - <i>BR</i>	1.00	335.8	10.00	302.22	Y	_____
3 CATALYTIC CONVERTER COVER - <i>buc</i>	1.00	188.5	10.00	169.65	Y	_____
4 TOP PANEL - <i>buc</i>	1.00	309.4	10.00	278.46	Y	_____
5 HEADLAMP CHROME BLACK MOULDING RIM RH - <i>CHA BR</i>	1.00	222.5	10.00	200.25	Y	_____
6 HEADLAMP CHROME BLACK MOULDING RIM LH - <i>mis</i>	1.00	222.5	10.00	200.25	Y	_____
7 CANOPY BRACKET GARNISH - <i>De</i>	1.00	398.6	10.00	358.74	Y	_____
8 WINDSCREEN PILLAR OUTER COVER - <i>BR</i>	1.00	245.5	10.00	220.95	Y	_____

TOTAL (PARTS) :

Gmo Gd 4.
05/1/18

2940.00

1997.37

EXCESS : : \$ \$ _____

NO. OF DAY : _____

RE-SURVEY : BEFORE / AFTER PAINTING

PART-BY-PART OR LUMP-SUM : \$ \$ _____

DATE OF SURVEY : ____/____/____

SURVEY BY : _____

CONTACT NO : _____

FAX NO : _____

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.



S THREE AUTOMOTIVE RECOVERY PTE LTD

TO :
ATTN : MOTOR CLAIM DEPT. T/P VEH. NO. : SH6126P

ESTIMATE REPORT 1st QUOTATION
OWNER'S PARTICULAR
NAME : JULIAH BINTE MOHAMED SAID
ADDRESS :

JOB NO. :

CONTACT :

LICENSE NO. : SLB1353Y TRANS. :
MAKE / MODEL : MINI COOPER
OWNER'S INSURER : ERGO INSURANCE PTE LTD
JOB-CODE : TP S/A : MICHELLE

CHASSIS NO :
ENGINE NO :

ACCIDENT DATE : 29-Dec-17

SUPPLYMENTRAY - 2

CLAIM DETAIL

	QTY	QUO-PRICE	DISC. %	DISC-PRICE	SUR DIS P	REV. PRICE
1 INTAKE TURBO HOSE	1.00	295.50	10.00	265.95	Y	
2 FRONT DRIVE SHAFT RH	1.00	1785	10.00	1606.50	Y	

TOTAL (PARTS) :

2080.50

1872.45

EXCESS : S\$

NO. OF DAY :

RE-SURVEY : BEFORE / AFTER PAINTING

PAY BY-PART OR LUMP-SUM : S\$

DATE OF SURVEY : / /

SURVEY BY :

CONTACT NO :

FAX NO :

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

M - 34879.95

S/N - 775

L - 5390

Supp - 3869.82

44914.77 - 20%
= 35931.80

From: jobithomas@eurokars.com.sg
Sent: 51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315
 Friday, 4 May 2018 9:22 AM
To: Shiau Chan (LKKAuto)
Cc: Guo Qiang (LKKAuto); SUR
Subject: RE: KINDLY ASSIST TO CHECK PARTS PRICES OF MINI COOPER

Dear Shiau Chan,

Line	Description	Quantity	
1	Hood	1	\$1,437.44
2	Bi-xenon Headlight LH	1	\$1,756.75
3	Bi-xenon Headlight RH	1	\$1,756.75
4	Condenser	1	\$1,138.63
5	Radiator	1	\$670.81
6	REAR BUMPER	1	\$862.39
7	reinforcement	1	\$450.76
8	ROOFTOP CANOPY (comes with bracket and windscreen)	1	\$23,518.31
9	shock absorber	1	\$309.50
10	upper arm	1	\$253.06
11	Rear Lwr arm	1	\$236.38
12	rear knuckle arm	1	\$908.88
13	Rear wheel hub bearing	1	\$433.20
14	front KNUCKLE ARM	1	\$455.51
15	front Wheel hub	1	\$482.07

Best Regards.



Jobi Thomas
 Insurance Claims Executive

TRANS EUROKARS PTE LTD
 12 Sungei Kadut Avenue
 Singapore 729648
 T: (65) 6363 3003 D: (65) 6360 2446 F: (65) 6360 2899
 E: jobithomas@eurokars.com.sg

From: Shiau Chan (LKKAuto) [<mailto:siewsc@lkkauto.com>]
Sent: Thursday, May 3, 2018 1:48 PM
To: Jobi Thomas <jobithomas@eurokars.com.sg>
Cc: Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: KINDLY ASSIST TO CHECK PARTS PRICES OF MINI COOPER

Dear Jobi,

Kindly assist to check the parts prices of MINI COOPER S 1.6 AT ABS D/AB 2WD 2DR GAS/D, chassis no. : WMWZP32040TY78141

The parts are following:

1. BONNET
2. FRONT HEADLAMP RH
3. FRONT HEADLAMP LH
4. AIR CON CONDENSOR
5. RADIATOR ASSY
6. REAR BUMPER
7. REAR BUMPER REINFORCEMENT
8. ROOFTOP CANOPY CONVERTIBLE
9. ROOFTOP CANOPY BRACKET HOUSING ASSY
10. REAR WINDSCREEN GLASS
11. REAR SHOCK ABSORBER RH
12. REAR LOWER ARM RH
13. REAR CONTROL ARM RH
14. REAR WHEEL HUP BEARING RH
15. REAR KNUCKLE ARM RH
16. FRONT KNUCKLE ARM RH
17. FRONT KNUCKLE ARM BEARING RH

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IN MOTOR CLAIM DEPT.

T/P VEH. NO.: SH6126P

ESTIMATE REPORT
OWNER'S PARTICULAR

1st QUOTATION

JOB NO.:

NAME: JULIAH BINTE MOHAMED SAID
ADDRESS:

CONTACT:

CHASSIS NO.:
ENGINE NO.:
VEHICLE NO.:
INSURER: ERGO INSURANCE PTE LTD
CODE: TP S/A: MICHELLE

ACCIDENT DATE: 29-Dec-17

ITEM DETAIL

MATERIALS

	QTY	QUO-PRICE	DISC. %	DISC-PRICE	SUR DIS P	REV PRICE
BONNET <i>Boinc</i>	1.00	1131.60	10.00	1018.44	Y	
BONNET MOULDING <i>cut</i>	1.00	190.27	10.00	171.24	Y	
BONNET CATCHER RH <i>cut</i>	1.00	355.00	10.00	319.50	Y	
BONNET CATCHER LH <i>cut</i>	1.00	37.55	10.00	33.80	Y	
BONNET CATCHER RH <i>cut</i>	1.00	37.55	10.00	33.80	Y	
BONNET CATCHER LH <i>cut</i>	1.00	105.20	10.00	94.68	Y	
BONNET CATCHER RH <i>cut</i>	1.00	105.20	10.00	94.68	Y	
BONNET CATCHER LH <i>cut</i>	1.00	223.00	10.00	200.70	Y	
BONNET CATCHER RH <i>cut</i>	1.00	223.00	10.00	200.70	Y	
BONNET HINGE RH <i>cut</i>	1.00	137.00	10.00	123.30	Y	
BONNET HINGE LH <i>cut</i>	1.00	137.00	10.00	123.30	Y	
BONNET RUBBER <i>cut</i>	1.00	42.60	10.00	38.34	Y	
FRONT GRILLE <i>cut</i>	1.00	183.40	10.00	165.06	Y	
FRONT GRILLE CHROME MOULDING <i>cut</i>	1.00	158.81	10.00	142.93	Y	
FRONT HEAD LAMP RH <i>cut</i>	1.00	1463.35	10.00	1317.02	Y	
FRONT HEAD LAMP LH <i>cut</i>	1.00	1463.35	10.00	1317.02	Y	
FRONT HEAD LAMP BULB RH <i>X</i>	1.00	679.44	10.00	611.50	Y	
FRONT HEAD LAMP BULB LH <i>X</i>	1.00	679.44	10.00	611.50	Y	
FRONT HEAD LAMP CONTROL UNIT <i>X</i>	1.00	1693.40	10.00	1524.06	Y	
FRONT BUMPER INNER SHIELD RH <i>cut</i>	1.00	186.90	10.00	168.21	Y	
FRONT BUMPER INNER SHIELD LH <i>cut</i>	1.00	186.90	10.00	168.21	Y	
FRONT BUMPER (SPORT) <i>cut</i>	1.00	1380.00	10.00	1242.00	Y	
FRONT BUMPER CHROME MOULDING <i>cut</i>	1.00	129.95	10.00	116.96	Y	
FRONT BUMPER CENTRE MESH <i>cut</i>	1.00	107.23	10.00	96.51	Y	
FRONT BUMPER LOWER EXTENSION <i>cut</i>	1.00	222.40	10.00	200.16	Y	
FRONT BUMPER SIDE MESH RH <i>cut</i>	1.00	101.00	10.00	90.90	Y	
FRONT BUMPER SIDE MESH LH <i>cut</i>	1.00	101.00	10.00	90.90	Y	
FRONT BUMPER REINFORCEMENT <i>cut</i>	1.00	532.71	10.00	479.44	Y	
FRONT NUMBER PLATE HOLDER <i>cut</i>	1.00	128.60	10.00	115.74	Y	

8673-30

FRONT BUMPER SPLASH SHIELD RH	1.00	285.30	10.00	256.77	Y
FRONT BUMPER SPLASH SHIELD LH	1.00	285.30	10.00	256.77	Y
FRONT SUPPORT PANEL	1.00	905.00	10.00	814.50	Y
AIR CON CONDENSOR	1.00	1062.60	10.00	956.34	Y
RADIATOR ASSY	1.00	1428.50	10.00	1285.65	Y
FRONT SHOCK ABSORBER RH	1.00	285.00	10.00	256.50	Y
FRONT SHOCK ABSORBER LH	1.00	285.00	10.00	256.50	Y
FRONT SHOCK ABSORBER TOP MOUNTING RH	1.00	165.40	10.00	148.86	Y
FRONT SHOCK ABSORBER TOP MOUNTING LH	1.00	165.40	10.00	148.86	Y
FRONT LOWER ARM RH	1.00	341.45	10.00	307.31	Y
FRONT LOWER ARM LH	1.00	341.45	10.00	307.31	Y
FRONT STABILIZER	1.00	253.15	10.00	227.84	Y
BOOT LID	1.00	920.50	10.00	828.45	Y
BOOT LID LOGO	1.00	68.55	10.00	61.70	Y
BOOT LID LOGO 'COPPER' EMBLEM	1.00	86.52	10.00	77.87	Y
BOOT LID LOGO 'S' EMBLEM	1.00	86.52	10.00	77.87	Y
BOOT LID HINGE RH	1.00	173.80	10.00	156.42	Y
BOOT LID HINGE LH	1.00	173.80	10.00	156.42	Y
BOOT LID NUMBER PLATE GARNISH	1.00	155.00	10.00	139.50	Y
INTAKE COOLER	1.00	687.80	10.00	619.02	Y
RADIATOR TANK	1.00	339.63	10.00	287.69	Y
RADIATOR HOSE	1.00	330.80	10.00	117.72	Y
HEADLAMP NOZZLE RH	1.00	220.85	10.00	198.77	Y
HEADLAMP NOZZLE LH	1.00	220.85	10.00	198.77	Y
HEADLAMP NOZZLE COVER RH	1.00	123.10	10.00	110.90	Y
HEADLAMP NOZZLE COVER LH	1.00	32.00	10.00	28.00	Y
HEADLAMP NOZZLE LOCK RH	1.00	32.00	10.00	28.00	Y
HEADLAMP NOZZLE LOCK LH	1.00	259.30	10.00	235.37	Y
HEADLAMP NOZZLE COVER RH	1.00	259.30	10.00	235.37	Y
HEADLAMP NOZZLE COVER LH	1.00	283.40	10.00	253.00	Y
HEADLAMP NOZZLE COVER RH	1.00	1380.00	10.00	124.00	Y
HEADLAMP NOZZLE COVER LH	1.00	33.15	10.00	29.00	Y
HEADLAMP NOZZLE COVER RH	4.00	1436.00	10.00	1272.00	Y
HEADLAMP NOZZLE COVER LH	1.00	143.80	10.00	131.00	Y
HEADLAMP NOZZLE COVER RH	1.00	105.00	10.00	94.00	Y
HEADLAMP NOZZLE COVER LH	1.00	105.00	10.00	94.00	Y
HEADLAMP NOZZLE COVER RH	1.00	173.10	10.00	153.79	Y
HEADLAMP NOZZLE COVER LH	1.00	158.00	10.00	142.20	Y
HEADLAMP NOZZLE COVER RH	1.00	331.80	10.00	316.62	Y
HEADLAMP NOZZLE COVER LH	1.00	63.00	10.00	568.99	Y
HEADLAMP NOZZLE COVER RH	1.00	102.00	10.00	91.80	Y
HEADLAMP NOZZLE COVER LH	1.00	102.00	10.00	91.80	Y
HEADLAMP NOZZLE COVER RH	1.00	725.00	10.00	652.50	Y
HEADLAMP NOZZLE COVER LH	1.00	85.30	10.00	76.77	Y
HEADLAMP NOZZLE COVER RH	1.00	269.20	10.00	242.28	Y

P705.86

7	REAR EXHAUST SILENCER	1.00	1895.00	10.00	1705.50	Y	
8	REAR EXHAUST MOUNTING	1.00	164.00	10.00	174.60	Y	
9	REAR EXHAUST UNDERCOVER	1.00	106.50	10.00	95.85	Y	
10	REAR EXHAUST HEAD SHIELD	1.00	194.00	10.00	174.60	Y	
11	REAR EXHAUST PIPE CENTRE	1.00	910.80	10.00	819.72	Y	
12	ROOFTOP CANOPY CONVERTIBLE	1.00	4280.00	10.00	3852.00	Y	
13	ROOFTOP CANOPY BRACKET HOUSING ASSY	1.00	3000.00	10.00	2700.00	Y	
14	REAR WINDSCREEN GLASS	1.00	950.00	10.00	855.00	Y	
15	REAR CANOPY MOULDING	1.00	295.00	10.00	265.50	Y	
16	THIRD BRAKE LAMP	1.00	286.25	10.00	257.63	Y	
17	REAR SHOCK ABSORBER RH	1.00	241.65	10.00	217.40	Y	
18	REAR SHOCK ABSORBER LH	1.00	241.65	10.00	217.40	Y	
19	REAR LOWER ARM RH	1.00	284.42	10.00	255.98	Y	
20	REAR LOWER ARM LH	1.00	284.42	10.00	255.98	Y	
21	REAR CONTROL ARM RH	1.00	267.75	10.00	267.75	Y	
22	REAR CONTROL ARM LH	1.00	267.75	10.00	267.75	Y	
23	REAR UPPER BALL JOINT RH	1.00	311.90	10.00	311.90	Y	
24	REAR UPPER BALL JOINT LH	1.00	311.90	10.00	311.90	Y	
25	REAR TRAILING ARM RH	1.00	709.30	10.00	638.37	Y	
26	REAR TRAILING ARM LH	1.00	709.30	10.00	638.37	Y	
27	REAR KNUCKLE ARM RH	1.00	612.27	10.00	612.27	Y	
28	REAR KNUCKLE ARM LH	1.00	612.27	10.00	612.27	Y	
29	FRONT FENDER RH	1.00	447.90	10.00	405.15	Y	
30	FRONT FENDER LH	1.00	165.00	10.00	148.50	Y	
31	FRONT FENDER PROTECTOR RH	1.00	157.00	10.00	141.30	Y	
32	FRONT FENDER PROTECTOR LH	1.00	157.00	10.00	141.30	Y	
33	FRONT FENDER INNER SHIELD RH	1.00	186.90	10.00	168.21	Y	
34	FRONT FENDER INNER SHIELD LH	1.00	186.90	10.00	168.21	Y	
35	HEADLAMP INNER GARNISH RH	1.00	176.50	10.00	158.85	Y	
36	HEADLAMP INNER GARNISH LH	1.00	176.50	10.00	158.85	Y	
37	FRONT KNUCKLE ARM RH	1.00	355.50	10.00	319.95	Y	
38	FRONT KNUCKLE ARM LH	1.00	355.50	10.00	319.95	Y	
39	FRONT LOWER BALL JOINT RH	1.00	385.65	10.00	347.09	Y	
40	FRONT LOWER BALL JOINT LH	1.00	385.65	10.00	347.09	Y	
41	FRONT LOWER BALL JOINT RH	1.00	2300.35	10.00	2070.32	Y	
42	FRONT LOWER BALL JOINT LH	1.00	2300.35	10.00	2070.32	Y	
43	STEERING TIE ROD RH	1.00	255.80	10.00	230.22	Y	
44	STEERING TIE ROD LH	1.00	255.80	10.00	230.22	Y	
45	STEERING TIE ROD END RH	1.00	164.90	10.00	148.41	Y	
46	STEERING TIE ROD END LH	1.00	164.90	10.00	148.41	Y	
47	FRONT LOWER BALL JOINT RH	1.00	1457.90	10.00	1312.11	Y	
48	FRONT LOWER BALL JOINT LH	1.00	667.00	10.00	600.30	Y	

TOTAL (PARTS):

54675.23

49207.71

17550.79

SPECIAL NETT ITEM

- 1 FRONT SPLASH SHIELD CLIPS /
- 2 FRONT NUMBER PLATE /
- 3 REAR NUMBER PLATE X
- 4 REAR FENDER INNER SHIELD CLIPS X
- 5 REAR END PANEL SEALANT X
- 6 FRONT FENDER SHIELD CLIPS RH /
- 7 FRONT FENDER SHIELD CLIPS LH /
- 8 FRONT FENDER PROTECTOR CIPS /
- 9 FRONT SPORT RIM RH /
- 10 FRONT SPORT RIM LH X
- 11 FRONT TYRES 203 45 R17 RH /
- 12 REAR WINDSCREEN SEALANT /
- 13 REAR WINDSCREEN PRIMER AND CLEANER /

1.00	60.00	0.00	60.00	Y	30
1.00	120.00	0.00	120.00	Y	15
1.00	120.00	0.00	120.00	Y	X
1.00	60.00	0.00	60.00	Y	X
1.00	80.00	0.00	80.00	Y	X
1.00	80.00	0.00	80.00	Y	30
1.00	80.00	0.00	80.00	Y	20
1.00	80.00	0.00	80.00	Y	30
1.00	880.00	0.00	880.00	Y	7 440
1.00	880.00	0.00	880.00	Y	X
1.00	400.00	0.00	400.00	Y	150
1.00	50.00	0.00	50.00	Y	20
1.00	50.00	0.00	50.00	Y	20

TOTAL (PARTS):

2940.00 2940.00

LABOUR

- 1 /RAIGHTEN AND PANEL BEAT ON ACCIDENT AREA
- 2 SPRAY PAINTING ON ACCIDENT AREA
- 3 REAR ENGINE MOUNTING
- 4 REAR STEERING RACK ASSY W/INSTALLING
- 5 REAR AIR CON CONDENSOR & TOP UP AIR CON GAS
- 6 REAR INTAKE COOLER W/INSTALLING
- 7 REAR ENGINE MOUNTING W/INSTALLING
- 8 REAR ENGINE MOUNTING AND ALIGN
- 9 TO CENTRE W/RESETTING AND CALIBRATION SYSTEM
- 10 CHECK WIRING SYSTEM
- 11 BALANCING TYRES
- 12 CONDUCT WHEEL ALIGNMENT
- 13 CONDUCT CHASSIS ALIGNMENT
- 14 REAR BEAT AND CARPET TO ASSIST REPAIR

1.00	2800.00	0.00	2800.00	Y	1000
1.00	2500.00	0.00	2500.00	Y	1000
1.00	800.00	0.00	800.00	Y	500
1.00	380.00	0.00	380.00	Y	
1.00	180.00	0.00	180.00	Y	
1.00	280.00	0.00	280.00	Y	
1.00	380.00	0.00	380.00	Y	
1.00	1200.00	0.00	1200.00	Y	
1.00	950.00	0.00	950.00	Y	
1.00	120.00	0.00	120.00	Y	
1.00	120.00	0.00	120.00	Y	
1.00	120.00	0.00	120.00	Y	
1.00	380.00	0.00	380.00	Y	
1.00	180.00	0.00	180.00	Y	

TOTAL (LABOUR):

10390.00 10390.00

TOTAL PARTS & LABOUR

68005.23 62537.71

EXCESS : \$

NO. OF DAY :

RE-SURVEY : BEFORE / AFTER PAINTING

PART-BY-PART OR LUMP-SUM

DATE OF SURVEY 03/01/2018

SURVEY BY : GURQIP

CONTACT NO :

\$

15 Days

FAX NO :

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18000026/Gqbe2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 23-05-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6126P	Veh. Inspected	SLB 1353Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18000077MFSH	Excess (\$)	0.00	
Assign From	KAREN TAN	Assign Date	02/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	MINI COOPER	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WMWZP32040TY78141	Colour	BLACK	
Odometer	126034	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/45 R17	PIRELLI	6 mm	
L/H Front Tyre	205/45 R17	PIRELLI	6 mm	
R/H Rear Tyre	205/45 R17	PIRELLI	6 mm	
L/H Rear Tyre	205/45 R17	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/12/2017	Inspection Date	03/01/2018	
Survey held at	S THREE AUTOMOTIVE & RECOVERY PTE LTD BLK 8 SIN MING IND EST #01-64/66 SINGAPORE 575643			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 6

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 1353Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	BUCKLED	1,131.60	1,131.60
1	BONNET MOULDING	CUT	190.27	190.27
1	BONNET AIR GRILLE	CRACKED	395.00	395.00
1	BONNET CATCH RH	BENT	37.55	37.55
1	BONNET CATCH LH	BENT	37.55	37.55
1	BONNET DAMPER RH	BROKEN	105.20	105.20
1	BONNET DAMPER LH	BROKEN	105.20	105.20
1	BONNET LOCK RH	BENT	253.00	253.00
1	BONNET LOCK LH	BENT	253.00	253.00
1	BONNET HINGE RH	BENT	137.00	137.00
1	BONNET HINGE LH	BENT	137.00	137.00
1	BONNET RUBBER	CUT	42.60	42.60
1	FRONT GRILLE	CRACKED	183.40	183.40
1	FRONT GRILL CHROME MOULDING	MISSING	158.81	158.81
1	FRONT HEADLAMP RH	CRACKED	1,463.35	1,463.35
1	FRONT HEADLAMP LH	CRACKED	1,463.35	1,463.35
1	FRONT HEADLAMP BULB RH	NOT NECESSARY	679.44	-
1	FRONT HEADLAMP BULB LH	NOT NECESSARY	679.44	-
1	FRONT HEADLAMP CONTROL UNIT	NOT NECESSARY	1,693.40	-
1	FRONT FENDER INNER SHIELD RH	TORN	186.90	186.90
1	FRONT FENDER INNER SHIELD LH	TORN	186.90	186.90
1	FRONT BUMPER (SPORT)	CRACKED	1,380.00	1,380.00
1	FRONT BUMPER CHROME MOULDING	MISSING	129.95	129.95
1	FRONT BUMPER CENTRE MESH	DISTORTED	107.23	107.23
1	FRONT BUMPER LOWER EXTENTION	BENT	222.40	222.40
1	FRONT BUMPER SIDE MESH RH	DEFORMED	101.00	101.00
1	FRONT BUMPER SIDE MESH LH	DEFORMED	101.00	101.00
1	FRONT LAMP LED RH	CRACKED	205.42	205.42
1	FRONT LAMP LED LH	CRACKED	205.42	205.42
1	FRONT BUMPER REINFORCEMENT	BENT	532.71	532.71
1	FRONT NUMBER PLATE HOLDER	DEFORMED	128.60	128.60

Report Ref No. CS/FCI18000026/Gqbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER SPLASH SHIELD RH	MISSING	285.30	285.30
1	FRONT BUMPER SPLASH SHIELD LH	MISSING	285.30	285.30
1	FRONT SUPPORT PANEL	BUCKLED	905.00	905.00
1	AIR CON CONDENSOR	BENT	1,062.60	1,062.60
1	RADIATOR ASSY	BENT	1,428.50	670.81
1	FRONT SHOCK ABSORBER RH	BENT	285.00	285.00
1	FRONT SHOCK ABSORBER LH	BENT	285.00	285.00
1	FRONT SHOCK ABSORBER TOP MOUNTING RH	BENT	165.40	165.40
1	FRONT SHOCK ABSORBER TOP MOUNTING LH	BENT	165.40	165.40
1	FRONT LOWER ARM RH	BENT	341.45	341.45
1	FRONT LOWER ARM LH	NOT NECESSARY	341.45	-
1	FRONT STABILIZER	NOT NECESSARY	253.15	-
1	BOOT LID	TO REPAIR SEE LABOUR	920.50	-
1	BOOTLID LOGO	NOT NECESSARY	68.55	-
1	BOOTLID LOGO 'COPPER' EMBLEM	NOT NECESSARY	86.52	-
1	BOOTLID LOGO 'S' EMBLEM	NOT NECESSARY	86.52	-
1	BOOTLID HINGE RH	NOT NECESSARY	173.80	-
1	BOOTLID HINGE LH	NOT NECESSARY	173.80	-
1	BOOTLID NUMBER PLATE GARNISH	NOT NECESSARY	155.00	-
1	INTAKE COOLER	CRACKED	687.80	687.80
1	RADIATOR FAN ASSY	CUT	819.65	819.65
1	RADIATOR SPARE TANK	DEFORMED	130.80	130.80
1	INTAKE COOLER HOSE	CUT	220.85	220.85
1	HEADLAMP NOZZLE RH	DAMAGED	123.10	123.10
1	HEADLAMP NOZZLE LH	NOT NECESSARY	123.10	-
1	HEADLAMP NOZZLE COVER RH	CUT	32.00	32.00
1	HEADLAMP NOZZLE COVER LH	SCRATCHED	32.00	32.00
1	BOOTLID INNER LOCK RH	NOT NECESSARY	259.30	-
1	BOOTLID INNER LOCK LH	NOT NECESSARY	259.30	-
1	BOOTLID RUBBER	NOT NECESSARY	283.40	-
1	REAR BUMPER	CUT	1,380.00	862.39
1	REAR BUMPER TOW HOOK COVER	NOT NECESSARY	33.15	-

Report Ref No. CS/FC118000026/Gqbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
4	REAR BUMPER REVERSE SENSOR	NOT NECESSARY	1,436.00	-
1	REAR BUMPER GRILLE CENTRE	CRACKED	145.80	145.80
1	REAR BUMPER LOWER SIDE GRILLE RH	NOT NECESSARY	105.00	-
1	REAR BUMPER LOWER SIDE GRILLE LH	NOT NECESSARY	105.00	-
1	REAR BUMPER CENTRE MESH	NOT NECESSARY	173.10	-
1	REAR BUMPER INNER SPONGE	DEFORMED	158.00	158.00
1	REAR BUMPER BEAM	NOT NECESSARY	351.80	-
1	REAR BUMPER REINFORCEMENT	BENT	632.21	450.76
1	REAR BUMPER AIR COVER RH	DEFORMED	102.00	102.00
1	REAR BUMPER AIR COVER LH	NOT NECESSARY	102.00	-
1	REAR END PANEL	NOT NECESSARY	725.00	-
1	REAR END AIR VENTS	NOT NECESSARY	85.30	-
1	REAR END PANEL INNER TRIM	NOT NECESSARY	269.20	-
1	REAR EXHAUST SILENCER	BENT	1,895.00	1,895.00
1	REAR EXHAUST MOUNTING	BENT	194.00	194.00
1	REAR EXHAUST UNDERCOVER	NOT NECESSARY	106.50	-
1	REAR EXHAUST HEAD SHIELD	BUCKLED	194.00	194.00
1	REAR EXHAUST PIPE CENTRE	BENT	910.80	910.80
1	ROOFTOP CANOPY CONVERTIBLE	TORN	4,280.00	4,280.00
1	ROOFTOP CANOPY BRACKET HOUSING ASSY	BENT	3,000.00	3,000.00
1	REAR WINDSCREEN GLASS	SCRATCHED	950.00	950.00
1	REAR CANOPY MOULDING	CUT	295.00	295.00
1	THIRD BRAKE LAMP	CUT	286.25	286.25
1	REAR SHOCK ABSORBER RH	BENT	241.55	241.55
1	REAR SHOCK ABSORBER LH	BENT	241.55	241.55
1	REAR LOWER ARM RH	BENT	284.42	236.38
1	REAR LOWER ARM LH	BENT	284.42	236.38
1	REAR CONTROL ARM RH	NOT NECESSARY	297.50	-
1	REAR CONTROL ARM LH	NOT NECESSARY	297.50	-
1	REAR WHEEL HUP BEARING RH	NECESSARY	346.55	346.55
1	REAR WHEEL HUP BEARING LH	NECESSARY	346.55	346.55
1	REAR TRAILING ARM RH	NOT NECESSARY	709.30	-
1	REAR TRAILING ARM LH	NOT NECESSARY	709.30	-

Report Ref No. CS/FCI18000026/Gqbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR KNUCKLE ARM RH	BENT	680.30	680.30
1	REAR KNUCKLE ARM LH	BENT	680.30	680.30
1	FRONT FENDER RH	BUCKLED	447.90	447.90
1	FRONT GARNISH S COVER RH	CUT	165.00	165.00
1	FRONT GARNISH S COVER LH	NOT NECESSARY	165.00	-
1	FRONT FENDER PROTECTOR RH	CRACKED	157.00	157.00
1	FRONT FENDER PROTECTOR LH	CRACKED	157.00	157.00
1	FRONT FENDER INNER SHIELD RH	REPEATED	186.90	-
1	FRONT FENDER INNER SHIELD LH	REPEATED	186.90	-
1	HEADLAMP INNER GARNISH RH	CRACKED	176.50	176.50
1	HEADLAMP INNER GARNISH LH	NOT NECESSARY	176.50	-
1	FRONT KNUCKLE ARM RH	BENT	355.50	355.50
1	FRONT KNUCKLE ARM LH	NOT NECESSARY	355.50	-
1	FRONT KNUCKLE ARM BEARING RH	NECESSARY	385.65	385.65
1	FRONT KNUCKLE ARM BEARING LH	NOT NECESSARY	385.65	-
1	STEERING RACK & PINION	NOT NECESSARY	2,300.35	-
1	STEERING TIE ROD RH	BENT	255.80	255.80
1	STEERIN TIE ROD LH	NOT NECESSARY	255.80	-
1	STEERING TIE ROD END RH	BENT	164.90	164.90
1	STEERING TIE ROD END LH	NOT NECESSARY	164.90	-
1	ENGINE CROSSMEMBER	BENT	1,457.90	1,457.90
1	ENGINE MOUNTING ASSY	BENT	667.00	667.00
1	BONNET FRONT MOULDING (ADDITIONAL)	CRACKED	296.50	296.50
1	TURBO RESONATOR (ADDITIONAL)	BROKEN	335.80	335.80
1	CATALYTIC CONVERTER COVER (ADDITIONAL)	BUCKLED	188.50	188.50
1	TOP PANEL (ADDITIONAL)	BUCKLED	309.40	309.40
1	HEADLAMP CHROME BLACK MOULDING RIM RH (ADDITIONAL)	BROKEN	222.50	222.50
1	HEADLAMP CHROME BLACK MOULDING RIM LH (ADDITIONAL)	MISSING	222.50	222.50
1	CANOPY BRACKET GARNISH (ADDITIONAL)	DEFORMED	398.60	398.60
1	WINDSCREEN PILLAR OUTER COVER (ADDITIONAL)	BROKEN	245.50	245.50
1	INTAKE TURBO HOSE (ADDITIONAL)	BROKEN	295.50	295.50
1	FRONT DRIVE SHAFT RH (ADDITIONAL)	CRACKED	1,785.00	1,176.65

Report Ref No. CS/FCI18000026/Gqbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-5,897.50	-4,089.40
			53,077.53	36,804.63
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT SPLASH SHIELD CLIPS (SN)	NECESSARY	60.00	30.00
1	FRONT NUMBER PLATE (SN)	NECESSARY	120.00	15.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	120.00	-
1	REAR FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	60.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	80.00	-
1	FRONT FENDER SHIELD CLIPS RH (SN)	NECESSARY	80.00	30.00
1	FRONT FENDER SHIELD CLIPS LH (SN)	NECESSARY	80.00	30.00
1	FRONT FENDER PROTECTOR CLIPS (SN)	NECESSARY	80.00	30.00
1	FRONT SPORT RIM RH (SN)	CUT	880.00	380.00
1	FRONT SPORT RIM LH (SN)	NOT NECESSARY	880.00	-
1	FRONT TYRES 205 45 R17 RH (SN)	CUT	400.00	150.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	30.00
1	REAR WINDSCREEN PRIMER AND CLEANER (SN)	NECESSARY	50.00	20.00
			2,940.00	715.00
	<u>LABOUR</u>			
	STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREA. INCLUSIVE OF THE REPAIR OF BOOT LID.		2,800.00	1,000.00
	SPRAY PAINTING ON ACCIDENT AREA.		2,500.00	1,400.00
	R&R FRONT & REAR SUSPENSION.		800.00	500.00
	R&R STEERING RACK ASSY W/INSTALLING.	NOT NECESSARY	380.00	-
	R&R AIR CON CONDENSOR & TOP UP AIR CON GAS.		180.00	100.00
	R&R INTAKE COOLER W/INSTALLING.		280.00	30.00
	R&R ENGINE MOUNTING W/INSTALLING.	NOT NECESSARY	380.00	-
	R&R ROOF TOP CANOPY AND RE-ALIGN TO CENTRE W/RESETTING AND CALIBRATION SYSTEM.		1,200.00	600.00
	R&R REAR WINDSCREEN GLASS CANOPY.		950.00	200.00
	CHECK WIRING SYSTEM.		120.00	30.00
	BALANCING TYRES.	NOT NECESSARY	120.00	-
	CONDUCT WHEEL ALIGNMENTS.		120.00	60.00
	CONDUCT CHASSIS ALIGNMENT.	NOT NECESSARY	380.00	-

Report Ref No. CS/FCI18000026/Gqbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	R&R SEAT AND CARPET TO ASSIST REPAIR.		180.00	120.00
			10,390.00	4,040.00
GRAND TOTAL			66,407.53	41,559.63
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				19,000.00

Report Ref No. CS/FCI18000026/Gqbe2

MARKET VALUE: \$45,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$25,732.00=NETT VALUE: \$19,268.00

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.