REF. CS3/AIG18000028 /Sbel Special Instruction. ASSIGNMENT (Office) OD TIPE WS I THRES ! OD RES ! EVA ! INV : MY : CS To instead Verbine 16 SKP 1239E no Markania and Itendon Automotive Ptc Ctd 280 Woodland Industrial Park E5 #01-19 Hawest a woodlands (767322) Programme Total DOA 30122017-0 12.00 Make of Veil CA / REV / REP. / REV 24 HRS 43P H.O.D. Endorsement. Parron Contacted. Active featuration ( X ) Estimate SGW 6846H - CC6/A1614010485/GZQBW 2 DOA: 31/05/2014 Pcol : 03012018 Dismontu

After repair: 19012018

AIG PRS



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

٩IG	ASIA PACIFIC IN	SURANCE PTE LTD	Ref : CS3/AIG18000	0028/Sb
CHA	SHENTON WAY #0 ARTIS BUILDING GAPORE 079120	08-16	Date: 02-01-2018	
			Code: AIG	
1		77.45	ars :- (THIRD PARTY CLA	IM)
	Insured Veh.	SGW 6846H	Veh. Inspected	SKP 2229E
	Policy No.	· · · · · · · · · · · · · · · · · · ·	Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From	CHIN LEE YING	Assign Date	02/01/2018
2.	<b>建设设施</b>	Vehicle F	articulars & Condition	
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes	- <del> </del>	Modification	
	Brakes General		Modification	
3.		φ <b>Co</b> l		
3.	General	Co.	Modification  Inditions of Tyres  Make	Balance
3.	General		nditions of Tyres	
3.	General		nditions of Tyres	Balance
3.	General  R/H Front Tyre		nditions of Tyres	Balance mm
3.	General  R/H Front Tyre  L/H Front Tyre		nditions of Tyres	Balance mm mm
3.	R/H Front Tyre L/H Front Tyre R/H Rear Tyre	Size	nditions of Tyres	mm mm mm
	R/H Front Tyre L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	Size	Make	mm mm mm
4.	R/H Front Tyre L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	Size	Make	Balance mm mm mm mm
4.	R/H Front Tyre L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	Size	Make  Make  iption of Damages	Balance mm mm mm mm
4.	R/H Front Tyre L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	Size  Description  Ger	miditions of Tyres  Make  ription of Damages	Balance mm mm mm mm
5	R/H Front Tyre L/H Front Tyre R/H Rear Tyre L/H Rear Tyre Accident Date Survey held at	Ger 30/12/2017 HENDON AUTOMOTIVE 280 WOODLANDS IND PAR #01-11 SINGAPORE 75732	miditions of Tyres  Make  ription of Damages  neral Information  Inspection Date	Balance mm mm mm mm output
5	R/H Front Tyre L/H Front Tyre R/H Rear Tyre L/H Rear Tyre Accident Date Survey held at	Ger 30/12/2017 HENDON AUTOMOTIVE 280 WOODLANDS IND PAR #01-11 SINGAPORE 75732	miditions of Tyres  Make  ription of Damages  neral Information  Inspection Date	Balance mm mm mm mm

- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED V... Page 1 of 1

## - FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGW6846H AND SKP2229E ON 30/12/2017

From: Chin, Lee-Ying

To: 'assignments', Admin A

Cc: Fong, Andy-SY

Sent: Tuesday, 2 January, 2018 2:11:35 PM

Hi LKK.

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

#### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

#### ٧.

HENDON AUTOMOTIVE PTE LTD

280 Woodlands industrial Park E5 #01-19, Harvest@Woodlands \$(757322)
TEL: 94592885 FAX: 63345178

Date:

Fre-repair Inspection

By Fax 6415 3727 Only

M/s AIG Asia Pacific Insurance Pte. Ltd AIG Building 78 Shenton Way #08-16 Singapore 079120

Dear Sit.

ACCIDENT INVOLVING SKP 22298 AND SGW 6846 H ON 30/12/17 @ 18:00

Worldward the stone marries

We are the appearated repair works hope at weble in a Skp 2009 &

We understand that you are the insurer of vehicle no. \$6747 6846 44

The owner of vehicle no. SEP 3336 this conhorised as to carry out the repairs to his vehicle which was do naged by your instred's vehicle. The owner intends to make a claim againts you instred and for instred's authorised driver for the accident which is consed whelly and/or contributed by your instred and/or your instred's ratheresed driver's negligence.

We hereby give you notice of the accident and apportunity re-inspect the damaged to the vehicle priority the commencement of the repairs.

blindly take note that we hereby give you but 38' notice to conduct a pre-repair inspection of vehicle in SkP 2329 6, at my premises.



Your inithfully

## Survey Department Check List (Case Handler)

Admin (	). Coop anadiones males a constitution of		landler		pist
· ·	): Case nandier to make sure a'l Informatio Assign Form				
	Reference No.	Y-Date	N-Date	<u>Y-Date</u>	N-Date
	Customer Code			į .	<del></del>
		<i>V</i>		-	<u> </u>
	Assign From				· -
	Assign Date			·	-
	Veh No (Inspected)			-	
	Veh No (insured)				
	D.O.A				
	Policy No				
	Claim No				
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type				
С	Weekend Charges				
N	Survey held at/Repairer				
С	Excess				
Surveyor	( ): Case handler to make sure the su	inianiar c	omplatoria	li roquirod	information
	ment Form	nveryo: c	ompletes a	n reganea	ialumation.
=	Vehicle No				<u> </u>
C	-				
	Regn Month/Year		<u> </u>		
•	Venicle Type Make & Model				1
N	-				
C	Engine Capacity. (C.C)			<u> </u>	·
	Colour		<u> </u>		
	Odometer. (Sp.Reading)  Chassis No				
		<u></u>			1
	General Condition			<u> </u>	
N	Steering				
N	Brake	V			1
N	Modification (Modi)	V		<u></u>	
C N	Tyre Size	V			
	Tyre Make	V			
	Tyre Balance	Y			
	Date of Inspection				
N	Survey held				
N	Des.of Damages	V			
(2) System	n - (Views/Merimen)				
C	Damaged Vehicle Photographs Uploaded				
(3) Works	hop Estimate/Assignment Form	· · · · · · · · · · · · · · · · · · ·			·
N	ALL Parts condition		T		<u> </u>
c	Market Value for OD cases				
c	Estimate Repair Cost for PRI (RSI, TMI, MSIG)		1	1	
c	Days of repair		<del> </del>	1	
C	Finalised Amount			-	
C	Re-inspection Cases to Finalize within 5 Days				
	n - (Views/Merimen)				<u> </u>
4) System C	Resurvey photo Uploaded		<del></del>	:	
_	The state of the s	L			<u>:</u>

\*C: Critical \*N: Non-Critical

Case Handler

Date

Reference No. :

MOTOR CAR (Frt)

		CONAC	<del>र</del> ाज्य र
Vehicle No:	skp	22278	C5 Jam

	ortion				
NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base Frt Number Plate Garnish			
		Fit Bumper	Def	7	
		Frt Bumper Clips	NEC		
		Frt Bumper Bracket	, , , ,	<u> </u>	
		Fit Bumper Side Retainer	NEC	1	
		Frt Bumper Reinforcement		Ė	
		Frt Bumper Beam			
		Frt Bumper Sponge			
		Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding	ļ		_
1015	991407	Frt Bumper Lower Spoiler	ļ	-	
1016	991438	Frt Bumper Sensor	├──	-	
1017	995100	Fri LH Bumper Fog Lamp Cover	(74	7	
		Fri RH Bumper Fog Lamp Cover Fri LH Bumper Fog Lamp	134	<del>'</del> -	$\vdash$
		Fri RH Bumper Fog Lamp			
		Pri Grille	Cr.	V	_
		Fri Grille Emblem	NEC		Ť
		Fri Grille Chrome Moulding	<u> </u>	Ť	<u> </u>
1023	991222	Frt Apron Panel	<b>†</b>		t
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn		Γ	L
1028	991277	Frt Brace Panel			
		Frt LH Headlemp Assy			
		Fri RH Headlamp Assy	CKK	V	
		Frt LH Side Lamp		L	
		Frt RH Side Lamp	SCP	./	1
1033	990248	Bonnet		R	
		Bonnet Emblem			
		Bonnet Lock	Ļ	╙	<u> </u>
		Bonnet Insulator	<u> </u>	╙	┞
		Bonnet Hinge	1	↓_	╄
1038	990261	Bonnet Damper	-	┼	┼
1039	990305	Bonnet Rubber	-	┼	╄
		Bonnet Cable		╂╼	┿
1041	990311	Bonnet Stand Air Con Condenser	╁	╁	╆
		Air Con Fan Assy	+	+-	+
1043	000124	Air Con Suction Pipe (Low Pressure)	+	╁╴	╈
1044	000119	Air Con Suction Hose	+	+-	╁
1043	790115	Air Con Discharge Pipe (High Pressure)	+	T	$\vdash$
1040	770174	Air Con Discharge Hose	$\vdash$	+-	${f +}$
			+	+-	╁
1048	990149	Air Con Liquid Pipe Air Con Receiver Drier	+	+	+-
1049	990111	Air Con Compressor Assy	+	1	†
		Air Con Beh	1.	1	1
		Radiator	<u> </u>	1	İ
1053	992738	Radiator Cowling		$\mathbf{I}$	
	992742	Radiator Fan Assy		Ι	
1055	992745	Radiator Fan Clutch		$\Box$	$\perp$
1056	992758	Radiator Hose Top	1	$\perp$	<u> </u>
1057	992757	Radiator Hose Bottom	1	1	$\perp$
1058	992741	Radiator Expansion Tank			$\perp$
1059	990151	Air Duct		1	丄
1060	990070	Air Cleaner Assy			_
1061	990056	Air Cleaner Hose		$\int_{-}^{-}$	
1062	990089	Air Cleaner Resonator	<b>↓</b>	_	1
1063	99171	Frt Exhaust Manifold		1	$\perp$
1064	99171:	Fri Exhaust Manifold Cover		1	4
1065	591054	Fri Exhaust Manifold Sensor (Oxygen)	1-	_	-
1066	991714	Front Exhaust Pipe	—	$\bot$	1
1067	99021	Battery	1	$\bot$	4
	00022	4 Battery Cover		┸	1
1068	770.44				
1069	99022	Battery Bracket  Battery Tray	Ţ		╀.

	INC	Item (	CON	4	701
1071	992205	Fuse Box			Ш
		Relay Box		<u></u>	Ш
1073	995053	Wiper Washer Tank /	Klim	٧.	$\vdash$
		Wiper Washer Tank Motor		<u> </u>	<b>├</b>
		Alternator Assy		<u> </u>	$\vdash \vdash$
		Alternator Belt		<del> </del>	$\vdash \dashv$
		Power Steering Pump			
		Power Steering Belt		_	╁╼┤
		Power Steering Cooler Pipe		ļ	Н
	992692	Power Steering Hose		_	
		ABS Pump Control Unit		<u> </u>	
		Brake Moster Pump Assy		┝	$\vdash$
1083	990403	Brake Booster Pump Assy		┝	$\vdash$
1084	991005	Engine Top Cover Engine Under Cover		<u> </u>	
1085	991011	Engine Mounting		⊢	┼╌┤
1007	000040	Engine Mounting Frt		$\vdash$	┪
1007	DOODED	Engine Mounting LH		┪	╆┯┪
		Engine Mounting RH		╁╌	$\vdash$
		Engine Mounting Rear		╁	┼┤
		Gear Box Mounting		1	⇈
_		Fr. LH Chassis Member		1	┿┤
1092	001420	Frt RH Chassis Member		1	╁┈┨
1004	331340	Frt Vertical Cross Member		+	† 1
1094	990/48	Frt Lower Cross Member		+	+
1004	221903	Frt LH Fender		+-	
1007	005077	Frt LH Fender Inner Panel		✝	+
		Frt LH Fender Lamp		+	
		Frt LH Fender Protector		⇈	$\vdash$
1100	991740	Frt LH Fender luner Shield		✝	П
1101		Frt LH Mudflap		†	П
		Fri LH Wheel Rim		T	П
1103		Frt LH Rim Cover	-	1	
1104		Frt LH Tyre		†	1
1105		Fri RH Fender	07	V	
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Fri RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield	Defo.	l	lacksquare
1110	991884	Frt RH Mudflap			
1111	992087	Fri RH Wheel Rim		<u> </u>	<del></del>
1112		Frt RH Rim Cover		┺	$\vdash$
1113		Frt RH Tyre		┺	-
		Frt Windscreen Glass		┺	<b>.</b>
1115	992117	Frt Windscreen Rubber		╄	
1116	992108	Frt Windscreen Moulding		↓	$\bot$
1117	992098	Frt Windscreen Sealant		$\bot$	
1118	991019	ERP Bracket		$\downarrow$	1
1119	991020	ERP Unit		-	1 -
1120	992140	Frt Wiper Arm	<u> </u>	+	—
1121	992142	Frt Wiper Blade	<u> </u>	+-	
1122	995045	Wiper Panel Garnish		+	┿
1123		Firewall Panel	<del></del>	+	+
1124	990753	Dashboard Assy	_	+	+
1125	992282	Glove Box Cover		+	+-
		Glove Box Compartment	-	+	+
1127	994483	Steering Wheel Airbag	<del> </del>	╁	+
1128	994485	Steering Wheel Airbag Sensor	<del>  -</del>	+	+
1129	1990749	Dashboard Airbag	$\vdash$	+-	+
1130	990750	Dashboard Airbag Sensor	<del> </del>	+-	+
1131	990029	Airbag Courrol Unit	<del>\</del> -	بإ.	出入
		Fri Driver Seat	1	Æ	W
1133		Fri RH Seat Belt Assy / V	bx	£	<del> </del>   <del>                                 </del>
1134	991899	Frt Passenger Seat	-	Ŧ	++
		Frt LH Seat Belt Assy	1	┿	+
1136	990247	Sticker	<del>  \</del>	╁	<del>\-</del> -
<b> </b>	<del> </del>	<del> </del>	5	ᅪ	外
	_L		<u> </u>	4	44
		i		n.	1 1

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver,
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	02/01/2018 10:28
Date Of Accident	30/12/2017 12:00
Exact Location Of Accident	LOYANG POINT CARPARK
Country/State of Loss	SINGAPORE

	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKP2229E	

Insured/Policyholder

Name Of Registered Owner ANG KHENG OON (HONG QING'EN)

NRIC No S7424262F

Email Address KHENGOON@SINGNET.COSG

Mobile Phone No (LOCAL) +65-98383702

Alternative Phone No OFFICE-98383702

**Vehicle Particulars** 

Manufacturer MAZDA

Model MADZA3 4-DOOR SEDAN 1.5L SP.6EAT

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

**Insurance Company** 

Name of Insurance Company AXA INSURANCE PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number GA250346/1

Cover Note Number

Driver

Name of Driver ANG KHENG OON (HONG QING'EN)

 NRIC No
 \$7424262F

 Date Of Birth
 28/07/1974

 Occupation
 INDOOR

 Date Of Driving Pass
 26/06/1992

Driving Experience 25 YEARS AND 6 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-98383702

Fax Number

Contact Number

EMail Address KHENGOON@SINGNET.CON.SG

- Address:

12 FLORA DRIVE

#02-11

Postcode

506943

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

**General Information of the Accident** 

Type Of Accident

COLLISION - CHANGE/CROSS LANE

Weather Conditions

**RAINING** 

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

5

Passenger 1

NAME:

: LIM MENG GUAT

GENDER:

: FEMALE

Passenger 2

NAME:

: GRACE

GENDER:

: FEMALE

Passenger 3

NAME:

: ANG RUI SHEN

GENDER:

: MALE

Passenger 4

NAME:

: ANG RUI YAN

GENDER:

: MALE

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station
Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO THE ATTACHMENT

Attachment(s)

Are accident photos available for attachment?

YES YES

Was there any video captured by Car Camera?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Was there any audio recorded?

SGW6846H

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

LOH PIANG KHUEN S1125998G

97837884

#### Accident Sketch Plan Pg. 1

#### **SKETCH PLAN**

#### **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature Date & Time: Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

GMMCSLeignFrankhine V3

#### **DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

#### SKETCH PLAN



Date & Lance

AFRICA STA

# ...CLAIM SUBFOLDER...(Pending for Survey Report) $$^{\tt PRI}$$

CLAIM SUE	LAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Jan 2018 Edit Reg		02 Jan 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

CLAIM SUBFOLDER DETA			[Created by adjuster]		
Insured:	Loh Piang Khuen, ID: S11259		Management of the second secon		
Main Claimant:	ANG KHENG OON (HONG QIN	···			
Vehicle Reg. No.:	SKP2229E	Date of Loss:	30/12/2017 12:00 - :59		
Claim Type:	<b>TP</b> / 9981000390SG	Policy/Cover Note No.:	1700004354 (Comprehensive)		
Vehicle Reg. No. (Insured):	SGW6846H	Policy No. (Claimant):			
		Excess:			
Repairer:	Hendon Automotive (HQ) 280 757322 Woodlands - Tel:	WOODLANDS INDUSTRIAL PARK I	E5, #01-19 HARVEST @ WOODLANDS,		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 [Handled by Chan, Klan-Chuan] Kian-Chuan, Chan@aig.com				
	Trial chamichangagicom				
Adjuster:			ed by Sebastian Yeang Wai Keen]		
	LKK Auto Consultants Pte Ltd [Final Rpt due 06/02/2018		process for malife subsets 1,000 mg Tota 6 is constant at author control opposition of a party control opposition opposition of a party control opposition		
Adjuster:  ASSOCIATED MAIL RECEI	LKK Auto Consultants Pte Ltd [Final Rpt due 06/02/2018		proceed for malife submits 1 of 100 miles a constant of miles and malife submits and malife submits and malife		
Adjuster:  ASSOCIATED MAIL RECEI	LKK Auto Consultants Pte Ltd [Final Rpt due 06/02/2018 IVED Equest To Upload TP GIA Report		View All Compose Case Ma		
Adjuster:  ASSOCIATED MAIL RECEI  AIG_SG (29/01/2018): Re  ALL ASSOCIATED TASKS	LKK Auto Consultants Pte Ltd [Final Rpt due 06/02/2018  EVED Equest To Upload TP GIA Report	View All Se	View All Compose Case Ma		

#### **Claim Documents**

\*SKP2229E (9981000390SG) [SGW6846H] TP ANG KHENG OON (HONG QING'EN) Dec 30 2017 12:00PM [Loh Piang Khuen] **Hendon Automotive** 

Up	load Documents Up	load Photos   Compose New Letter   Upload Video   Upload Audio	V	iew View in Br	owser ▼
Ass	essment Reports		1 pe	rpage ▼	<b>2</b>
No	Finalized On	AIG Asía Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	29/01/18 10:51	Accident Statement From:OD - Reg. No: SGW6846H, Claimant: LOH PIANG KHUEN	0	Load HTM	
Pho	otos/Images		3 pe	rpage ▼	<b>2</b>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/01/18 12:27	General View	•	Load JPG	<b>2</b>
2	27/01/18 12:27	General View	0	Load JPG	<b>2</b>
3	27/01/18 12:27	General View	0	Load JPG	
4	27/01/18 12:27	General View	0	Load JPG	•
5	27/01/18 12:27	General View	0	Load JPG	<b>3</b>
6	27/01/18 12:27	General View	0	Load JPG	<b>2</b>
7	27/01/18 12:27	General View	0	Load JPG	<b>2</b>
8	27/01/18 12:27	General View	Ð	Load JPG	<b>2</b>
9	27/01/18 12:27	General View	0	Load JPG	<b>2</b>
10	27/01/18 12:27	General View	0	Load JPG	
11	27/01/18 12:27	General View	0	Load JPG	W
12	27/01/18 12:27	General View	•	Load JPG	<b>₩</b>
13	27/01/18 12:27	General View	Ð	Load JPG	€
14	27/01/18 12:27	General View	0	Load JPG	₹
15	27/01/18 12:27	General View	0	Load JPG	Ø
16	27/01/18 12:27	General View	0	Load JPG	<b>2</b>
17	27/01/18 12:27	General View	0	Load JPG	<b>2</b>
18	27/01/18 12:27	General View	0	Load JPG	
19	27/01/18 12:27	General View	0	Load JPG	<b>7</b>
20	27/01/18 12:27	General View	0	Load JPG	Ø
21	27/01/18 12:27	General View	0	Load JPG	<b>2</b>
22	27/01/18 12:27	General View	0	Load JPG	<b>Z</b>
23	27/01/18 12:27	General View	0	Load JPG	<b>3</b>
24	27/01/18 12:27	General View	0	Load JPG	<b>2</b>
25	27/01/18 12:27	General View	0	Load JPG	Ø
26	27/01/18 12:27	General View	0	Load JPG	<b>2</b>
27	27/01/18 12:27	General View	0	Load JPG	€
28	27/01/18 12:27	General View	0	Load JPG	Z
29	27/01/18 12:27	General View	0	Load JPG	<b>2</b>
30	27/01/18 12:27	Chassis Number	0	Load JPG	

31	27/01/18 12:27	Odometer Reading	0	Load JPG	<b>2</b>
32	27/01/18 12:27	General View	Ō	Load JPG	
33	27/01/18 12:27	Photographs of Damaged Parts	0	Load JPG	<b>2</b>
34	27/01/18 12:27	Photographs of Damaged Parts	0	Load JPG	<b>2</b>
35	27/01/18 12:27	Photographs of Damaged Parts	ŏ	Load JPG	
36	27/01/18 12:27	Photographs of Damaged Parts	Ŏ	Load JPG	8
37	27/01/18 12:27	Photographs of Damaged Parts	Ō	Load JPG	2
38	27/01/18 12:27	Photographs of Damaged Parts	0	Load JPG	<b>2</b>
39	27/01/18 12:27	Photographs of Damaged Parts	0	Load JPG	2
40	27/01/18 12:27	Photographs of Damaged Parts	0	Load JPG	2
41	27/01/18 12:27	Photographs of Damaged Parts	0	Load JPG	
42	27/01/18 12:27	Photographs of Damaged Parts	0	Load JPG	•
43	27/01/18 12:27	Photographs of Damaged Parts	0	Load JPG	<b>2</b>
44	27/01/18 12:27	Photographs of Damaged Parts	0	Load JPG	<b>2</b>
45	27/01/18 12:27	Photographs of Damaged Parts	0	Load JPG	<b>2</b>
46	27/01/18 12:27	Photographs of Damaged Parts	0	Load JPG	2
47	27/01/18 12:27	Photographs of Damaged Parts	0	Load JPG	<b>2</b>
48	27/01/18 12:27	Photographs of Damaged Parts	0	Load JPG	2
49	27/01/18 12:27	Photographs of Damaged Parts	0	Load JPG	<b>2</b>
50	27/01/18 12:27	Photographs of Damaged Parts	0	Load JPG	€
51	27/01/18 12:27	Photographs of Damaged Parts	0	Load JPG	<b>2</b>
52	27/01/18 12:27	Photographs of Damaged Parts	0	Load JPG	<b>2</b>
53	27/01/18 12:27	Photographs of Damaged Parts	0	Load JPG	2
54	27/01/18 12:27	Photographs of Damaged Parts	0	Load JPG	8
55	27/01/18 12:27	Photographs of Damaged Parts	0	Load JPG	<b>2</b>
56	27/01/18 12:27	Photographs of Damaged Parts	0	Load JPG	<b>2</b>
57	27/01/18 12:27	Photographs of Damaged Parts	0	Load JPG	<b>2</b>
58	27/01/18 12:27	Photographs of Damaged Parts	0	Load JPG	<b>2</b>
59	27/01/18 12:27	Photographs of Damaged Parts	0	Load JPG	<b>2</b>
60	27/01/18 12:27	Photographs of Damaged Parts	0	Load JPG	<b>2</b>
61	27/01/18 12:27	Photographs of Damaged Parts	0	Load JPG	<b>8</b>
62	27/01/18 12:28	Photo After Spray	0	Load JPG	2
63	27/01/18 12:28	Photo After Spray	0	Load JPG	
64	27/01/18 12:28	Photo After Spray	0	Load JPG	
65	27/01/18 12:28	Photo After Spray	0	Load JPG	
66	27/01/18 12:28	Photo After Spray	0	Load JPG	<b>2</b>
67	27/01/18 12:28	Photo After Spray	0	Load JPG	<b>2</b>
68	27/01/18 12:28	Photo After Spray	0	Load JPG	
69	27/01/18 12:28	Photo After Spray	0	Load JPG	<b>2</b>
70	27/01/18 12:28	Photo After Spray	0	Load JPG	2
71	27/01/18 12:28	Photo After Spray	0	Load JPG	
72	27/01/18 12:28	Photo After Spray	0	Load JPG	
73	27/01/18 12:28	Photo After Spray	0	Load JPG	
74	27/01/18 12:28	Photo After Spray	0	Load JPG Load JPG	2
75 76	27/01/18 12:28 27/01/18 12:28	Photo After Spray Photo After Spray	0	Load JPG	
77	27/01/18 12:28	Photo After Spray	0	Load JPG Load JPG	
		Photo After Spray	0	Load JPG Load JPG	
78	27/01/18 12:28	riioto Aiter Spray	<b>.</b>	LUAU JPG	<b>T</b>

79	27/01/18 12:28	Photo After Spray	1	Load JPG	
80	27/01/18 12:28	Photo After Spray	0	Load JPG	
81	27/01/18 12:28	Photo After Spray	0	Load JPG	2
82	27/01/18 12:28	Photo After Spray	0	Load JPG	<b>2</b>
83	27/01/18 12:28	Photo After Spray	0	Load JPG	Ø
84	27/01/18 12:28	Photo After Spray	0	Load JPG	<b>2</b>
85	27/01/18 12:28	Photo After Spray	0	Load JPG	
86	27/01/18 12:28	Photo After Spray	•	Load JPG	<b>2</b>
87	27/01/18 12:28	Photo After Spray	0	Load JPG	2
88	27/01/18 12:28	Photo After Spray	0	Load JPG	
89	27/01/18 12:28	Photo After Spray	0	Load JPG	<b>2</b>
90	27/01/18 12:28	Photo After Spray	0	Load JPG	<b>2</b>
91	27/01/18 12:28	Photo After Spray	•	Load JPG	<b>2</b>
92	27/01/18 12:28	Photo After Spray	0	Load JPG	2
93	27/01/18 12:28	Photo After Spray	0	Load JPG	<b>2</b>

## **Documents Checklist**

DOCUMENTS CHECKLIST		Reset Save Print
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	<u> </u>	
	//	
Show Remarks To: Handling Insurer  Note: Remarks are private unless you show it to other parties.		

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** 

CS3/AIG18000028/SBE2

Date:

08/03/2018

REFERENCE

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1700004354

**Claimant Vehicle** No:

SKP2229E

Insured Vehicle No:

SGW6846H

Date of Loss:

30/12/2017

Nature of Claim:

ΤP

9981000390SG Claim No:

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

**SKP2229E** 

Make & Model:

MAZDA 3, 1.5 4 DOOR SEDAN SP (A)

Engine No:

P520224170

Reg. Date:

25/08/2014 (Man. Year: 2014)

Chassis No:

JM6BM42A8F0138122

Colour: **Engine Capacity:**  Brown

Odometer:

72658 km

Market Value/New Car Price:

1496 cc N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Engine Modification: Yes

No

Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size:

205/60 R16

Rear Tyre Size:

205/60 R16

Front Left Side: Front Right Side: Yokohama 6 mm Yokohama 6 mm Rear Left Side: Rear Right Side: Yokohama 6 mm Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	· · · · · · · · · · · · · · · · · · ·
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	· · · · · · · · · · · · · · · · · · ·
Nett Amount (S\$)	0.00	0.00	0.00	

**INSPECTION** 

Date of Assignment:

02/01/2018

Hendon Automotive (HQ)

Date Inspected:

02/01/2018 Inspected At:

280 WOODLANDS INDÚSTRIAL PARK E5, #01-19

HARVEST @ WOODLANDS

Singapore 757322

Estimated Period of Repair:

5.0 days

Adjuster:

Sebastian Yeang Wai Keen

Manager:

CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## **REPAIR DETAILS**

### **Recommended Parts**

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*FRT BUMPER	Deformed	0.00 F	*-F
2	1	*FRT BUMPER CLIPS	Necessary	0.00 F	*-F
3	1	*FRT BUMPER SIDE RETAINER	Necessary	0.00 F	*-F
4	1	*FRT RH BUMPER FOG LAMP COVER	Cut	0.00 F	*-F
5	1	*FRT GRILLE	Cracked	0.00 F	*-F
6	1	*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
7	1	*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*-F
8	1	*FRT RH SIDE LAMP	Scratched	0.00 F	*- F
9	1	*BONNET	Repair	0.00 F	*-F
10	1	*WIPER WASHER TANK	Deformed	0.00 F	*~F
11	1	*FRT RH FENDER	Dented	0,00 F	*-F
12	1	*FRT RH FENDER INNER SHIELD	Deformed	0.00 F	*-F
F=Fra	nchise part.	The state of the s			
			Total Parts (S\$)	0.00	0.00
		Report was unsubmitted durir	og this print-out		

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >