

မြန်မာ့ကျွန်း

Special Instructions:

45: \$ 3300.00

Third Parties

Claimant:

Surveyor: United Appraisal

Workshop: 8 Paragon.

From (Person): Christina Wang of MSU Date/Time: 08/13/2018
Estimated Cost: _____ Bill to: _____

OD/TP Re-inspection / (Evaluation)

To inspect Vehicle No: SDS 1414K Insured: SJM 2157A
at Workshop m/s S Paragon Tel: 9794 6477 (Edward)
of 71 Woodlands Ave 10 #01-10

Policy No: 71485658 BMT Claim No: 543535

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 27.12.2017
(Client's Present)

(Client's Record)

H.O.D. Enrolment/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 15.1.0 Confirmed with Final Fig , days (Red S / %; Original 4 days)

Date/Time: 10/5/18 Submit Final Fig \$2000, 3 days (Red \$1500 / 39 %; Original days)

MV: \$67K, LTA: \$44,473.00, NV: \$22,527.00

Submit PRS + Paper survey

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 11 MAY 2018

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Date _____

Basic & Addt

Transport

Photos

Others

Total

1) Date/Time 10/5/18 File Pass to typist

3) Date/Time _____ File Pass to _____

5) Date/Time _____ File Pass to _____

2) Date/Time _____ File Return to _____

4) Date/Time _____ File Return to _____

6) Date/Time _____ File Return to _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Dec 2017		02 Jan 2018 15:27 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TED SHIOK KWUN, ID: S1788933H								
Main Claimant:	HSIEH CHI KIN, ID: S7870912Z								
Vehicle Reg. No.:	SDS1414K	Date of Loss:	27/12/2017 18:00 - :59						
Claim Type:	TP / 543535	Policy/Cover Note No.:	71485658QMY (Comprehensive) Coverage: 27/12/2017 - 26/12/2018						
Vehicle Reg. No. (Insured):	SJM2757A	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	S Paragon Pte Ltd (HQ) 71 WOODLANDS AVE 10 #01-10 WOODLANDS INDUSTRIAL XCHANGE, 737743 Woodlands - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Imm.Advice due 03/01/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (08/03/2018): Alert - Adj Mandate Approved (S\$0.00) - SDS1414K - Claim Handler: Christina Wong 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

ASS. REC. BY:

REF:

C23 MSG18000061 Sb

Special Instruction:

SURVIVOR

Sebastian

ASSIGNMENT (Office)

From (Person):

Christina Ong of NSIG

Date/Time:

2/1/2018 @ 3:27pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8081414K

Insured:

SIM 2757A

at Workshop m/s

8 Paragon

Tel:

9914 6477

of

71 Woodlands Ave 10 #01-10

Policy No:

71485658QMY

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/12/17

CA / REV / REP. / REV 24 HRS WPI

H.O.D. Endorsement:

Date/Time:

04.01.2018 10:45am

Person Contacted:

Edward

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

Disassemble Part: 04.01.2018

After repair: 05.01.2018

27/01/18 2:38pm Email to Christina Wong thru mdfmen

REF: MSG 115

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 67k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 5051414K Yr Regn: 2007, Mar 12Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Estang 2.4A C.C. 2362Colour: White A/C: Insured / Std / NI / NASp. Reading: 111817 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ACKVO 7013153Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60R16R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 4/1/18 @ 1205pmSurvey held at 8 PargenDes. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop orO/S Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time / Action / Instruction

4/1/18 No GIA / Estimate

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report1) _____
Date/Time, File Return to?

2) _____

Report Format :

Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$ _____)☐ Interview (\$ _____)☐ Tech. Invs (\$ _____)☐ Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

) S + RS \$ _____

) Photos _____

) Others _____

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG18000061/Sb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 02-01-2018	
		Code : MSG	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SJM 2757A	Veh. Inspected	SDS 1414K
Policy No.	71485658QMY	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	02/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	27/12/2017	Inspection Date	04/01/2018
Survey held at	8 PARAGON - 71 WOODLANDS AVE 10 #01-06		
Repairer	-		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Dec 2017		02 Jan 2018 15:27 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by Insurer]	
Insured:	TEO SHIOK KWUN, ID: S1788933H		
Main Claimant:	HSIEH CHI KIN, ID: S7870912Z		
Vehicle Reg. No.:	SDS1414K	Date of Loss:	27/12/2017 17:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	71485658QMY (Comprehensive) Coverage: 27/12/2017 - 26/12/2018
Vehicle Reg. No. (Insured):	SJM2757A	Policy No. (Claimant):	
		Excess:	
Repairer:	8 Paragon Pte Ltd (HQ) 71 WOODLANDS AVE 10 #01-10 WOODLANDS INDUSTRIAL XCHANGE, 737743 Woodlands - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 03/01/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date

Priority

Type

Task Group

Subject

Handler

Assigned By

Completed On

Created On

Done?

No results.

Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin () : Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

	Y-Date	N-Date	Y-Date	N-Date
C Reference No.	✓			
C Customer Code	✓			
N Assign From	✓			
C Assign Date	✓			
C Veh No (Inspected)	✓			
C Veh No (Insured)	✓			
C D.O.A	✓			
C Policy No	✓			
C Claim No				
C Insurance Authorisation (CA /REV/REP)				
C Report Type	✓			
C Weekend Charges				
N Survey held at/Repairer	✓			
C Excess				

Surveyor () : Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C Vehicle No	✓			
C Regn Month/Year	✓			
N Vehicle Type	✓			
N Make & Model	✓			
C Engine Capacity. (C.C)	✓			
N Colour	✓			
C Odometer. (Sp.Reading)	✓			
C Chassis No	✓			
N General Condition	✓			
N Steering	✓			
N Brake	✓			
N Modification (Mod)	✓			
C Tyre Size	✓			
N Tyre Make	✓			
C Tyre Balance	✓			
C Date of Inspection	✓			
N Survey held	✓			
N Des.of Damages	✓			

(2) System - (Views/Merimen)

C Damaged Vehicle Photographs Uploaded	✓			
--	---	--	--	--

(3) Workshop Estimate/Assignment Form

N ALL Parts condition				
C Market Value for OD cases				
C Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C Days of repair				
C Finalised Amount				
C Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C Resurvey photo Uploaded				
---------------------------	--	--	--	--

Check By:

Case Handler

Date

*C: Critical *N: Non-Critical

View Sent Message

This mail is associated with :

***SDS1414K (543535)**
[SJM2757A]

TP
HSIEH CHI KIN
Dec 27 2017 6:00PM
[TEO SHIOK KWUN]
8 Paragon Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 27/01/2018 14:38 PM.
To MSIG_CWSF1
Subject Pre-repair Inspection

Dear Christina,

Refer to your assignment on 02.01.2018 at 3.27PM,

Please be informed that we have inspected the vehicle SDS 1414K on 04.01.2018 at 12.05PM.

At the time of inspection the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

SDS 1414k

Rear Bumper ✓ Cont 1417.80

Rear Bumper Lower Grassy ✓ SEE 45

Rear Bumper Retainer RH ✓ NEC 58.70

Labour: \$ 200

Spring Painting: \$ 450

Range: \$ 2200 - \$ 2700

UNITED Appraisal And Management Pte Ltd

Motor Vehicle Appraiser and Insurance Loss Adjuster
No. 8 Kaki Bukit Ave 4 #06-21 Premier @ Kaki Bukit Singapore 415875
Handphone No. : +65 9146 1186 Email : unitedappraisal@live.com.sg
Business Registration Nos. : 200817301N

Our ref. : UAM18.01.01-AK-STP-8PG-SDS1414K
Date : 30 Jan 2018

Hsieh Chi Kin

WITHOUT PREJUDICE

Dear Sir,

Re : Third Party Claim For Vehicle Registration No. SDS1414K

We refer to your instruction to appraise the above-mentioned vehicle on 02 January 2018

A static inspection was carried out and our report is enclosed for your perusal. The estimated cost of repair submitted by Messrs. 8 Paragon Pte Ltd for SGD 7,120.35 as per our attached schedule has been inspected thoroughly by us against the actual damages sustained on the above-mentioned vehicle and we recommend the replacement and rectification accordingly.

Our revised quotation for the repair is SGD 4,173.58. In our opinion, it to be excessive. Therefore, we recommend a contract lump-sum repair cost. This is more economical than to have the above-mentioned vehicle repaired on parts by/for parts basis. Invariably, the repairer has the prerogative/option for the recommended replacement parts to either be repaired or be replaced.

We have negotiated with the repairer and they have agreed to repair the above-mentioned vehicle for SGD 3,300.00 NETT. Which, in our opinion is fair and reasonable.

The repairer has agreed to undertake the repairs to your requirement at the recommended contract lump-sum. However, we have not given any instruction and authorisation to the repairer to proceed with the repairs.

Under normal circumstances, the entire repair of the damaged vehicle should be completed within a reasonable period of 4 (Four) days.

We are reverting the matter to you for a decision, and enclosed is our vehicle inspection report, appraisal schedule and invoice for services rendered.

Please do not hesitate to contact us if you have any queries on this matter.

Yours faithfully,
United Appraisal & Management Pte Ltd



Ananda K. Biswas Marc
Motor Vehicle Appraiser

Encls. :

The information contained in these document may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or use of this communication is strictly prohibited. If you received this document by error, please contact us immediately to arrange for its return.

UNITED Appraisal And Management Pte Ltd

Motor Vehicle Appraiser and Insurance Loss Adjuster
No. 8 Kaki Bukit Ave 4 #06-21 Premier @ Kaki Bukit Singapore 415875
Handphone No. : +65 9146 1186 Email : united.appraisal@live.com.sg
Business Registration Nos. : 200817301N

VEHICLE INSPECTION REPORT

To : Hsieh Chi Kin

Our ref. : UAM18.01.01-AK-STP-8PG-SDS1414K

Date : 30 Jan 2018

REFERENCE

Assign by	: Hsieh Chi Kin	Insured	: To be advice
Assign on	: 02 Jan 2018	Policy no.	: To be advice
Inspection on	: 02 Jan 2018	Claim no.	: To be advice
Accident on	: 27 Dec 2017	Sum insured	: To be advice
Workshop name	: 8 Paragon Pte Ltd	Excess	: Not applicable
Inspection at	: No 71 Woodlands Ave 10	3rd party Veh.	: To be advice
	#01-10 Woodlands Ind. Xchange	3rd party ins.	: To be advice
	Singapore 737743		

PARTICULARS OF DAMAGED VEHICLE

Registration no.	: SDS1414K	Odometer	: 111817 km
Make / Model	: Toyota Estima 2.4A	Chassis no.	: ACR507013153
Regn. date	: 12 Mar 2007	Engine no.	: 2AZ2156059
Body colour	: White	Engine cap.	: 2362 cc

PRE-ACCIDENT CONDITION OF VEHICLE (STATIC CHECK ONLY)

Steering	: In order	Paintwork	: Good
Footbrake	: In order	Undercarriage	: Serviceable
Handbrake	: In order	Gen. condition	: Good

TYRE CONDITION ON VEHICLE


	Make	Size	Tread depth	Type of road wheel
Front N/S	: Michelin	215/60R16	70%	Alloy
Front O/S	: Michelin	215/60R16	70%	Alloy
Rear N/S	: Michelin	215/60R16	70%	Alloy
Rear O/S	: Michelin	215/60R16	70%*	Alloy*

NOTE: The above percentages represent the estimated remaining life of tyre threads.

* Denotes damaged component/s

POINT OF IMPACT

On the off side rear in the direction from right to left.

**SYNOPSIS OF DAMAGES RESULTANT FROM THE ACCIDENT**

The impact of the collision has damaged / affected the o/s rear fender, rear undercarriage, rear bumper and etc...

Please refer to Annex A (Appraisalment Schedule) for a detailed account of the damages and photographs taken.

Note: Reinspection vehicle on 04 Jan 2018 for repair in progress.

RECOMMENDATION

The estimate cost of repair submitted by Messrs 8 Paragon Pte Ltd as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairers have agreed to undertake the repairs to the owner's satisfaction at our revision. We have not authorised the repairs.

Our adjusted cost of repair is SGD 3,300.00 to carry out the repairs. Please refer to Annex A (Appraisalment Schedule) for a detailed account of the cost estimates.

REMARKS

We have not authorised the repair. However, for information, under normal circumstances, the repair would takes approximately 4 (Four) working days to complete.

In accordance to your instruction, we have **NOT AUTHORISED** the repair to the damaged vehicle and the survey was conducted strictly on a "**WITHOUT PREJUDICE**" basis.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Appraisal Report, which includes evidence photographs.

Yours faithfully,
United Appraisal & Management Pte Ltd



Ananda K. Biswas Marc
Motor Vehicle Appraiser

APPRAISEMENT SCHEDULE

Annex A

Registration no. : SDS1414K

Our reference : UAM18.01.01-AK-STP-8PG-SDS1414K

S/N	Qty	Description	Condition / Remarks	Estimate by Wshop SGD	Adjusted Amt SGD
<u>LIST ITEMS</u>					
1	1	Rear fender o/s R	Serviceable	1373.00	0.00
2	1	Rear fender protector o/s X NN	Not Affected	154.00	0.00
3	1	Rear fender inner cowling o/s ✓ TN	Torn	115.00	115.00
4	1set	Rear fender inner cowling clip o/s ✓ NEC	Necessary	35.00	35.00
5	1	Rear fender glass moulding o/s X NN	Not Applicable	123.00	0.00
6	1	Rear fender air grille o/s X NN	Deformed	147.00	147.00
7	1	Rear shock absorber o/s X NN	Affected	321.00	321.00
8	1	Rear wheel hub bearing o/s X NN	Affected	386.00	386.00
9	1	Rear bumper ✓ TN	Deformed	981.85	981.85
10	1set	Rear bumper clip ✓ NEC	Necessary	60.00	60.00
11	2	Rear bumper side retainer @ SGD 132.25 ✓ CRK	O/S Cracked	264.50	132.25
				3960.35	2178.10
Less 0% / 25%				0.00	544.53
				3960.35	1633.58

SPECIAL NETT ITEMS

1	1	Sundries X NN	Necessary	50.00	30.00
2	1	Rear alloy rim o/s R ✓ Cut	Grazed	550.00	480.00
3	1	Rear tyre o/s 6% NN ✓ Cut X	Cut	180.00	150.00
				780.00	660.00
TOTAL				4740.35	2293.58

APPRAISEMENT SCHEDULE


Annex A



Registration no. : SDS1414K



Our reference : UAM18.01.01-AK-STP-8PG-SDS1414K


S/N	Qty	Description	Condition / Remarks	Estimate by Wshop SGD	Adjusted Amt SGD
			Balance C/F	4740.35	2293.58
<u>LABOUR & MISC CHARGES</u>					
1		To dismantle / renew the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.		800.00	600.00 400
2		To disconnect wire harness of electrical component to facilitate repairs, reconnect and check functions.		80.00	60.00 30
3		To remove and refit o/s rear tyre to replace o/s rear alloy rim. To perform tyre balancing.		80.00	60.00 ✓
4		To remove and refit o/s rear undercarriage for replacement of part.		300.00	280.00 80
5		To conduct computerize full wheel alignment.		120.00	100.00 60
6		To apply undercoating on the accident repair and replaced panel for rust protection.		200.00	180.00 X
7		Supply spray paint material and necessary items to respray o/s rear fender, rear bumper and other affected area / panel.		800.00	600.00 450
TOTAL				2380.00	1880.00
Total Parts and Labour Cost of Repair				7120.35	4173.58
Less (Lumpsum repair adjustment)					873.58
Adjustment Parts and Labour Cost of Repair					3300.00


3 days















Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0912Z
Vehicle Details	
Vehicle No.:	SDS1414K
Vehicle to be Exported:	No
Intended De-registration Date:	11 May 2018
Vehicle Make:	TOYOTA
Vehicle Model:	ESTIMA 2.4 A
Primary Colour:	White
Manufacturing Year:	2006
Engine No.:	2AZ2156059
Chassis No.:	ACR507013153
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$31,106.00
Original Registration Date:	12 Mar 2007
First Registration Date:	12 Mar 2007
Transfer Count:	1
Actual ARF Paid:	\$34,217.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Mar 2027
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$50,347.00
COE Rebate Amount:	\$44,473.00
Total Rebate Amount:	\$44,473.00

The information contained herein is correct as at 11 May 2018

OK



TOYOTA ESTIMA

Price Range ▼

Depreciation ▼

> 10 year(s) ▼

Vehicle Type ▼



Advanced Search

Used Car Comparison

— Comparing 3 Vehicles —

Toyota Estima 2.4A X (COE till 03/2027)



Add to Shortlist

Toyota Estima 2.4A (COE till 04/2027)



Add to Shortlist

Toyota Estima 2.4A (COE till 07/2027)



Add to Shortlist



Use search bar above to search to compare.

Clear All

Add all to Shortlist

Back to search result

CAR DETAILS

Price	\$69,800	\$75,800	\$61,800
Instalment	N.A.	N.A.	N.A.
Registration Date	30-Mar-2007	24-Apr-2007	02-Jul-2007
Manufactured	2006	2006	2006
Mileage	110,000 km	-	146,000 km
Transmission	Auto	Auto	Auto
Engine Cap	2,362 cc	2,362 cc	2,362 cc
Road Tax	\$1,802 /yr	\$1,802 /yr	\$1,802 /yr
Power	125.0 kW (167 bhp)	125.0 kW (167 bhp)	125.0 kW (167 bhp)
Curb Weight	1,700 kg	1,710 kg	1,700 kg
Features	Reliable DOHC 2.4L VVT-i Engine, 7 Speed CVT Transmission, SRS Airbags, ABS, Push Start, Keyless Entry, Dual Zone Climatic Aircon, 8 Seaters.	Powerful And Trustworthy Toyota VVTi Engine, Dual Auto Sliding Doors, Auto Headlights, Individual Rear Aircon Vent, SRS Airbags, ABS.	-
Accessories	Beige Interior, Leather Seats, 17" Sports Rims, DVD/Audio System, Front/ Rear Camera.	Beige Leather, Sports Rims, Touch Screen Audio, Reverse Sensors, Remote Control Keys With Sliding Door Access, 8 Seaters For Maximum Passenger Seats.	-
Description	Selling A Very Well Maintained 8 Seaters MPV. Regularly Serviced. No Repairs Needed. Consignment Vehicle. Great For Family With Kids. Please Call To Schedule For Viewing. High Trade In Welcome, Low Down Payment, In House Loan Available. Last 3 Owners Within The Family.	Sporty White Estima, Lowest Mileage, Under Utilized, Serviced Regularly, This Is An 8 Seater That Maximizes Passenger Capacity Over A Standard 7 Seaters, Very Well Kept And Clean Interior, Amazing Condition, Appointment To View Please.	Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only!
COE	\$50,347	\$52,008	\$52,473
OMV	\$26,775	\$32,994	\$26,607
ARF	\$29,453	\$36,294	\$29,268
Depreciation	\$7,850 /yr	\$8,580 /yr	\$6,760 /yr
No. of Owners	5	3	2
Type of Vehicle	MPV	MPV	MPV
Category	COE Car, Low Mileage Car	COE Car	COE Car
Availability	Available	Available	Available
Remarks	COE expiry date 2027-07-01	COE expiry date 2027-07-01	COE expiry date 2027-07-01

SELLER INFORMATION

Seller	Car2bond	Cars Connect	Boeki Auto & Marine	-
Address	210 Turf Club Road Lot C16	7 Kaki Bukit Road 1 #03-05	176 Sin Ming Drive #02-15	-
Office Number	64658178	-	65549390	-
Contact Person	Tim	Mr Yoon / Ms Ong	Boeki	-
Contact Number	64658178	64658178	65549390	-

[Home](#) |
 [New Cars](#) |
 [Used Cars](#) |
 [Sell My Car](#) |
 [Directory](#) |
 [Products](#) |
 [Insurance](#) |
 [Article](#) |
 [Forum](#) |
 [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or station wagons. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

Follow [sgCarMart.com](#)

[About Us](#) |
 [Careers](#) |
 [Contact Us](#) |
 [Sitemap](#) |
 [Terms of Service](#) |
 [Privacy Policy](#) |
 [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Dec 2017		02 Jan 2018 15:27 Edit Adj Rpt	S\$2,000.00 Edit Estimates	S\$2,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------




































CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	TEO SHIOK KWUN , ID: S1788933H	
Main Claimant:	HSIEH CHI KIN , ID: S7870912Z	
Vehicle Reg. No.:	SDS1414K	Date of Loss: 27/12/2017 18:00 - :59 [129 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 543535	Policy/Cover Note No.: 71485658QMY (Comprehensive) Coverage: 27/12/2017 - 26/12/2018
Vehicle Reg. No. (Insured):	SJM2757A	Policy No. (Claimant):
		Excess: S\$500.00
Repairer:	8 Paragon Pte Ltd (HQ) 71 WOODLANDS AVE 10 #01-10 WOODLANDS INDUSTRIAL XCHANGE, 737743 Woodlands - Tel:	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Imm.Advice due 03/01/2018]	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
• MSIG_SG (08/03/2018): Alert - Adj Mandate Approved (S\$0.00) - SDS1414K - Claim Handler: Christina Wong		

ALL ASSOCIATED TASKS	View All	Search Tasks	Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDS1414K (543535)
[SJM2757A]
TP
HSIEH CHI KIN
Dec 27 2017 6:00PM
[TEO SHIOK KWUN]
8 Paragon Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	27/01/18 14:35	General View						Load JPG	<input checked="" type="checkbox"/>	
2	27/01/18 14:35	General View						Load JPG	<input checked="" type="checkbox"/>	
3	27/01/18 14:35	General View						Load JPG	<input checked="" type="checkbox"/>	
4	27/01/18 14:35	General View						Load JPG	<input checked="" type="checkbox"/>	
5	27/01/18 14:35	General View						Load JPG	<input checked="" type="checkbox"/>	
6	27/01/18 14:35	General View						Load JPG	<input checked="" type="checkbox"/>	
7	27/01/18 14:35	General View						Load JPG	<input checked="" type="checkbox"/>	
8	27/01/18 14:35	General View						Load JPG	<input checked="" type="checkbox"/>	
9	27/01/18 14:35	General View						Load JPG	<input checked="" type="checkbox"/>	
10	27/01/18 14:35	General View						Load JPG	<input checked="" type="checkbox"/>	
11	27/01/18 14:35	General View						Load JPG	<input checked="" type="checkbox"/>	
12	27/01/18 14:35	General View						Load JPG	<input checked="" type="checkbox"/>	
13	27/01/18 14:35	General View						Load JPG	<input checked="" type="checkbox"/>	
14	27/01/18 14:35	General View						Load JPG	<input checked="" type="checkbox"/>	
15	27/01/18 14:35	General View						Load JPG	<input checked="" type="checkbox"/>	
16	27/01/18 14:35	Odometer Reading						Load JPG	<input checked="" type="checkbox"/>	
17	27/01/18 14:35	General View						Load JPG	<input checked="" type="checkbox"/>	
18	27/01/18 14:35	Chassis Number						Load JPG	<input checked="" type="checkbox"/>	
19	27/01/18 14:36	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
20	27/01/18 14:36	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
21	27/01/18 14:36	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
22	27/01/18 14:36	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
23	27/01/18 14:36	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
24	27/01/18 14:36	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
25	27/01/18 14:36	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
26	27/01/18 14:36	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
27	27/01/18 14:36	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
28	27/01/18 14:36	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
29	27/01/18 14:36	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
30	27/01/18 14:36	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
31	27/01/18 14:36	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
32	27/01/18 14:36	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
33	27/01/18 14:36	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
34	27/01/18 14:36	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
35	27/01/18 14:36	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
36	27/01/18 14:36	Photo After Spray						Load JPG	<input checked="" type="checkbox"/>	
37	27/01/18 14:36	Photo After Spray						Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
38	27/01/18 14:36	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
39	27/01/18 14:36	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
40	27/01/18 14:36	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
41	27/01/18 14:36	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
42	27/01/18 14:36	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
43	27/01/18 14:36	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
44	27/01/18 14:36	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
45	27/01/18 14:36	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
46	27/01/18 14:36	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
47	27/01/18 14:36	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
48	27/01/18 14:36	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
49	27/01/18 14:36	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
50	27/01/18 14:36	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
51	27/01/18 14:36	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
52	27/01/18 14:36	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
53	27/01/18 14:36	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page		<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	07/03/18 10:13	TP GIA report SDS1414K	1	Load PDF	
2	07/03/18 18:02	TP Survey Report	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	14/05/18 08:30	COLOUR PHOTO	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18000061/SRBE2

Date: 14/05/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	71485658QMY
Claimant Vehicle No :	SDS1414K	Insured Vehicle No :	SJM2757A
Date of Loss:	27/12/2017	Nature of Claim:	TP
		Claim No:	543535

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDS1414K	Engine No:	2AZ2156059
Make & Model:	TOYOTA ESTIMA, 2.4 (A)	Chassis No:	ACR507013153
Reg. Date:	12/03/2007 (Man. Year: 2006)	Odometer:	111817 km
Colour:	White		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,740.35	1,473.07	3,267.28	68.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,380.00	1,080.00	1,300.00	54.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,120.35	2,553.07	4,567.28	64.14
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	7,120.35	2,000.00	5,120.35	71.91
+ GST 7.00/7.00% (S\$)	498.42	140.00	358.42	71.91
Nett Amount (S\$)	7,618.77	2,140.00	5,478.77	71.91

INSPECTION

Date of Assignment: 02/01/2018
Date Inspected: 04/01/2018 Inspected At:

8 Paragon Pte Ltd (HQ)
71 WOODLANDS AVE 10 #01-10
WOODLANDS INDUSTRIAL XCHANGE
Singapore 737743

Estimated Period of Repair: 3.0 days

Adjuster: Sebastian Yeang Wai Keen**Manager:** Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$67,000.00(EST)-LTA REIMBURSEMENT VALUE: \$44,473.00=NETT VALUE: \$22,527.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 May 2018)
Parts:	M1-MPV	TOYOTA ESTIMA 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDS1414K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER O/S	Repair	1,373.00 F	*-FL
2	1		*REAR FENDER PROTECTOR O/S	Not Necessary	154.00 F	*-FL
3	1		*REAR FENDER INNER COWLING O/S	Torn	115.00 F	*115.00 FL
4	1		*SET REAR FENDER INNER COWLING CLIP O/S	Necessary	35.00 F	*35.00 FL
5	1		*REAR FENDER GLASS MOULDING O/S	Not Necessary	123.00 F	*-FL
6	1		*REAR FENDER AIR GRILLE O/S	Not Necessary	147.00 F	*-FL
7	1		*REAR SHOCK ABSORBER O/S	Not Necessary	321.00 F	*-FL
8	1		*REAR WHEEL HUB BEARING O/S	Not Necessary	386.00 F	*-FL
9	1		*REAR BUMPER	Torn	981.85 F	*981.85 FL
10	1		*SET REAR BUMPER CLIP	Necessary	60.00 F	*60.00 FL
11	1		*REAR BUMPER SIDE RETAINER	O/S Cracked	264.50 F	*132.25 FL
12	1		*SUNDRIES	Not Necessary	50.00 FS	*-FS
13	1		*REAR ALLOY RIM O/S	Cut	550.00 FS	*480.00 FS
14	1		*REAR TYRE O/S	Not Necessary	180.00 FS	*-FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,740.35	1,804.10
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	331.03
Total Parts (\$\$)	4,740.35	1,473.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	800.00	400.00
2	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS	New	80.00	30.00
3	TO REMOVE AND REFIT O/S REAR TYRE TO REPLACE O/S REAR ALLOY RIM. TO PERFORM TYRE BALANCING	New	80.00	60.00
4	TO REMOVE AND REFIT O/S REAR UNDERCARRIAGE FOR REPLACEMENT OF PART	New	300.00	80.00
5	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	60.00
6	TO APPLY UNDERCOATING ON THE ACCIDENT REPAIR AND REPLACED PANEL FOR RUST PROTECTION	New	200.00	0.00
7	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY O/S REAR FENDER, REAR BUMPER AND OTHER AFFECTED AREA / PANEL	New	800.00	450.00
Gross Labour Cost (S\$)			2,380.00	1,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >