

ASST. REC. BY:

REF:

CS/MS618000230 / DFB

Special Instruction:

Supervisor
Mamen

Bryan

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

M211

Date/Time:

04/01/2018 11:51am

Estimated Cost:

Bill to:

OL / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLM 8300X

Insured:

SJZ 3237J

at Workshop m/s

Teamwork

Tel:

6844 2475

of

53 Ubi Ave 1 # 01-24

Policy No:

2784 3959MCX

Claim No:

543536

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A 28122017

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time:

04/01/2018 11:51am

Person Contacted:

Chris

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate


SLM 8300X - X

SJZ 3237J - CS/MS618000059 / Kib

DOA: 28122017

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MY
 To inspect Vehicle No: _____
 at / Workshop no: _____
 at: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of VEH: _____
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 D/C Accident Report: _____ Consistent? Yes or No
 G/A / PP Seen: _____ Consistent? Yes or No
 Est. Repair: 12 days Res. Yes or No
 Cum. Sum: 20 Rs. 3 Yrs. Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT



at No: SLM 8300X Reg: 2017 April
 Type: MCycle / Bus / Van / Lorry / Taxi / Private / Other
 Truck / Trailer or
 Make: Toyota Corolla Altis 1598
 Colour: Red H/C Insured / Sto / No / NA
 Seating: 12950 T/Fold Insured / Sto / No / NA
 Eng No: 12RY339107
 C No: NR053REH104560077
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inspected / Jammed / Leaked / Burnt or
 Brakes: Inspected / Jammed / Leaked / Burnt or
 Mod: Nil / S / A / STD A / Rim or
 Tyre Size: P: 215 / 45 R 17
R: ———
 BS / DUN / EXNOVA / GY / PS / LIZA / MID / OHTSU / PIR / SUMI
 TOYO / YOKO or Mommu
 Front: _____ Rear: _____
 R/Ba: S mm R/Ba: S mm
 L/Ba: S mm L/Ba: S mm
 D/OA: 28/02/2017 D/O: 03/01/2018
 Surveyed at: TecumDinc Paga ubi
 Des. of Damages: Frt. / Rear / O/S / N/S / U/C / Roof top or
N/S Front 7 N/S Body 7 N/S Rear
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time: _____ Action / Instruction
MSG 652 3237J
MV MV 95K
LTA 56.4K
HL 38.6K
30/04/18 Final 2/3 14800/- with 12 days 7/11
(Red: 55713-35 40337 42! 73%)

RECEIVED 03 MAY 2018

Dist. The File Pass of: ☐ Prel. Report
215 Typist ☒ Final Report
 Dist. The File Record:
 Add Fee: ☐ ☐ ☐ ☐
 Report Form: TP
 LUNO 30/04/18 4300/-

Days Of Repair: 12
 Resurvey No. of Trip: 2
 Add Fee: ☐ ☐ ☐ ☐
 Report Form: TP
 LUNO 30/04/18 4300/-

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Dec 2017		04 Jan 2018 10:51 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	STARHIGH ASIA PACIFIC PTE LTD, Co. Reg. No.: 200618190W		
Main Claimant:	CHEAH MEE YIN, ID: 57778050E		
Vehicle Reg. No.:	SLM8300X	Date of Loss:	28/12/2017 23:00 - :59
Claim Type:	TP / 543536	Policy/Cover Note No.:	27843959MCX (Comprehensive) Coverage: 01/03/2017 - 28/02/2018
Vehicle Reg. No. (Insured):	5JZ3237J	Policy No. (Claimant):	
		Excess:	S\$3,500.00
Repairer:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 05/01/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18000230/Dtb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 04-01-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJZ 3237J	Veh. Inspected	SLM 8300X
Policy No.	27843959MCX	Coverage (\$)	0.00
Claim No.	543536	Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	04/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	28/12/2017	Inspection Date	04/01/2018
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Pte Ltd

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Singapore 408934

Paya Ubi Industrial Park

Tel : 6844 2475 Fax : 6844 2474

E-mail : claims@teamworkgarage.com

Register number : 201015366H

3RD PARTY CLAIM ESTIMATION

Vehicle number	: SLM8300X
Make / Model	: TOYOTA ALTIS
Chassis number	: MR053REH104560077
Accident date	: 28.12.2017
Reference	: 1712-55

M/s MSIG Insurance (S) Pte Ltd

16 Raffles Quay

#24-01 Hong Leong Building

Singapore 048581

Qty Particulars

Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		Unit Price - SGD \$
1	FRONT BUMPER broken	683.30 ✓
1	FRONT BUMPER TOP RUBBER NH	45.00 X
2	FRONT BUMPER SIDE RETAINER N/S broken o/s NH	34.00 68.00 ✓
1	FRONT BUMPER REINFORCEMENT U/t	380.00 ✓
1	FRONT BUMPER LOWER GRILLE damaged	239.00 ✓
2	FRONT BUMPER FOG LAMP COVER N/S mounting brace o/s NH	105.00 210.00 ✓
1	FRONT RH FOG LAMP N/S mounting brace o/s NH	125.00 250.00 ✓
1	FRONT GRILLE crack	379.00 ✓
1	FRONT GRILLE EMBLEM LOGO Nec	61.00 ✓
1	FRONT SUPPORT PANEL r/w	708.00 X
2	HORN NH	171.00 X
2	FRONT HEADLAMP N/S broken o/s NH	462.50 925.00 ✓
1	FRONT LH FENDER Bnc	430.60 ✓
1	FRONT LH FENDER EMBLEM LOGO -VVTI Nec	49.00 ✓
1	FRONT LH FENDER INNER SHIELD damaged	183.00 ✓
1	FRONT LH WIPER TOP GARNISH NH	377.00 X
1	FRONT BONNET U/t	780.00 ✓
1	BONNET LOCK NH	191.00 X
1	BONNET INSULATOR NH	224.00 X
2	BONNET HINGE r/w	182.00 X
1	AIRCON CONDENSER NH	1431.00 X
1	RADIATOR NH	1781.20 X
1	RADIATOR TOP COWLING NH	306.00 X
1	RADIATOR FAN ASSY NH	410.59 X
1	RADIATOR EXPANSION TANK NH	145.00 X
1	FRONT LH FENDER INNER WHEELHOUSE Dam r/w	648.00 X
1	FRONT LH CHASSIS FRAME NH	715.30 X
1	FRONT LH SHOCK ABSORBER distorted	475.00 ✓
1	FRONT LH KNUCKLE ARM distorted	454.00 ✓
1	FRONT LH KNUCKLE ARM BEARING D. m	149.00 ✓
1	FRONT LH LOWER ARM broken	536.00 ✓
1	FRONT LH STEERING TIE ROD END U/t	169.00 ✓
1	FRONT LH DRIVE SHAFT distorted	721.20 ✓
1	STEERING RACK AND PINION S/S Dam	2419.00 ✓

1	FRONT ENGINE MOUNTING <i>MM</i>	319.30 X
1	SIDE ENGINE MOUNTING <i>MM</i>	291.50 X
1	REAR GEARBOX MOUNTING <i>MM</i>	389.00 X
1	GEARBOX ASSY <i>MM</i>	28000.00 X
1	FRONT LH DOOR PANEL <i>Svc</i>	1270.70 ✓
1	FRONT LH DOOR INNER TRIM <i>mounting crack</i>	697.50 ✓
1	FRONT LH DOOR LOCK ASSY <i>Svc</i>	581.65 X
1	FRONT RH DOOR REGULATOR <i>Wt</i>	573.80 ✓
1	REAR LH DOOR PANEL <i>Rebuilt</i>	1097.80 ✓
1	REAR LH DOOR INNER TRIM <i>mounting crack</i>	649.09 ✓
1	REAR LH DOOR LOCK ASSY <i>Svc</i>	549.50 X
1	REAR LH DOOR REGULATOR <i>MM</i>	539.20 X
2	FRONT LH DOOR HINGE <i>Svc</i>	132.70 X
1	FRONT LH DOOR CHECKER <i>Svc</i>	122.50 X
2	REAR LH DOOR HINGE <i>replace</i>	132.70 X
1	REAR LH DOOR CHECKER <i>Svc</i>	122.60 X
1	REAR AXLE BEAM <i>distorted</i>	1932.00 ✓
1	REAR LH WHEEL HUB AND BEARING <i>MM</i>	520.70 X
1	REAR LH SHOCK ABSORBER <i>distorted</i>	650.00 ✓
1	FRONT LH PILLAR <i>Svc</i>	1097.09 X
1	LH SILL PANEL <i>Rebuilt</i>	860.40 ✓
16565.89		57425.92
Less 25%		14356.48
12424.41		43069.44
Subtotal		
Balance C/F		43069.44
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
Balance B/F		43069.44
1 SET	FRONT BUMPER CLIP <i>MM</i>	60.00 30/-
1 SET	FRONT FENDER INNER SHIELD CLIP <i>MM</i>	50.00 20/-
1 SET	FRONT GRILLE CLIP <i>MM</i>	30.00 20/-
1 BOT	COOLANT <i>Svc</i>	50.00 X
3 BOT	TRANSMISSION FULID <i>MM</i>	300.00 X
1	NUMBER PLATE <i>Svc</i>	60.00 X
2	RIM <i>cut n/s front n/s rear</i>	1600.00 1000/-
1	TYRE <i>Svc</i>	500.00 X
1070/-		
Subtotal		2650.00
Balance C/F		45719.44
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
Balance B/F		45719.44
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	60.00 30/-
2	REMOVE AND REPLACE RADIATOR AND TOP UP COOLANT	200.00 <i>MM</i>
3	REMOVE AND REPLACE CONDENSER AND TOP UP GAS	200.00 <i>MM</i>
4	REMOVE AND REFIT FRONT DASHBOARD	400.00 <i>MM</i>
5	REMOVE AND REFIT ENGINE ASSY	500.00 <i>MM</i>

6	REMOVE AND RENEW GEARBOX ASSY	500.00 NH
7	MOUNT VEHICLE ON BENCH FOR CHASSIS REPLACEMENT	500.00 NH
8	CHECK FRONT WHEEL ALIGNMENT	150.00 80/-
9	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS	200.00 180/-
10	TRANSFER PARTS ATTACHMENT , FROM OLD FRONT DOOR TO NEW	200.00 60/-
11	TRANSFER PARTS ATTACHMENT , FROM OLD REAR DOOR TO NEW	200.00 60/-
12	PANEL BEATING ON AFFECTED AREAS	2500.00 600/-
13	SPRAY PAINTING ON AFFECTED AREAS	2000.00 1400/-
14	APPLY ANTI RUST ON AFFECTED AREAS	200.00 80/-
Subtotal		7810.00
Grand total		53529.44
03/01/2018 2105 hrs		16984.41
NOT Author		1557.97
L/S NH		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

12 days
2 Kk Auto

18542.38
L/S 14800/-

Check MV

Check part prices.



TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Singapore 408934

Paya Ubi Industrial Park

Tel : 6844 2475 Fax : 6844 2474

E-mail : claims@teamworkgarage.com

Register number : 201015366H

3RD PARTY CLAIM SUPPLEMENTRY ITEMS

M/s MSIG Insurance (S) Pte Ltd

16 Raffles Quay

#24-01 Hong Leong Building

Singapore 048581

Vehicle number	:	SLM8300X
Make / Model	:	TOYOTA/ALTIS
Chassis number	:	MR053REH104560077
Accident date	:	28 December 2017
Reference	:	1712-55

Qty	Particulars	Unit Price - SGD \$
	<u>PARTS REPLACEMENT - LIST ITEMS</u>	
1	FRONT LH STABILISER LINK <i>Bt</i>	281.30 ✓
1	LH REAR FENDER <i>Dented</i>	1173.50 ✓
1	FRONT BUMPER SPONGE <i>turn</i>	59.20 ✓
1	FRONT UNDERCOVER <i>crack</i>	120.30 ✓
1	AIR DUCT <i>damaged</i>	68.00 ✓
1	AIR FILTER BOX <i>broken</i>	175.00 ✓
		1877.30
	Less 25%	469.32
	Subtotal	1407.98
	Balance C/F	1407.98
	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	1407.98
1	REMOVE AND RENEW REAR UNDERCARRIAGE P. PARTS <i>150/-</i>	200.00 150/-
	Subtotal	200.00
	Grand total	1607.98
		1557.97

Sup
2K11 Auto
[Signature]

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/12/2017 12:54
Date Of Accident	28/12/2017 21:25
Exact Location Of Accident	JUNCTION OF BALESTIER ROAD TOWARDS CTE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM8300X
Insured/Policyholder	
Name Of Registered Owner	CHEAH MEE YIN
NRIC No	S7778050E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96479869
Alternative Phone No	OTHERS-97459446

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P1925165
Cover Note Number	

Driver

Name of Driver	CHEAH MEE YIN
NRIC No	S7778050E
Date Of Birth	02/06/1977
Occupation	INDOOR
Date Of Driving Pass	13/12/2001
Driving Experience	16 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96479869
Fax Number	
Contact Number	OTHERS-97459446
Email Address	NOEMAIL

Address	17 BALMEG HILL # 03-35 SINGAPORE
Postcode	119919
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH STATEMENT RECORDED BY JIA MIN - PROGRESSIVE AUTOMOTIVE PTE LTD TEL 67415336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO WITH OWNER WORKSHOP
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJZ3237J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TANG YU KIANG
NRIC/Passport Number	
Contact Number	98765339
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	CHEAH MEE YIN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SLM8300X
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


29/12/17
12.52pm

JsaMin

Sketch Plan #2

SKETCH PLAN

JUNCTION AT BALESTIER TOWARD CTE EX1



My car was travelling along Balestier Road towards CTE. While the traffic light was green in my favor and all the vehicles at the opposite side of the traffic were completely stopped, I make gradually make a right turn towards the slip road of CTE. While my car was in the process of turning, Vehicle B without stopping due to traffic light was red at his direction, travelling in a fast speed beating the red light and hit onto my car left side portion of my car resulting damages and starches along the left side portion of my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Signature of Reporting Centre Personnel

29/12/17
13 52pm

John M. M.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6544-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 12 Jan 2018

Preliminary Advice

Insured Vehicle No	: SJZ3237J	Accident Date	: 28/12/2017
TP Vehicle No	: SLM8300X	Assignment Date	: 04/01/2018
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 12.00
Date of Inspection	: 03/01/2018		
Inspection At	: TEAMWORK GARAGE PTE LTD (HQ) 53 UBI AVE 1 #01-24, PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front, n/sbody n/s rear claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	53,529.44
Revised Amount	:S\$	15,170.17
Check Items (Estimated)	:S\$	0.00
Total	:S\$	15,170.17
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Inis Auth'ed	Status
Main	29 Dec 2017		04 Jan 2018 10:51 Edit Adj Rpt	\$S\$14,800.00 Edit Estimates	\$S\$14,800.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	STARHIGH ASIA PACIFIC PTE LTD, Co. Reg. No.: 200618190W		
Main Claimant:	CHEAH MEE YIN, ID: 57778050E		
Vehicle Reg. No.:	SLM8300X	Date of Loss:	28/12/2017 23:00 - :59 [8 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 543536	Policy/Cover Note No.:	27843959MCK (Comprehensive) Coverage: 01/03/2017 - 28/02/2018
Vehicle Reg. No. (Insured):	SJZ32373	Policy No. (Claimant):	
		Excess:	\$S\$3,500.00
Repairer:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 03/02/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLM8300X (543536)
[SJZ3237J]
TP
CHEAH MEE YIN
Dec 28 2017 11:00PM
[STARHIGH ASIA PACIFIC PTE LTD]
Teamwork Garage Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View View in Browser	
Assessment Reports							1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	12/01/18 13:24	Adjuster Immediate Advice		 Load HTM				
Photos/Images							3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	27/03/18 13:09	Front View Right		 Load JPG	☒			
2	27/03/18 13:09	Front View Left		 Load JPG	☒			
3	27/03/18 13:09	General View		 Load JPG	☒			
4	27/03/18 13:09	General View		 Load JPG	☒			
5	27/03/18 13:09	General View		 Load JPG	☒			
6	27/03/18 13:09	General View		 Load JPG	☒			
7	27/03/18 13:09	General View		 Load JPG	☒			
8	27/03/18 13:09	General View		 Load JPG	☒			
9	27/03/18 13:09	General View		 Load JPG	☒			
10	27/03/18 13:09	General View		 Load JPG	☒			
11	27/03/18 13:09	General View		 Load JPG	☒			
12	27/03/18 13:09	General View		 Load JPG	☒			
13	27/03/18 13:09	General View		 Load JPG	☒			
14	27/03/18 13:09	General View		 Load JPG	☒			
15	27/03/18 13:09	General View		 Load JPG	☒			
16	27/03/18 13:09	General View		 Load JPG	☒			
17	27/03/18 13:09	General View		 Load JPG	☒			
18	27/03/18 13:09	General View		 Load JPG	☒			
19	27/03/18 13:09	General View		 Load JPG	☒			
20	27/03/18 13:09	General View		 Load JPG	☒			
21	27/03/18 13:09	General View		 Load JPG	☒			
22	27/03/18 13:09	General View		 Load JPG	☒			
23	27/03/18 13:09	General View		 Load JPG	☒			
24	27/03/18 13:09	General View		 Load JPG	☒			
25	27/03/18 13:09	General View		 Load JPG	☒			
26	27/03/18 13:09	General View		 Load JPG	☒			
27	27/03/18 13:09	General View		 Load JPG	☒			
28	27/03/18 13:09	General View		 Load JPG	☒			
29	27/03/18 13:09	General View		 Load JPG	☒			
30	27/03/18 13:09	General View		 Load JPG	☒			
31	27/03/18 13:09	General View		 Load JPG	☒			
32	27/03/18 13:09	General View		 Load JPG	☒			
33	27/03/18 13:09	General View		 Load JPG	☒			
34	27/03/18 13:09	General View		 Load JPG				

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
35	27/03/18 13:09	General View	 Load JPG	☒
36	27/03/18 13:09	General View	 Load JPG	☒
37	27/03/18 13:09	General View	 Load JPG	☒
38	27/03/18 13:09	General View	 Load JPG	☒
39	27/03/18 13:09	General View	 Load JPG	☒
40	27/03/18 13:09	General View	 Load JPG	☒
41	27/03/18 13:09	General View	 Load JPG	☒
42	27/03/18 13:09	General View	 Load JPG	☒
43	27/03/18 13:09	General View	 Load JPG	☒
44	27/03/18 13:09	General View	 Load JPG	☒
45	27/03/18 13:09	General View	 Load JPG	☒
46	27/03/18 13:09	General View	 Load JPG	☒
47	27/03/18 13:09	General View	 Load JPG	☒
48	27/03/18 13:09	General View	 Load JPG	☒
49	27/03/18 13:09	General View	 Load JPG	☒
50	27/03/18 13:09	General View	 Load JPG	☒
51	27/03/18 13:09	General View	 Load JPG	☒
52	27/03/18 13:09	General View	 Load JPG	☒
53	27/03/18 13:09	General View	 Load JPG	☒
54	27/03/18 13:09	General View	 Load JPG	☒
55	27/03/18 13:09	General View	 Load JPG	☒
56	27/03/18 13:09	General View	 Load JPG	☒
57	27/03/18 13:09	General View	 Load JPG	☒
58	27/03/18 13:09	General View	 Load JPG	☒
59	27/03/18 13:09	General View	 Load JPG	☒
60	27/03/18 13:09	General View	 Load JPG	☒
61	27/03/18 13:09	General View	 Load JPG	☒
62	27/03/18 13:09	General View	 Load JPG	☒
63	27/03/18 13:09	General View	 Load JPG	☒
64	27/03/18 13:09	General View	 Load JPG	☒
65	27/03/18 13:09	General View	 Load JPG	☒
66	27/03/18 13:09	General View	 Load JPG	☒
67	27/03/18 13:09	General View	 Load JPG	☒
68	27/03/18 13:09	General View	 Load JPG	☒
69	27/03/18 13:09	General View	 Load JPG	☒
70	27/03/18 13:09	General View	 Load JPG	☒
71	27/03/18 13:09	General View	 Load JPG	☒
72	27/03/18 13:09	General View	 Load JPG	☒
73	27/03/18 13:09	General View	 Load JPG	☒
74	27/03/18 13:09	General View	 Load JPG	☒
75	27/03/18 13:09	General View	 Load JPG	☒
76	27/03/18 13:09	General View	 Load JPG	☒
77	27/03/18 13:09	General View	 Load JPG	☒
78	27/03/18 13:09	General View	 Load JPG	☒
79	27/03/18 13:09	General View	 Load JPG	☒
80	27/03/18 13:09	General View	Load JPG	☒
81	27/03/18 13:09	General View	Load JPG	☒
82	27/03/18 13:09	General View	Load JPG	☒
83	27/03/18 13:09	General View	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	27/03/18 13:09	General View	 Load JPG	☒
85	27/03/18 13:09	Odometer Reading	 Load JPG	☒
86	27/03/18 13:09	Chassis Number	 Load JPG	☒
87	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
88	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
89	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
90	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
91	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
92	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
93	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
94	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
95	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
96	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
97	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
98	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
99	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
100	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
101	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
102	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
103	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
104	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
105	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
106	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
107	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
108	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
109	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
110	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
111	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
112	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
113	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
114	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
115	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
116	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
117	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
118	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
119	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
120	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
121	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
122	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
123	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
124	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
125	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
126	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
127	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
128	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
129	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
130	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
131	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
132	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
133	27/03/18 13:10	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
134	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
135	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
136	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
137	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
138	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
139	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
140	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
141	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
142	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
143	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
144	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
145	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
146	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
147	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
148	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
149	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
150	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
151	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
152	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
153	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
154	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
155	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
156	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
157	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
158	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
159	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
160	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
161	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
162	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
163	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
164	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
165	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
166	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
167	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
168	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
169	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
170	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
171	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
172	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
173	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
174	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
175	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
176	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
177	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
178	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
179	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
180	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
181	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
182	27/03/18 13:10	Reinspection Photo	 Load JPG	☒
183	27/03/18 13:10	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
184	27/03/18 13:10	Reinspection Photo		☒
185	27/03/18 13:10	Reinspection Photo		☒
186	27/03/18 13:10	Reinspection Photo		☒
187	27/03/18 13:10	Reinspection Photo		☒
188	27/03/18 13:10	Reinspection Photo		☒
189	27/03/18 13:10	Reinspection Photo		☒
190	27/03/18 13:10	Reinspection Photo		☒
191	27/03/18 13:10	Finishing Photo		☒
192	27/03/18 13:10	Finishing Photo		☒
193	27/03/18 13:10	Finishing Photo		☒
194	27/03/18 13:10	Finishing Photo		☒
195	27/03/18 13:10	Finishing Photo		☒
196	27/03/18 13:10	Finishing Photo		☒
197	27/03/18 13:10	Finishing Photo		☒
198	27/03/18 13:10	Finishing Photo		☒
199	27/03/18 13:10	Finishing Photo		☒
200	27/03/18 13:10	Finishing Photo		☒
201	27/03/18 13:11	Finishing Photo		☒
202	27/03/18 13:11	Finishing Photo		☒
203	27/03/18 13:11	Finishing Photo		☒
204	27/03/18 13:11	Finishing Photo		☒
205	27/03/18 13:11	Finishing Photo		☒
206	27/03/18 13:11	Finishing Photo		☒
207	27/03/18 13:11	Finishing Photo		☒
208	27/03/18 13:11	Finishing Photo		☒
209	27/03/18 13:11	Finishing Photo		☒
210	27/03/18 13:11	Finishing Photo		☒
211	27/03/18 13:11	Finishing Photo		☒
212	27/03/18 13:11	Finishing Photo		☒
213	27/03/18 13:11	Finishing Photo		☒
214	27/03/18 13:11	Finishing Photo		☒
215	27/03/18 13:11	Finishing Photo		☒
216	27/03/18 13:11	Finishing Photo		☒
217	27/03/18 13:11	Finishing Photo		☒
218	27/03/18 13:11	Finishing Photo		☒
219	27/03/18 13:11	Finishing Photo		☒
220	27/03/18 13:11	Finishing Photo		☒
221	27/03/18 13:11	Finishing Photo		☒
222	27/03/18 13:11	Finishing Photo		☒
223	27/03/18 13:11	Finishing Photo		☒
224	27/03/18 13:11	Finishing Photo		☒
225	27/03/18 13:11	Finishing Photo		☒
226	27/03/18 13:11	Finishing Photo		☒
227	27/03/18 13:11	Finishing Photo		☒
228	27/03/18 13:11	Finishing Photo		☒
229	27/03/18 13:11	Finishing Photo		☒
230	27/03/18 13:11	Finishing Photo		☒
231	27/03/18 13:11	Finishing Photo		☒
232	27/03/18 13:11	Finishing Photo		☒
233	27/03/18 13:11	Finishing Photo		☒

Assessment Reports				1 per page	☒
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
234	27/03/18 13:11	Finishing Photo		 Load JPG	☒
Documentation				1 per page	☒
No	Finalized On		MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/01/18 16:51	TP GIA Rep - SLM8300X		 Load PDF	
2	02/01/18 16:51	Email from Third Party		 Load PDF	
3	02/01/18 16:52	OI GIA Rep - SJZ3237J		 Load PDF	
4	04/01/18 10:53	Email frm TP - Appoint LKK as SJE		 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^v

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18000230/DTBQ2

Date: 07/05/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 27843959MCX

Claimant Vehicle No : SLM8300X

Insured Vehicle No : SJZ3237J

Date of Loss: 28/12/2017

Nature of Claim: TP

Claim No: 543536

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLM8300X

Make & Model: TOYOTA COROLLA ALTIS, 1.6 CVT (A)

Engine No: 1ZRY339107

Reg. Date: 12/04/2017 (Man. Year: 2016)

Chassis No: MR053REH104560077

Colour: Red

Odometer: 12950 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17

Rear Tyre Size: 215/45 R17

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	47,127.41	14,902.39	32,225.02	68.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,010.00	3,640.00	4,370.00	54.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	55,137.41	18,542.39	36,595.02	66.37
Approved Total (Overridden) (S\$)		14,800.00		
(S\$)	55,137.41	14,800.00	40,337.41	73.16
+ GST 7.00/7.00% (S\$)	3,859.62	1,036.00	2,823.62	73.16
Nett Amount (S\$)	58,997.03	15,836.00	43,161.03	73.16

INSPECTION

Date of Assignment: 04/01/2018

Date Inspected: 03/01/2018 Inspected At:

Teamwork Garage Pte Ltd (HQ)
53 Ubi Ave 1 #01-24, Paya Ubi Industrial
Park
Singapore 408934

Estimated Period of Repair: 12.0 days

Adjuster: BRYAN TANI

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 May 2018)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM8300X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	683.30 FL	*683.30 FL
2	1		*FRONT BUMPER TOP RUBBER	Not Necessary	45.00 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER	N/S Broken / O/S Not Necessary	68.00 FL	*34.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	380.00 FL	*380.00 FL
5	1		*FRONT BUMPER LOWER GRILLE	Deformed	239.00 FL	*239.00 FL
6	1		*FRONT BUMPER FOG LAMP COVER	N/S MtgCracked/O/SNotNecessary	210.00 FL	*105.00 FL
7	1		*FRONT RH FOG LAMP	N/S MtgCracked/O/SNotNecessary	250.00 FL	*125.00 FL
8	1		*FRONT GRILLE	Cracked	379.00 FL	*379.00 FL
9	1		*FRONT GRILLE EMBLEM LOGO	Necessary	61.00 FL	*61.00 FL
10	1		*FRONT SUPPORT PANEL	Repair	708.00 FL	*- FL
11	2		*HORN	Not Necessary	171.00 FL	*- FL
12	1		*FRONT HEADLAMP	N/S Broken / O/S Not Necessary	925.00 FL	*462.50 FL
13	1		*FRONT LH FENDER	Buckled	430.60 FL	*430.60 FL
14	1		*FRONT LH FENDER EMBLEM LOGO -VVIT	Necessary	49.00 FL	*49.00 FL
15	1		*FRONT LH FENDER INNER SHIELD	Deformed	183.00 FL	*183.00 FL
16	1		*FRONT LH WIPER TOP GARNISH	Not Necessary	377.00 FL	*- FL
17	1		*FRONT BONNET	Bent	780.00 FL	*780.00 FL
18	1		*BONNET LOCK	Not Necessary	191.00 FL	*- FL
19	1		*BONNET INSULATOR	Not Necessary	224.00 FL	*- FL
20	2		*BONNET HINGE	Repair	182.00 FL	*- FL
21	1		*AIRCON CONDENSER	Not Necessary	1,431.00 FL	*- FL
22	1		*RADIATOR	Not Necessary	1,781.20 FL	*- FL
23	1		*RADIATOR TOP COWLING	Not Necessary	306.00 FL	*- FL
24	1		*RADIATOR FAN ASSY	Not Necessary	410.59 FL	*- FL
25	1		*RADIATOR EXPANSION TANK	Not Necessary	145.00 FL	*- FL
26	1		*FRONT LH FENDER INNER WHEELHOUSE	Repair	648.00 FL	*- FL
27	1		*FRONT LH CHASSIS FRAME	Not Necessary	715.30 FL	*- FL
28	1		*FRONT LH SHOCK ABSORBER	Distorted	475.00 FL	*475.00 FL
29	1		*FRONT LH KNUCKLE ARM	Distorted	454.00 FL	*454.00 FL
30	1		*FRONT LH KNUCKLE ARM BEARING	Damaged	149.00 FL	*149.00 FL
31	1		*FRONT LH LOWER ARM	Broken	536.00 FL	*536.00 FL
32	1		*FRONT LH STEERING TIE ROD END	Bent	169.00 FL	*169.00 FL
33	1		*FRONT LH DRIVE SHAFT	Distorted	721.20 FL	*721.20 FL
34	1		*STEERING RACK AND PINION	Damaged	2,419.00 FL	*2,419.00 FL
35	1		*FRONT ENGINE MOUNTING	Not Necessary	319.30 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*SIDE ENGINE MOUNTING	Not Necessary	291.50 FL	*- FL
37	1		*REAR GEARBOX MOUNTING	Not Necessary	389.00 FL	*- FL
38	1		*GEARBOX ASSY	Not Necessary	28,000.00 FL	*- FL
39	1		*FRONT LH DOOR PANEL	Buckled	1,270.70 FL	*1,270.70 FL
40	1		*FRONT LH DOOR INNER TRIM	Mtg Cracked	697.50 FL	*697.50 FL
41	1		*FRONT LH DOOR LOCK ASSY	Serviceable	581.65 FL	*- FL
42	1		*FRONT RH DOOR REGULATOR	Bent	573.80 FL	*573.80 FL
43	1		*REAR LH DOOR PANEL	Dented	1,097.80 FL	*1,097.80 FL
44	1		*REAR LH DOOR INNER TRIM	Mtg Cracked	649.09 FL	*649.09 FL
45	1		*REAR LH DOOR LOCK ASSY	Serviceable	549.50 FL	*- FL
46	1		*REAR LH DOOR REGULATOR	Not Necessary	539.20 FL	*- FL
47	2		*FRONT LH DOOR HINGE	Repair	132.70 FL	*- FL
48	1		*FRONT LH DOOR CHECKER	Repair	122.50 FL	*- FL
49	2		*REAR LH DOOR HINGE	Repair	132.70 FL	*- FL
50	1		*REAR LH DOOR CHECKER	Repair	122.60 FL	*- FL
51	1		*REAR AXLE BEAM	Distorted	1,932.00 FL	*1,932.00 FL
52	1		*REAR LH WHEEL HUB AND BEARING	Not Necessary	520.70 FL	*- FL
53	1		*REAR LH SHOCK ABSORBER	Distorted	650.00 FL	*650.00 FL
54	1		*FRONT LH PILLAR	Repair	1,097.09 FL	*- FL
55	1		*LH SILL PANEL	Dented	860.40 FL	*860.40 FL
56	1		*SET FRONT BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
57	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	50.00 FS	*20.00 FS
58	1		*SET FRONT GRILLE CLIP	Necessary	30.00 FS	*20.00 FS
59	1		*BOT COOLANT	Serviceable	50.00 FS	*- FS
60	3		*BOT TRANSMISSION FUILD	Not Necessary	300.00 FS	*- FS
61	1		*NUMBER PLATE	Serviceable	60.00 FS	*- FS
62	2		*RIM	Cut	1,600.00 FS	*1,000.00 FS
63	1		*TYRE	Serviceable	500.00 FS	*- FS
64	1		*FRONT LH STABILISER LINK	Bent	281.30 FL	*281.30 FL
65	1		*LH REAR FENDER	Dented	1,173.50 FL	*1,173.50 FL
66	1		*FRONT BUMPER SPONGE	Torn	59.20 FL	*59.20 FL
67	1		*FRONT UNDERCOVER	Cracked	120.30 FL	*120.30 FL
68	1		*AIR DUCT	Deformed	68.00 FL	*68.00 FL
69	1		*AIR FILTER BOX	Broken	175.00 FL	*175.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **61,953.22** **19,513.19**
 - List Item Discount on L Items 25.00/25.00% (S\$) **14,825.81** **4,610.80**

Total Parts (S\$) **47,127.41** **14,902.39**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK FRONT WIRING AND LIGHTING SYSTEM	New	60.00	30.00
2	REMOVE AND REPLACE RADIATOR AND TOP UP COOLANT	New	200.00	0.00
3	REMOVE AND REPLACE CONDENSER AND TOP UP GAS	New	200.00	0.00
4	REMOVE AND REFIT FRONT DASHBOARD	New	400.00	0.00
5	REMOVE AND REFIT ENGINE ASSY	New	500.00	0.00
6	REMOVE AND RENEW GEARBOX ASSY	New	500.00	0.00
7	MOUNT VEHICLE ON BENCH FOR CHASSIS REPLACEMENT	New	500.00	0.00
8	CHECK FRONT WHEEL ALIGNMENT	New	150.00	80.00
9	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS	New	200.00	180.00
10	TRANSFER PARTS ATTACHMENT ,FROM OLD FRONT DOOR TO NEW	New	200.00	60.00
11	TRANSFER PARTS ATTACHMENT ,FROM OLD REAR DOOR TO NEW	New	200.00	60.00
12	PANEL BEATING ON AFFECTED AREAS	New	2,500.00	1,600.00
13	SPRAY PAINTING ON AFFECTED AREAS	New	2,000.00	1,400.00
14	APPLY ANTI RUST ON AFFECTED AREAS	New	200.00	80.00
15	REMOVE AND RENEW REAR UNDERCARRIAGE PARTS	New	200.00	150.00
Gross Labour Cost (S\$)			8,010.00	3,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >