

ASS. REC. BY:

REF:

CS/FCL18000239 / K11b2

Special Instruction:

Surveyor

Kelvin

ASSIGNMENT (Office)

From (Person):

AWS Karen Tan

of

FCL

Date/Time

04.01.2018 3:23pm

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB 87108

Insured:

SHA 1476D

at Workshop m/s

Premier

Tel:

6544 6689

of

23 Changi South Ave 2 #03-02

Policy No:

Claim No:

D18000126MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

31.12.2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wpi'

H.O.D. Endorsement:

Date/Time:

04.01.2018 3:45pm

Person Contacted:

Vincent

Vehicle:

IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SHB 87108 - NBA / INC17002654 / Y

DOA: 09/02/2017

SHA 1476D - CS/FCL14012514 / U16k3

DOA: 29/06/2014

REF:

Kalvin

REF:

ASSIGNMENT


25 Nov 2013

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: _____
at Workshop no: _____
of: _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Report)
Make of Veh: _____

(Policy Condition)
Remark: **The veh had commenced its repair at the time of inspection**

Bal or Market Value: _____
IDAC Accident Report: _____ Consistent? Yes or No
GIA PR Seen: _____ Consistent? Yes or No
Est. Repairs: _____ days Res: Yes or No
Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle IN / OUT



Vehicle: **SHB 8710B**
Type: M Car / M Cycle / Bus / Van / Lorry / T ~~1~~ / Prime Mover /
Truck / Trailer or
Make: **KIA optima** 1685
Colour: **Silver** Insured / Std / NI / NA
Sp Reading: **536385** Radio Insured / Std / NI / NA
Eng No: _____
C No: **KNAH M414ME545211**
Gen Cond: Good / ~~Fair~~ / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Mod: Nil / S/Rim / ~~STD~~ / Rim or
Tyre Size: F: **205/65R16**
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or **Maxxis**
Front: _____ Rear: _____
R Bal: **7** mm R Bal: **7** mm
L Bal: **7** mm L Bal: **7** mm
D O A: **31/2/12** D O A: **4/1/8**
Survey held at: **Premis**
Des of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or
Rear o/s
The U/C / Chassis frame / Body Structure affected due to collision

Date Time Action Instruction
11/1/8 : **Contracted up \$3100/ 5 Days (Red. 5862.50 : 65%) FCZ**

RECEIVED 15 JAN 2018

Date Time File Pass to: **15/1 Typist**
Date Time File Return to: _____
☐ Preli. Report
☒ Final Report

Days Of Repair: **5**
Resurvey No. of Trip: **1**

Report Format: **TP**
Lump Sum / I.B: **3100**

Add Fee: ☐ Site Insp \$
☐ Inter \$
☐ Rep \$
☐ Trav \$

Survey Fee	170
Transportation	50
	50
	35
	305



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18000239/K1tb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 04-01-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 1476D	Veh. Inspected	SHB 8710B
Policy No.		Coverage (\$)	0.00
Claim No.	D18000126MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	04/01/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	31/12/2017	Inspection Date	04/01/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	03-01-2018	Our Ref No. D18000126MFSH
Accident Date	31-12-2017	Claim Type. Third Party
Insured Vehicle	SHA1476D	Third Party Vehicle. SHB8710B
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02	
Contact Person.	GOH WEE DEK	
Contact No.	62148880/ 65446682	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/232554)



PRI Documents



Close



PRI Header Details

Claim No	D18000126MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & PRI SERVIC
Workshop Name	PREMIER AUTOMOTIVE SERVICES PTE LTD (Contact Person : GOH WEE DEK)	Survey Location & Contact Details	23 CHANGI SOUTH AVENUE 2 #03-02 Mobile: 65446682 , Phone: 62148880 , Fax: EmailId: WEEDEK.GOH@PREMIERTAXI.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: LIABILITY UNCLEAR:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA1476D	TP Vehicle No	SHB87
PRI Recieved Date	03-01-2018 02:56:17 PM	Surveyor Appointed Date	04-01-2018 03:23:37 PM	Surveyor Accept Date	04-01-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	04-01-2018	Upload Survey Report *:	
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	----------------------

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents

File Name

Action

Surveyor Job Remarks

Enquire Transaction History**Transaction History Details**

Log Date/Time:	25 Nov 2013 / 10:29:21	Receipt No.:	AACCK001-AX239-131125-000014
Asset Type:	Vehicle	Transaction Amount:	\$75,658.00
Asset ID:	SHB8710B	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20131125102921964999		

Vehicle No.:	SHB8710B
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	25 Nov 2013
Original Registration Date:	25 Nov 2013
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414ME5452119
Engine No.:	D4FDDH308765
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2013
Open Market Value:	\$19,721.00
Minimum PARF Benefit:	\$7,332.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	25 Nov 2013 10:29:21
COE No.:	2013112501000908G
COE Expiry Date:	24 Nov 2021
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$63,297.00
Lifespan Expiry Date:	24 Nov 2021
Owner ID Type:	Company

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

2-Jan-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8710 B

1 pc	Bootlid emblem X "	\$	27.00
1 pc	Bootlid CRDi X "	\$	29.00
1 pc	End panel X repair	\$	250.00
1 pc	End panel garnish X	\$	74.00
1 pc	Floorboard trim o/s X	\$	184.00
1 pc	Rear muffler assy X suc	\$	1,009.00
1 pc	Rear exhaust pipe hanger X suc	\$	49.00
2 pcs	Licence plate lamp @ \$30.00 X suc	\$	60.00
1 pc	o/s taillamp panel X repair	\$	218.00
1 pc	o/s floor side panel X repair	\$	65.00
1 pc	Rear o/s air vent X suc	\$	30.00
1 pc	Rear o/s tail lamp	\$	421.00
1 pc	Bootlid o/s reflector X suc	\$	350.00
1 pc	Rear o/s fender X repair	\$	1,205.00
1 pc	Rear o/s fender inner shield X suc	\$	120.00
1 pc	Rear windscreen moulding X "	\$	87.00
1 pc	Rear bumper	\$	696.00
1 pc	Rear bumper lower cover	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 n/s X suc o/s	\$	58.00
1 pc	Rear bumper inner sponge	\$	114.00
1 pc	Rear bumper reinforcement	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 n/s X suc o/s	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 X suc	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 X suc	\$	36.00
1 pc	Rear bumper reflector o/s	\$	46.00
		\$	6,085.00
Less 10%		\$	608.50
		\$	5,476.50

S/NETT

1 set	Rear bumper clips	\$	48.00
1 set	End panel inner garnish clips X	\$	30.00
1 set	Bootlid lower garnish clips	\$	60.00
1 set	Rear fender inner shield clips X	\$	38.00
1 pc	Rear o/s fender sticker	\$	60.00
1 set	Bootlid stickers X	\$	100.00
1 set	Reverse sensor	\$	280.00

200

2-Jan-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8710 B

Sundry *new*

20
\$ ~~50.00~~

To dismantle / replace exhaust pipe

\$ ~~120.00~~ *x 3*

To dismantle / replace reverse sensor to new bumper and reset to the same

\$ ~~120.00~~ *30*

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

\$ ~~180.00~~ *50*

To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the ~~the~~ end panel, o/s floor side panel, rear o/s tail lamp panel, rear o/s fender. Including knock-out, straighten, repair, reshape and adjust of the same

\$ ~~1,200.00~~ *800*

To putty and spray painting on bootlid lower garnish, rear o/s fender, rear bumper, end panel, rear o/s taillamp panel, o/s floor side panel.

\$ ~~1,000.00~~ *540*

To apply rustproofing on the repaired and replaced panels.

\$ ~~200.00~~ *50*

\$ 8,962.50

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

9012.50

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin (Ktk)
4/1/18 1630hrs
4 Days
45
After Repair p/b

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18000239/K1tbn2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 16-01-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 1476D	Veh. Inspected	SHB 8710B
Policy No.	D-15072701MFSH	Coverage (\$)	0.00
Claim No.	D18000126MFSH	Excess (\$)	0.00
Assign From	KARENT	Assign Date	04/01/2018

2. Vehicle Particulars & Condition

Make & Model	KIA OPTIMA	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	KNAGM414ME5452119	Colour	SILVER
Odometer	536385	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/65 R16	MAXXIS	7 mm
L/H Front Tyre	205/65 R16	MAXXIS	7 mm
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	31/12/2017	Inspection Date	04/01/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8710B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOTLID EMBLEM	NOT NECESSARY	27.00	-
1	BOOTLID CRDI	NOT NECESSARY	29.00	-
1	END PANEL	TO REPAIR SEE LABOUR	250.00	-
1	END PANEL GARNISH	SERVICEABLE	74.00	-
1	FLOORBOARD TRIM O/S	SERVICEABLE	184.00	-
1	REAR MUFFLER ASSY	SERVICEABLE	1,009.00	-
1	REAR EXHAUST PIPE HANGER	SERVICEABLE	49.00	-
2	LICENCE PLATE LAMP @\$30.00	SERVICEABLE	60.00	-
1	O/S TAILLAMP PANEL	TO REPAIR SEE LABOUR	218.00	-
1	O/S FLOOR SIDE PANEL	TO REPAIR SEE LABOUR	65.00	-
1	REAR O/S AIR VENT	SERVICEABLE	30.00	-
1	REAR O/S TAIL LAMP	CRACKED	421.00	421.00
1	BOOTLID O/S REFLECTOR	SERVICEABLE	350.00	-
1	REAR O/S FENDER	TO REPAIR SEE LABOUR	1,205.00	-
1	REAR O/S FENDER INNER SHIELD	SERVICEABLE	120.00	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	87.00	-
1	REAR BUMPER	DEFORMED	696.00	696.00
1	REAR BUMPER LOWER COVER	CRACKED	206.00	206.00
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00	O/S CRACKED / N/S SERVICEABLE	58.00	29.00
1	REAR BUMPER INNER SPONGE	TORN	114.00	114.00
1	REAR BUMPER REINFORCEMENT	CRACKED	607.00	607.00
2	REAR BUMPER STAY O/S & N/S	O/S BENT / N/S SERVICEABLE	108.00	53.00
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @\$18.00	SERVICEABLE	36.00	-
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @\$18.00	SERVICEABLE	36.00	-
1	REAR BUMPER REFLECTOR O/S	CRACKED	46.00	46.00

Report Ref No. CS/FCI18000239/K1tbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-608.50	-217.20
			5,476.50	1,954.80
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
1	SET END PANEL INNER GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET BOOTLID LOWER GARNISH CLIPS (SN)	NECESSARY	60.00	60.00
1	SET REAR FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	38.00	-
1	REAR O/S FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	SET BOOTLID STICKERS (SN)	NOT NECESSARY	100.00	-
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			716.00	438.00
	<u>LABOUR</u>			
	TO DISMANTLE/REPLACE EXHAUST PIPE.	NOT NECESSARY	120.00	-
	TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	30.00
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.		180.00	50.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. TO HEAT/WELD, CUT-OFF THE END PANEL, O/S FLOOR SIDE PANEL, REAR O/S TAIL LAMP PANEL, REAR O/S FENDER, INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE SAME.		1,200.00	800.00
	TO PUTTY AND SPRAY PAINTING ON BOOTLID LOWER GARNISH, REAR O/S FENDER, REAR BUMPER, END PANEL, REAR O/S TAILLAMP PANEL, O/S FLOOR SIDE PANEL.		1,000.00	540.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		200.00	50.00
			2,820.00	1,470.00
	GRAND TOTAL		9,012.50	3,862.80



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,100.00
---	--	--	----------

Report Ref No. CS/FCI18000239/K1tbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.