ASS. REC. BY	Ri	EF: CB /FCLI	80003H0/KY	OCT Special	Instruction	É
Survajor	Kemulh	ASSIGNM	ENT (Office)			
From (Person	. Teo Swee Keeping	of	F(L	Dat	te/Time:	04012618 3-10pm
Estimated Cor	st		Bill to:			
OD/W/W	STTP RES / OD RES /	EVA/INV/MV/	cs			
To Inspect Ve	chicle No	THE 537ILC		Insured	S	THC 31897
at Workshop	m/z	Truns Cab		Tel		
of		Mo. 2 AMB	St 63			*
			Claim No:	D 18000	3690	nFSH)
Sum Insured:			Excess:			
Make of Veh (Client's Recon				D.(D.A	81011010
CA / REV Date/Time	REP. / REV 24 HRS 0401 2018 315pm	Person Contacted.	Corrly	Vela	LOD Fac	OUT
Date/Time	Action/Instruction (V) Estimat	1			
	SHC 5374C -			320		DOA- 1910-15
	SH(31897-)	5	39	1		
	Submit US	\$ 28 K	b du			
	Red : \$ 125,4	95.02 ,82	٤ ٪.			

AARNONES

ASS REC BY	Ri	EF: CB /FCL18	0002H0/KY	OCT Special	Instruction	
Survajov =	Kernelh	ASSIGNMI	NT (Office)			
From (Person	Teo Swee Keeng	of 3	a.	De	te/Time:	04012618 3-10pm
Estimated Co	st		Bill to:		-	
OD / W	STTP RES / OD RES /	EVA/INV/MV/	3			
To Inspect Ve	chicle No.	SHC 537ILC		Insured	S	HC 31897
at Workshop	m/z	Truns Cab		Tel	6257	133 D
of		No. 2 AMK				
			Claim No:	D 18000	3691	1 F S H
Sum Insured			Excess:			
Make of Veh (Client's Record				D.	0.A	U1 01 2018
CA / REV	REP. / REV 24 HRS 04012018 315pm	Person Contacted.	Corely	Vels	R.O.D. East	OUT
Date/Time	Action/Instruction (V) Estimati				
	SHC 5374C -			340		DOA- 1910-15
	왜(31697 -)	c				
	Submit LIS	\$ 28 K . H	dux			
	Red : \$ 125,4					

ADVINORES

ASS. REC. BY: REF: /-CI/	
Kenneth	SSIGNMENT
From: Date:	
Estimated Cost	- Veh No: SIAC 5374 C Yr Regn: 10, 14
OD/TP/WS/TP RES/OD RES/EVA/INV/MV	Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxl / Prime Mover / Truck / Trailer or
To Inspect Vehicle No:	
at Workshop m/s Trans Cel	Make: Reserve lossan co 1885
of CES	Colour White IRe AIC: Insured / Std / NI / NA
Insured:	Sp.Reading 53/685 T/Radio: Insured / Std / NI / NA
Policy No.	Eng/No.
Claims No.	CNO: VI=11BL 15AUC 279845
Sum Insured: Excess:	Gen. Cond: Good / Fair / Poor / Burnt
(Client's Record)	Steering: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Brake: Ingrder / Jammed / Leaked / Burnt or
	Modi: Mil S/Rim / STD A/Rim or
(Policy Condition)	Tyre Size: F. Giti 215/60R16
Permark: The veh had commenced its N/S O/S	R:/E1/4,
repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
Ball or Market Value:	TOYO/YOKO or
IDAC Accident Rport: Consistent? : Yes or No	Eroni Rear
GIA / PR Seen: Consistent7 : Yes or No	L/Bail P mm R/Bail A mm
Est Repairs: 16 days Res.: Yes or No	mm USal + mm
Lum Sum: 20% 3 Val.: Yes or No	Survey held at 001 4/1/18
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Roofton or
Date: Person Contacted: Vehicle: IN / OUT	015 0004
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
- 5/1 Ple pass to Corkeine	
RECEIVED 2	
Coto/Time, File Pass to?	
I L Prell, Report Da	ys Of Repair: 16
Coto/Time, File Return to 1.	survey No. of Trip: Survey Fee: 1704 3185
	Transportation: E.N.
Add Fee:	: Site Insp (\$)_s - Rs_s
Report Format : 1P	: Interview (\$) Photos 30
Market Santage Control of the Contro	Tech Invs (\$) Others
Lump Sum / I.B.I: (S 26K	Weekend (\$
	7074L 2/4014



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

			nationale Des Experts En Auto	mobile		
FIF	ST CAPITAL INS	URANCE LTD	Ref : CS/FCI180003	240/Krb		
	ROBINSON ROAL 3-01 CITY HOUSE	SINGAPORE 068877	Date: 04-01-2018 Code: FCI2			
1.:		Policy Particul	ars :- THIRD PARTY CLA	IM		
	Insured Veh.	SHC 3189J	Veh. Inspected	SHC 5374C		
	Policy No.		Coverage (\$)	0.00		
	Claim No.		Excess (\$)	0.00		
	Assign From	TEO SWEE KEONG	Assign Date	04/01/2018		
2.		Vehicle P	articulars & Condition			
	Make & Model		c.c	0		
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.	Colour				
	Odometer	*	Steering			
	Brakes		Modification			
	General					
3.		Con	ditions of Tyres			
_		Size	Make	Balance		
_	R/H Front Tyre			mm		
_	L/H Front Tyre			mm		
_	R/H Rear Tyre			mm		
N.	L/H Rear Tyre			mm		
		Descri	ption of Damages			
	English No.	Gene	eral Information			
	Accident Date	01/01/2018	Inspection Date	04/01/2018		
	Survey held at	TRANS-CAB AUTO SERVICE				
		NO.2 ANG MO KIO ST 63 SINGAPORE 569111				
a.			Remarks			
	A)THE INSPECTIO	ON WAS CONDUCTED ON A"V CE TO YOUR INSTRUCTIONS.	VITHOUT PREJUDICE" BAS	IS.		

MOTOR SURVEY ASSIGNMENT

Our Ref No. SH (3189)

Accident Date 1/1/18

Claim Type 3rd Party

Insured Vehicle SHC 3189 J

Third Party Vehicle SHC5374C

Survey Location Trans - cab Auto Service Pte Ly Contact Person Candy Kong No- 2 Ang Ma Kio Street 63

S'pore 569 111

6257 1330

Survey Type

Without prejudice (Est. \$153,495.02)

Appointed Surveyor

Contact Person

Fax No. 6841 6315

Contact Number

6256 356

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

Encl. Accident Reports & est.

cc: Workshop Trans-Cab Awdo Service Pte Ltd Attention Candy Kong

Officer In charge Serene Ver

IMPORTANT NOTE

Kindly submit the survey report by email only to surveyor@first-insurance.com.sg within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Catherine Chong (LKK Auto)

From: Teo Swee Keong <TeoSweeKeong@first-insurance.com.sg>

Sent: Thursday, 4 January, 2018 3:10 PM

To: 'assignments@lkkauto.com'

Cc: Serene Ler; Candy Kong (candy.kong@transcab.com.sg)

NEW SURVEY ASSIGNMENT - OUR REF: SHC3189J DOA 1/1/2018 TP:

SHC5374C

Attachments: img-104091918-0001.pdf; MOTOR SURVEY ASSIGNMENT.pdf

Dear Sirs

Subject:

New survey request for your handling.

Thanks and Regards,

SK Teo

Motor Claims Dept

MS First Capital Insurance Ltd | 36 Robinson Road #16-01 City House Singapore 068877 | DID : 6507 3848 | Fax No. : 6507 3849 | Company Regn. No. 195000106C A member of MS&AD Insurance Group

email: MotorClaims@first-insurance.com.sg

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to www.first-insurance.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged. If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

----Original Message-----From: Harminder Kaur

Sent: Thursday, January 04, 2018 9:31 AM

To: Teo Swee Keong <TeoSweeKeong@first-insurance.com.sg>

Subject: FW: ARRANGE FOR SURVEY SHC5374C

SURVEY

Best Regards, Harminder Kaur Motor Claims

MS First Capital Insurance Ltd | 36 Robinson Road #16-01 City House Singapore 068877 | TEL: 6507 3848 | Fax No.: 6507 3849 | Company Regn. No. 195000106C A member of MS&AD Insurance Group

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to www.first-insurance.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged. If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

----Original Message----

From: Candy Kong [mailto:candy.kong@transcab.com.sg]

Sent: Thursday, January 4, 2018 9:30 AM

To: Motor_Claims < Motor_Claims@first-insurance.com.sg > Cc: Aini Binte Md Min < aini@first-insurance.com.sg >

C. AIN DIRE NO MIN CONGRESS MISCHAELE

Subject: ARRANGE FOR SURVEY SHC5374C

Dear all,

PLS ARRANGE LKK AUTO CONSULTANTS PTE LTD TO SURVEY.

Please arrange for survey as below:

SHC3189J - 01.01.2018 at 0715 Hrs - SHC5374C

Lunch time: 12pm - 1pm.

Kindly pls dun arrange survey during lunch time.

"We Agree to let your In-house surveyor assess/ survey our vehicle with estimate."

Thks & Rdgs Candy Kong Claims Service Assistant

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Date Of Driving Pass

Driving Experience

Mobile Number Fax Number Contact Number

EMail Address

Gender

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

alorisad.	A DESIGNATION OF THE AMERICAN
	ACCIDENT STATEMENT
Date Of Report	02/01/2018 15:03
Date Of Accident	01/01/2018 07:15
Exact Location Of Accident	ECP TOWARDS AIRPORT
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHC5374C
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666
Vehicle Particulars	
Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No. Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	
Driver	
Name of Driver	WANG SWEE FOOK
NRIC No	S0063705Z
Date Of Birth	13/10/1953
Occupation	OUTDOOR

21/09/1973

MALE

NOEMAIL

44 YEARS AND 3 MONTHS

(LOCAL) +65-84186632

Address

BLK 8 BEDOK SOUTH AVENUE 2

#09-304

Postcode

450008

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

OTHER - RELIEF

Vehicle

Vehicle Registration Number of Driver's Own

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD ON COLLISION

Weather Conditions

RAINING

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

Passenger 1

4 NAME:

- UNKNOWN

GENDER:

: MALE

Passenger 2

NAME:

: UNKNOWN

GENDER:

MALE

Passenger 3

NAME:

: UNKNOWN

GENDER:

FEMALE

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

BEDOK NEIGHBOURHOOD POLICE POST

Police Station Address

ROAD: BLK 15 BEDOK SOUTH ROAD #01-117 , POSTCODE: 460015 .

COUNTRY: SINGAPORE

Police Station Contact

TEL NO: 1800-2419999 - FAX NO: 64431687

Was notice of intended Prosecution given?

NO

If Yes against whom?

Circumstances of Accident

PLEASE SEE ATTACH POLICE REPORT: T/20180101/2042

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SHC3189J

Vehicle Make/Model/Colour

COMFORT TAXI

Details Of Properties

Page 2 of 24

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

TAXI

LEE ENG HUA

511897331

DETAILS OF INJURED PERSON 1

WANG SWEE FOOK Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SHC5374C

Were seat belts worn?

YES

Was this injured conveyed to hospital by

ambulance?

NO

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims:
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

Sketch Plan #2 Pg. 1

KETCH PLAN					
		-1/1			
		NO			
					
化二苯基酚基苯基苯苯					100 0 0 0 0 0 0
				1	
SCRIBE CIRCUMSTANCE					
	pls see	ottech	Polie	balant	
	_				
CLARATION Ve declare the foregoing par	ticulars are true in every	respect.		Cond)
olicyholder's Signature ste & Time:	Driver's Signatu	re the policyholder)	Rep Nar	orting Centre Person	nel's Signature
	Date & Time:	bouck lower)		C/FIN No.:	

SWANG Swar Planters_VS





Police Station Of Origin:

Bedok NPP

15 Bedok South Road #01-117 SINGAPORE

Tel No: 1800-2419999

REPORT OF A TRAFFIC ACCIDENT

£41.42591	35,839	6199040	188711
			1001/11/00
T/20180	101/204	12	

Report No. T/20180101/2042

1 of 4

Date/Time Report Made: 01/01/2018 14:26			Vide Report No.: G/20180101/0143	Station Diary No.: 16	
Informa	nt's Partice	ulars	10000000000000000000000000000000000000	1000年代的基本的基本的基本的	
	Informant: SWEE FOO		Address: APT BLK 8 BEDOK SOL 460008	JTH AVENUE 2 #09-304 SINGAPORE	
	/ ID No.: 0 / S00637	05Z	Contact No.: Home/Office:	Mobile: 84186632	
National SINGAP	ity: ORE CITIZ	EN	Email:		
Sex: Male	Age: 64	Date of Birth: 13/10/1953	Type of informant: Driver	V 21	
Race: Chinese			Language:	Institution / School Name:	
Occupation: Taxi driver			Driving Licence Information: Class: Date of Expiry:		

Type of Accident:	Non-Injury Government Prope	rty Drink Drive: No	Date/Time of Accident: 01/01/2018 07:15	Type of Location: Straight Road
	TEXPRESSWAY	exit before Marine Road Surface: Wet		Road Speed Limit:
Traffic Flow:		Traffic Control: Not Controlled	The second secon	Traffic Volume: Moderate
One Way			,	

Vehicle No	Туре	Make	Model	Color of Condition	Noted Passenge
SHC3189J	Car			Seriously Damaged	3
SHC5374C	Car			Seriously Damaged	3

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA





Police Station Of Origin: Bedok NPP

Report No. T/20180101/2042

15 Bedok South Road #01-117 SINGAPORE 460015

Tel No: 1800-2419999

CONTINUATION OF REPORT

Name	LEE ENG HUA			ID No		S1189733I
Related Vehicle	SHC3189J (Car)			Conta	ct No.	NIL
Hospital/Clinic	NIL			Class Driving Licent Expiry	g ce &	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Disch	arge	NIL	
No. of Days gran	ted Medical Leave	NIL	Degree of I	njury	NIL	
enver 4	经营业 医心内部		200		8000 (141)	建设是"被求明的"等
Name	WANG SWEE FOOK			ID No.		S0063705Z
Related Vehicle	SHC5374C (Car)			Conta	ct No.	84186632
Hospital/Clinic	HEALTHLINE FAMIL SURGERY	Y CLINIC &		Class Drivin Licent Expiry	g :e &	Class: NIL Date of Expiry: NIL
Date Treatment	01/01/2018		Date Disch	arge	01/01	/2018
44 F Ph	ted Medical Leave	03	Degree of I	mli ente	Clinh	

Brief Details.

On 01/01/2017 at about 0715hrs, I was travelling in my vehicle (SHC5374C) along ECP towards Airport on the extreme right lane of 4 lane road along with 03 passenger. While driving along the said location, suddenly one vehicle (SHC3189J) from the 3rd lane of 4 lane road drove into the onto the extreme right lane and collided onto the metal railing.

I then applied the brake to slow down my vehicle and steer to the left wanting to overtake his vehicle. However, in the midst of over taking the said vehicle after it had collided onto the metal railing, it bounced back and collided onto my front right portion of my vehicle. I then drove my vehicle to the right side of the road to avoid any obstruction to other vehicle. I then exited the vehicle and checked if anybody was injured.

Subsequently I called for Police, shortly after both Police and Ambulance had arrived we were checked by the paramedic and nobody was conveyed. We were then advised by one of the Traffic Police officer to lodge a Police traffic accident report.

On the same day at about 1100hrs, I went over to HealthLine Family Clinic & Surgery Pte Ltd located at Blk 25A Chai Chee Road #01-467 for a checkup as I felt some pain. I was then given 03 days medical certification.

I am lodging this report as instructed by the Traffic Police officer.





Police Station Of Origin: Bedok NPP 15 Bedok South Road #01-117 SINGAPORE 3 of 4 Report No. T/20180101/2042

460015 CONTINUATION OF REPORT Tel No: 1800-2419999

CONTINUATION OF REPORT





Police Station Of Origin: Bedok NPP

15 Bedok South Road #01-117 SINGAPORE

460015

Tel No: 1800-2419999

4 of 4

Report No. T/20180101/2042

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report G / Sgt 1 TAN EDMUND NEIL	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 01/01/2018 14:26
Officer In Charge Of Case: TP / AEIT / SSI GOH GEOK LYE Contact No.: 65476148	Classification Of Case:
Authentication Stamp NP168	Manager Committee Committe

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHC5374C
Vehicle to be Exported:	Yes
Intended De-registration Date:	02 Jan 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C002057
Chassis No.:	VF1ABL15AUC279845
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	21 Oct 2014
First Registration Date:	21 Oct 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Oct 2022
	\$9,373.00

COE Expiry Date:	20 Oct 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,938.00
COE Rebate Amount:	\$30,552.00
Total Rebate Amount:	\$39,925.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 Jan 2018

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5374C

Not Notherholds

(1 Ly & 28,000/2

Renny After Pains

Book Value?

Vehicle No.: Chassis No.:

Vehicle Make: Vehicle Model:

Date of Accident :

Third Party Insurer:

LATITUDE

RENAULT

SHC 5374C

VF1ABL15AUC279845

1.1.2018

FCIL

PART	LIST
------	------

1	1	BUMPER COVER FRT		CP 1,259.42 -
2	,	BUMPER SPOILER FRT	5	7 - 1,233.42
3	1		3	201.73
	1	BUMPER ABSORBER FRT	\$	394.66
4	1	BUMPER RETAINER FRT LH	\$	
5	1	BUMPER SUPPORT FRT	\$	∫ 123.88 X
6	1	BUMPER RETAINER FRT RH	\$	97 "150.77 X
7	1	BUMPER SUPPORT FRT	\$	1L 123.88 X
8	1	BUMPER UNDERTRAY FRT	\$	0,7 472.83
9	1	BUMPER GRILLE LOWER FRT	\$	14 266.80 X
10	1	BUMPER FOG LAMP GRILLE LH	\$	√m 207.21 ×
11	1	BUMPER FOG LAMP GRILLE RH	\$	Dd 207.21 -
12	1	BUMPER BEAM FRT	\$	By 914.08
13	1	TOW COVER FRT	\$	Im 28.61 X
14	1	RADIATOR GRILLE	\$	Sin 1,707.78 X
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	£ 225.36 ₹
16	1	RADIATOR GRILLE FRAME	\$	CM 1,353.75 -
17	1	FRAME FULL SUPPORT PANEL	\$	CM2 615.90 -
18	1	FRAME FULL SUPPORT BRACKET	\$	12 89.79 X ₺
19	1	FRONT BRACE PANEL	\$	17 177.22 V 1
20	1	HORN	\$	Jh 314.17 2
21	1	HORN BRACKET	\$	1 40.45 X b
22	1	HEADLAMP RH	\$	Br 1,184.43
23	1	HEADLAMP PANEL FRT RH	\$	01) 152.15
24	1	HEADLAMP HARNESS	\$	√L 928.29 X
25	1	BONNET	\$	四 1,941.63 —
26	1	BONNET INSULATOR	\$	∫_ 405.73 ×
27	1	BONNET STRUT LH	\$	5 88.61 ×
28	1	BONNET STRUT RH	\$	1 88.61 ×
29	1	BONNET HINGE LH	\$	M 348.31 X

* 9 8				
30	1	BONNET HINGE RH	\$	R 348.31 X €
31	1	BONNET LOCK	\$	77 305.48 X 🕁
32	1	BONNET CABLE	\$	Sh 119.19 X
33	1	BONNET CABLE COVER	s	∫ h 161.03 ×
34	1	BONNET SEAL OUTER	\$	∫ 92.36 ×
35	1	BONNET SEAL INNER	\$	157.28 X
36	1	FENDER PANEL FRT RH	\$	By 783.83
37	1	WHEELARCH FRT RH	\$	EPA 278.84
38	1	FENDER BRACKET LOWER RH	\$	0,, 15.79
39	1	FENDER INSULATOR RH	\$	130.84 ★
40	1	WIPER RESERVOIR	\$	nu 348.25 -
41	1	WIPER RESERVOIR NECK	\$	nu 136.11 -
42	1	WIPER RESERVOIR MOTOR	\$	Sher 270.06 -
43	1	AIR CLEANER LOWER	\$	Pm 271.26 X
44	1	AIR CLEANER HOSE	\$	5m 76.14 X
45	1	AUTO COMPUTER	\$	J'h 5,032.17 X
46	1	STEERING PUMP ELECTRIC	\$	∫ 2,306.90 X
47	1	STEERING PINION RACK	\$	B1172 4,413.112
48	1	ENGINE HARNESS	\$	4,084.54
49	1	SUBFRAME OUTER FRT	\$	2,652.45 7
50	1	SUBFRAME BRACKET OUTER RH	\$	92.36 7
51	1	ENGINE MOUNTING RH	\$	Sn 552.55 7 X
52	1	FUSE BOX	\$	987.39
53	1	ENGINE MOUNTING RH	\$	552.55 7
54	1	ENGINE MOUNTING LOWER	\$	562.42
55	1	ENGINE MOUNTING UPPER	\$	592.02
56	1	VEHICLE HARNESS PASS ROOM	\$	10,003.86
57	1	AIR CLEANER BOX	\$	√ 464.20 X
58	1	TURBO DUCT	\$	1,027.80 y
59	1	OIL PAN ASSEMBLY	\$	⁷ 2,283.91 ≺
60	1	A/C CONDENSER	\$	2,020.37 <
61	1	A/C CONDENSER GARNISH RH UPPER	5	√4 39.67 × √4 59.60 ×
62	1	A/C CONDENSER GARNISH RH	3	
63	1	A/C PIPE CONDENSER TO COMPRESSOR	3	5 208.39 √
64 65	1	A/C PIPE CONDENSER TO EXPENSION VALVE A/C PIPE COMPRESSOR	3	558.72 X
66		A/C PIPE COMPRESSOR	3	Pa 658.72
67	1	A/C COMRPESSOR	\$	5 2,684.61
68	10	AIR COOLER		C. 702.00
69	1	AIR INTERCOOLER HOSE (LONG)		5 1,014.13 X
70	1	AIR INTERCOOLER HOSE (LONG) AIR INTERCOOLER HOSE (Short)	4	Sin 375.14
71	1	TRANSMISSION COOLER	4	JL 1,219.30
72	210	TRANSMISSION COOLER PAD	4	July 17.96
73	1	RADIATOR	\$	Sh 1,202.20
74	2	RADIATOR STUD UPPER	\$	14.41)
	9.7	ANAMAN AND SECOND SECON	-	11.10

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5374C

75	2	RADIATOR BUSH UPPER	\$	50.12
76	2	RADIATOR MTG LOWER	\$	Ju 55.85
77	1	RADIATOR FAN COWLING	\$	J' 820.54
78	1	RADIATOR FAN MOTOR LH	\$	5 967.36 X
79	1	RADIATOR FAN MOTOR RH	\$	Ju 1,479.46
80	1	RADIATOR TANK	5	J'm 324.62
81	1	RADIATOR HOSE UPPER	\$	Sh 240.56
82	1	RADIATOR HOSE LOWER	\$	√ 491.18
83	1	RADIATOR TANK HOSE	\$	Sh 61.18
84	1	WINDSCREEN FRT	\$	CM 1,364.06
85	1	SEATBELT LH	\$	72 2,937.80
86	1	SEATBELT RH	\$	Sn 2,925.37 3
87	1	SEATBELT BUCKLE LH	\$	5 984.13 ¢ x
88	1	SEATBELT BUCKLE RH	\$	7 949 80 7
89	1	PASSENGER AIRBAG	\$	Burs 3,412.40
90	1	STEERING AIRBAG	\$	7 2,525.75 —
91	1	AIRBAG COMPUTER	\$	الا 1,259.82 س
92	1	AIRBAG SENSOR	\$	724.63 -
93	1	AIRBAG SENSOR	\$	NE 289.30 -
94	1	ROTARY SWITCH	5	1,253.11 W
95	1	DASHBOARD	\$	4,900.54
96	1	BUMPER COVER REAR	\$	1,108.46 X
97	1	BUMPER LOWER REAR	\$	768.84 X
98	1	BUMPER BRACKET CTR REAR	\$	113.47
99	1	BUMPER BRACKET SIDE LH REAR	\$	ار 135.97 /
100	1	BUMPER BRACKET CTR LH REAR	\$	Ju 44.99
101	1	BUMPER BRACKET SIDE RH REAR	\$	√ 135.97 X
102	1	BUMPER BRACKET CTR RH REAR	\$	√ h 44.99
103	1	BUMPER BEAM REAR	\$	777.52
104	1	BUMPER BEAM BRACKET LH REAR	\$	7 225.95 A
105	1	BUMPER BEAM BRACKET RH REAR	\$	M 225.95 JO
106	1	FENDER PANEL REAR RH	\$	3,299.13
107	1	WHEELARCH REAR RH	\$	⁹ 543.47 X
108	1	FENDER PANEL INNER TRIM REAR RH	\$	77 671.45 X 10
109	1	FENDER PANEL REAR LH	\$	A 3,299.13 ∠ D
110	1	WHEELARCH REAR LH	\$	S⊢ 543.47 x
111	1	FENDER PANEL INNER TRIM REAR LH	\$	√ 671.45 X
112	1	LOWER ARM REAR RH	\$	n 905.99 x
113	1	KUCKLE ARM REAR RH	\$	1 736.67 ×
				0.000

AAD1801-026

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5374C

114	1	ABSORBER REAR RH	\$	7 ≥ 389.75 ×
115	1	ABSORBER BOLT REAR RH	s	54 52.10 x
116	1	ABSORBER DUST COVER REAR RH	S	√L 92.16 X
117	1	DOOR PANEL REAR RH	S	B 2,844.66 —
118	1	DOOR SEAL REAR RH	\$	J 187.08 ×
119	1	DOOR PANEL FRT RH	\$	By 2,844.66 —
120	1	DOOR HINGE UPPER RH	\$	€ 261.28 L
121	1	DOOR HINGE LOWER RH	S	1 300.55 —
122	1	DOOR CHECK FRT RH	s	£ 194.77 \
123	1	DOOR CHECK BOLT	\$	راب 22.69
124	1	DOOR LOCK FRT RH	\$	7 908.75 b
125	1	DOOR CATCH FRT RH	\$	1 131.23
126	1	DOOR HANDLE OUTER FRT RH	\$	Ju 477.76
127	1	DOOR HANDLE COVER FRT RH	\$	Ju 13.22
128	1	DOOR HANDLE MODULE FRT RH	\$	J- 133.60
129	1	DOOR REGULATOR FRT RH	\$	√ 505.19 \ v
130	1	DOOR REGUALTOR MOTOR FRT RH	\$	75 796.46 X
131	1	DOOR REGULATOR GUIDE FRT RH	\$	Ph 120.97
132	1	DOOR GLASS FRT RH	\$	Sh 625.96
133	1	DOOR FINISHER FRT RH	\$	J- 515.06
134	1	DOOR MOULDING FRT RH	\$	Ju 176.82
135	1	DOOR FINISHER CLIP KIT FRT RH	\$	AA 90.97
136	1	DOOR CASING FRT RH	\$	Sc 1,509.06
137	1	DOOR CASING LIGHT	\$	Ju 82.49
138	1	DOOR GRAB HANDLE FRT RH	\$	Sh 210.96
139	1	DOOR MIRROR RH	\$	√h 1,725.73
140	1	DOOR WEATHERSTRIP FRT RH	\$	Pm 410.27
141	1	DOOR SEAL LOWER FRT RH	\$	5 91.17
142	1	DOOR GLASS RUNNER SEAL FRT RH	\$	€ 626.36
143	1	DOOR WAIST SEAL OUTER FRT RH	\$	Sh 291.27
144	1	DOOR WAIST SEAL INNER FRT RH	\$	Ja 122.15)
145	1	DOOR PANEL REAR RH	\$ /20	reof 2,844.66 X
146	1	DOOR GUIDE REAR RH	\$	176 82 X
147	1	DOOR HINGE UPPER RH	\$	By 274.50 -
148	1	DOOR HINGE LOWER RH	\$	马 300.55 —
149	1	DOOR CHECK REAR RH	\$	∫ 203.06 X
150	1	DOOR LOCK REAR RH	\$	N 908.75 (9
151	1	DOOR GRAB HANDLE REAR RH	\$	√ ₄ 210.96≺
152	1	DOOR HANDLE OUTER REAR RH	\$	Ju 126.49 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5374C

153	1	DOOR HANDLE CAP REAR RH	\$	Sh 35.52 \
154	1	DOOR HANDLE COVER REAR RH	\$	13.22
155	1	DOOR HANDLE MODULE REAR RH	\$	In 133.60 (x
156	1	DOOR FINISHER REAR RH	5	Jh 423.10
157	1	DOOR WHEATHESTRIP REAR RH	5	1 410.66
158	1	DOOR SEAL REAR RH	\$	162.02
159	1	DOOR WAIST SEAL OUTER REAR RH	\$	Ju 334.69
160	1	DOOR MOULDING REAR RH	\$.	176.82
161	1	FENDER PANEL REAR RH	5 horses	3,299.13 X
162	1	FENDER PANEL INNER TRIM REAR	5	√n 671.45 x
163	1	WHEELARCH REAR RH	5	543.47 X
164	1/31	LOWER ARM RH L70Y	5	B 685.76 —
165	1 15	KUNCKLE ARM RH L70Y	5	By 846.98 —
166	1	KUNCKLE HUB+BEARING RH	5	1× 497.69 -
167	1	KUNCKLE ARM SHIELD RH	\$	In 131.43 R
168	1	KUNCKLE ARM PLATE RH	\$	S- 174.05 ₺
169	1	BRAKE DISC FRT	\$	1 275.49 X
170	1	ABSORBER FRT RH	\$	四 360.54
171	1	ABSORBER MOUNTING KIT RH	\$	Sh 440.66 F
172	1	ABSORBER DUST COVER	\$	Sh 228.72 ⊀
173	1	STABILIZER BAR FRT L70Y	\$	3 604.65 <u></u>
174	1	STABILIZER LINK FRT L70Y	\$	By 117.22
175	1	BRAKE CALIPER FRT RH L70Y	\$	656.94 X
176	1	BRAKE CALIPER BRACKET FRT RH L70Y	\$	14 555.12 X
177	1	ABS SENSOR FRT RH L70Y	\$	S~ 255.75 ℃
178	1	DRIVESHAFT RH	\$	A 1,747.45
179	1	ROCKER PANEL INNER GARNISH LH	\$	Sm 466.51 X
180	1	ROCKER PANEL INNER LH	\$	1,024.79 X
				1 40

TOTAL	\$ 143,892.66
10%	\$ 14,389.27
	\$ 129,503.39

Specical Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$ ~~ 52.00 X
2	1SET	BUMPER CLIP FRT	\$ Mz 66.00 -
3	1	BUMPER BRACKET CLIP FRT LH	\$ 22 12.00 X
4	1	BUMPER SUPPORT CLIP FRT LH	\$ 1√ 10.50 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5374C

5	1	BUMPER BRACKET CLIP FRT RH	\$	12.00
6	1	BUMPER SUPPORT CLIP FRT RH	ć	10.50
7	1	TOW COVER FRT	•	14.50
8	1SET	RADAITOR GRILLE SCREW	4	~~ 16.00
9	1SET	BUMPER GRILLE LOWER CLIP	\$	12 69.00 X
10	1SET	FRAME FULL SUPPORT PANEL CLIP	4	70.00
11	2	FRAME FULL SUPPORT PANEL NUT	\$	20.00
12	2	FRAME FULL SUPPORT PANEL STUD	\$	30.00
13	1SET	WHEELARCH CLIP FRT LH	\$	30.50
14	1SET	WHEELARCH CLIP FRT RH	Š	Men 29.40
15	1	CAP HUB RH FRT	\$	mil 35.00
16	1	RIM RH FRT	s	By 385.00
17	1	TYRE RH FRT	\$ 231	Pin 330.00 Folin
18	1SET	BUMPER RR CLIP	\$	12 66.00 X
19	1SET	BUMPER BEAM BOLT	\$	~~ 22.22 X
20	1SET	PARKING AID	\$	5- 600.00 X
21	1	BUMPER BRACKET CLIP CTR REAR	\$	72 15.00
22	1	BUMEPR BRACKET SIDE CLIP LH REAR	S	12.00
23	1	BUMEPR RETAINER CLIP LH REAR	\$	n 10.40
24	-1	BUMEPR BRACKET SIDE CLIP RH REAR	\$	12.00
25	1	BUMEPR RETAINER CLIP RH REAR	\$	12 10.40
26	1SET	BOOT FINISHER CLIP	\$	25.10 X
27	1	Rear boots sticker "trans-cab"	\$	30.00
28	1	Rear boots sticker "6555-3333"	\$	1~ 30.00
29	1	FENDER PANEL INNER TRIM CLIP REAR RH	\$	22.00
30	1	FENDER PANEL INNER TRIM CLIP REAR LH	\$	NA 22.00
31	1SET	WHEELARCH CLIP LH RR	5	32.34
32	1SET	WHEELARCH CLIP RH RR	\$	A ~ 32.34/
33	2	Rear windscreen sealant	\$	12 80.00 GOSA
34	1	Windscreen moulding	\$	1 4 100.00 -
35	1	Rear Windscreen Inner Sponge Seal	\$	ra 100.00 30in
36	1	EXHAUST MOUNTING REAR	\$	J ← 65.50 ×
37	1	EXHAUST BRACKET REAR	\$	Jun 22.22 X
38	1SET	Front licence plate with holder	\$	5 80.00 €
39	1SET	Rear licence plate with holder	\$	1 × 80.00 ×
40	1	DOOR STICKER "6555-3333"LH	\$	1 80.00 bosh
41	1	DOOR STICKER "6555-3333"RH	\$	12 80.00 605a
42	1	LOWER ARM BOLT L70Y	\$	Nn 34.14 8
43	1	LOWER ARM NUT L70Y	\$	NN 19.93 X

Trans-cab	Auto	Services Pte Ltd	AAD1801-026
No. 2 Ang N	Ao Kio St	reet 63 Singapore 569111	
Tel No. : 628	87 6666	Fax No.: 6257 1330	
CO./GST Re	g. No. 20	1019626G	
SHC 5374C			
44	1	LOWER ARM BOLT L70Y	\$ Nr 34.14 X
45	1	LOWER ARM NUT L70Y	\$ ペ~ 30.59 ✓
46	1	ABSORBER BOLT	\$ 12 44.01 X
47	1	ABSORBER NUT	\$ ~~ 17.56 ×
48	1	BRAKE DISC SCREW FRT	\$ 15.20 X
49	1	KUNCKLE ARM BOLT RH	\$ en 14.21 X
50	1	BRAKE CALIPER BRACKET BOLT FRT RH L70Y	\$ 19.93 X
		TOTAL	\$ 3,051.62
		TOTAL PART	\$ 132,555.02
		LABOUR	
		Panel beating, knocking and straightening the	
		necessary portion, remove and renewal of parts,	17001
		adjust and realign the same	\$ 7,500.00
		Towing Fees.	\$ 120.00 5of
		To apply paint protection system (PPS) maintain	
		and enhancement	\$ 71 380.00 X
		Putty and spray painting of the affected portion.	\$ 6,000.00 1766
		To rust-proofing of the affected areas.	\$ 170.00 129
		To remove and refit interior fittings, trimings,	
		garnish, fittings and other, to enable repair.	\$ 380.00 /00
		To check steering geometry and computer wheel	
		alignment	\$ 220.00 601
		To transfer of tire, rim and on wheel balancing.	\$ 170.00 29

To Check Electrical Lighting Concerned.

170.00 401

Trans-cab Auto Services Pte Ltd

AAD1801-026

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5374C

To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$		380.00	25
priedriatic jack.	3		300.00	-
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	M	170.00	X
To transfer of rear luggage floor panel fittings,		47		
attachment and perform water seepage test.	\$	2	170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	n	380.00	×
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	n	170.00	×
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn	380.00	×
To transfer of tailgate fittings and conduct water seepage test.	\$	nn	170.00	ζ.
To transfer of rear windscreen fittings, attachments and perform water seepage test.	\$		380.00	120
To reinstall rear bumper parking sensor.	\$	11	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	n	280.00	X
To repair and realign rear exhaust pipe.	\$	na	170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	Republi	380.00	×
To lift-up engine with gear box and refit.	5	NA	440.00	X
	4.7		The state of the s	

Trans-cab Auto Services Pte Ltd

AAD1801-026

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330 CO./GST Reg. No. 201019626G

SHC 5374C

To remove and renew power steering pump, oil			
cooler pipe and final checking and testing.	\$	12 440.00 X	
To remove and refit air bag system and reset.	5	480.00 22	ed
To drop diesel tank, pipes, hoses to facilitate			
bodywork repair, final checking and testing.	\$	Λυ 380.00 X	
To vacuum, replace, refix and recharge air			
condenser	\$	380.00 /	001
To replace, refix and top up coolant for radiator	\$	170.00	Sel
To vacuum, replace, refix and recharge Air Cil			
Intercooler	\$	170.00 3	01
To Transfer Of Fender Fittings, Attachments And			
Perform Water Seepage Test.	\$	イセ 170.00 >	K.
TOTAL	\$	20,940.00	
Over All Total	\$	153,495.02	

LUMP SUM (REPAIR)

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- * To display damaged part(s) during resurvey
- * Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- + No itlegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Interna	ationale Des Experts En Autom	elidor
FIRS	ST CAPITAL INSU	RANCE LTD	Ref : CS/FCI1800024	40/Krbe2
	OBINSON ROAD 01 CITY HOUSES	INGAPORE 068877	Date: 21-06-2018 Code: FCI2	
1.		Policy Particula	rs :- THIRD PARTY CLAI	M
	Insured Veh.	SHC 3189J	Veh. Inspected	SHC 5374C
	Policy No.		Coverage (\$)	0.00
	Claim No.	D18000369MFSH	Excess (\$)	0.00
	Assign From	TEO SWEE KEONG	Assign Date	04/01/2018
2.	1-5/05	Vehicle Pa	rticulars & Condition	BURNE AND IN BELL
	Make & Model	RENAULT LATITUDE (A)	c.c	1995
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	VF1ABL15AUC279845	Colour	WHITE / RED
	Odometer	531695	Steering	JAMMED
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.		Conc	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	GITI	8 mm
	L/H Front Tyre	215/60 R16	GITI	8 mm
	R/H Rear Tyre	215/60 R16	FALKEN	7 mm
	L/H Rear Tyre	215/60 R16	FALKEN	7 mm
4.	HORN TO	THE PERSON NAMED IN COLUMN TO SERVICE AND ADDRESS OF THE PERSON NAMED IN COLUMN TO SE	ption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	O/S BODY.	
	DAMAGES SEE D	ETAILS.		
5.		Gene	eral Information	THE SEVEN IN
	Accident Date	01/01/2018	Inspection Date	04/01/2018
	Survey held at	TRANS-CAB AUTO SERVIC	ES PTE LTD	
		NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a.			Remarks	COLUMN CONTRACTOR
	B)THE INSPECTION	NSISTENT TO ACCIDENT REP ON WAS CONDUCTED ON A ⁴ 1 CE TO YOUR INSTRUCTIONS	WITHOUT PREJUDICE" BAS	SIS. SED REPAIRS.
5b.			ate Days of Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	16 Working Da	iys



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 10

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5374C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER FRT	CRACKED	1,259.42	1,259.42
1	BUMPER SPOILER FRT	DISTORTED	181.75	181.75
1	BUMPER ABSORBER FRT	MISSING	394.68	394.68
1	BUMPER RETAINER FRT LH	SERVICEABLE	151.41	
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	
1	BUMPER RETAINER FRT RH	SERVICEABLE	150.77	
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	
-1	BUMPER UNDERTRAY FRT	DISTORTED	472.83	472.83
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	266.80	
- 1	BUMPER FOG LAMP GRILLE LH	SERVICEABLE	207.21	
1	BUMPER FOG LAMP GRILLE RH	DENTED	207.21	207.21
1	BUMPER BEAM FRT	BENT	914.08	914.08
1	TOW COVER FRT	SERVICEABLE	28.61	
-1	RADIATOR GRILLE	SERVICEABLE	1,707.78	
1	RADIATOR GRILLE BADGE 'RENAULT'	SERVICEABLE	225.36	
1	RADIATOR GRILLE FRAME	CRACKED	1,353.75	1,353.75
1	FRAME FULL SUPPORT PANEL	CRACKED	615.90	615.90
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	89.79	
1	FRONT BRACE PANEL	TO REPAIR SEE LABOUR	177.22	
1	HORN	SERVICEABLE	314.17	
1	HORN BRACKET	TO REPAIR SEE LABOUR	40.45	
-1	HEADLAMP RH	BROKEN	1,184.43	1,184.43
1	HEADLAMP PANEL FRT RH	DISTORTED	152.15	152.15
1	HEADLMAP HARNESS	SERVICEABLE	928.29	
1	BONNET	BENT	1,941.63	1,941.63
1	BONNET INSULATOR	SERVICEABLE	405.73	
1	BONNET STRUT LH	SERVICEABLE	88,61	
1	BONNET STRUT RH	SERVICEABLE	88.61	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 10

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	348.31	
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	348.31	V.
1	BONNET LOCK	TO REPAIR SEE LABOUR	305.48	2
1	BONNET CABLE	SERVICEABLE	119.19	100
1	BONNET CABLE COVER	SERVICEABLE	161.03	- 5
1	BONNET SEAL OUTER	SERVICEABLE	92.36	
1	BONNET SEAL INNER	SERVICEABLE	157.28	15
1	FENDER PANEL FRT RH	BENT	783.83	783.83
1	WHEELARCH FRT RH	CRACKED	278.84	278.84
1	FENDER BRACKET LOWER RH	DISTORTED	15.79	15.79
1	FENDER INSULATOR RH	SERVICEABLE	130.84	
1	WIPER RESERVOIR	DENTED	348.25	348.25
1	WIPER RESERVOIR NECK	DENTED	136.11	136.11
1	WIPER RESERVOIR MOTOR	SHORTED	270.06	270.06
1	AIR CLEANER LOWER	SERVICEABLE	271.26	
-1	AIR CLEANER HOSE	SERVICEABLE	76.14	
1	AUTO COMPUTER	SERVICEABLE	5,032.17	
1	STEERING PUMP ELECTRIC	SERVICEABLE	2,306.90	
1	STEERING PINION RACK	BENT / JAMMED	4,413.11	4,413.11
1	ENGINE HARNESS	SERVICEABLE	4,084.54	
1	SUBFRAME OUTER FRT	SERVICEABLE	2,652.45	
1	SUBFRAME BRACKET OUTER RH	SERVICEABLE	92.36	
1	ENGINE MOUNTING RH	SERVICEABLE	552.55	
- 1	FUSE BOX	SERVICEABLE	987.39	
1	ENGINE MOUNTING RH	SERVICEABLE	552.55	
1	ENGINE MOUNTING LOWER	SERVICEABLE	562.42	
1	ENGINE MOUNTING UPPER	SERVICEABLE	592.02	
1	VEHICLE HARNESS PASS ROOM	SERVICEABLE	10,003.86	
1	AIR CLEANER BOX	SERVICEABLE	464.20	
1	TURBO DUCT	SERVICEABLE	1,027.80	
1	OIL PAN ASSEMBLY	SERVICEABLE	2,283.91	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 10

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
-1	A/C CONDENSER	SERVICEABLE	2,020.37	
1	A/C CONDENSER GARNISH RH UPPER	SERVICEABLE	39.67	
1	A/C CONDENSER GARNISH RH	SERVICEABLE	59.60	
1	A/C PIPE CONDENSER TO COMPRESSOR	SERVICEABLE	208.39	
-1	A/C PIPE CONDENSER TO EXPENSION VALVE	SERVICEABLE	658.72	
1	A/C PIPE COMPRESSOR	SERVICEABLE	334.29	
1	A/C PIPE	SERVICEABLE	658.72	
1	A/C COMPRESSOR	SERVICEABLE	2,684.61	
1	AIR COOLER	SERVICEABLE	792.60	
1	AIR INTERCOOLER HOSE (LONG)	SERVICEABLE	1,014.13	
4	AIR INTERCOOLER HOSE (SHORT)	SERVICEABLE	375.14	
1	TRANSMISSION COOLER	SERVICEABLE	1,219.30	
1	TRANSMISSION COOLER PAD	SERVICEABLE	17.96	
1	RADIATOR	SERVICEABLE	1,202.20	
2	RADIATOR STUD UPPER	SERVICEABLE	14.41	
2	RADIATOR BUSH UPPER	SERVICEABLE	50.12	
2	RADIATOR MTG LOWER	SERVICEABLE	55.85	
-1	RADIATOR FAN COWLING	SERVICEABLE	820.54	
1	RADIATOR FAN MOTOR LH	SERVICEABLE	967.36	100
-1	RADIATOR FAN MOTOR RH	SERVICEABLE	1,479.46	
1	RADIATOR TANK	SERVICEABLE	324.62	
1	RADIATOR HOSE UPPER	SERVICEABLE	240.56	
1	RADIATOR HOSE LOWER	SERVICEABLE	491.18	
4	RADIATOR TANK HOSE	SERVICEABLE	61.18	
1	WINDSCREEN FRT	CRACKED	1,364.06	1,364.06
1	SEATBELT LH	JAMMED	2,937.80	2,937.80
1	SEATBELT RH	SERVICEABLE	2,925.37	500000000
1	SEATBELT BUCKLE LH	SERVICEABLE	984.13	
1	SEATBELT BUCKLE RH	SERVICEABLE	949.80	
1	PASSENGER AIRBAG	BURST	3,412.40	3,412.40
1	STEERING AIRBAG	BURST	2,525.75	2,525.75
4	AIRBAG COMPUTER	NECESSARY	1,259.82	1,259.82
1	AIRBAG SENSOR	NECESSARY	724,63	724.63



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 10

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	AIRBAG SENSOR	NECESSARY	289.30	289.30
1	ROTARY SWITCH	NECESSARY	1,253.11	1,253.11
1	DASHBOARD	TORN	4,900.54	4,900.54
1	BUMPER COVER REAR	SERVICEABLE	1,108.46	23-
1	BUMPER LOWER REAR	SERVICEABLE	768.84	(3)
-1	BUMPER BRACKER CTR REAR	SERVICEABLE	113.47	7.0
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	72
:1	BUMPER BRACKET CTR LH REAR	SERVICEABLE	44.99	9
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	6/2
-1	BUMPER BRACKET CTR RH REAR	SERVICEABLE	44.99	7.4
1	BUMPER BEAM REAR	TO REPAIR SEE LABOUR	777.52	
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE	225.95	12
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	4.5
-1	FENDER PANEL REAR RH	BENT	3,299.13	3,299.13
1	WHEELARCH REAR RH	SERVICEABLE	543.47	72
1	FENDER PANEL INNER TRIM REAR RH	TO REPAIR SEE LABOUR	671.45	
া	FENDER PANEL REAR LH	TO REPAIR SEE	3,299.13	
-1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR LH	SERVICEABLE	671.45	
4	LOWER ARM REAR RH	SERVICEABLE	905.99	-
1	KNUCKLE ARM REAR RH	SERVICEABLE	736,67	
1	ABSORBER REAR RH	SERVICEABLE	389.75	-
1	ABSORBER BOLT REAR RH	SERVICEABLE	52.10	
1	ABSORBER DUST COVER REAR RH	SERVICEABLE	92.16	
1	DOOR PANEL REAR RH	BENT	2,844.66	2,844.66
1	DOOR SEAL REAR RH	SERVICEABLE	187.08	1.0
1	DOOR PANEL FRT RH	BENT	2,844.66	2,844.66
1	DOOR HINGE UPPER RH	BENT	261.28	261.28
-1	DOOR HINGE LOWER RH	BENT	300.55	300.55
1	DOOR CHECK FRT RH	SERVICEABLE	194.77	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 10

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	DOOR CHECK BOLT	SERVICEABLE	22.69	1800
1	DOOR LOCK FRT RH	TO REPAIR SEE LABOUR	908.75	22
1	DOOR CATCH FRT RH	TO REPAIR SEE LABOUR	131.23	9
1	DOOR HANDLE OUTER FRT RH	SERVICEABLE	477.76	9
1	DOOR HANDLE COVER FRT RH	SERVICEABLE	13.22	
1	DOOR HANDLE MODULE FRT RH	SERVICEABLE	133.60	- 10
1	DOOR REGULATOR FRT RH	SERVICEABLE	505.19	V
1	DOOR REGULATOR MOTOR FRT RH	SERVICEABLE	796.46	53
1	DOOR REGULATOR GUIDE FRT RH	SERVICEABLE	120.97	2
1	DOOR GLASS FRT RH	SERVICEABLE	625.96	10
1	DOOR FINISHER FRT RH	SERVICEABLE	515.06	
1	DOOR MOULDING FRT RH	SERVICEABLE	176.82	5
1	DOOR FINISHER CLIP KIT FRT RH	NOT NECESSARY	90.97	2.
1	DOOR CASING FRT RH	SERVICEABLE	1,509.06	
1	DOOR CASING LIGHT	SERVICEABLE	82.49	3
1	DOOR GRAB HANDLE FRT RH	SERVICEABLE	210.96	3.
1	DOOR MIRROR RH	SERVICEABLE	1,725.73	
1	DOOR WEATHERSTRIP FRT RH	SERVICEABLE	410.27	- 0
1	DOOR SEAL LOWER FRT RH	SERVICEABLE	91.17	2
1	DOOR GLASS RUNNER SEAL FRT RH	SERVICEABLE	626.36	1/2
-1	DOOR WAIST SEAL OUTER FRT RH	SERVICEABLE	291.27	5
1	DOOR WAIST SEAL INNER FRT RH	SERVICEABLE	122.15	
1	DOOR PANEL REAR RH	REPEATED	2,844.66	2
1	DOOR GUIDE REAR RH	SERVICEABLE	176.82	
1	DOOR HINGE UPPER RH	BENT	274.50	274.5
1	DOOR HINGE LOWER RH	BENT	300.55	300.5
1	DOOR CHECK REAR RH	SERVICEABLE	203.06	
1	DOOR LOCK REAR RH	TO REPAIR SEE LABOUR	908.75	
1	DOOR GRAB HANDLE REAR RH	SERVICEABLE	210.96	3.
1	DOOR HANDLE OUTER REAR RH	SERVICEABLE	126.49	
1	DOOR HANDLE CAP REAR RH	SERVICEABLE	35,52	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 10

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	DOOR HANDLE COVER REAR RH	SERVICEABLE	13.22	
1	DOOR HANDLE MODULE REAR RH	SERVICEABLE	133.60	12
1	DOOR FINISHER REAR RH	SERVICEABLE	423.10	-
1	DOOR WEATHERSTRIP REAR RH	SERVICEABLE	410.66	18
1	DOOR SEAL REAR RH	SERVICEABLE	162.02	
1	DOOR WAIST SEAL OUTER REAR RH	SERVICEABLE	334.69	12
1	DOOR MOULDING REAR RH	SERVICEABLE	176.82	6
1	FENDER PANEL REAR RH	REPEATED	3,299.13	13
1	FENDER PANEL INNER TRIM REAR	SERVICEABLE	671.45	2
1	WHEELARCH REAR RH	SERVICEABLE	543.47	19
1	FRT LOWER ARM RH L70Y	BENT	685.76	685.76
1	FRT KNUCKLE ARM RH L70Y	BENT	846.98	846.98
1	KNUCKLE HUB + BEARING RH	NECESSARY	497.69	497.69
1	KNUCKLE ARM SHIELD RH	SERVICEABLE	131.43	
1	KNUCKLE ARM PLATE RH	SERVICEABLE	174.05	,
1	BRAKE DISC FRT	SERVICEABLE	275.49	9
1	ABSORBER FRT RH	BENT	360,54	360.54
1	ABSORBER MOUNTING KIT RH	SERVICEABLE	440.66	5
1	ABSORBER DUST COVER	SERVICEABLE	228.72	
1	STABILIZER BAR FRT L70Y	BENT	604.65	604.68
1	STABILIZER LINK FRT L70Y	BENT	117.22	117.22
1	BRAKE CALIPER FRT RH L70Y	SERVICEABLE	656.94	
- 1	BRAKE CALIPER BRACKET FRT RH L70Y	SERVICEABLE	555.12	19
1	ABS SENSOR FRT RH L70Y	SERVICEABLE	255.75	V.
1	DRIVESHAFT RH	BENT	1,747.45	1,747.45
1	ROCKER PANEL INNER GARNISH LH	SERVICEABLE	466.51	7.
1	ROCKER PANEL INNER LH	TO REPAIR SEE	1,024.79	(1
	LESS 10% DISCOUNT		-14,389.26	-4,857.69
			129,503.38	43,719.16
	SPECIAL NETT ITEMS			
1	SET RADIATOR GRILLE FRAME CLIP (SN)	NOT NECESSARY	52.00	
্ৰ	SET BUMPER CLIP FRT (SN)	NECESSARY	66.00	66.00



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:7 of 10

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	BUMPER BRACKET CLIP FRT LH (SN)	NOT NECESSARY	12.00	
1	BUMPER SUPPORT CLIP FRT LH (SN)	NOT NECESSARY	10.50	
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	19
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	10.50	8
1	TOW COVER FRY (SN)	SERVICEABLE	14.50	33
1	SET RADIATOR GRILLE SCREW (SN)	NOT NECESSARY	16.00	
1	SET BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	- 9
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	3.5
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	9
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	
1	SET WHEELARCH CLIP FRT LH (SN)	NOT NECESSARY	30.50	
1	SET WHEELARCH CLIP FRT RH (SN)	NECESSARY	29.40	29.40
1	CAP HUB RH FRT (SN)	MISSING	35.00	35.00
1	RIM RH FRT (SN)	BENT	385.00	385.00
1	TYRE RH FRT (SN) (70%)	PUNCTURE	330.00	231.00
-1	SET BUMPER RR CLIP (SN)	NOT NECESSARY	66.00	
1	SET BUMPER BEAM BOLT (SN)	NOT NECESSARY	22 22	
-1	SET PARKING AID (SN)	SERVICEABLE	600.00	
1	BUMPER BRACKET CLIP CTR REAR (SN)	NOT NECESSARY	15.00	
-1	BUMPER BRACKET SIDE CLIP LH REAR (SN)	NOT NECESSARY	12.00	
1	BUMPER RETAINER CLIP LH REAR (SN)	NOT NECESSARY	10.40	
-1	BUMPER BRACKET SIDE CLIP RH REAR (SN)	NOT NECESSARY	12.00	
1	BUMPER RETAINER CLIP RH REAR (SN)	NOT NECESSARY	10.40	
-1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	25.10	
1	REAR BOOTS STICKER "TRANS-CAB" (SN)	NOT NECESSARY	30.00	
- 1	REAR BOOTS STICKER "6555-3333" (SN)	NOT NECESSARY	30.00	
1	FENDER PANEL INNER TRIM CLIP REAR RH (SN)	NOT NECESSARY	22.00	
1	FENDER PANEL INNER TRIM CLIP REAR LH (SN)	NOT NECESSARY	22.00	
1	SET WHEELARCH CLIP LH RR (SN)	NOT NECESSARY	32.34	
1	SET WHEELARCH CLIP RH RR (SN)	NOT NECESSARY	32.34	
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
-1	WINDSCREEN MOULDING	NECESSARY	100.00	100.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607196-R

Page No.:8 of 10

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	65.50	8
- 1	EXHAUST BRACKET REAR (SN)	SERVICEABLE	22 22	
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	80.00	
-1	SET REAR LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	80.00	12
1	DOOR STICKER "6555-3333" LH (SN)	NECESSARY	80.00	60.00
1	DOOR STICKER "6555-3333" RH (SN)	NECESSARY	80.00	60.00
1	LOWER ARM BOLT L70Y (SN)	NOT NECESSARY	34,14	n.
-1	LOWER ARM NUT L70Y (SN)	NOT NECESSARY	19.93	II.
1	LOWER ARM BOLT L70Y (SN)	NOT NECESSARY	34.14	
্ৰ	LOWER ARM NUT L70Y (SN)	NOT NECESSARY	30.59	
1	ABSORBER BOLT (SN)	NOT NECESSARY	44.01	
1	ABSORBER NUT (SN)	NOT NECESSARY	17.56	
1	BRAKE DISC SCREW FRT (SN)	NOT NECESSARY	15.20	
-1	KNUCKLE ARM BOLT RH (SN)	NOT NECESSARY	14.21	
1	BRAKE CALIPER BRACKET BOLT FRT RH L70Y (SN)	NOT NECESSARY	19.93	
	LABOUR		3,051.63	1,036.40
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FRAME FULL SUPPORT BRACKET, FRONT BRACE PANEL, HORN BRACKET, BONNET HINGE LH, BONNET HINGE RH, BONNET LOCK,)		7,500.00	1,700.00
	BUMPER BEAM REAR, BUMPER BEAM BRACKET LH REAR, BUMPER BEAM BRACKET RH REAR, FENDER PANEL INNER TRIM REAR RH, FENDER PANEL REAR LH, DOOR LOCK FRT RH, DOOR CATCH FRT RH, DOOR LOCK REAR RH AND ROCKER PANEL INNER LH. }		•	
	TOWING FEES.		120.00	50.00
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	1,760.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	120.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.		380.00	100.00



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:9 of 10

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO CHECK STEERING EOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.		170.00	20,00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	40.00
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.		380.00	250.00
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF TAIKGATE FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		380.00	120.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.	NOT NECESSARY	170.00	
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	280.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	REPEATED	380.00	-
	TO LIFT-UPP ENGINE WITH GEAR BOX AND REFIT.	NOT NECESSARY	440.00	
	TO REMOVE AND RENEW POWER STEERING PUMP, OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	NOT NECESSARY	440.00	-
	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET.		480.00	200.00
	TO DROP DIESEL TANK, PIPES, HOSES, TO FACILITATE BODYWORK REPAIR, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER.		380.00	100.00
	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR,		170.00	50.00



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:10 of 10

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO VACUUM, REPLACE, REFIX AND RECHARGE OIL INTERCOOLER.	NOT NECESSARY	170.00	50.00
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	Y.
			20,940.00	4,620.00
	GRAND TOTAL		153,495.01	49,375.56

RECOMMENDED COST OF LUMP SUM REPAIRS	28,000.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/FCI18000240/Krbe2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.