

ASS. REC. BY:

REF: CS/FCL18000243/Udpn2

Special Instruction:

Surveyor:

Marius.

ASSIGNMENT (Office)

From (Person): CWS May Chui of FCL Date/Time: 04.01.2018 9:02am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SH 3142L Insured: SHB 403061

at Workshop m/s Tan Lim Motor Tel: 6858 5151

of 51 Defu Lane 10

Policy No: 015072701MFSH Claim No: D18000137MTSH

Sum Insured: Excess:

Make of Veh: D.O.A. 31.12.2017
(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time: 04.01.2018 10:42am Person Contacted: William Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SH 3142L - CI/FCL15014554/D	DA: 04082015
	SHB 403061 - CS/FCL15015233/R14502	DA: 05092015

REF: FCL

ASSIGNMENT

From: Date: 01/01/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 51 3142L

at Workshop n/s: Tan Lim

of

Insured

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

I/A/C Accident Report: Consistent? : Yes or No

C/A / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'WP'

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: 51/3142L Yr Regn: 12 14

Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) / Prime Mover /

Truck / Trailer or C A /

Make: H/underi Elctre cc 159/

Colour: yellow / black A/C: Insured / Std / NI / NA

Sp. Reading: 438964 T.Radio: Insured / Std / NI / NA

Eng/No:

C/No: KMHDH41CM EU128979

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

maxxis

Front

Rear

R/Bal: 6 mm

R/Bal: 6 mm

L/Bal: 6 mm

L/Bal: 6 mm

D.O.A: 31/12/17

D.O.I: 4/1/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/1/18 4/5 to 1600 confirmed with willian.

5/1/18 email preli to may.

RECEIVED 03 JAN 2018

Date/Time: File Pass to? ☐ : Preli. Report08/1/18 ☐ : Final Report

Date/Time: File Return to?

Days Of Repair: 3

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS - S

Photos

Diagrams

TOTAL

Add Fee: ☐ Site Insp / S☐ Interview / S☐ Tech. Insps / S☐ Weekend / S

Report Format:

Lump Sum / I.B.R. / S

TP

1600

130

50

41

221

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18000243/Uqb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 04-01-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 4030G	Veh. Inspected	SH 3142L
Policy No.		Coverage (\$)	0.00
Claim No.	D18000137MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	04/01/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	31/12/2017	Inspection Date	04/01/2018
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Survey Department Check List (Case Handler)

Reference No. : CS/FC/18000743/UGP
Policy Type: OD / TP / TP RES / TL / EVA

SH 3142L

Case Handler

Typist

Admin (Ceth): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (Mawa): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓			
✓			

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By: [Signature] 08/1/18
Case Handler Date

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	03-01-2018	Our Ref No. D18000137MFSH
Accident Date	31-12-2017	Claim Type. Third Party
Insured Vehicle	SHB4030G	Third Party Vehicle. SH3142L
Survey Location	51 DEFU LANE 10	
Contact Person.	LAM WEI SHONG WILLIAM	
Contact No.	68585151/ 0	Fax No. 68580877
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TAN LIM MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/232566)



PRI Documents



Close



PRI Header Details

Claim No	D18000137MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & TAI
Workshop Name	TAN LIM MOTOR PTE LTD (Contact Person : LAM WEI SHONG WILLIAM)	Survey Location & Contact Details	51 DEFU LANE 10 Mobile: 0 , Phone: 68585151 , Fax: 6858087 EmailId: WEI.SHONG@TLMOTOR.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: ACCIDENT NOT REPORT		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHB4030G	TP Vehicle No	SH314:
PRI Recieved Date	03-01-2018 05:13:03 PM	Surveyor Appointed Date	04-01-2018 09:02:35 AM	Surveyor Accept Date	04-01-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	04-01-2018	Upload Survey Report *:	
-----------------------------	--	----------------------	------------	-------------------------	----------------------

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents

File Name

Action

Surveyor Job Remarks

Ai Phing (LKKAuto)

From: Ai Phing (LKKAuto)
Sent: Friday, 5 January, 2018 1:54 PM
To: 'Claim Workflow System'
Cc: MAYCHUA@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18000137MFSH/1
Attachments: SH 3142L .pdf

Dear May,

Enclosed herewith preliminary advise of vehicle SH 3142L.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 4 January, 2018 10:44 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18000137MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

"WISHES YOU A HAPPY NEW YEAR 2018"

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Thursday, 4 January, 2018 9:02 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; MAYCHUA@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18000137MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18000137MFSH

Date: 05-01-2018

Our Ref: CS/FCI18000243/Uqb

The Motor Claims Department
First Capital Insurance Ltd

Without Prejudice

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SH 3142L.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 04-01-2018 at the premises of M/s TAN LIM MOTOR and have the following to report:-

Workshop Estimate Amount	: S\$ 3,863.84
Revised Estimate Amount	: S\$ 1,600.00
"Check" Items Amount	: S\$ -
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages
at the rear portion.



Yours faithfully

Marcus Chua
Automotive Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 2705A

Vehicle Details

Vehicle No.: SH3142L

Vehicle to be Exported: Yes

Intended De-registration Date: 02 Jan 2018

Vehicle Make: HYUNDAI

Vehicle Model: ELANTRA 1.6 AT ABS D/AB 2WD 4DR

Primary Colour: Black

Manufacturing Year: 2014

Engine No.: G4FGEU255998

Chassis No.: KMHDH41CMEU128979

Maximum Power Output: 97.0 kW (130 bhp)

Open Market Value: \$10,867.00

Original Registration Date: 23 Dec 2014

First Registration Date: 23 Dec 2014

Transfer Count: 0

Actual ARF Paid: \$10,867.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 22 Dec 2022

PARF Rebate Amount: \$8,150.00

Intended COE Rebate Details

COE Expiry Date: 22 Dec 2022

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$51,668.00

COE Rebate Amount: \$32,101.00

Total Rebate Amount: \$40,251.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 Jan 2018

First Capital Insured's Veh No : SHB4030G

Date of Accident : 31 December 2017



陳林摩呀私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Mr Pay Kim Swee

Date : 03 January 2018

Estimate To Repair SH3142L - Hyundai Elantra 1.6GLS

Chassis No : KMHDH41CMEU128979

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	bootlid - Elantra badge	\$ 49.00
02	1 pc	bootlid - centre emblem badge	\$ 27.00
03	1 pc	bootlid - GLS badge	\$ 26.00
04	1 pc	rear bumper	\$ 459.00
05	2 ps	rear bumper reflectors @ \$75.00	\$ 150.00
06	1 pc	rear bumper lower centre pad	\$ 69.80
07	1 pc	rear bumper reinforcement	\$ 277.00
08	1 pc	rear bumper absorber foam	\$ 89.00
09	2 ps	rear bumper brackets @ \$41.00	\$ 82.00
10	2 ps	rear bumper side retainers @ \$26.00	\$ 52.00
11	2 ps	rear bumper side guide @ \$41.00	\$ 82.00
12	3 ps	rear bumper bottom brackets @ \$41.00	\$ 123.00
13	2 ps	rear bumper top brackets @ \$18.00	\$ 36.00
14	10 ps	rear bumper clips @ \$4.30	\$ 43.00
15	1 pc	rear end panel	\$ 385.00
16	1 pc	rear end panel inner trim	\$ 55.00
		Less 20 %	\$ 2,004.80
			\$ 400.96
			\$ 1,603.84
<u>SPECIAL NETT ITEMS</u>			
17	1 set	rear bumper parking sensor	\$ 450.00
			\$ 450.00
<u>LABOUR & MISC. CHARGES</u>			
01		To reinstall of rear bumper parking sensor.	\$ 120.00
02		To rust-proofing of the affected areas.	\$ 100.00
03		To check electrical lighting concerned.	\$ 60.00
04		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 750.00
05		Putty and spray painting of the affected portion.	\$ 780.00
			\$ 1,810.00
			\$ 3,863.84
		Total	

Our Consultants hence notify the Assigner of the following:

- To be done after spray painting
- To survey damages (part) during resurvey
- Parts prices are subject to confirmation
- The paint survey is on a "Without Prejudice" basis
- No further modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised by Repairer



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18000243/Uqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 10-01-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4030G	Veh. Inspected	SH 3142L	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D18000137MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	04/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI ELANTRA (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KMHDH41CMEU128979	Colour	YELLOW / BLACK	
Odometer	438964	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MAXXIS	6 mm	
L/H Front Tyre	195/65 R15	MAXXIS	6 mm	
R/H Rear Tyre	195/65 R15	MAXXIS	6 mm	
L/H Rear Tyre	195/65 R15	MAXXIS	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/12/2017	Inspection Date	04/01/2018	
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 3142L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID-ELANTRA BADGE	NOT NECESSARY	49.00	-
1	BOOTLID-CENTRE EMBLEM BADGE	NOT NECESSARY	27.00	-
1	BOOTLID-GLS BADGE	NOT NECESSARY	26.00	-
1	REAR BUMPER	DENTED / DEFORMED	459.00	459.00
2	REAR BUMPER REFLECTORS @\$75.00	NOT NECESSARY	150.00	-
1	REAR BUMPER LOWER CENTRE PAD	DEFORMED / CUT	69.80	69.80
1	REAR BUMPER REINFORCEMENT	CRACKED	277.00	277.00
1	REAR BUMPER ABSORBER FOAM	NOT FITTED	89.00	-
2	REAR BUMPER BRACKETS @\$41.00	NOT NECESSARY	82.00	-
2	REAR BUMPER SIDE RETAINERS @\$26.00	BENT	52.00	52.00
2	REAR BUMPER SIDE GUIDE @\$41.00	NOT NECESSARY	82.00	-
3	REAR BUMPER BOTTOM BRACKETS @\$41.00	CRACKED	123.00	123.00
2	REAR BUMPER TOP BRACKETS @\$18.00	NOT NECESSARY	36.00	-
10	REAR BUMPER CLIPS @\$4.30	NECESSARY	43.00	43.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	385.00	-
1	REAR END PANEL INNER TRIM	NOT NECESSARY	55.00	-
	LESS 20% DISCOUNT		-400.96	-204.76
			1,603.84	819.04
SPECIAL NETT ITEMS				
1	SET REAR BUMPER PARKING SENSOR (SN)	SHORTED	450.00	200.00
			450.00	200.00
LABOUR				
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.		120.00	50.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	100.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		60.00	20.00
	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		750.00	420.00

Report Ref No. CS/FCI18000243/Uqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		780.00	500.00
			1,810.00	990.00
	GRAND TOTAL		3,863.84	2,009.04
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,600.00

Report Ref No. CS/FCI18000243/Uqbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.