

PRS

REF: MLD

ASSIGNMENT

From:

Date:

21-11-2017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

FBB 8485Y

at Workshop mis

Speedy Motor

of

10 Amk Ind Park 2A #05-21

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAO Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

OA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle IN / OUT

Veh No:

FBB 8485Y

Yr Regn:

AUG 2007

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

HONDA CB400

cc 399

Colour:

White / R/B

A/C:

Insured / Std / NI / NA

Sp. Reading:

134128

T/Radio: Insured / Std / NI / NA

Eng No:

C/No:

JH2NC39976 M200902

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

P:

120/60/R17 MEIZELER

R:

160/60/R17 MIC

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

Rear:

R/Bal:

7

mm

R/Bal:

7

mm

L/Bal:

mm

L/Bal:

mm

D.O.A:

15/11/2017

D.O.A:

21/11/2017

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT / OS BODY N/S BODY

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time/ File Pass to:



Preli. Report

Days Of Repair:

1



Final Report

Resurvey No. of Trip:

Survey Fee

Date/Time/ File Return to:

Transportation

2

Add Fee:



Site Insp: \$

1.000 - 10.000



Interview: \$

Phone



Tech. Insp: \$

Driver



Web-end: \$

TOTAL

Report Format:

Lump Sum / L.B / h / e