



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4204C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (CONSISTENT)	DENTED	603.60	603.60
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	504.35	-
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$180.00 (CONSISTENT)	NOT NECESSARY	360.00	-
1	REAR BUMPER SIDE BRACKET (CONSISTENT)	NOT NECESSARY	49.00	-
1	REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	22.00	22.00
1	REAR BUMPER SPONGE (CONSISTENT)	NOT NECESSARY	143.40	-
1	REAR BUMPER UNDER COVER (CONSISTENT)	NOT NECESSARY	225.00	-
	LESS 20% DISCOUNT		-381.47	-125.12
			1,525.88	500.48
	<u>LABOUR</u>			
	PANEL BEATING .		350.00	200.00
	SPRAY PAINTING CHARGE.		200.00	180.00
			550.00	380.00
GRAND TOTAL			2,075.88	880.48

RECOMMENDED COST OF REPAIRS			880.48
------------------------------------	--	--	---------------

Report Ref No. CC4/ASM18000264/K1ps3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.