



English (default) ▾

MOVA AUTOMOTIVE PTE LTD ▾



SERVICE REQUESTS

MESSAGES

CLAIMS

88m00697
CK/30376

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving 1 2007 LEXUS RX350 3.5 (SBR1688R)

Date of Loss December 31, 2017

Time of Loss 17.30

Loss Description SBR1688R(INSR) HIT GX3947P (TP)

Comment

Workshop Details

Total Rebate Amount

0

Nett Loss Amount

\$0.00

Assigned Workshop

MOVA AUTOMOTIVE PTE LTD

Target Date of Completion *

01/13/2018



Days of work completion *

9

USX Auto Consultants hence notify the Registrar of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Registrar

Signature:

Date:

Taughtin 97445749 8 days
Ex \$400
Resurvey before paint
10/01/18 @ 145pm.
sure@pkauts.com
Rovant



SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts

Add

EDIT	SR NO	QUAN TTY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISC QUNTY	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	1	1			FRONT BUMPER		RY		400		400	Reviewing	
	2	10			FRONT BUMPER CLIPS		WV		2.5		25	Reviewing	
	3	1			FOG LAMP ASSY RH		X old damage		190		190	Reviewing	
	4	1			FRONT FENDER LH		bf		400		400	Reviewing	
	5	1			FRONT FENDER LAMP LH		X		150		150	Reviewing	
	6	1			FRONT FENDER INNER GARNISH LH		X		75		75	Reviewing	

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISC QUNTY%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	7	10			FRONT FENDER COWLING CLIPS	X			2.5		25	Reviewing	
	8	1			FRONT DOOR MIRROR COVER LH - RESPRAY	Ry			0		0	Reviewing	
	9	1			FRONT DOOR LH	ht-			850		850	Reviewing	
	10	1			FRONT DOOR PROTECTOR LH	cut-			165		165	Reviewing	
	11	1			FRONT DOOR CHECKER LH	X			130		130	Reviewing	
	12	1			FRONT DOOR LOCK LH - CHECK	?			0		0	Reviewing	
	13	1			FRONT DOOR GLASS REGULATOR MOTOR LH - CHECK	X			0		0	Reviewing	
	14	1			FRONT DOOR GLASS REGULATOR LH - CHECK	X			0		0	Reviewing	
	15	1			FRONT DOOR WEATHERSTRIP LH	?			135		135	Reviewing	

EDIT	SR NO	QUAN TTY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISC QUNTY	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	16	1			CENTER PILLAR LH - REPAIR	Qty			0		0	Reviewing	
	17	1			REAR DOOR LH	ht-			650		650	Reviewing	
	18	1			REAR DOOR HINGE TOP LH	?			50		50	Reviewing	
	19	1			REAR DOOR CHECKER LH	?			130		130	Reviewing	
	20	1			REAR DOOR HINGE BOTTOM LH	?			50		50	Reviewing	
	21	1			REAR DOOR PROTECTOR LH	cut-			165		165	Reviewing	
	22	1			REAR DOOR LOCK LH - CHECK	x			0		0	Reviewing	
	23	1			REAR DOOR WEATHERSTRIP LH	?			135		135	Reviewing	
	24	1			REAR DOOR GLASS REGULATOR MOTOR LH - CHECK	?			0		0	Reviewing	
	25	1			REAR DOOR GLASS REGULATOR LH - CHECK	?			0		0	Reviewing	

EDIT	SR NO	QUAN TTY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISC QUANTITY	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	26	1			REAR FENDER ARCH PANEL	bt			650		650	Reviewing	
	27	1			REAR BUMPER - REPAIR	Ry			0		0	Reviewing	
	28	10			REAR BUMPER CLIPS	wec			2.5		25	Reviewing	

Labour

Add

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR RSR	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	1		TO CUT / WELD REAR ARCH PANEL LH, KNOCK AND STRAIGHTEN CENTER PILLAR LH, FRONT DOOR PILLAR LH, REPAIR BUMPER, REMOVE AND REPLACE ACCIDENT DAMAGED PARTS, REALIGN ALL CONNECTION.	0	1200	0	Reviewing		
	2		SPRAY PAINT FRONT BUMPER, FRONT FENDER LH, FRONT DOOR PILLAR LH, FRONT DOOR LH, FRONT DOOR MIRROR COVER LH, CENTER PILLAR LH, REAR DOOR LH, REAR FENDER LH, REAR BUMPER AND PROTECTOR	0	0	1600	Reviewing	1300	
	3		REMOVE AND REPLACE FRONT AND REAR DOOR MECHANISM AND CHECK LOCKING SYSTEM	0	100	0	Reviewing		

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	4		REMOVE AND REPLACE REAR SEAT ASSY, INNER TRIM, REAR FLOOR CARPET, GARNISH	0	100 60	0	Reviewing		
	5		REMOVE AND REPLACE REVERSE SENSOR AND CHECK FUNCTION	0	40 50	0	Reviewing		



- SERVICE REQUESTS
- MESSAGES
- CLAIMS

<< **Assessment Details**

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous

Summary

Claim Amount \$7,440.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Spare Parts	\$4,400.00	\$4,400.00
Labour	\$1,440.00	\$1,440.00
Paint	\$1,600.00	\$1,600.00

Submit for Review