

REF: CS3 / ACG 17010229 / Gvb-1 ez

Special Instruction:

US: ~~4~~ 13400.00

From (Person): Norsiah of Alm Date/Time: 02012018
Estimated Cost: _____ Bill to: _____

Third Parties:

Claimant:

Surveyor: Sincere Appraisal

Workshop: Xin Yun Auto

OD/TP Re-inspection) Evaluation

To Inspect Vehicle No: SLB 8A8C Insured: SLD 483B

at Workshop m/s Xin Yun Auto Tel: _____
of 8 Kakli Bukit Ave 4 #05-23

Policy No: _____ Claim No: 4149 44302586 (003)

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 11-05-2017
(Client's Record)

05-01-2018 (Friday) @ 2pm

H.O.D. Endorsement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 10/2/18 Confirmed with Sub. # 15135 Final Fig 2 days (Red \$ / %; Original 114 days)

Date/Time: 16/3/18 Submit Final Fig 156950, 9 days (Red \$ 6450 / 48 %; Original days)

[illegible]

RECEIVED IN NOV 23 1963

Para(1) : Parts found not replaced (To highlight *R* or *UB*, *LR*, *Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)	

Para(3) : Nett Value

Market Value :

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date:

2017 Reimbursement

100-443887-100

... ..

NAME _____ **DATE** _____

210

Date/Time		File Pass to		File Return to		Total	
1)	Date/Time <u>16/3- typist</u>	File Pass to		2)	Date/Time	File Return to	
3)	Date/Time	File Pass to		4)	Date/Time	File Return to	
5)	Date/Time	File Pass to		6)	Date/Time	File Return to	

ASSIGNMENT

From _____ Date _____

Estimated Cost: _____

OD / TP / WS / TP RES / CD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop no: _____

of _____

insured _____

Policy No: _____


Claims No: _____

Sum Insured _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GLA / FR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLB 8298C Reg: 25 Apr 2016

Type: M/Cay / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make: Mit Lancer No: 1590Colour: Red A.O. Insured / Std / NI / NASo. Reading: 32108 T. Pable Insured / Std / NI / NA

Eng No: _____

C No: _____

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRM / STD A/Rim orTyre Size F: 205/60 R16
R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R. Bal. 6 mm R. Bal. 6 mmL. Bal. 6 mm L. Bal. 6 mmD.O.A. _____ D.O.I. 05-01-18Survey held at: w/s 2pmDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time File Pass to:

☐

Preli. Report

☐

Final Report

Date/Time File Return to:

Date:

Report Format:

Lump Sum: A.B. + S

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp. \$☐ Inter. Insp. \$☐ Tech. Insp. \$☐ Des. Insp. \$

Survey Fee

Transportation

L.S. + P.C. + S.

Fuel

Other

TOTAL

Torque 5 Pte Ltd

No. 8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 (U.S. & GST Reg. No. 2013132216)

ESTIMATION REPORT

Estimation No. : E17020003

Vehicle No : SGX2152Y
 Make & Model : HONDA CIVIC 2.0L A
 Year of Manufacture : 2007

No	Description	Qty	U/P	Amt
----	-------------	-----	-----	-----

Section: List Items

1	Front bumper	1.00	458.00	0.00	✓
2	Front bumper clip	1.00	50.00	0.00	✓
3	Front bumper side retainer RH	1.00	83.40	0.00	✓
4	Headlamp RH	1.00	967.00	0.00	✓
5	Headlamp lower bracket RH	1.00	87.90	0.00	✓
6	RH front fender	1.00	546.00	0.00	✓
7	RH front fender cowl - <i>del</i>	1.00	131.20	0.00	✓
8	RH front fender cowl clips	1.00	50.00	0.00	✓
9	RH rocker panel	1.00	313.60	0.00	✓
10	RH rocker panel garnish <i>del</i>	1.00	400.00	0.00	✓
11	RH rocker panel garnish clip	1.00	50.00	0.00	✓
12	RH front knuckle arm	1.00	323.60	0.00	✓
13	RH front knuckle bearing	1.00	136.20	0.00	✓
14	RH front lower arm	1.00	292.10	0.00	✓
15	RH front shock absorber	1.00	358.20	0.00	✓
16	RH front tie rod	1.00	84.20	0.00	✓
17	RH front tie rod end	1.00	84.80	0.00	✓
18	Steering rack and pinion	1.00	1960.10	0.00	✓
19	Front crossmember	1.00	1642.80	0.00	✓
20	RH front door	1.00	882.40	0.00	✓
21	RH front door hinge top	1.00	69.50	0.00	✓
22	RH front door hinge bottom	1.00	69.50	0.00	✓
23	RH front door weatherstrip	1.00	131.20	0.00	✓
24	RH front door outer protector	1.00	126.00	0.00	✓
25	RH front door outer chrome moulding	1.00	84.00	0.00	✓

RH Front Door Trim 1 clips *new*

Continue on next page...

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile**AIG ASIA PACIFIC INSURANCE PTE LTD**

Ref : CS3/AIG17010229/vb-1

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 04-01-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SLD 483B	Veh. Inspected	SLB 8298C
Policy No.		Coverage (\$)	0.00
Claim No.	4149443025SG(003)	Excess (\$)	0.00
Assign From	NORSIAH	Assign Date	02/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	24/05/2017	Inspection Date	05/01/2018
Survey held at	XIN YUN AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-59 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Catherine Chong (LKK Auto)

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Tuesday, 2 January, 2018 5:28 PM
To: assignments
Subject: FW: Revise offer Our Ref: 4149443025SG(003) Your Ref: RA.509933.J

Importance: High

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Md Noor, Norsiah [mailto:Norsiah.MdNoor@aig.com]
Sent: Tuesday, 2 January, 2018 4:53 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: FW: Revise offer Our Ref: 4149443025SG(003) Your Ref: RA.509933.J
Importance: High

Dear Team,

Refer to below email.

Please assist to conduct physical re-inspection on the Third-party's vehicle.

Thank you

Norsiah Md Noor
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419-1606 | Fax +(65) 6835-7417
Norsiah.MdNoor@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Ham [<mailto:riaz@justice.com.sg>]

Sent: Tuesday, January 02, 2018 11:32 AM

To: Md Noor, Norsiah

Subject: RE: Revise offer Our Ref: 4149443025SG(003) Your Ref: RA.509933.J

WITHOUT PREJUDICE

Hi Ms Norsiah Md Noor,

Please be informed that our client's vehicle (SLB8298C) can be re-inspected as follows:

RI Date:05/01/2017 Friday Afternoon 2pm.

Location: Xin Yun Auto, Blk8 Kaki Bukit Ave4 #05-23 Premier @ Kaki Bukit Singapore 415875

Kindly inform your surveyor to come on time as our client's schedule is really tight.

Thank you and Best Regards,

HAM

RIAZ LLC

Tel: 6534 0110

Fax: 6534 0220

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Sincere Appraisal Services

81 Ubi Avenue 4 #06-28 UB.One Singapore 408830

Tel : 6636 4628 Fax : 6636 4638 E-mail : sincereappraisal@gmail.com

Company Registration No. 53159958B

VEHICLE DAMAGE INSPECTION REPORT

Our Ref: 300/TP/2017

Date: 14/6/2017

REFERENCE

Date of loss: 24/5/2017

Claimant: Chan Chuen Onn

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLB8298C

Reg date: 25/4/2016

Colour: Red

Type: Motor Car

Type of Claims: Third Party

Make & Mitsubishi

Model Lancer EX 1.6 AT

Engine No: 4A92CG6558

Chassis No: JMYSRCY1AGU004052

Odometer No: 19518km

Engine Cap: 1590cc

CONDITION OF VEHICLE AT THE TIME OF SURVEY

(STATIC ONLY)

General Condition: Good

Steering: Good

Engine Modification: Nil

Paint work: Good

Handbrake: Good

Pre-accident

Footbrake: Good

Damage: Nil

CONDITION OF TYRES

Front Left Size: Yokohama 205/60R16 70%

Front Right Size: Yokohama 205/60R16 70%

Rear Left Size: Yokohama 205/60R16 70%

Rear Right Size: Yokohama 205/60R16 70%

The above percentages represent the remaining life of the tyre threads

COST OF REPAIRS

Parts

Repairer S\$ Adjuster S\$

\$ 14,736.70 \$ 11,853.10

Labour

\$ 5,720.00 \$ 4,920.00

Calculated Cost (S\$) :

\$ 20,456.70 \$ 16,773.10

Recommended Lump Sum Repair Cost (S\$) : \$ 13,400.00

Date of Assignment: 24/5/2017

Date Inspected: 24/5/2017

Est. repair Period: 14 days


Inspected At: Xin Yun Auto Pte Ltd

Blk C, #01-59

Kaki Bukit Autobay

Singapore 417883

POINT OF IMPACT



BRIEF CIRCUMSTANCES OF ACCIDENT

The Insured's vehicle collided onto the Third Party's Vehicle along Havelock towards CTE Expressway.

GENERAL DESCRIPTION OF DAMAGES

Our visual inspection of the vehicle revealed that the damages noted are at the front and rear portion.

SPECIAL REMARKS

We have inspected the actual damages found on the vehicle and recommend the replacement of parts and repairs accordingly. The estimated repair cost is \$20,456.70. The repairer has agreed to undertake the repairs at our adjusted lump sum amount of \$13,400.

We have not authorised the repair. Under normal circumstances, estimated 14 working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.



Dave Chang
Automotive Appraiser
AUTO. ENG, CAE, CGI
MIRTE, MSAAA, MTM

Automotive Appraiser: Dave Chang

Please note that this report is solely based on our findings at the time and place of inspection. This inspection has been carried out to our best knowledge and ability. Any other liability is hereby excluded.

ANNEX A

REPAIR DETAILS**Recommended Parts**

No	Qty	Description	Condition	Repairer's Amount	Adjusted Amount
1	1	Front bumper reinforcement	deformed	\$ 324.00	\$ 324.00 DD
2	2	Front bumper bracket	bent/necessary	\$ 114.00	\$ 114.00 NS
3	2	Front bumper retainer	bent/necessary	\$ 116.00	\$ 116.00 NN
4	1	Front grille with emblem assy	cracked	\$ 282.00	\$ 282.00
5	1	Front bonnet assy	repair	\$ 984.00	\$ -
6	1	Front bonnet lock	bent	\$ 124.00	\$ 124.00
7	1	Front support panel	repair	\$ 762.00	\$ -
8	1	Front support panel top garnish	warped/bent	\$ 241.00	\$ 241.00
9	1	Front right headlamp	cut/bent	\$ 779.00	\$ 779.00
10	1	Front left headlamp	cut/bent	\$ 779.00	\$ 779.00
11	1	Front left fog lamp	bent	\$ 282.00	\$ 282.00 XNA
12	1	Front right fog lamp	bent	\$ 282.00	\$ 282.00 XNA
				\$ 5,069.00	\$ 3,323.00
Less 10 %				\$ 506.90	\$ 332.30
				\$ 4,562.10	\$ 2,990.70

Special Nett Items

1	1	Front sport bumper assy with lower spoiler	dented/cracked	\$ 1,400.00	\$ 1,400.00 67
2	12	Front sport bumper clips	necessary	\$ 50.00	\$ 50.00 30
3	6	Front grille clips	necessary	\$ 20.00	\$ 20.00 10
4	6	Front support panel top garnish clips	necessary	\$ 20.00	\$ 20.00 10
5	1	Front no plate with garnish	necessary	\$ 80.00	\$ 80.00 40
				\$ 1,570.00	\$ 1,570.00

Total Parts

\$ 6,132.10 \$ 4,560.70

ANNEX A

REPAIR DETAILS

Recommended Parts

No	Qty	Description	Condition	Repairer's Amount	Adjusted Amount
1	2	Rear bumper bracket	bent/necessary	\$ 114.00	\$ 114.00 XNS
2	2	Rear bumper retainer	bent/necessary	\$ 116.00	\$ 116.00 56
3	1	Rear bumper centre reinforcement	bent/necessary	\$ 287.00	\$ 287.00 210
4	2	Rear bumper reflector	bent/necessary	\$ 66.00	\$ 66.00
5	1	Rear bumper tow cover	cut/warped	\$ 46.00	\$ 46.00 XNN
6	1	Rear bootlid assy	dented	\$ 883.00	\$ 883.00 760
7	1	Rear bootlid lock	bent	\$ 123.00	\$ 123.00
8	1	Rear bootlid lock catch	bent	\$ 55.00	\$ 55.00 XNN
9	2	Rear bootlid rubber stopper	necessary	\$ 36.00	\$ 36.00 XNN
10	2	Rear bootlid damper	malfunction	\$ 205.00	\$ 205.00 XNN
11	1	Rear bootlid inner trim cover	warped	\$ 221.00	\$ 221.00 XNN
12	1	Rear bootlid weatherstrip	warped	\$ 186.00	\$ 186.00 160
13	1	Rear bootlid left taillamp	cut/bent	\$ 382.00	\$ 382.00 XNN
14	1	Rear bootlid right taillamp	cut/bent	\$ 382.00	\$ 382.00 XNN
15	1	Rear left taillamp	cut/bent	\$ 579.00	\$ 579.00 400
16	1	Rear right taillamp	cut/bent	\$ 579.00	\$ 579.00 400
17	1set	Rear no plate lamp	bent/necessary	\$ 123.00	\$ 123.00 XNN
18	1	Rear left fender inner side garnish	warped/cut	\$ 388.00	\$ 388.00 XNN
19	1	Rear right fender inner side garnish	warped/cut	\$ 388.00	\$ 388.00 XNN
20	1	Rear end lower panel	repair	\$ 669.00	\$ -
21	1	Rear end lower panel top garnish	bent	\$ 126.00	\$ 126.00
22	1	Rear spare tyre top cover	bent	\$ 251.00	\$ 251.00 XNN
23	1	Rear exhaust muffler assy	repair	\$ 789.00	\$ -
				\$ 6,994.00	\$ 5,536.00
Less 10%				\$ 699.40	\$ 553.60
				\$ 6,294.60	\$ 4,982.40

Special Nett Items

1	1	Rear sport bumper assy with lower spoiler	cracked	\$ 1,400.00	\$ 1,400.00 600
2	10	Rear sport bumper clips	necessary	\$ 50.00	\$ 50.00 30
3	8	Rear bootlid inner trim cover clips	necessary	\$ 30.00	\$ 30.00 20
4	6	Rear left fender inner side garnish clips	necessary	\$ 30.00	\$ 30.00 20
5	6	Rear right fender inner side garnish clips	necessary	\$ 30.00	\$ 30.00 20
6	4	Rear end lower panel top garnish clips	necessary	\$ 20.00	\$ 20.00 15
7	1	Rear end lower panel sealant	necessary	\$ 120.00	\$ 120.00 50
8	1	Rear view camera	malfunction	\$ 300.00	\$ 300.00 XNN
9	1	Rear no plate with garnish	necessary	\$ 80.00	\$ 80.00 40
10	2	Rear bumper reverse sensor	malfunction	\$ 250.00	\$ 250.00 200
				\$ 2,310.00	\$ 2,310.00
Total parts				\$ 8,604.60	\$ 7,292.40

ANNEX B

REPAIR DETAILS

Recommended Labour

No.	Description	Repairer's Amount	Adjusted Amount
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$ 1,000.00	\$ 900.00 500
2	To putty and spray painting front portion.	\$ 1,000.00	\$ 900.00 600
3	To check wiring and focus front headlamp.	\$ 50.00	\$ 30.00
4	To remove and install front bonnet lock mechanism.	\$ 80.00	\$ 60.00 X
5	To apply anti rust proofing to front affected area.	\$ 120.00	\$ 100.00 X
6	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,400.00	\$ 1,200.00 600
7	To putty and spray painting rear portion.	\$ 1,400.00	\$ 1,200.00 700
8	To check rear lighting and wiring.	\$ 50.00	\$ 30.00
9	To remove and install rear bootlid lock mechanism.	\$ 80.00	\$ 60.00
10	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 140.00	\$ 120.00 60
11	To apply anti rust proofing to rear affected area.	\$ 140.00	\$ 120.00 50
12	To remove and install rear bumper reverse sensor.	\$ 80.00	\$ 60.00 50
13	To remove and install rear view camera.	\$ 80.00	\$ 60.00 X
14	Towing service.	\$ 100.00	\$ 80.00 X
Total labour :		\$ 5,720.00	\$ 4,920.00

ANNEX C

REPAIR DETAILS

Adjusted Repair Cost

	Repairer's Amount	Adjusted Amount
Total parts :	\$ 14,736.70	\$ 11,853.10
Total labour :	\$ 5,720.00	\$ 4,920.00
Total repair cost :	\$ 20,456.70	\$ 16,773.10

Adjusted Repair Cost (Lump Sum Repair)

\$ 13,400.00

9 days

192

Front Portion

NAC	INC	Item	CON	ACQ
1001	991835	Frt Number Plate	67	V
1002	991837	Frt Number Plate Base	67	V
1003	991839	Frt Number Plate Garnish	67	V
1004	991300	Frt Bumper Assembly	22	V
1005	992341	Frt Bumper Clips	22	V
1006	991325	Frt Bumper Bracket		
1007	991462	Frt Bumper Side Retainer		
1008	991433	Frt Bumper Reinforcement	DD	
1009	991313	Frt Bumper Beam		
1010	991463	Frt Bumper Sponge		
1011	991427	Frt Bumper Protector		
1012	991420	Frt Bumper Pad		
1013	991353	Frt Bumper Grille	CR	V
1014	991301	Frt Bumper Moulding		
1015	991407	Frt Bumper Lower Spoiler		
1016	991438	Frt Bumper Sensor		
1017	995100	Frt LH Bumper Fog Lamp Cover		
1018	991355	Frt RH Bumper Fog Lamp Cover		
1019	995079	Frt LH Bumper Fog Lamp		
1020	995080	Frt RH Bumper Fog Lamp		
1021	991793	Frt Grille	DD	
1022	991328	Frt Grille Emblem	NEC	
1023	991799	Frt Grille Chrome Moulding		
1024	991222	Frt Apron Panel	DD	
1025	992013	Frt Support Panel	DD	
1026	992025	Frt Support Panel Top Garnish Cover	DL	
1027	992416	Horn		
1028	991277	Frt Brace Panel		
1029	995153	Frt LH Headlamp Assy	CR	V
1030	991821	Frt RH Headlamp Assy	CR	V
1031	995088	Frt LH Side Lamp		
1032	995089	Frt RH Side Lamp		
1033	990248	Bonnet		
1034	991328	Bonnet Emblem		
1035	990287	Bonnet Lock	67	V
1036	990285	Bonnet Insulator		
1037	990273	Bonnet Hinge		
1038	990261	Bonnet Damper		
1039	990305	Bonnet Rubber		
1040	990252	Bonnet Cable		
1041	990311	Bonnet Stand		
1042	990119	Air Con Condenser		
1043	990122	Air Con Fan Assy		
1044	990134	Air Con Suction Pipe (Low Pressure)		
1045	990118	Air Con Suction Hose		
1046	990133	Air Con Discharge Pipe (High Pressure)		
1047	990114	Air Con Discharge Hose		
1048	990149	Air Con Liquid Pipe		
1049	995066	Air Con Receiver Drier		
1050	990111	Air Con Compressor Assy		
1051	995264	Air Con Belt		
1052	995074	Radiator		
1053	992738	Radiator Cowling		
1054	992742	Radiator Fan Assy		
1055	992743	Radiator Fan Clutch		
1056	992758	Radiator Hose Top		
1057	992757	Radiator Hose Bottom		
1058	992741	Radiator Expansion Tank		
1059	990151	Air Duct		
1060	990073	Air Cleaner Assy		
1061	990056	Air Cleaner Hose		
1062	990039	Air Cleaner Resonator		
1063	991712	Frt Exhaust Manifold		
1064	991713	Frt Exhaust Manifold Cover		
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)		
1066	991711	Front Exhaust Pipe		
1067	990719	Drifter		
1068	990224	Brake Cover		
1069	990223	Brake Band		
1070	990220	Brake Line		

NAC	INC	Item	CON	ACQ
1071	992275	Flare Box		
1072	992276	Flare Box		
1073	992277	Wiper Washer Tank		
1074	992278	Wiper Washer Tank Mount		
1075	992279	Alternator Assy		
1076	990160	Alternator Belt		
1077	992682	Power Steering Pump		
1078	992683	Power Steering Belt		
1079	994431	Power Steering Cooler Pipe		
1080	992682	Power Steering Hose		
1081	990010	ABS Pump Control Unit		
1082	990427	Brake Master Pump Assy		
1083	990403	Brake Booster Pump Assy		
1084	991005	Engine Top Cover		
1085	991011	Engine Under Cover		
1086	990946	Engine Mounting		
1087	990949	Engine Mounting Fr		
1088	990950	Engine Mounting LH		
1089	990952	Engine Mounting RH		
1090	990951	Engine Mounting Rear		
1091	992234	Gear Box Mounting		
1092	991520	Frt LH Chassis Member		
1093	991520	Frt RH Chassis Member		
1094	990728	Frt Vertical Cross Member		
1095	991863	Frt Lower Cross Member		
1096	995070	Frt LH Fender		
1097	995072	Frt LH Fender Inner Panel		
1098	995147	Frt LH Fender Lamp		
1099	995148	Frt LH Fender Protector		
1100	991740	Frt LH Fender Inner Shield		
1101	995179	Frt LH Mudflap		
1102	995170	Frt LH Wheel Rim		
1103	994025	Frt LH Rim Cover		
1104	995065	Frt LH Tyre		
1105	995071	Frt RH Fender		
1106	991739	Frt RH Fender Inner Panel		
1107	991744	Frt RH Fender Lamp		
1108	991752	Frt RH Fender Protector		
1109	991740	Frt RH Fender Inner Shield		
1110	991884	Frt RH Mudflap		
1111	992087	Frt RH Wheel Rim		
1112	994025	Frt RH Rim Cover		
1113	995065	Frt RH Tyre		
1114	992093	Frt Windscreen Glass		
1115	992117	Frt Windscreen Rubber		
1116	992108	Frt Windscreen Moulding		
1117	992093	Frt Windscreen Sealant		
1118	991019	SRP Bracket		
1119	991020	SRP Bolt		
1120	992140	Frt Wiper Arm		
1121	992142	Frt Wiper Blade		
1122	995045	Wiper Pad Garnish		
1123	991126	Firewall Panel		
1124	990753	Dashboard Assy		
1125	992282	Glove Box Cover		
1126	992281	Glove Box Compartment		
1127	994483	Steering Wheel Airbag		
1128	994485	Steering Wheel Airbag Sensor		
1129	990749	Dashboard Airbag		
1130	990750	Dashboard Airbag Sensor		
1131	990020	Airbag Control Unit		
1132	990064	Frt Driver Seat		
1133	991922	Frt RH Seat Belt Assy		
1134	991800	Frt Passenger Seat		
1135	991801	Frt LH Seat Belt Assy		
1136	990247	Door		

SLB 8298C

Richard

1/6

12

9/6/2017

MOTORCAR (Rear)

2/2

Rear Portion

NAC	INC	Item	CON	ACOM
1137	993626	Rear Number Plate	RA	✓
1138	993627	Rear Number Plate Base		
1139	993630	Rear Number Plate Garnish	RA	✓
1140	993632	Rear Number Plate Lamp		
1141	993958	Rear Bumper	BR	✓
1142	993035	Rear Bumper Upper		
1143	993017	Rear Bumper Lower		
1144	993054	Rear Bumper Side		
1145	993103	Rear Bumper Tow Cover		
1146	992341	Rear Bumper Clips	DR	✓
1147	992976	Rear Bumper Bracket		
1148	993068	Rear Bumper Side Retainer	DR	✓
1149	993045	Rear Bumper Reinforcement	BU	✓
1150	992970	Rear Bumper Beam		
1151	993077	Rear Bumper Sponge		
1152	992999	Rear Bumper Damper		
1153	993040	Rear Bumper Protector		
1154	993036	Rear Bumper Pad		
1155	993026	Rear Bumper Moulding		
1156	993044	Rear Bumper Reflector	CRA	✓
1157	993023	Rear Bumper Lower Spoiler		
1158	994023	Reverse Sensor	DR	✓
1159	993327	Rear End Panel	DIS	✓
1160	993339	Rear End Panel Top Garnish		
1161	993333	Rear End Panel Inner Trim	DIS	✓
1162	990333	Boot Compartment Inner Trim	TN	✓
1163	993851	Rear LH Taillamp	CRA	✓
1164	993853	Rear LH Taillamp Garnish		
1165	993859	Rear LH Taillamp Panel		
1166	995116	Rear RH Taillamp	CRA	✓
1167	993853	Rear RH Taillamp Garnish		
1168	993859	Rear RH Taillamp Panel		
1169	993554	Rear Apron Panel		
1170	992855	Bootlid	DD	✓
1171	991328	Bootlid Emblem	NEC	✓
1172	990356	Bootlid Handle		
1173	995250	Bootlid Moulding		
1174	990376	Bootlid Reflector		
1175	995222	Bootlid Lamp LH		
1176	992899	Bootlid Lamp RH		
1177	995243	Bootlid Lock	BT	✓
1178	990377	Bootlid Rubber	W/Weather Strip	✓
1179	990382	Bootlid Hinge	RA	✓
1180	993377	Bootlid Spoiler		
1181	994543	Tailgate		
1182	991328	Tailgate Emblem		
1183	994643	Tailgate Outer Handle		
1184	994640	Tailgate Moulding		
1185	994543	Tailgate Garnish		
1186	994643	Tailgate Reflector		
1187	994549	Tailgate Lamp		
1188	994546	Tailgate Protector		
1189	994678	Tailgate Wiper Arm		
1190	994677	Tailgate Wiper Blade		
1191	994579	Tailgate Wiper Nozzle		
1192	994553	Tailgate Wiper Motor		
1193	994502	Tailgate Glass		
1194	994606	Tailgate Glass Rubber		
1195	994604	Tailgate Glass Moulding		
1196	994607	Tailgate Glass Sealant		
1197	994629	Tailgate Lock		
1198	994651	Tailgate Rubber		
1199	994511	Tailgate Hinge		
1200	994594	Tailgate Damper		
1201	994613	Tailgate Inner Board		

NAC	INC	Item	CON	ACOM
1202	993784	Spare Tyre Board		
1203	994823	Spare Tyre Panel		
1204	993655	Spare Tyre		
1205	994326	Spare Tyre Lock Screw		
1206	993787	Spare Tyre Cover		
1207	993323	Triangle Breakdown Sign		
1208	990507	CD Changer Ass.		
1209	990164	Antenna		
1210	990534	Centre Exhaust Pipe Ass.		
1211	990532	Centre Exhaust Mounting		
1212	993364	Rear Exhaust Pipe		
1213	993357	Rear Exhaust Chrome Pipe		
1214	993361	Rear Exhaust Mounting		
1215	993358	Rear Exhaust Heat Shield		
1216	995223	Rear LH Chassis Member		
1217	993165	Rear RH Chassis Member		
1218	993436	Rear LH Fender		
1219	993449	Rear LH Fender Protector		
1220	993420	Rear LH Fender Inner Panel		
1221	993431	Rear LH Fender Inner Trim	DIS	✓
1222	993415	Rear LH Fender Inner Garnish		
1223	993425	Rear LH Fender Inner Shield		
1224	993621	Rear LH Mudflap		
1225	993933	Rear LH Wheel Rim		
1226	994025	Rear LH Rim Cover		
1227	995065	Rear LH Tyre		
1228	993456	Rear RH Fender		
1229	993450	Rear RH Fender Protector		
1230	993420	Rear RH Fender Inner Panel		
1231	993431	Rear RH Fender Inner Trim	✓	
1232	993415	Rear RH Fender Inner Garnish		
1233	993425	Rear RH Fender Inner Shield		
1234	993622	Rear RH Mudflap		
1235	993934	Rear RH Wheel Rim		
1236	994025	Rear RH Rim Cover		
1237	995065	Rear RH Tyre		
1238	993162	Rear Fender Extension Panel LH		
1239	993491	Rear Fender Extension Panel RH		
1240	993430	Rear Fender Inner Top Garnish		
1241	993573	Rear Fender 1/4 Glass		
1242	993452	Rear Fender 1/4 Glass Rubber		
1243	993453	Rear Fender 1/4 Glass Sealant		
1244	993949	Rear Windscreen Glass		
1245	993976	Rear Windscreen Rubber		
1246	993961	Rear Windscreen Moulding		
1247	993555	Rear Windscreen Sealant		
1248	994729	Third Brake Light		
1249	993335	Rear Fender Air Grille	RA	DIS
1250	992167	Fuel Lid		
1251	992168	Fuel Neck		
1252	992179	Fuel Tank		
1253	992184	Fuel Tank Bracket		
1254	992191	Fuel Tank Filler		
1255	990257	Shocker		

Signature
9/6/2017

Claim Documents

***SLB8298C (4149443025SG)
[SLD483B]**

TP

CHAN CHUEN ONN

May 24 2017 11:55AM

[Slamet Ardiano]

Xin Yun Auto Private Limited

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	Like	Viewer
Photos/Images						3 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print	
1	07/06/17 19:32	General View				Load JPG		
2	07/06/17 19:32	General View				Load JPG		
3	07/06/17 19:32	General View				Load JPG		
4	07/06/17 19:32	General View				Load JPG		
5	07/06/17 19:32	General View				Load JPG		
6	07/06/17 19:32	General View				Load JPG		
7	07/06/17 19:32	General View				Load JPG		
8	07/06/17 19:32	General View				Load JPG		
9	07/06/17 19:32	General View				Load JPG		
10	07/06/17 19:32	General View				Load JPG		
11	07/06/17 19:32	General View				Load JPG		
12	07/06/17 19:32	Odometer Reading				Load JPG		
13	07/06/17 19:32	General View				Load JPG		
14	07/06/17 19:32	General View				Load JPG		
15	07/06/17 19:32	General View				Load JPG		
16	07/06/17 19:32	General View				Load JPG		
17	07/06/17 19:32	General View				Load JPG		
18	07/06/17 19:32	General View				Load JPG		
19	07/06/17 19:32	General View				Load JPG		
20	07/06/17 19:32	General View				Load JPG		
21	07/06/17 19:32	General View				Load JPG		
22	07/06/17 19:32	General View				Load JPG		
23	07/06/17 19:32	General View				Load JPG		
24	07/06/17 19:32	General View				Load JPG		
25	07/06/17 19:32	General View				Load JPG		
26	07/06/17 19:32	General View				Load JPG		
27	07/06/17 19:32	General View				Load JPG		
28	07/06/17 19:32	General View				Load JPG		
29	07/06/17 19:32	General View				Load JPG		
30	07/06/17 19:32	General View				Load JPG		
31	07/06/17 19:32	General View				Load JPG		
32	07/06/17 19:32	General View				Load JPG		
33	07/06/17 19:32	General View				Load JPG		
34	07/06/17 19:32	General View				Load JPG		
35	07/06/17 19:34	Photographs of Damaged Parts				Load JPG		
36	07/06/17 19:34	Photographs of Damaged Parts				Load JPG		
37	07/06/17 19:34	Photographs of Damaged Parts				Load JPG		
38	07/06/17 19:34	Photographs of Damaged Parts				Load JPG		
39	07/06/17 19:34	Photographs of Damaged Parts				Load JPG		

40	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
41	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
42	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
43	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
44	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
45	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
46	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
47	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
48	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
49	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
50	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
51	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
52	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
53	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
54	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
55	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
56	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
57	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
58	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
59	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
60	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
61	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
62	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
63	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
64	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
65	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
66	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
67	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
68	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
69	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
70	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
71	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
72	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
73	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
74	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
75	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
76	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
77	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
78	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
79	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
80	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
81	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
82	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
83	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
84	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
85	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
86	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
87	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
88	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
89	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒

90	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
91	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
92	07/06/17 19:34	Photographs of Damaged Parts	1	Load JPG	☒
93	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
94	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
95	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
96	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
97	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
98	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
99	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
100	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
101	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
102	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
103	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
104	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
105	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
106	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
107	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
108	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
109	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
110	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
111	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
112	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
113	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
114	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
115	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
116	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
117	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
118	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
119	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
120	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
121	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
122	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
123	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
124	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
125	07/06/17 19:36	Photo After Spray	1	Load JPG	☒
126	07/06/17 19:36	Photo After Spray	1	Load JPG	☒

Documentation

1 per page

☒

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	08/06/17 12:01	OI GIA Report	1	Load PDF

Documents Checklist**DOCUMENTS CHECKLIST**

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG17010229/GBE2

Date: 13/06/2017

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100472691
 Claimant Vehicle No : SLB8298C Insured Vehicle No : SLD483B
 Date of Loss: 24/05/2017 Nature of Claim: TP Claim No: 4149443025SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLB8298C
 Make & Model: MITSUBISHI LANCER EX, 1.6 (A) Engine No: 4A92CG6558
 Reg. Date: 25/04/2016 (Man. Year: 2015) Chassis No: JMYSRCY1AGU004052
 Colour: Red Odometer: 19521 km
 Engine Capacity: 1590 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm
 Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/05/2017
 Date Inspected: 31/05/2017 Inspected At: Xin Yun Auto Private Limited (HQ)
 1 Kaki Bukit Avenue 6, #01-59 Autobay
 @ Kaki Bukit
 Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Broken	0.00 F	*.F
2	1		*REAR NUMBER PLATE GARNISH	Broken	0.00 F	*.F
3	1		*REAR BUMPER	Broken	0.00 F	*.F
4	1		*REAR BUMPER CLIPS	Damaged	0.00 F	*.F
5	1		*REAR BUMPER SIDE RETAINER	Damaged	0.00 F	*.F
6	1		*REAR BUMPER REINFORCEMENT	Buckled	0.00 F	*.F
7	2		*REAR BUMPER REFLECTOR	Cracked	0.00 F	*.F
8	1		*SET REVERSE SENSOR	Damaged	0.00 F	*.F
9	1		*REAR END PANEL	Repair	0.00 F	*.F
10	1		*REAR END PANEL TOP GARNISH	Distorted	0.00 F	*.F
11	1		*BOOT COMPARTMENT INNER TRIM	Torn	0.00 F	*.F
12	1		*REAR LH TAILLAMP	Cracked	0.00 F	*.F
13	1		*REAR RH TAILLAMP	Cracked	0.00 F	*.F
14	1		*BOOTLID	Dented	0.00 F	*.F
15	4		*BOOTLID EMBLEM	Necessary	0.00 F	*.F
16	1		*BOOTLID LOCK	Bent	0.00 F	*.F
17	1		*BOOTLID RUBBER WEATHERSTRIP	Buckled	0.00 F	*.F
18	1		*REAR LH FENDER INNER TRIM	Distorted	0.00 F	*.F
19	1		*REAR FENDER AIR GRILLE LH	Distorted	0.00 F	*.F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/05/2017 16:06
Date Of Accident	24/05/2017 12:00
Exact Location Of Accident	HAVELOCK TWDS CTE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB8298C
Insured/Policyholder	
Name Of Registered Owner	CHAN CHUEN ONN
NRIC No	S7341948D
Email Address	CHAN.CHUEN.ONN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96457080
Alternative Phone No	OFFICE-96457080

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LANCER EX

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P10007505R00
Cover Note Number	

Driver

Name of Driver	CHAN CHUEN ONN
NRIC No	S7341948D
Date Of Birth	30/10/1973
Occupation	INDOOR
Date Of Driving Pass	02/09/1994
Driving Experience	22 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96457080
Fax Number	
Contact Number	OFFICE-96457080
Email Address	CHAN.CHUEN.ONN@GMAIL.COM

Address	BLK 84A LORONG 2 TOA PAYOH #25-311
Postcode	311084
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION- CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

MY VEHICLE WAS STATIONARY. SUDDENLY, VEHICLE B HIT ONTO MY VEHICLE REAR. DUE TO THE IMPACT, MY VEHICLE ROLL FORWARD AND HIT ONTO VEHICLE C. TOTAL 3 VEHICLES WERE INVOLVED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLD483B
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	FBK5345R
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

VEHICLE C

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claim process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate police liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand and acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/ are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurer/lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigation relating to the claims;

investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers'lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyer/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder)/ Date
& Time

Witnessed by Reporting Centre
Personal

Sketch Plan

The sketch plan area contains a vertical diagram of a vehicle. At the top is a circle labeled 'C'. Below it is an oval labeled 'O'. Below the oval is a rectangle labeled 'A'. Below the rectangle 'A' is another rectangle labeled 'B'. The rectangles 'A' and 'B' have a small triangle on their left side, pointing towards the center of the vehicle diagram.

Describe Circumstances of the Accident

my vehicle was stationary, ~~swinging~~ vehicle B #17
onto my vehicle rear. Due to the impact, my vehicle
roll forward and #17 onto vehicle C. Total 3
vehicles was involved.

Declaration

I/We declare the foregoing particulars are true in every respect.

[Handwritten signature]

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder)/ Date
& Time

Witnessed by Reporting Centre
Personal

Insurance Co. BUDGET INSURANCE
Vehicle No. SLB 8298C Date of accident 2/05/2002
☐ Reporting Only
☐ Own Damage Claim
☒ Third Party Claim



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS3/AIG17010229/Gvbe2-1		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 16-03-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	SLD 483B	Veh. Inspected	SLB 8298C	
Policy No.		Coverage (\$)	0.00	
Claim No.	4149443025SG(003)	Excess (\$)	0.00	
Assign From	NORSIAH	Assign Date	02/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI LANCER	c.c	1590	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JMYSRCY1AGU004052	Colour	RED	
Odometer	32108	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	YOKOHAMA	6 mm	
L/H Front Tyre	205/60 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	24/05/2017	Inspection Date	05/01/2018	
Survey held at	8 KAKI BUKIT AVE 4 #05-23			
Repairer	XIN YUN AUTO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 8298C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
2	REAR BUMPER BRACKET	NO SUCH PARTS	114.00	-
2	REAR BUMPER RETAINER	REPLACED	116.00	56.00
1	REAR BUMPER CENTRE REINFORCEMENT	REPLACED	287.00	210.00
2	REAR BUMPER REFLECTOR	REPLACED	66.00	66.00
1	REAR BUMPER TOW COVER	NOT NECESSARY	46.00	-
1	REAR BOOTLID ASSY	REPLACED	883.00	760.00
1	REAR BOOTLID LOCK	REPLACED	123.00	123.00
1	REAR BOOTLID LOCK CATCH	NOT NECESSARY	55.00	-
2	REAR BOOTLID RUBBER STOPPER	NOT NECESSARY	36.00	-
2	REAR BOOTLID DAMPER	NOT NECESSARY	205.00	-
1	REAR BOOTLID INNER TRIM COVER	NOT NECESSARY	221.00	-
1	REAR BOOTLID WEATHERSTRIP	REPLACED	186.00	160.00
1	REAR BOOTLID LEFT TAILLAMP	NOT NECESSARY	382.00	-
1	REAR BOOTLID RIGHT TAILLAMP	NOT NECESSARY	382.00	-
1	REAR LEFT TAILLAMP	REPLACED	579.00	400.00
1	REAR RIGHT TAILLAMP	REPLACED	579.00	400.00
1	SET REAR NO PLATE LAMP	NOT NECESSARY	123.00	-
1	REAR LEFT FENDER INNER SIDE GARNISH	NOT NECESSARY	388.00	-
1	REAR RIGHT FENDER INNER SIDE GARNISH	NOT NECESSARY	388.00	-
1	REAR END LOWER PANEL	REPAIRED SEE LABOUR	669.00	-
1	REAR END LOWER PANEL TOP GARNISH	REPLACED	126.00	126.00
1	REAR SPARE TYRE TOP COVER	NOT NECESSARY	251.00	-
1	REAR EXHAUST MUFFLER ASSY	REPAIRED SEE LABOUR	789.00	-
1	FRONT BUMPER REINFORCEMENT	REPLACED	324.00	324.00
2	FRONT BUMPER BRACKET	NO SUCH PARTS	114.00	-
2	FRONT BUMPER RETAINER	NOT NECESSARY	116.00	-
1	FRONT GRILLE WITH EMBLEM ASSY	REPLACED	282.00	282.00
1	FRONT BONNET ASSY	REPAIRED SEE LABOUR	984.00	-
1	FRONT BONNET LOCK	REPLACED	124.00	124.00

Report Ref No. CS3/AIG17010229/Gvbe2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT SUPPORT PANEL	REPAIRED SEE LABOUR	762.00	-
1	FRONT SUPPORT PANEL TOP GARNISH	REPLACED	241.00	241.00
1	FRONT RIGHT HEADLAMP	REPLACED	779.00	779.00
1	FRONT LEFT HEADLAMP	REPLACED	779.00	779.00
1	FRONT LEFT FOG LAMP	NOT NECESSARY	282.00	-
1	FRONT RIGHT FOG LAMP	NOT NECESSARY	282.00	-
	LESS 10% DISCOUNT		-1,206.30	-483.00
			10,856.70	4,347.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR SPORT BUMPER ASSY WITH LOWER SPOILER (SN)	REPLACED	1,400.00	600.00
10	REAR SPORT BUMPER CLIPS (SN)	REPLACED	50.00	30.00
8	REAR BOOTLID INNER TRIM COVER CLIPS (SN)	REPLACED	30.00	20.00
6	REAR LEFT FENDER INNER SIDE GARNISH CLIPS (SN)	REPLACED	30.00	20.00
6	REAR RIGHT FENDER INNER SIDE GARNISH CLIPS (SN)	REPLACED	30.00	20.00
4	REAR END LOWER PANEL TOP GARNISH CLIPS (SN)	REPLACED	20.00	15.00
1	REAR END LOWER PANEL SEALANT (SN)	REPLACED	120.00	50.00
1	REAR VIEW CAMERA (SN)	NOT NECESSARY	300.00	-
1	REAR NO PLATE WITH GARNISH (SN)	REPLACED	80.00	40.00
2	REAR BUMPER REVERSE SENSOR (SN)	REPLACED	250.00	200.00
1	FRONT SPORT BUMPER ASSY WITH LOWER SPOILER (SN)	REPLACED	1,400.00	600.00
12	FRONT SPORT BUMPER CLIPS (SN)	REPLACED	50.00	30.00
6	FRONT GRILLE CLIPS (SN)	REPLACED	20.00	10.00
6	FRONT SUPPORT PANEL TOP GARNISH CLIPS (SN)	REPLACED	20.00	10.00
1	FRONT NO PLATE GARNISH (SN)	REPLACED	80.00	40.00
			3,880.00	1,685.00
	<u>LABOUR</u>			
	TOWING SERVICE.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN FRONT AFFECTED AREA AND REPLACE FRONT DAMAGED PARTS.		1,000.00	500.00
	TO PUTTY AND SPRAY PAINTING FRONT PORTION.		1,000.00	600.00

Report Ref No. CS3/AIG17010229/Gvbe2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND FOCUS FRONT HEADLAMP.		50.00	30.00
	TO REMOVE AND INSTALL FRONT BONNET LOCK MECHANISM.	NOT NECESSARY	80.00	-
	TO APPLY ANTI RUST PROOFING TO FRONT AFFECTED AREA.	NOT NECESSARY	120.00	-
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR END LOWER PANEL, REAR EXHAUST MUFFLER ASSY, FRONT BONNET ASSY AND FRONT SUPPORT PANEL.		1,400.00	600.00
	TO PUTTY AND SPRAY PAINTING REAR PORTION.		1,400.00	700.00
	TO CHECK REAR LIGHTING AND WIRING.		50.00	30.00
	TO REMOVE AND INSTALL REAR BOOTLID LOCK MECHANISM.		80.00	60.00
	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR.		140.00	60.00
	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA.		140.00	50.00
	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR.		80.00	50.00
	TO REMOVE AND INSTALL REAR VIEW CAMERA.	NOT NECESSARY	80.00	-
			5,720.00	2,680.00
GRAND TOTAL			20,456.70	8,712.00

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,950.00
--	--	--	----------

Report Ref No. CS3/AIG17010229/Gvbe2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

