

ASS. REC. BY:

REF:

CS/SPF18000320/Sq02

Special Instruction:

Submitted by: Sebastian

ASSIGNMENT (Office)

From (Person): Tim Wei Yea

of

SPF

Date/Time: 04/01/2018 2:11pm

Estimated Cost:

Bill to:

OD/TP+WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

OX 46R

Insured:

at Workshop m/s

SMRT

Tel:

of

60 Woodland Ind Park E4

Policy No:

Claim No:

H0MSPTA16000399

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

CA / REV / REP. / REV 24 HRS

05-01-2018

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle: IN/OUT

Date/Time

Action/Instruction (☒) ESTIMATED

OX 46R - CS/SPF17003051/D46

SPF 01/02/17

30/1/18 @ 2.33pm revert to wei yea by email.

Labour hrs = 80.5 hrs ; parts : - no parts prices available.

ASSIGNMENTFrom: _____ Date: **05/01/2018**

Estimated Cost: _____

☒ **OD** / TP / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: **QX 46R**at Workshop no: **SMRT**of **60 woodlands Ind Prk E4**

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **Qx 46 R**Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime MoverTruck / Trailer or **Police Car**Make: **Subaru Impreza**Colour: **White**

A.O. Insured / Std / NI / NA

So. Reading: **No Display**

T. Radio: Insured / Std / NI / NA

Eng. No: _____

C No: _____

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrakes: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim orTyre Size: F: **195/60R15**R: **11**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R. Bal. **6** mmR. Bal. **6** mmL. Bal. **6** mmL. Bal. **6** mm

D.O.A. _____

D.O.I. **5/1/18**Survey held at: **213 Sungai Kadut Dr**Des. of Damages: ☒ Fr ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date Time Action / Instruction

5/1/18 10.0 GIA (Estimate incomplete, new one will be provided soon)

Date/Time File Pass to:

☐

Preli. Report

☐

Final Report

Date/Time File Return to:

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee

Transportation

Phone

Email

Total

Add Fee:

☐
☐
☐
☐

Site Insp. / \$

Inspection / \$

Testing / \$

Misc. / \$

Report Format: **OD**

Lump Sum: J.B. / \$

250**350**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF18000320/Sqb	
CONTRACT MANAGEMENT SECTION (SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333		Date : 05-01-2018	
		Code : SPF3	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.	Veh. Inspected	QX 46R	
Policy No.	Coverage (\$)	0.00	
Claim No. HOMSPFETQ16000399	Excess (\$)	0.00	
Assign From LIM WEI YEA	Assign Date	04/01/2018	
2. Vehicle Particulars & Condition			
Make & Model	c.c	0	
Engine No. HIDDEN	Year of Reg.		
Chassis No.	Colour		
Odometer	Steering		
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	Inspection Date	05/01/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

Catherine Chong (LKK Auto)

From: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>
Sent: Thursday, 4 January, 2018 2:21 PM
To: assignments
Cc: Kim Pang CHAY (SPF); Kwee Huat TAN (SPF); Perry HE (SPF); Bernard SEAH (SPF); Peng Seng NG (SPF); 'Ai Phing (LKKAuto)'; 'Shiau Chan (LKKAuto)'
Subject: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX46R)
Attachments: QX0046R.xlsx

Hi Catherine,

Please provide Appraisal Services for SPF vehicles, **QX46R**, already at SMRT Automotive Services.
In attached, please find the Parts and Labour required for the repair of this vehicle, as recommended by SMRT.

Kindly contact the following SMRT personnel before viewing the vehicle:

- Mr Kong Sew Kui or
- Mr Jason Yeo

Thank you and best regards,



WeiYea LIM
Contract Management
AEMD, PLD
Singapore Police Force
DID: (65) 6478 4844 | FAX: (65) 6478 4838



Together We Keep Our Home Safe and Secure

Join us at the **HOME TEAM SHOW & FESTIVAL**
at the Singapore Sports Hub from 3 – 7 May.
Find out more at www.htfest2017.sg

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 30 January 2018 2:23 PM
To: Wei Yea LIM (SPF); SUR
Cc: Kim Pang CHAY (SPF); Kwee Huat TAN (SPF); Perry HE (SPF); Bernard SEAH (SPF); Peng Seng NG (SPF); Rashid ABU HASAN (SPF); assignments
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX46R & GBC7544L)
Attachments: QX46R Photo.pdf; QX46R.xls

Dear Wei Yea,

Please refer to the attachment.

Best Regards,

Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wei Yea LIM (SPF) [mailto:LIM_Wei_Yea@spf.gov.sg]
Sent: Monday, 29 January 2018 4:29 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>; assignments <assignments@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX46R & GBC7544L)

Hi Shiau Chan,

Need your kind update on the assessment of this vehicle, QX46R.

Thank you and best regards,

WeiYea LIM
Contract Management
AEMD, Police Logistics Department
Singapore Police Force
DID: (65) 6478 4844



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Wei Yea LIM (SPF)

Sent: Wednesday, 17 January, 2018 5:12 PM

To: 'Shiau Chan (LKKAUTO)' <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>; assignments <assignments@lkkauto.com>

Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX46R & GBC7544L)

Hi Shiau Chan,

Noted with thanks.

Do feedback if you need any assistance from my side to expedite process.

Thank you and best regards,



WeiYea LIM
Contract Management
AEMD, PLD
Singapore Police Force
DID: (65) 6478 4844 | FAX: (65) 6478 4838



Together We Keep Our Home Safe and Secure
Join us at the HOME TEAM SHOW & FESTIVAL
at the Singapore Sports Hub from 3 – 7 May.
Find out more at www.htfest2017.sg

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Shiau Chan (LKKAUTO) [<mailto:siewsc@lkkauto.com>]

Sent: Wednesday, 17 January, 2018 5:02 PM

To: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; SUR <sur@lkkauto.com>

Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>; assignments <assignments@lkkauto.com>

Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX46R & GBC7544L)

Dear Wei Yea,

Please be informed that we are still pending for complete estimate of QX 46R from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

From: Admin-D (LKKAUTO)

Sent: Monday, 15 January 2018 7:19 PM

To: 'Wei Yea LIM (SPF)' <LIM_Wei_Yea@spf.gov.sg>; SUR <sur@lkkauto.com>

Cc: 'Kim Pang CHAY (SPF)' <CHAY_Kim_Pang@spf.gov.sg>; 'Kwee Huat TAN (SPF)' <TAN_Kwee_Huat@spf.gov.sg>; 'Perry HE (SPF)' <Perry_HE@spf.gov.sg>; 'Bernard SEAH (SPF)' <Bernard_SEAH@spf.gov.sg>; 'Peng Seng NG (SPF)' <NG_Peng_Seng@spf.gov.sg>; 'Rashid ABU HASAN (SPF)' <Rashid_Abu_Hasan@spf.gov.sg>; assignments <assignments@lkkauto.com>

Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX46R & GBC7544L)

Dear Wei Yea,

Thank you for your email.

Dear Shiau Chan / Janice,

Kindly assist.

Our Ref: CS/SPF18000320/Sqb & CS/SPF18000586/T1rb

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wei Yea LIM (SPF) [mailto:LIM_Wei_Yea@spf.gov.sg]

Sent: Monday, 15 January, 2018 6:32 PM

To: assignments <assignments@lkkauto.com>

Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>; 'Ai Phing (LKKAUTO)' <aiaphing@lkkauto.com>; 'Shiau Chan (LKKAUTO)' <siewsc@lkkauto.com>

Subject: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX46R & GBC7544L)

Hi Catherine,

May I check if there's any update on the appraisals of the following vehicles, requested previously:

- 1) QX 46R
- 2) GBC 7544L

Thanks to advice.

Best regards,



WeiYea LIM
Contract Management
AEMD, PLD
Singapore Police Force
DID: (65) 6478 4844 | FAX: (65) 6478 4838

THE HOME TEAM CELEBRATES
NS50



Together We Keep Our Home Safe and Secure

Join us at the **HOME TEAM SHOW & FESTIVAL**
at the Singapore Sports Hub from 3 – 7 May.
Find out more at www.htfest2017.sg

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Registration No. QX 46R

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	FRONT BUMPER	1	CRACKED			
1.2	FRONT BUMPER RETAINER RH	1	NECESSARY			
1.3	FRONT BUMPER RETAINER LH	1	NECESSARY			
1.4	FRONT BUMPER SUPPORT	1	DENTED			
1.5	FRONT BUMPER FOG LAMP LH	1	CRACKED			
1.6	FRONT BUMPER FOG LAMP RH	1	CRACKED			
1.7	FRONT NUMBER PLATE WITH CASING	1	CRACKED			
1.8	R/H HEAD LAMP	1	CRACKED			
1.9	L/H HEAD LAMP	1	CRACKED			
1.10	HEAD LAMP SUPPORT LH	1	BENT			
1.1	HEAD LAMP SUPPORT RH	1	BENT			
1.1	FRONT SUPPORT PANEL	1	BENT			
1.1	HORN	1	DAMAGED			
1.1	BONNET	1	BENT			
1.2	BONNET HINGE LH	1	BENT			
1.2	BONNET HINGE RH	1	BENT			
1.2	BONNET INNER LOCK	1	DAMAGED			
1.2	BONNET LOCK	1	DAMAGED			
1.2	BONNET INSULATOR WITH RETAINER	1	NECESSARY			
1.20	BONNET RUBBER SEAL	1	NECESSARY			
1.2	RADIATOR	1	CRACKED			
1.2	RADIATOR UPPER & LOWER HOSE	1	TORN			
1.2	RADIATOR CAP	1	DAMAGED			
1.2	RADIATOR WATER TANK	1	UNCONFIRM			
1.3	RADIATOR FAN MOTOR	1	UNCONFIRM			
1.3	RADIATOR FAN	1	UNCONFIRM			
1.3	RADIATOR COWLING	1	CRACKED			
1.3	RADIATOR GRILL	1	CRACKED			
1.3	AIR CON CONDENSER	1	DENTED			
1.30	AIR CON CONDENSER FAN MOTOR	1	UNCONFIRM			
1.3	AIR CON CONDENSER FAN	1	UNCONFIRM			
1.3	AIR CON CONDENSER COWLING	1	UNCONFIRM			
1.3	AIR CON CONDENSER PIPE	1	BENT			
1.3	WIPER TANK	1	CRACKED			
1.4	POWER STEERING PUMP	1	DAMAGED			
1.4	POWER STEERING PUMP HOSE	1	UNCONFIRM			
1.4	POWER STEERING TANK	1	CRACKED			

1.4	ALTERNATOR	1	UNCONFIRM			
1.4	ALTERNATOR COVER	1	DEFORMED			
1.40	MAIN PULLEY	1	UNCONFIRM			
1.4	MAIN PULLEY BELT	1	TORN			
1.4	ENGINE COVER	1	UNCONFIRM			
1.4	ENGINE MOUNTING	1	UNCONFIRM			
1.4	GEAR BOX MOUNTING	1	UNCONFIRM			
1.5	ABS PUMP	1	UNCONFIRM			
1.5	FRONT MUD FLAP LH	1	TORN			
1.5	FRONT MUD FLAP RH	1	DEFORMED			
1.5	REAR BOOT LID HINGE LH	1	BENT			
1.5	REAR BOOT LID HINGE RH	1	BENT			
1.50	REAR BOOT LID	1	DENTED			
1.5	REAR BOOT LID LOCK	1	DAMAGED			
1.5	REAR BOOT PANEL LOCK	1	BENT			
1.5	SPARE TYRE PANEL	1	DENTED			
1.5	END PANEL UPPER AND LOWER	1	DENTED			
1.6	REAR BUMPER	1	CRACKED			
1.6	REAR BUMPER RETAINER LH	1	NECESSARY			
1.6	REAR BUMPER RETAINER RH	1	NECESSARY			
1.6	REAR BUMPER SUPPORT	1	BENT			
1.6	REAR NUMBER PLATE WITH CASING	1	SCRATCHED			
1.60	L/H TAIL LAMP	1	CRACKED			
1.6	R/H TAIL LAMP	1	CRACKED			
1.6	BOOT LID FLOOR BOARD	1	DEFORMED			
1.6	REAR BOOT LID RUBBER SEAL	1	TORN			
1.6	REAR BOOT LID LOCK CASING	1	MISSING			
1.7	REAR EXHAUST PIPE	1	DENTED			
1.7	EXHAUST PIPE SILENCER	1	BENT			
3	SCOPE OF REPAIRS					
3.1	FRONT BUMPER, FRONT SUPPORT PANEL & FRONT NUMBER PLATE:					11
	REPLACE FRONT BUMPER, BOTH SIDE RETAINERS, FRONT BUMPER SUPPORT & FRONT NUMBER PLATE					
	REMOVE & REPLACE FRONT SUPPORT PANEL					
	PUTTY & SPRAY PAINT FOR FRONT COMPLETE BUMPER					
3.2	LEFT & RIGHT HEAD-LAMP:					3
	REMOVE & REPLACE LEFT & RIGHT HEAD-LAMP					
	REMOVE & REPLACE LEFT & RIGHT HEAD-LAMP SUPPORT					
	WIRING FOR BOTH HEAD-LAMPS					

3.3	FRONT BONNET:					5
	REMOVE & REPLACE FRONT BONNET					
	REMOVE & REPLACE FRONT BONNET HINGES, INNER LOCK, LOCK & INSULATOR					
3.4	ENGINE COMPARTMENT:					16
	REMOVE & REPLACE RADIATOR, RADIATOR CAP, UPPER & LOWER HOSE					
	REMOVE & REPLACE WATER TANK FAN & COWLING					
	REMOVE & REPLACE AIR-CON CONDENSER, AIR-COND CONDENSER FAN & COWLING					
	REMOVE & REPLACE WIPER TANK					
	REMOVE & REPLACE POWER STEERING PUMP, POWER STEERING HOSE & POWER STEERING TANK					
	REMOVE & REPLACE ALTERNATOR & ALTERNATOR COVER					
	REMOVE & REPLACE MAIN PULLEY & MAIN PULLEY BELT					
	REMOVE & REPLACE ENGINE COVER					
	REMOVE & REPLACE ABS PUMP					
	REMOVE & REPLACE ENGINE AND GEAR BOX MOUNTING					
3.5	LEFT & RIGHT MUD FLAPS:					0.5
	REMOVE & REPLACE LEFT & RIGHT MUD FLAPS					
3.6	REAR BUMPER & REAR NUMBER PLATE:					5
	REMOVE & REPLACE REAR BUMPER, REAR BUMPER SUPPORT, BOTH SIDE RETAINERS & REAR NUMBER PLATE					
	PUTTY & SPRAY PAINT FOR REAR COMPLETE BUMPER					
3.7	LEFT & RIGHT TAIL-LAMP:					1
	REMOVE & REPLACE LEFT & RIGHT TAIL-LAMPS					
	WIRING FOR BOTH TAIL-LAMPS					
3.8	REAR BOOT:					20
	REMOVE & REPLACE BOOT LID					
	REMOVE & REPLACE SPARE TYRE PANEL					
	REMOVE & REPLACE END PANEL (UPPER AND LOWER)					
	REPLACE BOOT LID UPPER AND LOWER LOCK					

	REMOVE & REPLACE BOTH REAR BOOT LID HINGES					
	REMOVE & REPLACE REAR BOOT LID FLOOR BOARD					
	REMOVE & REPLACE REAR BOOT LID RUBBER SEAL					
	REMOVE & REPLACE REAR BOOT LID CASING					
	PUTTY & SPRAY PAINT FOR REAR BOOT LID & SPARE TYRE BOOTH AREA					
3.9	LEFT & RIGHT FENDER:					8
	PANEL BEATING FOR BOTH LEFT & RIGHT FENDER					
	PUTTY & SPRAY PAINT FOR BOTH LEFT & RIGHT FENDER					
3.10	REAR LH PANEL:					3
	PANEL BEATING FOR REAR LH PANEL					
	PUTTY & SPRAY PAINT FOR REAR LH PANEL					
3.1	EXHAUST PIPE SYSTEM:					3
	REMOVE & REPLACE EXHAUST PIPE SYSTEM					
3.1	LEFT & RIGHT SKIRTING:					5
	REPAIR & RE-ALIGN BOTH LEFT & RIGHT SKIRTING					
	PUTTY & SPRAY PAINT FOR BOTH LEFT & RIGHT SKIRTING					
COSTING		TOTAL PARTS COST			\$0.00	
		TOTAL MAN-HOUR				80.5



Scope Of Work

Home Team Agency

not complete !!

SCOPE OF WORK

1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR :	SMRT	VEH TYPE :	MARK CAR	UNIT :	TP	Reference No.
VEH NO :	QX 46 R	REPAIR TYPE :	ACCIDENT			0046/SPF/4W/17/12/22
VEH MAKE/MODEL :	SUBARU IMPREZA 5MT					

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
1	Scope Of Repairs					
1	Front bumper ✓ CRK	\$540.00	1	17%	631.80	631.80
2	Front bumper retainer LH ✓ NEC	\$24.00	1	17%	28.08	28.08
3	Front bumper retainer RH ✓ NEC	\$24.00	1	17%	28.08	28.08
4	Front bumper support bracket ✓ DT	\$376.00	1	17%	439.92	439.92
5	Front fog lamp LH ✓ CRK	\$554.00	1	17%	648.18	648.18
6	Front fog lamp RH ✓ CRK	\$554.00	1	17%	648.18	648.18
7	Front number plate with casing ✓ CRK	\$50.00	1	17%	58.50	58.50
8	R/H head lamp ✓ CRK	\$880.00	1	17%	1029.60	1029.60
9	L/H head lamp ✓ CRK	\$880.00	1	17%	1029.60	1029.60
10	Head lamp support bracket LH ✓ BT	\$64.00	1	17%	74.88	74.88
11	Head lamp support bracket RH ✓ BT	\$64.00	1	17%	74.88	74.88
12	Front support panel top ✓ BT	\$473.00	1	17%	553.41	553.41
13	Bonnet ✓ BT	\$920.00	1	17%	1076.40	1076.40
14	Bonnet hinge LH ✓ BT	\$27.00	1	17%	31.59	31.59
15	Bonnet hinge RH ✓ BT	\$27.00	1	17%	31.59	31.59
16	Bonnet lock Assy ✓ DMG	\$220.00	1	17%	257.40	257.40
17	Bonnet insulator with retaining clips ✓ NEC	\$400.00	1	17%	468.00	468.00
18	Bonnet rubber seal ✓ NEC	\$75.00	1	17%	87.75	87.75
19	Radiator ✓ CRK	\$720.00	1	17%	842.40	842.40
20	Radiator upper & lower hose ✓ TN	\$56.00	1	17%	65.52	65.52
21	Radiator water tank ?	\$67.00	1	17%	78.39	78.39
22	Radiator fan motor Assy ?	\$272.00	2	17%	318.24	636.48
23	Radiator cowl ✓ CRK	\$155.00	1	17%	181.35	181.35
24	Air con condenser ✓ DT	\$657.00	1	17%	768.69	768.69
25	Air con condenser piping Assy ✓ BT	\$330.00	1	17%	386.10	386.10
26	Wiper water reservoir tank ✓ CRK	\$216.00	1	17%	252.72	252.72
27	Power steering pump ✓ DMG	\$1,036.00	1	17%	1212.12	1212.12
28	Power steering pump hose Assy ?	\$105.00	1	17%	122.85	122.85
29	Power steering tank ✓ CRK	\$136.00	1	17%	159.12	159.12
30	Alternator ?	\$1,360.00	1	17%	1591.20	1591.20
31	Alternator cover ✓ Deform	\$38.00	1	17%	44.46	44.46
32	Main pulley ?	\$136.00	1	17%	159.12	159.12
33	Main pulley belt ✓ TN	\$96.00	1	17%	112.32	112.32
34	Engine top cover ?	\$160.00	1	17%	187.20	187.20
35	Front mud flap LH ✓ TN	\$58.00	1	17%	67.86	67.86
36	Front mud flap RH ✓ Deform	\$58.00	1	17%	67.86	67.86
37	Rear boot lid hinge LH ✓ BT	\$58.00	1	17%	67.86	67.86
38	Rear boot lid hinge RH ✓ BT	\$58.00	1	17%	67.86	67.86
39	Rear bumper ✓ CRK	\$588.00	1	17%	687.96	687.96
40	Rear bumper retainer RH ✓ NEC	\$52.00	1	17%	60.84	60.84
41	Rear bumper retainer LH ✓ NEC	\$52.00	1	17%	60.84	60.84
42	Rear bumper support bracket ✓ BT	\$110.00	1	17%	128.70	128.70
43	Rear number plate with casing ✓ SCR	\$50.00	1	17%	58.50	58.50
44	L/H tail lamp ✓ CRK	\$421.00	1	17%	492.57	492.57
45	R/H tail lamp ✓ CRK	\$421.00	1	17%	492.57	492.57
46	Boot compartment floor board ✓ Deform	\$480.00	1	17%	561.60	561.60
47	Rear boot lid rubber seal ✓ TN	\$225.00	1	17%	263.25	263.25
48	Rear boot lid lock Assy ✓ JM	\$185.00	1	17%	216.45	216.45
49	Rear exhaust pipe ✓ DT	\$560.00	1	17%	655.20	655.20
50	Exhaust pipe silencer ✓ BT	\$1,200.00	1	17%	1200.00	1200.00
2	Additional Services					
2.1	NA			0%	0.00	0.00
Remarks:				Parts Total:	10,451.80	

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
1	Scope Of Repairs			
1.1	Front Bumper, Front Support Panel & Front Number Plate:	59.00	14	826.00
	Replace Front Bumper, Both Side Retainers, Front Bumper Support & Front Number Plate			

Name:		Name:		Name:	
Date:		Date:		Date:	
Sign:		Sign:		Sign:	
All completed repairs must be verified by Home Team Contract Manager / Fleet Manager before payment can be made					



Scope Of Work
Home Team Agency

Sgb

SCOPE OF WORK

1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR	SMRT	VEH TYPE :	M/CAR	UNIT	TP
VEH NO :	QX 46 R		REPAIR TYPE:	ACCIDENT	
VEH MAKE/MODEL	SUBARU IMPREZA		ODOMETER:	NA	

Reference No.
0046/SPF/4W/17/12/22

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark	Total Parts Cost Per Unit After Mark Up (\$)
1	Scope Of Repairs					
1	Front bumper ✓ CRK		1		0.00	0.00
2	Front bumper retainer RH ✓ NEC		1		0.00	0.00
3	Front bumper retainer LH ✓ NEC		1		0.00	0.00
4	Front bumper support ✓ DT		1		0.00	0.00
5	Front bumper fog lamp LH ✓ CRK		1		0.00	0.00
6	Front bumper fog lamp RH ✓ CRK		1		0.00	0.00
7	Front number plate with casing ✓ CRK		1		0.00	0.00
8	R.H head lamp ✓ CRK		1		0.00	0.00
9	L.H head lamp ✓ CRK		1		0.00	0.00
10	head lamp support LH ✓ BT		1		0.00	0.00
11	head lamp support RH ✓ BT		1		0.00	0.00
12	Front support panel ✓ BT		1		0.00	0.00
13	Trim ✓ DMG		1		0.00	0.00
14	Bonnet ✓ BT		1		0.00	0.00
15	Bonnet hinge LH ✓ BT		1		0.00	0.00
16	Bonnet hinge RH ✓ BT		1		0.00	0.00
17	Bonnet inner lock ✓ DMG		1		0.00	0.00
18	Bonnet lock ✓ DMG		1		0.00	0.00
19	Bonnet insulator with retainer ✓ NEC		1		0.00	0.00
20	Bonnet rubber seal ✓ NEC		1		0.00	0.00
21	Radiator ✓ CRK		1		0.00	0.00
22	Radiator upper & lower hose ✓ TN		1		0.00	0.00
23	Radiator cap ✓ DMG		1		0.00	0.00
24	Radiator water tank ✓		1		0.00	0.00
25	Radiator fan motor ✓		1		0.00	0.00
26	Radiator fan ✓		1		0.00	0.00
27	Radiator cooling fan ✓ CRK		1		0.00	0.00
28	Radiator grill ✓ CRK		1		0.00	0.00
29	Air con condenser ✓ DT		1		0.00	0.00
30	Air con condenser fan motor ✓		1		0.00	0.00
31	Air con condenser fan ✓		1		0.00	0.00
32	Air con condenser cowling ✓		1		0.00	0.00
33	Air con condenser pipe ✓ BT		1		0.00	0.00
34	Wiper tank ✓ CRK		1		0.00	0.00
35	Power steering pump ✓ DMG		1		0.00	0.00
36	Power steering pump hose ✓		1		0.00	0.00
37	Power steering tank ✓ CRK		1		0.00	0.00
38	Alternator ✓		1		0.00	0.00
39	Alternator cover ✓ Deform		1		0.00	0.00
40	Main pulley ✓		1		0.00	0.00
41	Main pulley belt ✓ TN		1		0.00	0.00
42	Engine cover ✓		1		0.00	0.00
43	Engine mounting ✓		1		0.00	0.00
44	Engine bay mounting ✓		1		0.00	0.00
45	AHIS pump ✓		1		0.00	0.00
46	Front mud flap LH ✓ TN		1		0.00	0.00
47	Front mud flap RH ✓ Deform		1		0.00	0.00
48	Rear boot lid hinge LH ✓ BT		1		0.00	0.00
49	Rear boot lid hinge RH ✓ BT		1		0.00	0.00
50	Rear boot lid ✓ DT		1		0.00	0.00
51	Rear boot lid lock ✓ DMG		1		0.00	0.00
52	Rear boot panel lock ✓ BT		1		0.00	0.00
53	Space side panel ✓ DT		1		0.00	0.00
54	Trunk panel upper and lower ✓ DT		1		0.00	0.00
55	Rear bumper ✓ CRK		1		0.00	0.00
56	Rear bumper retainer LH ✓ NEC		1		0.00	0.00
57	Rear bumper retainer RH ✓ NEC		1		0.00	0.00
58	Rear bumper support ✓ BT		1		0.00	0.00
59	Rear number plate with casing ✓ SCR		1		0.00	0.00
60	L.H tail lamp ✓ CRK		1		0.00	0.00
61	R.H tail lamp ✓ CRK		1		0.00	0.00
62	Boot lid floor board ✓ Deform		1		0.00	0.00
63	Rear boot lid rubber seal ✓ TN		1		0.00	0.00
64	Rear boot lid lock casing ✓ MS		1		0.00	0.00
65	Rear exhaust pipe ✓ DT		1		0.00	0.00
66	Exhaust pipe silencer ✓ BT		1		0.00	0.00
2	Additional Services					
2.1	NA			0%	0.00	0.00
Remarks:		Parts Total:				

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
1	Scope Of Repairs			
1.1	Front Bumper, Front Support Panel & Front Number Plate:	11	✓	0.00
	Replace Front Bumper, Both Side Retainers, Front Bumper Support & Front Number Plate			
	Remove & Replace Front Support Panel			
	Putty & Spray Paint for Front Complete Bumper			
1.2	Left & Right Head-Lamp:	3	✓	0.00
	Remove & Replace Left & Right Head-Lamp			
	Remove & Replace Left & Right Head-Lamp Support			
	Wiring for Both Head-Lamps			
1.3	Front Bonnet:	5	✓	0.00
	Remove & Replace Front Bonnet			
	Remove & Replace Front Bonnet Hinges, Inner Lock, Lock & Insulator			
1.4	Engine Compartment:	16	✓	0.00
	Remove & Replace Radiator, Radiator Cap, Upper & Lower Hose			



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF18000320/Sqbe2

CONTRACT MANAGEMENT SECTION

(SINGAPORE POLICE FORCE)

1 MOUNT PLEASANT ROAD

BLK 8 OLD POLICE ACADEMY SINGAPORE 298333

Date : 21-03-2018



Code : SPF3

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	QX 46R
Policy No.		Coverage (\$)	0.00
Claim No.	HOMSPFETQ16000399	Excess (\$)	0.00
Assign From	LIM WEI YEA	Assign Date	04/01/2018

2. Vehicle Particulars & Condition

Make & Model	SUBARU IMPREZA	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	JF1GD5KJ36G054327	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R15	FALKEN	6 mm
L/H Front Tyre	195/60 R15	FALKEN	6 mm
R/H Rear Tyre	195/60 R15	FALKEN	6 mm
L/H Rear Tyre	195/60 R15	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date		Inspection Date	05/01/2018
Survey held at	2B SUNGEI KADUT DR		
Repairer	SMRT AUTOMOTIVE SERVICES PTE LTD		

5a. Remarks

--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Registration No. QX 46R

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	FRONT BUMPER	1	CRACKED			
1.2	FRONT BUMPER RETAINER RH	1	NECESSARY			
1.3	FRONT BUMPER RETAINER LH	1	NECESSARY			
1.4	FRONT BUMPER SUPPORT	1	DENTED			
1.5	FRONT BUMPER FOG LAMP LH	1	CRACKED			
1.6	FRONT BUMPER FOG LAMP RH	1	CRACKED			
1.7	FRONT NUMBER PLATE WITH CASING	1	CRACKED			
1.8	R/H HEAD LAMP	1	CRACKED			
1.9	L/H HEAD LAMP	1	CRACKED			
1.10	HEAD LAMP SUPPORT LH	1	BENT			
1.11	HEAD LAMP SUPPORT RH	1	BENT			
1.12	FRONT SUPPORT PANEL	1	BENT			
1.13	HORN	1	DAMAGED			
1.14	BONNET	1	BENT			
1.15	BONNET HINGE LH	1	BENT			
1.16	BONNET HINGE RH	1	BENT			
1.17	BONNET INNER LOCK	1	DAMAGED			
1.18	BONNET LOCK	1	DAMAGED			
1.19	BONNET INSULATOR WITH RETAINER	1	NECESSARY			
1.20	BONNET RUBBER SEAL	1	NECESSARY			
1.21	RADIATOR	1	CRACKED			
1.22	RADIATOR UPPER & LOWER HOSE	1	TORN			
1.23	RADIATOR CAP	1	DAMAGED			
1.24	RADIATOR WATER TANK	1	UNCONFIRM			
1.25	RADIATOR FAN MOTOR	1	UNCONFIRM			
1.26	RADIATOR FAN	1	UNCONFIRM			
1.27	RADIATOR COWLING	1	CRACKED			

1.28	RADIATOR GRILL	1	CRACKED			
1.29	AIR CON CONDENSER	1	DENTED			
1.30	AIR CON CONDENSER FAN MOTOR	1	UNCONFIRM			
1.31	AIR CON CONDENSER FAN	1	UNCONFIRM			
1.32	AIR CON CONDENSER COWLING	1	UNCONFIRM			
1.33	AIR CON CONDENSER PIPE	1	BENT			
1.34	WIPER TANK	1	CRACKED			
1.35	POWER STEERING PUMP	1	DAMAGED			
1.36	POWER STEERING PUMP HOSE	1	UNCONFIRM			
1.37	POWER STEERING TANK	1	CRACKED			
1.38	ALTERNATOR	1	UNCONFIRM			
1.39	ALTERNATOR COVER	1	DEFORMED			
1.40	MAIN PULLEY	1	UNCONFIRM			
1.41	MAIN PULLEY BELT	1	TORN			
1.42	ENGINE COVER	1	UNCONFIRM			
1.43	ENGINE MOUNTING	1	UNCONFIRM			
1.44	GEAR BOX MOUNTING	1	UNCONFIRM			
1.45	ABS PUMP	1	UNCONFIRM			
1.46	FRONT MUD FLAP LH	1	TORN			
1.47	FRONT MUD FLAP RH	1	DEFORMED			
1.48	REAR BOOT LID HINGE LH	1	BENT			
1.49	REAR BOOT LID HINGE RH	1	BENT			
1.50	REAR BOOT LID	1	DENTED			
1.51	REAR BOOT LID LOCK	1	DAMAGED			
1.52	REAR BOOT PANEL LOCK	1	BENT			
1.53	SPARE TYRE PANEL	1	DENTED			
1.54	END PANEL UPPER AND LOWER	1	DENTED			
1.55	REAR BUMPER	1	CRACKED			
1.56	REAR BUMPER RETAINER LH	1	NECESSARY			
1.57	REAR BUMPER RETAINER RH	1	NECESSARY			
1.58	REAR BUMPER SUPPORT	1	BENT			
1.59	REAR NUMBER PLATE WITH CASING	1	SCRATCHED			
1.60	L/H TAIL LAMP	1	CRACKED			
1.61	R/H TAIL LAMP	1	CRACKED			
1.62	BOOT LID FLOOR BOARD	1	DEFORMED			
1.63	REAR BOOT LID RUBBER SEAL	1	TORN			
1.64	REAR BOOT LID LOCK CASING	1	MISSING			
1.65	REAR EXHAUST PIPE	1	DENTED			
1.66	EXHAUST PIPE SILENCER	1	BENT			

3	SCOPE OF REPAIRS					
3.1	FRONT BUMPER, FRONT SUPPORT PANEL & FRONT NUMBER PLATE:					11
	REPLACE FRONT BUMPER, BOTH SIDE RETAINERS, FRONT BUMPER SUPPORT & FRONT NUMBER PLATE					
	REMOVE & REPLACE FRONT SUPPORT PANEL					
	PUTTY & SPRAY PAINT FOR FRONT COMPLETE BUMPER					
3.2	LEFT & RIGHT HEAD-LAMP:					3
	REMOVE & REPLACE LEFT & RIGHT HEAD-LAMP					
	REMOVE & REPLACE LEFT & RIGHT HEAD-LAMP SUPPORT					
	WIRING FOR BOTH HEAD-LAMPS					
3.3	FRONT BONNET:					5
	REMOVE & REPLACE FRONT BONNET					
	REMOVE & REPLACE FRONT BONNET HINGES, INNER LOCK, LOCK & INSULATOR					
3.4	ENGINE COMPARTMENT:					16
	REMOVE & REPLACE RADIATOR, RADIATOR CAP, UPPER & LOWER HOSE					
	REMOVE & REPLACE WATER TANK FAN & COWLING					
	REMOVE & REPLACE AIR-CON CONDENSER, AIR-COND CONDENSER FAN & COWLING					
	REMOVE & REPLACE WIPER TANK					
	REMOVE & REPLACE POWER STEERING PUMP, POWER STEERING HOSE & POWER STEERING TANK					
	REMOVE & REPLACE ALTERNATOR & ALTERNATOR COVER					
	REMOVE & REPLACE MAIN PULLEY & MAIN PULLEY BELT					
	REMOVE & REPLACE ENGINE COVER					
	REMOVE & REPLACE ABS PUMP					
	REMOVE & REPLACE ENGINE AND GEAR BOX MOUNTING					

3.5	LEFT & RIGHT MUD FLAPS:					0.5
	REMOVE & REPLACE LEFT & RIGHT MUD FLAPS					
3.6	REAR BUMPER & REAR NUMBER PLATE:					5
	REMOVE & REPLACE REAR BUMPER, REAR BUMPER SUPPORT, BOTH SIDE RETAINERS & REAR NUMBER PLATE					
	PUTTY & SPRAY PAINT FOR REAR COMPLETE BUMPER					
3.7	LEFT & RIGHT TAIL-LAMP:					1
	REMOVE & REPLACE LEFT & RIGHT TAIL-LAMPS					
	WIRING FOR BOTH TAIL-LAMPS					
3.8	REAR BOOT:					20
	REMOVE & REPLACE BOOT LID					
	REMOVE & REPLACE SPARE TYRE PANEL					
	REMOVE & REPLACE END PANEL (UPPER AND LOWER)					
	REPLACE BOOT LID UPPER AND LOWER LOCK					
	REMOVE & REPLACE BOTH REAR BOOT LID HINGES					
	REMOVE & REPLACE REAR BOOT LID FLOOR BOARD					
	REMOVE & REPLACE REAR BOOT LID RUBBER SEAL					
	REMOVE & REPLACE REAR BOOT LID CASING					
	PUTTY & SPRAY PAINT FOR REAR BOOT LID & SPARE TYRE BOOTH AREA					
3.9	LEFT & RIGHT FENDER:					8
	PANEL BEATING FOR BOTH LEFT & RIGHT FENDER					
	PUTTY & SPRAY PAINT FOR BOTH LEFT & RIGHT FENDER					
3.10	REAR LH PANEL:					3
	PANEL BEATING FOR REAR LH PANEL					
	PUTTY & SPRAY PAINT FOR REAR LH PANEL					
3.11	EXHAUST PIPE SYSTEM:					3

	REMOVE & REPLACE EXHAUST PIPE SYSTEM					
3.12	LEFT & RIGHT SKIRTING:					5
	REPAIR & RE-ALIGN BOTH LEFT & RIGHT SKIRTING					
	PUTTY & SPRAY PAINT FOR BOTH LEFT & RIGHT SKIRTING					
COSTING		TOTAL PARTS COST			\$0.00	
		TOTAL MAN-HOUR				80.5

Registration No. QX 46R

Vehicle Inspected By

YEANG WAI KEEN
Automotive Assessor

ADRIAN LING WAI PING
*B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.