

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

ALC

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No

SHB932E

Ref. No

TAX/01/18/2010

Reg. Date

30/10/2013

Vehicle Type

TAXI

Make

Model

TOYOTA PRIUS

Name of Driver

PRIUS

LEONG KENG CHEONG

(LIANG JINXIANG)

Type of Accident

HEAD TO REAR

Date / Time of Accident

02/01/2018 11:10:00 PM

Accident Reported Date / Time :

03/01/2018 12:00:00 AM

Surveyor is Required?

Yes

Survey by

Vehicle is Towed Back?

No

Towed Back Date/Time

Replacement Vehicle issued? :

Accident Repair Job Card No :

000024093902

Special Instruction to ARC, if any :

DROVE IN / SLJ6602D

Prepared Date

03/01/2018 01:00:18 PM

Sunt man @ SHINI 6555 8888

- Lung Sum Repair.

 Quertion Mark Item
 Photo.

 Photo After Paint
 90036121

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- · To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Sebastian years altrauto.com.

Section B - 10 be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U00-5694097

Mileage

0

Work Shop :

Repair Completed Date / Time:

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

338.00

0.00

Total Spray Painting Charges

558.00

0.00

Total Material Charges

Total Labout Charges

699.59

713.87

Other Charges

280.00

0.00

TOTAL

1,875.59

0.00

Lum Sum Total

1,900.00

0.00

No. of Repair Days

3.00

0.00

Prepared / Adjusted By

2 days

Arc / Surveyor Sing Off Date

03/01/2018 05:08:05 PM

01/01/1900 12:00:00 AM

Prepared / Adjusted Date

Remarks

Prepared Date : 03/01/2018 05:08:05 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No

Invoice No

Quotation Date

Invoice Date :

Invoice Amount :

Prepared Date:

Page:

Section D - Details of Repair Estimates

Part 1 - Labour Works

lob Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
TO REPAIR REAR PORTION	338.00	0.00 200		
Total Labour	338.00	0.00		

Part 2 - Spray Painting & Panel Beating Related Works

lob Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
TO REPSRAY REAR BUMPER	378.00		0.00 200	
TO RESPRAY BUMPER BEAM	180.00	?	0.00	
Total Spray Painting & Panel Beating	558.00		0.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

lob Scope	Quotation from ARC	Adjusted by Surveyor, if applicable			
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0:00 30			
TO REPLACE SUNDRY PARTS	100.00	0.00 ×			
TO WASH AND VACUUM	60.00	0.00 ×			
Total Other Costs	280.00	0.00			

AX/01/18/2010

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen d	Surveyor Approved	Photos Attached
52159- 47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No UK
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace / N	ENO
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace 7	No
52575- 47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace 7	No
52562- 47010			TAIL LAMP BRACKET, RH	1	30.70	25.00	23.02	Replace	Replace 7	No
52023- 12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace 7	No
	TOTAL MATERIALS TOTAL MATERIALS(Discounted)						892.35 892.34 699.59 713.87			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

AX/01/18/2010