

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

		PRE-REPAIR I	INSPECTION REPORT	
FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS3/FCI18000337/M1d3s2	
			Date: 25-04-2018	
7,755			Code: FCI2	
1.			lars :- (THIRD PARTY CLAIN	(A)
	Insured Veh.	SHC 387Z	Veh. Inspected	SJT 2680A
	Policy No.	D-15072702MFSH	Coverage (\$)	0.00
	Claim No.	D18000154MFSH	Excess (\$)	0.00
	Assign From	LURENE JAW	Assign Date	05/03/2018
2.		Vehicle	Particulars & Condition	
	Make & Model	MERCEDES BENZ	c.c	1597
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	WDD2040452A317546	Colour	GREY
	Odometer	77193 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.		Co	onditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	225/45R17	GOODYEAR	8 mm
	L/H Front Tyre	225/45R17	GOODYEAR	8 mm
	R/H Rear Tyre	225/45R17	GOODYEAR	8 mm
	L/H Rear Tyre	225/45R17	GOODYEAR	8 mm
1.		Desc	cription of Damages	
	THE VEHICLE SUSTAINED DAMAGES AT THE		E O/S FRONT PORTION.	
5.		Ge	neral Information	
	Accident Date	17/12/2017	Inspect Date / Time	05/03/2018 (03:52 PM)
	Survey held at	THIAM HENG HUAT PTE L	TD	
Э		176 SIN MING DRIVE #05-14 SINGAPORE 57572	1	
5a.			Remarks	
	B) THE REPAIR E	STIMATE WAS NOT PRESEN VAS TOLD TO PREPARE THI EASE FIND DAMAGED VEHI		S. TION.

Report Ref No. CS3/FCI18000337/M1d3s2

Inspected By

MA CHIN FOOK

Automotive Assessor

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.