

REF: NS / INC 18000373 / Svbe2

ASSIGNMENT

From: _____ Date: _____

Veh No: SUC 4628C Yr Regn: 3/9/2019

Estimated Cost: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: _____

Make: Toyota Prius c.c 1798

at Workshop m/s _____

Colour: Maroon A/C: Insured / Std / NI / NA

of _____

Sp. Reading: 376008 T/Radio: Insured / Std / NI / NA

Insured: Ym 8585L

Eng/No: _____

Policy No. 5085358500-01 18-10-2017

C/No: JTKN 314 40574 8033

Claims No. NT/0976517-002

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____ Excess: _____

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh: _____

Modi: NT / S/Rim / STD A/Rim or

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Tyre Size: F: 195/65R15 R: _____

Bal. or Market Value: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Palken

IDAC Accident Rpt: _____ Consistent?: Yes or No

Front R/Bal. 6 mm Rear R/Bal. 6 mm

GIA / PR Seen: _____ Consistent?: Yes or No

L/Bal. 6 mm L/Bal. 6 mm

Est. Repairs: _____ days Res.: Yes or No

D.O.A. 4/1/18 D.O.I. 5/1/18

Lum Sum: _____ % 3 Val.: Yes or No

Survey held at SMART

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Rear O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

SHC 18032 - NS / INC 17063464 / Svbe2 REF: 3017 TAX / 01/18/2019
Ym 8585L - x LKX NTUC

22/1/18 Sebastian confirmed LS \$3550 (Red 5933.30, 60M)

RECEIVED 22/01/2018

Date/Time, File Pass to? : Preli. Report : Final Report

Days Of Repair: 7 Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:	160
Transportation:	
S + RS, SI	
Photos	35
Others	
TOTAL	195

2) 23/1 - typist

Add Fee: : Site Insp (\$) : Interview (\$) : Tech. Invs (\$) : Weekend (\$)

Report Format: Lump Sum / I.B.I.: (\$ 3550)



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18000373/Svb	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556	Date: 08-01-2018
	Code: INC4



1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YM 8585L	Veh. Inspected	SHC 4628C
Policy No.	5085358500-01	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	05/01/2018

2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages	

5. General Information			
Accident Date	04/01/2018	Inspection Date	05/01/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks	
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.	

Veron Chen (LKKAuto)

From: mtreg <mtreg@income.com.sg>
Sent: Tuesday, 23 January 2018 11:27 AM
To: Veron Chen (LKKAuto)
Subject: FW: REQUEST FOR CLAIM NUMBER

Hi

All claim created.

With Regards

Azlin Rani
Senior Administrator, Motor Insurance
www.income.com.sg



From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Tuesday, 23 January, 2018 8:52 AM
To: mtreg
Subject: REQUEST FOR CLAIM NUMBER

Dear Sir/Madam,

Kindly provides us the claim number.

S/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle
1	MT/0976517-002	SMRT TAXIS PTE LTD	SHC 4628C	YM 8585I
2	MT/0976168-002	SMRT TAXIS PTE LTD	SHB 1235C	GBA 1177

D.O.A	Time of Accident	Estimate	Tentative repair cost
4/1/2018	21:00	\$9,483.30	\$3,550.00
31/12/2017	22:30	\$16,243.30	\$6,997.74

Regards,

Veron Chen | Case Handler

Veron Chen Consultants Pte Ltd

561 | email :sur@lkkauto.com | fax: 6256-4315

Hello, NAC_PAYA_UBI_800601

My Desktop
Notice of Loss

Policy Query

Policy No.

Vehicle No. (For Motor)

Date of Accident

Search

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="checkbox"/>	5085358500-01	EASY LINK LEASING PTE. LTD.	201543643N	GFT	Third Party, Fire & Theft	YM8585L	YM8585L	18/10/2017	

Continue

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 5369K

Vehicle Details

Vehicle No.: SHC4628C
Vehicle to be Exported: No
Intended De-registration Date: 08 Jan 2018
Vehicle Make: TOYOTA
Vehicle Model: PRIUS TAXI (SMRT)
Primary Colour: Maroon
Manufacturing Year: 2014
Engine No.: 2ZR6116773
Chassis No.: JTDKN36U405748033
Maximum Power Output: 100.0 kW (134 bhp)
Open Market Value: \$32,920.00
Original Registration Date: 03 Sep 2014
First Registration Date: 03 Sep 2014
Transfer Count: 0
Actual ARF Paid: \$8,088.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 02 Sep 2022

PARF Rebate Amount: \$6,066.00

Intended COE Rebate Details

COE Expiry Date: 02 Sep 2022

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$50,704.00

COE Rebate Amount: \$29,476.00

Total Rebate Amount: \$35,542.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 08 Jan 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/01/2018 09:18
Date Of Accident	04/01/2018 21:00
Exact Location Of Accident	OLD JURONG RD SLIP RD TO UPPER BUKIT TIMAH RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4628C
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	
Driver	
Name of Driver	YUE SEE PENG
NRIC No	S1149443I
Date Of Birth	14/04/1955
Occupation	OUTDOOR
Date Of Driving Pass	05/04/1977
Driving Experience	40 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 323 BUKIT BATOK STREET 33
 06-104
 Postcode 650323
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident /
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. / NO
 Number of Passengers (Including Driver) 4

Passenger 1 NAME: : UNKNOWN
 GENDER: : FEMALE
 Passenger 2 NAME: : UNKNOWN
 GENDER: : FEMALE
 Passenger 3 NAME: : UNKNOWN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS STATIONARY ALONG THE SLIP ROAD OF OLD JURONG ROAD WITH THREE PASSENGERS ON BOARD TO GIVE WAY TO THE ONCOMING TRAFFIC ON UPPER BUKIT TIMAH ROAD WHEN THE VEHICLE YM8585L FROM BEHIND COLLIDED ONTO THE REAR PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: FILE TOO LARGE
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YM8585L
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category GOODS VEHICLE

Vehicle Registration Number of Driver's Own Vehicle (if applicable) CHUA SOON HOCK
 NRIC/Passport Number S7608436Z
 Insurance Company of Driver's Own Vehicle (if applicable)
 Contact Number

General Information of the Accident

Postcode
 Type Of Accident Collision- Chain Collision
 Weather Conditions Clear
 Nature Of Damage Road Surface Dry
 No. Of Passenger (Including Driver)

Was any body injured in the Accident? No
 Was any other material or property damaged? Yes

Details of Police Action

Was the accident reported to the police? No
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? No
 If Yes, against whom?

Circumstances of Accident

Are accident photos available for attachment? Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGD1807D
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SGY1754L
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DBS 6878-9078⁸⁷
 - Poh King

Details of Witness

Name
 Phone Number
 Email Address

Sketch Plan Pg. 1


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have Insured vehicle(s) involved in this accident (all insurer(s) who have Insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes");
- (b) all insurer(s) who have Insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Handwritten signature of the driver

Handwritten date: 5/1/2018

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Photo

TOYOTA MOTOR CORPORATION

JTDKN36U405748033


1-805 kg
1-805 kg
1-1020 kg
2- 980 kg

C/TR
3R9 /FA20
A/TM
-01A/P410
PLANTC25

MODEL ZVW30R-AHXEBW

296 7


Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo




SMRT Accident Vehicle Repair Estimates

NT4C

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4628C
 Ref. No : TAX/01/18/2019
 Reg. Date : 03/09/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : YUE SEE PENG
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 04/01/2018 09:00:00 PM
 Accident Reported Date / Time : 05/01/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 04/01/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024093934
 Special Instruction to ARC,if any :
 TOWED \$40 / YM8585L
 Prepared Date : 05/01/2018 09:42:54 AM



Sebastian .
 5/1/2018.
 - Long Sun Repair .
 - Question Mark Item Photo .
 - Photo After Paint .
 9003614

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

sebastianyang@lkkauto.com.

Ammon
 5/1/18

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U405748033

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 1,656.00	0.00
Total Material Charges	: 3,758.13	3,758.13
Other Charges	: 845.00	0.00
TOTAL	: 7,273.13	0.00
Lum Sum Total	: 7,250.00	0.00
No. of Repair Days	: 7.00	0.00 5 days
Prepared / Adjusted By	:	
Arc / Surveyor Sing Off Date	: 05/01/2018 11:16:44 AM	01/01/1900 12:00:00 AM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 05/01/2018 11:16:44 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 1/5/2018 11:18:59 AM

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	1,014.00	0.00 600
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00	0.00
TO RESPRAY REAR PANEL	180.00	0.00
TO RESPRAY REAR FENDER RH	378.00	0.00 200
TO RESPRAY REAR RH WHEEL HOUSE	180.00	0.00
TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0.00
TO RESPRAY TROUGH BACK DOOR RH	180.00	0.00 50
Total Spray Painting & Panel Beating	1,656.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
OWING CHARGE	80.00	0.00 x
TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0.00 60
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 50
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 30
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00 ✓
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 x
Total Other Costs	845.00	0.00

1
2
3

Part Number	Partion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace ✓	No CKK
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace ✓	No NEC
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace X	No
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace ?	No
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace ?	No
58307-47060		6505522	END PANEL	1	602.10	25.00	451.57	Replace	Replace ?	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace ✓	No CKK
52591-47021			BUMPER SEAL, RR RH	1	65.70	25.00	49.27	Replace	Replace ?	No
81551-47180		6505462	TAIL LAMP RH	1	557.80	10.00	502.02	Replace	Replace ✓	No CKK
52562-47010			TAIL LAMP BRACKET, RH	1	30.70	25.00	23.02	Replace	Replace ?	No
61604-47090			FENDER RR/RH	1	766.80	25.00	575.10	Replace	Replace ✓	No DT
			STICKER DECAL SMRT	1	7.80	0.00	7.80	Replace	Replace ✓	No NEC
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓	No NEC
62710-47130			QUARTER GLASS RR/RH	1	846.50	25.00	634.87	Replace	Replace ✓	No NEC
61607-47060			PANEL SUB-ASSY, QTR	1	588.40	25.00	441.30	Replace	Replace ?	No
62940-16060			DUCT ASSY, QUARTER	1	70.40	25.00	52.80	Replace	Replace ✓	No Deform
58302-47030			FLOOR PANEL RR/RH	1	209.90	25.00	157.42	Replace	Replace ?	No
61621-47030			TROUGH, BACK DOOR	1	110.90	25.00	83.17	Replace	Replace ✓	No DT
61711-47020			PANEL, ROOF SIDE OUTER RH	1	134.80	25.00	101.10	Replace	Replace R	No
61733-47020			PANEL, ROOF SIDE INNER FRONT RH	1	134.80	25.00	101.10	Replace	Replace R	No
61731-47020			PANEL, ROOF SIDE,	1	134.80	25.00	101.10	Replace	Replace R	No
61625-47040			EXTENSION, QUARTER	1	55.70	25.00	41.77	Replace	Replace ?	No
61623-47010			EXTENSION, QUARTER	1	83.50	25.00	62.62	Replace	Replace ?	No
61713-47020			REINFORCE, ROOF SIDE	1	91.90	25.00	68.92	Replace	Replace ?	No
61743-47010			REINFORCEMENT, BACK	1	89.50	25.00	67.12	Replace	Replace ?	No
	COMMO N		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace X	No
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace ✓	No NEC
65637-47021		6505480	FENDER LINER RR/RH	1	141.30	25.00	105.97	Replace	Replace ?	No
TOTAL MATERIALS								4,697.72	4,697.66	
TOTAL MATERIALS(Discounted)								3,758.13	3,758.13	

Added Spare Parts / Material Usage After Surveyor Signed off

Number	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LI Check
TOTAL SUPPLEMENTARY MATERIALS								



Handwritten notes: +2 DOP, 11-1-18 / 09:28, 11-1-18 / 13:28

Handwritten signature: Chea


SMRT Accident Vehicle Repair Estimates

Handwritten note: 5-1-18 / 13:28

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre


Reg. No : SHC4628C
 Ref. No : TAX/01/18/2019
 Reg. Date : 03/09/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : YUE SEE PENG
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 04/01/2018 09:00:00 PM
 Accident Reported Date / Time : 05/01/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : *sebastian*
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 04/01/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024093934
 Special Instruction to ARC, if any :
 TOWED \$40 / YM8585L *Niac 4s*
 BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN (LKK) & Email : *sebastianyeang @lkkauto.com* HP:90036121
 LUMPSUM REPAIR
 Prepared Date : 05/01/2018 09:42:54 AM

Handwritten note: 12/1



Recording Camera
 Radio Antenna
 1st witness *R* _____ Date *5-1-18*
 2nd witness _____ Date _____

Vehicle to Wega Date In: *01/5* Towing: _____
 Time In: *1400* Driver: *Hwa*
 Wega Job No: *01/0014*
 Vehicle sent to SMRT Date In: *12/1/18* Towing: _____
 Time In: *1015* Driver: *Ch*
 Received by (SMRT): _____



Attached Supplementary

Handwritten note: 12/01/18 11.00 P955

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U405748033 Mileage : 0

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	1,000.00
Total Spray Painting Charges	: 1,656.00	650.00
Total Material Charges	: 2,688.27	2,472.43
Other Charges	: 765.00	-572.43
TOTAL	: 6,123.27 9483.30	3,550.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 8.00	7.00 /
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date	: 05/01/2018 11:16:44 AM	05/01/2018 01:28:28 AM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 05/01/2018 11:16:44 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1801-0369 Invoice No :
Quotation Date : 13/1 Invoice Date :
Invoice Amount : 0.00 Prepared Date : 1/5/2018 11:18:59 AM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	1,014.00	1,000.00 /
Total Labour	1,014.00	1,000.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00 /
TO RESPRAY BUMPER BEAM	180.00	0.00
TO RESPRAY REAR PANEL	180.00	100.00 /
TO RESPRAY REAR FENDER RH	378.00	200.00 /
TO RESPRAY REAR RH WHEEL HOUSE	180.00	100.00 /
TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0.00
TO RESPRAY TROUGH BACK DOOR RH	180.00	50.00 /
Total Spray Painting & Panel Beating	1,656.00	650.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	60.00 /
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00 /
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	50.00 /
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30.00 /
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	125.00 /
TO REPLACE SUNDRY PARTS	100.00	20.00 /
TO WASH AND VACUUM	60.00	0.00
Lump Sum Adjustment by Surveyor	0.00	-887.43
Total Other Costs	765.00	-572.43

9483.30

L/S: \$ 3550

Sebastian
22/1/18

2472.43
 1000.00
 650.00
 315.00

 4437.43
 Lump Sum -20%

 3549.94

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached	
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No	CRK
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No	NEC
			SENSOR REVERSE	0	180.00	0.00	0.00	Replace	Not given	No	X
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.28	Replace	Check	No	X
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Check	No	X
58307-47060		6505522	END PANEL	1	602.10	25.00	451.58	Replace	Check	No	X
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace	No	CRK
52591-47021			BUMPER SEAL, RR RH	1	65.70	25.00	49.28	Replace	Check	No	X
81551-47180		6505462	TAIL LAMP RH	1	557.80	10.00	502.02	Replace	Replace	No	CRK
52562-47010			TAIL LAMP BRACKET, RH	1	30.70	25.00	23.03	Replace	Check	No	X
61604-47090			FENDER RR/RH	1	766.80	25.00	575.10	Replace	Replace	No	DT
			STICKER DECAL SMRT	1	7.80	0.00	7.80	Replace	Replace	No	
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No	
62710-47130			QUARTER GLASS RR/RH	1	846.50	25.00	634.87	Replace	Replace	No	
61607-47060			PANEL SUB-ASSY, QTR	1	588.40	25.00	441.30	Replace	Check	No	X
62940-16060			DUCT ASSY, QUARTER	1	70.40	25.00	52.80	Replace	Replace	No	Defom
58302-47030			FLOOR PANEL RR/RH	1	209.90	25.00	157.43	Replace	Check	No	X
61621-47030			TROUGH, BACK DOOR	1	110.90	25.00	83.17	Replace	Replace	No	DT
61711-47020			PANEL, ROOF SIDE OUTER RH	1	134.80	100.00	0.00	Replace	Repair	No	R
61733-47020			PANEL, ROOF SIDE INNER FRONT RH	1	134.80	100.00	0.00	Replace	Repair	No	R
61731-47020			PANEL, ROOF SIDE,	1	134.80	100.00	0.00	Replace	Repair	No	R
61625-47040			EXTENSION, QUARTER	1	55.70	25.00	41.78	Replace	Check	No	X
61623-47010			EXTENSION, QUARTER	1	83.50	25.00	62.63	Replace	Check	No	X
61713-47020			REINFORCE, ROOF SIDE	1	91.90	25.00	68.93	Replace	Check	No	X
61743-47010			REINFORCEMENT, BACK	1	89.50	25.00	67.13	Replace	Check	No	X
	COMMON		SEALANT W/SCREEN	0	37.00	0.00	0.00	Replace	Not given	No	X
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No	NEC
65637-47021		6505480	FENDER LINER RR/RH	1	141.30	25.00	105.98	Replace	Check	No	X
52562-47010			TAIL LAMP BRACKET, RH	1	30.70	25.00	23.02	Replace	Replace	No	S
TOTAL MATERIALS							6048.30	4,200.45	2,472.43		
TOTAL MATERIALS(Discounted)								2,688.27	2,472.43		



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Thatcham describe

NTUC INCOME INSURANCE CO-OPERATIVE LTD	Ref: NS/INC18000373/Svbe2
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556	Date: 25-01-2018
	Code: INC4



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YM 8585L	Veh. Inspected	SHC 4628C
Policy No.	5085358500-01	Coverage (\$)	0.00
Claim No.	MT/0976517-002	Excess (\$)	0.00
Assign From		Assign Date	05/01/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36U405748033	Colour	MAROON
Odometer	376008	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	6 mm
L/H Rear Tyre	195/65 R15	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/01/2018	Inspection Date	05/01/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4628C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER REAR (DISC 25%)	CRACKED	458.60	343.95
1	BUMPER SIDE RETAINER RR/RH (DISC 25%)	CRACKED	94.80	71.10
1	FENDER RR/RH (DISC 25%)	BENT	766.80	575.10
1	QUARTER GLASS RR/RH (DISC 25%)	NECESSARY	846.50	634.87
1	DUCT ASSY, QUARTER (DISC 25%)	DEFORMED	70.40	52.80
1	TROUGH, BACK DOOR (DISC 25%)	DENTED	110.90	83.17
1	TAIL LAMP BRACKET, RH (DISC 25%)	CRACKED	30.70	23.02
1	TAIL LAMP RH (DISC 10%)	CRACKED	557.80	502.02
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	STICKER DECAL SMRT (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	SEALANT SIKAFLEX (SN)	NECESSARY	37.00	37.00
1	SENSOR REVERSE	NOT NECESSARY	180.00	-
1	BUMPER REINFORCEMENT REAR	NOT NECESSARY	205.70	-
1	ARM SUB-ASSY, RR BUMPER RH	NOT NECESSARY	139.60	-
1	END PANEL	NOT NECESSARY	602.10	-
1	BUMPER SEAL, RR RH	NOT NECESSARY	65.70	-
1	TAIL LAMP BRACKET, RH	NOT NECESSARY	30.70	-
1	PANEL SUB-ASSY, QTR	NOT NECESSARY	588.40	-
1	FLOOR PANEL RR/RH	NOT NECESSARY	209.90	-
1	EXTENSION, QUARTER	NOT NECESSARY	55.70	-
1	EXTENSION, QUARTER	NOT NECESSARY	83.50	-
1	REINFORCE, ROOF SIDE	NOT NECESSARY	91.90	-
1	REINFORCEMENT, BACK	NOT NECESSARY	89.50	-
1	SEALANT W/SCREEN	NOT NECESSARY	37.00	-
1	FENDER LINER RR/RH	NOT NECESSARY	141.30	-
1	PANEL, ROOF SIDE OUTER RH	TO REPAIR	134.80	-
1	PANEL, ROOF SIDE INNER FRONT RH	TO REPAIR	134.80	-
1	PANEL, ROOF SIDE	TO REPAIR	134.80	-
			6,048.30	2,472.43

Report Ref No. NS/INC18000373/Svbe2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		1,619.00	1,295.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		1,656.00	650.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			3,435.00	1,965.00
	GRAND TOTAL		9,483.30	4,437.43
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			3,550.00

Report Ref No. NS/INC18000373/Svbe2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.