

ASS. REC. BY:

REF: CSLMSG18000380/T1qdz

Special Instructions:

Surveyor
Menmen

ASSIGNMENT (Office)

From (Person): Monica Chung of MSIG

Date/Time: 05/01/2018 @ 5:01pm

Estimated Cost: Bill to:

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ ENV ☐ MV ☐ CS

To Inspect Vehicle No: SKW 303A

Insured: SGF 3438L

at Workshop m/s: Performance

Tel: 63190174

of 303 Alexandra Road

Policy No: A80370498MCX

Claim No: 544428

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 3/01/2018

CA / REV / REP. / REV 24 HRS 'wp'

08/01/17

H.O.D. Endorsement:

Date/Time: 08/01/17 @

Person Contacted: Caroline

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SKW 303A - CC4/AXA16008684/K1ya3g2 D.O.A. = 07/05/2016
	SGF 3438L - X
09/11/18 @	3.16pm revised to Monica Chung via Menmen.
12/12/18 @	11.19am confirmed with Caroline from Ag \$223344.55, 7 days.
	CRD \$9543.50, 297.7

ASSIGNMENT

From: _____ Date: 15/12/2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKW 303A

at Workshop mis: Performance

of: 303 Alexandra Rd

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKW 303A Yr Regn: 2015 Sep

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 520I cc: 1997

Colour: Black A/C Insured / Std / NI / NA

Sp Reading: 52674 T/Radio: Insured / Std / NI / NA

Eng No: _____

C No: WBA5A320X0D 828757

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R17

R: n n

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. D.O.L: 5/8/18 @ 1630

Survey held at: PML

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt 4/5, 4/c

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

2/7/2018

RECEIVED 8 JUL 2018

Date/Time File Pass to?

02/7/2018

Date/Time File Return to?

2

☐ : Prel. Report

☐ : Final Report

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

1 3 + 78 81

Photo:

Other:

TOTAL

Add Fee: ☐ Site Insp \$

☐ Interview \$

☐ Tech. Insp \$

☐ Weekend \$

Report Format:

Lump Sum / I.B.I: \$ 13344.55

MER-7P



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18000380/T1qd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 08-01-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGF 3438L	Veh. Inspected	SKW 303A
Policy No.	A80370498MKC	Coverage (\$)	0.00
Claim No.	544428	Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	08/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	03/01/2018	Inspection Date	08/01/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 2 July 2018 11:19 AM
To: 'PBSP'; Taufikh (LKKAUTO)
Cc: SUR
Subject: RE: 1236299: FINAL REPORT / SKW303A

Dear Caroline,

WITHOUT PREJUDICE

Confirm final fig \$23,344.55 before GST and 7 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Friday, 27 April 2018 1:16 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Subject: Fw: 1236299: FINAL REPORT / SKW303A

Dear Shiau Chan

Please assist to confirm COR. Urgent.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Keith Leo Chi Yung
Sent: Tuesday, 27 February 2018 10:07 AM
To: Taufikh (LKK Auto)
Cc: PBSP
Subject: RE: 1236299: FINAL REPORT / SKW303A

Dear Taufikh

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 09 Jan 2018

Preliminary Advice

Insured Vehicle No	: SGF3438L	Accident Date	: 03/01/2018
TP Vehicle No	: SKW303A	Assignment Date	: 05/01/2018
Make	: BMW 520i	Est. Duration of Repair	: 7
Date of Inspection	: 05/01/2018		
Inspection At	: PERFORMANCE MOTORS LIMITED		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion, undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	30,947.10
Revised Amount	:S\$	11,484.15
Check Items (Estimated)	:S\$	17,089.65
Total	:S\$	28,573.80

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4601D
Vehicle Details	
Vehicle No.:	SKW303A
Vehicle to be Exported:	No
Intended De-registration Date:	09 Jan 2018
Vehicle Make:	B.M.W.
Vehicle Model:	520i AT D/AB 2WD 4DR HID NAV
Primary Colour:	Brown
Manufacturing Year:	2015
Engine No.:	A5671164N20B20B
Chassis No.:	WBA5A320X0D828757
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$40,870.00
Original Registration Date:	30 Sep 2015
First Registration Date:	30 Sep 2015
Transfer Count:	0
Actual ARF Paid:	\$49,218.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2025
PARF Rebate Amount:	\$36,913.00
Intended COE Rebate Details	
COE Expiry Date:	29 Sep 2025
COE Category:	E - Open Category
COE Period(Years):	10

QP Paid:	\$61,010.00
COE Rebate Amount:	\$47,113.00
Total Rebate Amount:	\$84,026.00

The information contained herein is correct as at 09 Jan 2018

OK



bmw 520

Price Range

Depreciation

2015

Vehicle Type

Home » Used Cars » Premium Automobiles » BMW 5 Series 520i

Tools & Tips

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

BMW 5 Series 520i

Overview

Financial

Accessories

Similar

Research

Photos

Map



Premium Automobiles

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Car Details

Price **\$151,999**

Depreciation **\$16,900 /yr**
[View models with similar depreciation](#)

Reg Date **25-Aug-2015**
(7yrs 7mths 15days COE left)

Manufactured **2015**

Mileage **40,000 km (16.8k /yr)**

Transmission **Auto**

Engine Cap **1,997 cc**

Road Tax **\$1,210 /yr**

Power **135.0 kW (181 bhp)**
[View specs of the BMW 5 Series Sedan \(2010-2017\)](#)

Curb Weight **1,615 kg**

Features **2.0L TwinPower Turbocharged, 8 Speed Steptronic Transmission, ABS, ESP, SRS Airbags, Keyless Entry Push/Start, Cruise Control.**

Accessories **17" Rims, M Steering, I-Drive With Navigation And Bluetooth, Power Tailgates, Comfort Access, Front And Rear Sensors, Reverse Camera.**

Description **Sporty Black 520i PML Maintained And Under Warranty, Premium Pre-Owned 110 Points Check, Trade In And Flexible Finance Package Available, Please SMS Now For Viewing Appointment And More Details!**

COE **\$62,140**



Seller Information

Company

Car Leasing

CL LEASING
YOUR PREFERRED CAR LEASING
OPTION IN SINGAPORE

6759 7117 8720 5000 8720 8000

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/01/2018 12:19
Date Of Accident	03/01/2018 15:50
Exact Location Of Accident	PIE-BKE EXIT TOWARDS WOODLANDS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW303A
Insured/Policyholder	
Name Of Registered Owner	CHEN CHU LIOW
NRIC No	S1774601D
Email Address	CLCHEN01@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-96709438
Alternative Phone No	OFFICE-96503818

Vehicle Particulars

Manufacturer	BMW
Model	520I
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P1678669
Cover Note Number	

Driver

Name of Driver	CHEN CHU LIOW
NRIC No	S1774601D
Date Of Birth	10/04/1966
Occupation	INDOOR
Date Of Driving Pass	18/05/1987
Driving Experience	30 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96709438
Fax Number	
Contact Number	OFFICE-96503818
Email Address	CLCHEN01@YAHOO.COM.SG

Address	2 PETIR ROAD #23-12
Postcode	678265
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGF3438L
Vehicle Make/Model/Colour	TOYOTA VIOS BLACK
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	VELLUNISWARAN S/O PANEERSELVAN
NRIC/Passport Number	S8802360I
Contact Number	90068159
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	FRONT
No. Of Passenger (Including Driver)	1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:
04/01/18
10.07am

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 3 Jan 2018, afternoon 3:50 pm, or I was driving on PIE - BKE exit towards woodland, near lamp post 1171510. A black Toyota Vios registration number SGF 3438L skidded on my right. The said vehicle hit the road railing on the right side of the road and then suddenly skidded across the road in front of me.

I was not able to stop on time and the other vehicle hit the front right side of my car. Both cars came to a stop by then.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature
Date & Time:

04/01/18
(10.07am)

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401555M GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64795601 (AfterSales)
64795624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

#CAR IN#

ESTIMATE

04 JAN 2018

Estimate No. : b1 45382
Date Estimated : 04/01/2018
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 3

- ESTIMATE REPAIR FOR -

Chen Chu Liow
Apt Blk 2 Petir Road
#23-12

Singapore 678265

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKW303A	D828757	30/09/2015	520iA	0

DESCRIPTION

VALUE

To replace front bumper, right front fender and attachment
include knocking cause by the accident

1700 2,550.00

Painting front bumper, right front fender

1730 1,923.00

To carry out body cavity preservation.
(Per panel).

100 118.00

To replace right headlight including program
and conduct tests for proper function.

451 450 531.00

To replace right front rim including balancing. (1x).

80 94.00

To tow accident vehicle to PML workshop.

195.00

To remove and install front suspension for inspection and
replace damaged parts.

photo 2256 2,655.00

To check steering geometry and conduct wheel alignment
according to BMW specification (2x)

902 1,062.00

To replace electromechanical power steering including
program, initialize steering column adjustment and conduct
checks for proper function.

photo 752 885.00

Sundries.

nec ? 150.00

Total Labour 1: 10,163.00

DESCRIPTION

QTY PRIC

VALUE

FRONT AXLE SUPPORT

1 1,799.00

? 1,799.00

WISHBONE TOP

1 529.00

? 529.00

LH TENSION STRUT W/RUBBER MOUNTING

1 480.90

x 480.90

RH TENSION STRUT W/RUBBER MOUNTING

1 480.90

x 480.90

LH WISHBONE W/RUBBER MOUNTING

1 577.05

? 577.05

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401659M GST Reg. No M2-0020081-X



353, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190122 (AfterSales)
Fax. 64747770

380, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64756601 (AfterSales)
64756624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 45382
Date Estimated : 04/01/2018
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKW303A	D828757	30/09/2015	520iA	0

DESCRIPTION

QTY

PRIC

VALUE

RH WISHBONE W/RUBBER MOUNTING
RH WISHBONE W/RUBBER MOUNTING
WHEEL HUB WITH BEARING FRT
FRT RH CARRIER
FRT GUIDE SUPPORT
FRT RH SPRING STRUT
SPRING PAD LOWER
SPRING PAD UPPER
FRONT SWING SUPPORT
STABILIZER FRT W/RUBBER MOUNTING
LH TIE ROD
RH TIE ROD
EXCH STEERING BOX ELECTR.
ALLOY RIM 8Jx17 MULTI SPOKE 456
HUB CAP WITH CHROME EDGE (BMW)
FRT RH FENDER
SET MOUNTS PDC SENSOR FRT (PDC)
FRT LH BOTTOM DEFORMATION ELEMENT
FRT RH BOTTOM DEFORMATION ELEMENT
FRT BUMPER CARRIER
FRT BUMPER BOTTOM MOUNT
GRILLE AIR INLET MIDDLE
RH GRILLE AIR INLET PARTLY CLOSED
FRT SHOCK ABSORBER
FRT BUMPER RH PROTECTIVE RUBBER STR
FRT BUMPER PANEL PRIMED (PDC)
COVERING PRIMEND LH
COVERING PRIMEND RH
FRT LH GRILLE (BASIS)
FRT RH GRILLE (BASIS)
EMBLEM GROMMET
BMW EMBLEM
FRT RH COVER F REAR WHEELHOUSE
FRT RH WHEEL ARCH COVER
COVER BOTTOM RIGHT
HOSE LINE HEADLIGHT CLEANING SYSTEM
RH HIGH PRESSURE NOZZLE
RH BI-XENON HEADLIGHT
RH FOG LIGHT LED
DECOUPLING RING PDC TORQUE CONVERTE
ULTRASONIC TRANSDUCER JATOBA WB65

1

577.05

577.05

1

577.05

577.05

1

503.00

503.00

1

453.70

453.70

1

144.15

144.15

1

586.20

586.20

1

15.15

15.15

1

17.80

17.80

1

107.90

107.90

1

457.85

457.85

1

297.70

297.70

1

297.70

297.70

1

4,369.95

4,369.95

1

859.70

859.70

1

23.75

23.75

1

842.30

842.30

1

31.95

31.95

1

99.25

99.25

1

99.25

99.25

1

668.10

668.10

1

153.65

153.65

1

80.65

80.65

1

68.65

68.65

1

46.80

46.80

1

21.75

21.75

1

1,246.40

1,246.40

1

43.70

43.70

1

43.70

43.70

1

117.50

117.50

1

117.50

117.50

2

0.80

1.60

1

67.80

67.80

1

124.00

124.00

1

124.00

124.00

1

71.30

71.30

1

46.35

46.35

1

174.90

174.90

1

2,566.95

2,566.95

1

381.55

381.55

4

5.05

20.20

1

368.80

368.80

Total Parts :

20,784.10

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401558W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438188
Tel. 63190888 (AfterSales)
Fax. 63449773

316, Alexandra Road
Sime Darby Business Centre
Singapore 155944
Tel. 63190528 (AfterSales)
63190533/330 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 45382
Date Estimated : 04/01/2018
Prepared By : Gary Poh Chai Hoon

Page No. : 3 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKW303A	D828757	30/09/2015	520iA	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 3/1/18 @ 1650 Excess S\$ _____

Surveyor's Name Tanfimer Sign _____

Surveyor's Tel 97495744 Authorised Yes / No _____

Authorized Date - WP Time _____

REPAIRS TO BE COMPLETED BY DATE 3/1/18 EST. Yes / No _____

Surveyor's Email tanfimer@ultraauto.com

No. of Working Days Required 6 - 7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Labour 1	:	10,163.00
Parts	:	20,784.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,166.30
Grand Total	:	33,113.40

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

32888.45

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Page No. :

Estimate No. : b1 45382
Date Estimated : 04/01/2018
Prepared By : Gary Poh Chai Hoon

REPAIR FOR -
Chen Chu Liow
Apt Blk 2 Petir Road
#23-12

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 678265

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE	ORIGINAL PRICE	DISC. %	NETT
SKW303A	D828757	30/09/2015	520iA	0			
DESCRIPTION							
# To replace RH LED foglamp include removing attachments to facilitate repairs and conducting checks for proper function					226.00		226.00
# To remove and install brake discs, brake pads, brake hoses and brake calipers include bleeding of brake system, conduct brake tests and checks for leak					853.00		853.00
# To conduct electrical system checks at the front section for proper function include adjustment of headlights					150.00		150.00
# To remove old PDC assembly and reconnect to new bumper include conducting checks for proper function					150.00		150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# HEX NUT WITH FLANGE M16X1.5-10 ZNN1 *	9.65	4.00		rec 38.60
# SPHERICAL COLLAR SCREW M12X1.25X45 *	7.70	8.00		rec 61.60
# COMBINATION NUT M14X1.5 *	5.65	3.00		rec 16.95
# FRT RH 1 SIDE PANEL BRACKET *	67.45	1.00		bt 67.45
# LEVER RH *	7.00	1.00		de 7.00
# RH HEADLAMP SUPPORT *	125.35	1.00		bt 125.35
# ENGINE COMP. SHIELD UNDERRIDE PROT. *	202.15	1.00		de 202.15
# GASKET SET *	42.85	1.00		nld 42.85

Total Labour : 1,379.00
Total Parts : 561.95
Total Labour & Parts : 1,940.95

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 45382
Date Estimated : 04/01/2018
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Chen Chu Liow
Apt Blk 2 Petir Road
#23-12

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 678265

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE	ORIGINAL PRICE	DISC. %	NETT
SKW303A	D828757	30/09/2015	520iA	0			
DESCRIPTION							
To replace front bumper and attachments, front RH fender, RH headlamp support, engine compartment shield, underide protector, RH bottom cover, RH high pressure nozzle include knocking out dents caused by the accident					1700.00		1,700.00
To spray paint front bumper and front RH fender					1730.00		1,730.00
To carry out body cavity preservation. (Per panel).					100.00		100.00
To replace RH bi xenon headlight include programming and conducting tests for proper function					451.00		451.00
To replace front RH wheel rim include balancing (1x)					80.00		80.00
To tow accident vehicle to PML workshop.					195.00		195.00
* To remove and install front suspension for inspection include replacement of damaged parts					2256.00		2,256.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (2x)					902.00		902.00
* To replace electromechanical power steering including program, initialize steering column adjustment and conduct checks for proper function.					752.00		752.00
# To replace RH LED foglamp include removing attachments to facilitate repairs and conducting checks for proper function					226.00		226.00 (1A)
# To remove and install brake discs, brake pads, brake hoses and brake calipers include bleeding of brake system, conduct brake tests and checks for leak					853.00		853.00 (4A)
# To conduct electrical system checks at the front section for proper function include adjustment of headlights					150.00		150.00 (4A)
# To remove old PDC assembly and reconnect to new bumper include conducting checks for proper function					150.00		150.00 (1A)

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Sundries 150.00 150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# HEX NUT WITH FLANGE M16X1.5-10 ZNN1 *	9.65	4.00		38.60 <i>Ch</i>
RH TENSION STRUT W/RUBBER MOUNTING	480.90	1.00		480.90
RH WISHBONE W/RUBBER MOUNTING	577.05	1.00		577.05
WHEEL HUB WITH BEARING FRT	503.00	1.00		503.00
# SPHERICAL COLLAR SCREW M12X1.25X45 *	7.70	8.00		61.60 <i>Ch</i>
FRT RH CARRIER	599.70	1.00		599.70
RH TIE ROD	297.70	1.00		297.70
EXCH STEERING BOX ELECTR.	4,369.95	1.00		4,369.95
# COMBINATION NUT M14X1.5 *	5.65	3.00		16.95 <i>Ch</i>
ALLOY RIM 8Jx17 MULTI SPOKE 456	859.70	1.00		859.70
# FRT RH 1 SIDE PANEL BRACKET *	67.45	1.00		67.45 <i>Ch</i>
FRT RH FENDER	842.30	1.00		842.30
FRT SHOCK ABSORBER	46.80	1.00		46.80
# LEVER RH *	7.00	1.00		7.00 <i>Ch</i>
FRT BUMPER PANEL PRIMED (PDC)	1,246.40	1.00		1,246.40
EMBLEM GROMMET	0.80	2.00		1.60
BMW EMBLEM	67.80	1.00		67.80
# RH HEADLAMP SUPPORT *	125.35	1.00		125.35 <i>Ch</i>
# ENGINE COMP. SHIELD UNDERRIDE PROT. *	202.15	1.00		202.15 <i>Ch</i>
COVER BOTTOM RIGHT	71.30	1.00		71.30
RH HIGH PRESSURE NOZZLE	174.90	1.00		174.90
RH BI-XENON HEADLIGHT	2,566.95	1.00		2,566.95
# GASKET SET *	42.85	1.00		42.85 <i>Ch</i>
RH FOG LIGHT LED	381.55	1.00		381.55

SUPPLEMENTARY ITEMS

Total Labour :	9,695.00
Total Parts :	13,649.55
Total Labour & Parts :	23,344.55
Deduction for Excess :	0.00
Total Repair Costs less Excess:	23,344.55
GST @7%:	1,634.12
Grand Total :	24,978.67

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jan 2018		05 Jan 2018 17:01 Edit Adj Rpt	S\$23,344.55 Edit Estimates	S\$23,344.55 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	UNITED WORKS PTE LTD, Co. Reg. No.: 200716702D		
Main Claimant:	CHEN CHU LIOW, ID: S1774601D		
Vehicle Reg. No.:	SKW303A	Date of Loss:	03/01/2018 16:00 - :59 [27 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 544428	Policy/Cover Note No.:	A80370498MCX (Comprehensive) Coverage: 07/04/2017 - 06/04/2018
Vehicle Reg. No. (Insured):	SGF3438L	Policy No. (Claimant):	
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 04/02/2018]		
Driver/Custodian (Insured):	VELLUNISWARAN S/O PANEERSELVAM (), NRIC: S8802360I, Tel: +6590068159		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKW303A (544428)
[SGF3438L]
TP
CHEN CHU LIOW
Jan 3 2018 4:00PM
[UNITED WORKS PTE LTD]
Performance Motors Limited

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View View in Browser

Video				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	11/01/18 14:24	Video - AccidentTP	Load MP4		

Assessment Reports				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	05/01/18 17:03	Accident Statement From: SC - Reg. No: SGF3438L, Claimant: UNITED WORKS PTE LTD	Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	09/01/18 15:16	Adjuster Immediate Advice	Load HTM		

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	02/07/18 11:16	Odometer Reading	Load JPG	☒	
2	02/07/18 11:16	Chassis Number	Load JPG	☒	
3	02/07/18 11:16	General View	Load JPG	☒	
4	02/07/18 11:16	General View	Load JPG	☒	
5	02/07/18 11:16	General View	Load JPG	☒	
6	02/07/18 11:16	General View	Load JPG	☒	
7	02/07/18 11:16	General View	Load JPG	☒	
8	02/07/18 11:16	General View	Load JPG	☒	
9	02/07/18 11:16	General View	Load JPG	☒	
10	02/07/18 11:16	General View	Load JPG	☒	
11	02/07/18 11:16	General View	Load JPG	☒	
12	02/07/18 11:16	General View	Load JPG	☒	
13	02/07/18 11:16	General View	Load JPG	☒	
14	02/07/18 11:16	General View	Load JPG	☒	
15	02/07/18 11:16	General View	Load JPG	☒	
16	02/07/18 11:16	General View	Load JPG	☒	
17	02/07/18 11:16	General View	Load JPG	☒	
18	02/07/18 11:16	General View	Load JPG	☒	
19	02/07/18 11:16	General View	Load JPG	☒	
20	02/07/18 11:16	General View	Load JPG	☒	
21	02/07/18 11:16	General View	Load JPG	☒	
22	02/07/18 11:16	General View	Load JPG	☒	
23	02/07/18 11:16	General View	Load JPG	☒	
24	02/07/18 11:16	General View	Load JPG	☒	
25	02/07/18 11:16	General View	Load JPG	☒	
26	02/07/18 11:16	General View	Load JPG	☒	
27	02/07/18 11:16	General View	Load JPG	☒	
28	02/07/18 11:16	General View	Load JPG	☒	

Video			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
29	02/07/18 11:16	General View	 Load JPG	☒
30	02/07/18 11:16	General View	 Load JPG	☒
31	02/07/18 11:16	General View	 Load JPG	☒
32	02/07/18 11:16	General View	 Load JPG	☒
33	02/07/18 11:16	General View	 Load JPG	☒
34	02/07/18 11:16	General View	 Load JPG	☒
35	02/07/18 11:16	General View	 Load JPG	☒
36	02/07/18 11:16	General View	 Load JPG	☒
37	02/07/18 11:16	General View	 Load JPG	☒
38	02/07/18 11:16	General View	 Load JPG	☒
39	02/07/18 11:16	General View	 Load JPG	☒
40	02/07/18 11:16	General View	 Load JPG	☒
41	02/07/18 11:16	General View	 Load JPG	☒
42	02/07/18 11:16	General View	 Load JPG	☒
43	02/07/18 11:16	General View	 Load JPG	☒
44	02/07/18 11:16	General View	 Load JPG	☒
45	02/07/18 11:16	General View	 Load JPG	☒
46	02/07/18 11:16	General View	 Load JPG	☒
47	02/07/18 11:16	General View	 Load JPG	☒
48	02/07/18 11:16	General View	 Load JPG	☒
49	02/07/18 11:16	General View	 Load JPG	☒
50	02/07/18 11:16	General View	 Load JPG	☒
51	02/07/18 11:16	General View	 Load JPG	☒
52	02/07/18 11:16	General View	 Load JPG	☒
53	02/07/18 11:16	General View	 Load JPG	☒
54	02/07/18 11:16	General View	 Load JPG	☒
55	02/07/18 11:16	General View	 Load JPG	☒
56	02/07/18 11:16	General View	 Load JPG	☒
57	02/07/18 11:16	General View	 Load JPG	☒
58	02/07/18 11:16	General View	 Load JPG	☒
59	02/07/18 11:16	General View	 Load JPG	☒
60	02/07/18 11:16	General View	 Load JPG	☒
61	02/07/18 11:16	General View	 Load JPG	☒
62	02/07/18 11:16	General View	 Load JPG	☒
63	02/07/18 11:16	General View	 Load JPG	☒
64	02/07/18 11:16	General View	 Load JPG	☒
65	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
66	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
67	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
68	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
69	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
70	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
71	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
72	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
73	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
74	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
75	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
76	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
77	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
78	02/07/18 11:16	Reinspection Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
79	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
80	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
81	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
82	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
83	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
84	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
85	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
86	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
87	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
88	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
89	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
90	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
91	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
92	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
93	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
94	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
95	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
96	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
97	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
98	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
99	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
100	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
101	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
102	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
103	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
104	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
105	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
106	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
107	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
108	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
109	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
110	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
111	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
112	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
113	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
114	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
115	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
116	02/07/18 11:16	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	05/01/18 17:02	PML NOMINATE LKK TO BE THE SJE	 Load PDF	
2	05/01/18 17:03	ESTIMATE	 Load TIF	
3	05/01/18 17:03	TP GIA REPORT	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/07/18 11:52	SUPPLEMENTART PART	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18000380/GQD3Q2

Date: 10/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A80370498MCX

Claimant Vehicle No: SKW303A

Insured Vehicle No: SGF3438L

Date of Loss: 03/01/2018

Nature of Claim: TP

Claim No: 544428

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKW303A

Make & Model: BMW 520i, 2.0 (A)

Engine No: A5671164N20B20B

Reg. Date: 30/09/2015 (Man. Year: 2015)

Chassis No: WBA5A320X0D828757

Colour: Black

Odometer: 52674 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17

Rear Tyre Size: 225/55 R17

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,642.05	13,799.55	7,842.50	36.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,392.00	9,545.00	1,847.00	16.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	33,034.05	23,344.55	9,689.50	29.33
+ GST 7.00/7.00% (S\$)	2,312.38	1,634.12	678.26	29.33
Nett Amount (S\$)	35,346.43	24,978.67	10,367.76	29.33

INSPECTION

Date of Assignment: 05/01/2018

Date Inspected: 05/01/2018 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Jul 2018)
Parts: 143	BMW 520i 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKW303A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*FRONT AXLE SUPPORT	Not Necessary	1,799.00 FS	*- FS
3	1		*WISHBONE TOP	Not Necessary	529.00 FS	*- FS
4	1		*LH TENSION STRUT W/RUBBER MOUNTING	Not Necessary	480.90 FS	*- FS
5	1		*RH TENSION STRUT W/RUBBER MOUNTING	Bent	480.90 FS	*480.90 FS
6	1		*LH WISHBONE W/RUBBER MOUNTING	Not Necessary	577.05 FS	*- FS
7	1		*RH WISHBONE W/RUBBER MOUNTING	Not Necessary	577.05 FS	*- FS
8	1		*RH WISHBONE W/RUBBER MOUNTING	Bent	577.05 FS	*577.05 FS
9	1		*WHEEL HUB WITH BEARING FRT	Bent	503.00 FS	*503.00 FS
10	1		*FRT RH CARRIER	Bent	599.70 FS	*599.70 FS
11	1		*FRT GUIDE SUPPORT	Not Necessary	144.15 FS	*- FS
12	1		*FRT RH SPRING STRUT	Not Necessary	586.20 FS	*- FS
13	1		*SPRING PAD LOWER	Not Necessary	15.15 FS	*- FS
14	1		*SPRING PAD UPPER	Not Necessary	17.80 FS	*- FS
15	1		*FRONT SWING SUPPORT	Not Necessary	107.90 FS	*- FS
16	1		*STABILIZER FRT W/RUBBER MOUNTING	Not Necessary	457.85 FS	*- FS
17	1		*LH TIE ROD	Not Necessary	297.70 FS	*- FS
18	1		*RH TIE ROD	Bent	297.70 FS	*297.70 FS
19	1		*EXCH STEERING BOX ELECTR	Bent	4,369.95 FS	*4,369.95 FS
20	1		*ALLOY RIM 8JX17 MULTI SPOKE 456	Cut	859.70 FS	*859.70 FS
21	1		*HUB CAP WITH CHROME EDGE (BMW)	Not Necessary	23.75 FS	*- FS
22	1		*FRT RH FENDER	Bent	842.30 FS	*842.30 FS
23	1		*SET MOUNTS PDC SENSOR FRT (PDC)	Not Necessary	31.95 FS	*- FS
24	1		*FRT LH BOTTOM DEFORMATION ELEMENT	Not Necessary	99.25 FS	*- FS
25	1		*FRT RH BOTTOM DEFORMATION ELEMENT	Not Necessary	99.25 FS	*- FS
26	1		*FRT BUMPER CARRIER	Not Necessary	668.10 FS	*- FS
27	1		*FRT BUMPER BOTTOM MOUNT	Not Necessary	153.65 FS	*- FS
28	1		*GRILLE AIR INLET MIDDLE	Not Necessary	80.65 FS	*- FS
29	1		*RH GRILLE AIR INLET PARTLY CLOSED	Not Necessary	68.65 FS	*- FS
30	1		*FRT SHOCK ABSORBER	Bent	46.80 FS	*46.80 FS
31	1		*FRT BUMPER RH PROTECTIVE RUBBER STR	Not Necessary	21.75 FS	*- FS
32	1		*FRT BUMPER PANEL PRIMED (PDC)	Deformed	1,246.40 FS	*1,246.40 FS
33	1		*COVERING PRIMEND LH	Not Necessary	43.70 FS	*- FS
34	1		*COVERING PRIMEND RH	Not Necessary	43.70 FS	*- FS
35	1		*FRT LH GRILLE (BASIS)	Not Necessary	117.50 FS	*- FS
36	1		*FRT RH GRILLE (BASIS)	Not Necessary	117.50 FS	*- FS
37	2		*ELEMENT GROMMET	Necessary	1.60 FS	*1.60 FS
38	1		*BMW EMBLEM	Necessary	67.80 FS	*67.80 FS
39	1		*FRT RH COVER REAR WHEELHOUSE	Not Necessary	124.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*FRT RH WHEEL ARCH COVER	Not Necessary	124.00 FS	*- FS
41	1		*COVER BOTTOM RIGHT	Deformed	71.30 FS	*71.30 FS
42	1		*HOSE LINE HEADLIGHT CLEANING SYSTEM	Not Necessary	46.35 FS	*- FS
43	1		*RH HIGH PRESSURE NOZZLE	Deformed	174.90 FS	*174.90 FS
44	1		*RH BI-XENON HEADLIGHT	Cracked	2,566.95 FS	*2,566.95 FS
45	1		*RH FOG LIGHT LED	Necessary	381.55 FS	*381.55 FS
46	4		*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	20.20 FS	*- FS
47	1		*ULTRASONIC TRANSDUCER JATOBA WB65	Not Necessary	368.80 FS	*- FS
48	4		*HEX NUT WITH FLANGE M16X1.5-10 ZNN1	Necessary	38.60 FS	*38.60 FS
49	8		*SPHERICAL COLLAR SCREW M12X1.25X45	Necessary	61.60 FS	*61.60 FS
50	3		*COMBINATION NUT M14X1.5	Necessary	16.95 FS	*16.95 FS
51	1		*FRT RH 1 SIDE PANEL BRACKET	Bent	67.45 FS	*67.45 FS
52	1		*LEVER RH	Deformed	7.00 FS	*7.00 FS
53	1		*RH HEADLAMP SUPPORT	Bent	125.35 FS	*125.35 FS
54	1		*ENGINE COMP .SHIELD UNDERRIDE PROT	Deformed	202.15 FS	*202.15 FS
55	1		*SET GASKET	Necessary	42.85 FS	*42.85 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					21,642.05	13,799.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE RH LED FOGLAMP INCLUDE REMOVING ATTACHMENTS TO FACILITATE REPAIRS AND CONDUCTING CHECKS FOR PROPER FUNCTION	New	226.00	226.00
2	TO REMOVE AND INSTALL BRAKE DISCS ,BRAKE PADS ,BRAKE HOSES AND BRAKE CALIPERS INCLUDE BLEEDING OF BRAKE SYSTEM ,CONDUCT BRAKE TESTS AND CHECKS FOR LEAK	New	853.00	853.00
3	TO CONDUCT ELECTRICAL SYSTEM CHECKS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDE ADJUSTMENT OF HEADLIGHTS	New	150.00	150.00
4	TO REMOVE OLD PDC ASSEMBLY AND RECONNECT TO NEW BUMPER INCLUDE CONDUCTING CHECKS FOR PROPER FUNCTION	New	150.00	150.00
5	TO REPLACE FRONT BUMPER ,RIGHT FRONT FENDER AND ATTACHMENT INCLUDE KNOCKING CAUSE BY THE ACCIDENT	New	2,550.00	1,700.00
6	PAINTING FRONT BUMPER ,RIGHT FRONT FENDER	New	1,923.00	1,730.00
7	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
8	TO REPLACE RIGHT HEADLIGHT INCLUDING PROGRAM AND CONDUCT TESTS FOR PROPER FUNCTION	New	531.00	451.00
9	TO REPLACE RIGHT FRONT RIM INCLUDING BALANCING	New	94.00	80.00
10	TO TOW ACCIDENT VEHICLE TO PML WORKSHOP	New	195.00	195.00
11	TO REMOVE AND INSTALL FRONT SUSPENSION FOR INSPECTION AND REPLACE DAMAGED PARTS	New	2,655.00	2,256.00
12	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION	New	1,062.00	902.00
13	TO REPLACE ,ELECTROMECHANICAL POWER STEERING INCLUDING PROGRAM ,INITIALIZE STEERING COLUMN ADJUSTMENT AND CONDUCT CHECKS FOR PROPER FUNCTION	New	885.00	752.00
Gross Labour Cost (\$\$)			11,392.00	9,545.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >