ASS. REC. BY	REF. CS/MSG18000391/890302
Muimin - From (Person Estimated Co	Saborstian ASSIGNMENT (Office) Cuthuine Thia of MSIG Duto Time 08/01/2018@10-39am
To inspect Vent Workshop	st TP RES / OD RES / EVA / ENV / MV / CS  ethicle No: WC 4796 y Insured: Ponc / A  Insured: Ponc / A  Surgai Kadut Strut 1  Surgai Kadut Strut 1
Policy No: F Sum Insured: Make of Veh	8 2862 6097 MKC Claim No: 541659  Excess: \$2,000-00
	1) REP. / REV 24 HRS  11:13am Oorloi)   Person Contracted: Mr. Wong Vehicle IN OUT
Date/Time	WC4796Y-X
	Surveyor ple check marked value & rebote to defermine wither vehicle is economical to repair. Ple check Brake system tyrus conditions and steering wheel system if thy are in efficient conditions, as our insured indicated that the steering wheel was locked and unable to shift to right. And also Request for Survicing Records.

360

TOTAL

". Velicle WC 4796Y MS14-00 DOA: 15/12/17

11/01/18@10,720 venert to Catherine Then via Meines. (pending setting vectory vector from opinion).
07/2/18@11,3700 venert to catherine This on menimen.

07/3/18 0 3,44p. Huey Ni informed C/A va Meinen.

18/3/18 @ 1.17m informed Donald C/A & Ex \$5000 by reunil.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

MSI	G INSURANCE (S	INGAPORE) PTE LTD	Ref : CS/MSG18000	0391/Sqd3				
	RAFFLES QUAY -01 HONG LEONG	BLDG SINGAPORE 048581	Date: 08-01-2018 Code: MSG					
1.		Policy Particul	ars :- OWN DAMAGE					
	Insured Veh.		Veh. Inspected	WC 4796Y				
	Policy No.	B28626097MKC	Coverage (\$)	0.00				
	Claim No.	541659	Excess (\$)	2,000.00				
	Assign From	MERIMEN (CATHERINE THIA)	Assign Date	08/01/2018				
2.		Vehicle Parti	culars & Condition					
	Make & Model		c.c	0				
	Engine No.	HIDDEN	Year of Reg.					
	Chassis No.		Colour					
	Odometer		Steering					
	Brakes		Modification					
	General							
3.		Conditi	ions of Tyres					
		Size	Make	Balance				
	R/H Front Tyre			mm				
	L/H Front Tyre			mm				
	R/H Rear Tyre			mm				
	L/H Rear Tyre			mm				
4.		Descripti	on of Damages	del centro de la companya del c				
5.	The majorates of	Genera	I Information					
	Accident Date	15/12/2017	Inspection Date	08/01/2018				
	Survey held at Repairer	42A SUNGAI KADUT STREET SAMWOH CORPORATION PTE		environme messon del				
5a.	The second	R	emarks					
	A)THE MARKET V	ALUE IS S\$(EST. AVER.	AGE)	NEW PROPERTY.				
	B)IN ACCORDANG	CE TO YOUR INSTRUCTIONS, W	E HAVE AUTHORISED R	EPAIRS.				

# ...CLAIM SUBFOLDER...(New Assignment)

AIM SUB	FOLDER TRACK		The Addison	Agr Rei		Add Submitted	Ins with as	Status				
Main	18 Dec 2017	Est Submitted	08 Jan 2018 10:39 Assign	100				New Assignment Cancel Case				
Main		Refere	nce	CI	aim Detail	s	Documents	Show All				
		ATLE	-				[Created by	insurer]				
CLAIM S Insured:	UBFOLDER DET	SAMWOH RE	ADY MIX PTE	LTD, Co		200409069N	15/12/2017 1	0:00 - :59				
Vehicle Re	eg. No.:	WC4796Y			Date of Lo		B28626097M	KC (Comprehensive)				
Claim Typ	e:	OD / 54165	59		Policy/Cov	ver Note No.:	Coverage: 17	Coverage: 17/11/2017 - 16/11/2018				
			Excess: 5\$2,000.00									
Repairer:		Samwoh Cor	Samwoh Corporation Pte Ltd (HQ) 25E Sungei Kadut Street 1, 729333 Sungei Kadut - Tel: 6269 7288  MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 [Handled by Catherine Thia Shi Yi									
Handling	Insurer:		- 6594 2545]  LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 [Imm.Advice due 09/01/2018]  RENGAN KARUPPAIAH (34 / Maie), NRIC: G6731692X, Tel: +6593709330									
Adjuster:		LKK Auto Co										
Driver/Cu	istodian:							ebates to determine inditions and also the				
Adj Asg.	Remarks:	whether the	vehicle is econor	mical to r	epair, rieas Micient con	ditions as our ins	ke system, tyres co ured indicated that records. Thank you	the steering wheel was				
ASSOCI	ATED MAIL REC	EIVED					View.	All   Compose Case Mail				
There are	e no mail for this	case.										
	SOCIATED TAS					View All	Search Tasks   Cres	ate New Task   Complete				
	SOCTATED TASK	(5					AND THE RESERVE OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUM	Created On Done				

## Vimmala D/O Raja Singam

From:

Adeline Lee <adeline.lee@lchlockton.com.sg>

Sent:

Monday, 8 January, 2018 9:47 AM

To:

Eng Huey Ni

Cc:

Lynn Wee; Vimmala D/O Raja Singam

Subject:

RE: Accident involving WC4796Y at Woodland Avenue 5 on 15 December 2017 (hit onto

tree) (17075)

Attachments:

WC4796Y Quotation.pdf

Dear Huey Ni

Please see attached for your further action.

The damaged vehicle is now at Samwoh's workshop at 42A Sungel Kadut Street 1, Singapore 729347 and please contact the following PIC to conduct survey:-

Mr. Wong Kok Fu - 9827 0155 Mr. Jou Chung Fat - 96444018

Best Regards Adeline Lee LCH Lockton Pte Ltd Insurance Brokers and Consultants No. 6 Raffles Quay #22-00 Singapore 048580 DID: (+65) 6439 4166

Tel: (+65) 6221 3366, Fax: (+65) 6220 9497 Email: adeline.lee@lchlockton.com.sg

From: Adeline Lee

Sent: Tuesday, 2 January 2018 1:18 PM

To: 'Eng Huey Ni' <HueyNi\_Eng@sg.msig-asia.com>

Cc: Lynn Wee <lynn.wee@lchlockton.com.sg>; Vimmala D/O Raja Singam <vimmala\_rajasingam@sg.msig-asia.com> Subject: RE: Accident involving WC4796Y at Woodland Avenue 5 on 15 December 2017 (hit onto tree) (17075)

Dear Huey Ni

Note your advice. We will inform Samwoh on the same.

Best Regards Adeline Lee LCH Lockton Pte Ltd Insurance Brokers and Consultants No. 6 Raffles Quay #22-00 Singapore 048580 DID: (+65) 6439 4166

Tel: (+65) 6221 3366, Fax: (+65) 6220 9497 Email: adeline.lee@lchlockton.com.sg

From: Eng Huey Ni [mailto:HueyNi Eng@sg.msig-asia.com]

Sent: Tuesday, 2 January 2018 12:10 PM

To: Adeline Lee <adeline.lee@lchlockton.com.sg>

Cc: Lynn Wee < <a href="mailto:lynn.wee@lchlockton.com.sg">lynn.wee@lchlockton.com.sg</a>; Vimmala D/O Raja Singam < <a href="mailto:vimmala-rajasingam@sg.msig-asia.com">vimmala-rajasingam@sg.msig-asia.com</a> Subject: RE: Accident involving WC4796Y at Woodland Avenue 5 on 15 December 2017 (hit onto tree) (17075)

### WITHOUT PREJUDICE

Our Ref: M541659

Hi Adeline.

Thanks for taking my call.

Cynthia has left our company. My colleague Mala and I are the officer-in-charge for this case.

Please advise the workshop personnel to put up estimate (based on visible damages) and forward a copy to us before our surveyor go down to survey. Any internal parts can put up later as supplementary.

Huey Ni

From: Adeline Lee [mailto:adeline.lee@lchlockton.com.sg]

Sent: Tuesday, 2 January 2018 11:59 AM

To: Cynthia Tan < cynthia tan@sg.msig-asia.com>

Cc: Lynn Wee < <a href="mailto:lynn.wee@lchlockton.com.sg">lynn.wee@lchlockton.com.sg</a>; Eng Huey Ni <a href="mailto:hueyNi Eng@sg.msig-asia.com">hueyNi Eng@sg.msig-asia.com</a>

Subject: RE: Accident involving WC4796Y at Woodland Avenue 5 on 15 December 2017 (hit onto tree) (17075)

Dear Cynthia

Have your surveyor contacted the workshop's PIC to conduct survey? Please advise status.

Best Regards Adeline Lee LCH Lockton Pte Ltd Insurance Brokers and Consultants No. 6 Raffles Quay #22-00 Singapore 048580

DID: (+65) 6439 4166 Tel : (+65) 6221 3366 , Fax : (+65) 6220 9497 Email: adeline.lee@lchlockton.com.sg

From: Joyce Poh

Sent: Friday, 22 December 2017 2:32 PM

To: cynthia tan@SG.msig-asia.com; Adeline Lee <adeline.lee@Ichlockton.com.sg>

Cc: Lynn Wee < lynn.wee@lchlockton.com.sg>

Subject: FW: Accident involving WC4796Y at Woodland Avenue 5 on 15 December 2017 (hit onto tree) (17075)

Dear Cynthia

Append below advice for your attention.

Please assist.

Thanks & Best Regards Joyce Pah

From: Donald Jesus Molina Go [mailto:donald.go@samwoh.com.sg]

Sent: Friday, December 22, 2017 12:00 PM To: Joyce Poh < joyce.poh@lchlockton.com.sg>

Cc: Lynn Wee < <a href="mailto:lynn.wee@lchlockton.com.sg">lynn.wee@lchlockton.com.sg</a>; Insurance Dept <a href="mailto:grp.lnsurance@samwoh.com.sg">grp.lnsurance@samwoh.com.sg</a>; Adeline Lee

<adeline.lee@lchlockton.com.sg>

Subject: Re: Accident involving WC4796Y at Woodland Avenue 5 on 15 December 2017 (hit onto tree) (17075)

Dear Ms. Joyce,

As per conversation, we would like to request for survey pending our repair quotation because our workshop is the midst of preparing quotation of damage parts.

The subject vehicle is now at our workshop at 42A Sungel Kadut Street 1, Singapore 729347.

Contact person;

Mr. Wong Kok Fu - 9827 0155 Mr. Jou Chung Fat - 96444018

Best regards, Donald Best Regards, Donald DID 63652639 HP 93819627

On Wed, Dec 20, 2017 at 5:27 PM, Adeline Lee <adeline.lee@lchlockton.com.sg> wrote:

Dear Donald

Received the IDAC & police report . We shall forward the same to MSIG

Look forward to receiving the estd repair cost.

Best Regards

Adeline Lee LCH Lockton Pte Ltd Insurance Brokers and Consultants No. 6 Raffles Quay #22-00 Singapore 048580

DID: (+65) 6439 4166

Tel: (+65) 6221 3366 , Fax: (+65) 6220 9497 Email: adeline.lee@lchlockton.com.sg

From: Donald Jesus Molina Go [mailto:donald.go@samwoh.com.sg]

Sent: Wednesday, 20 December 2017 4:20 PM
To: Adeline Lee <a href="mailto:adeline.lee@lchlockton.com.sg">adeline.lee@lchlockton.com.sg</a>

Cc: Lynn Wee < <a href="mailto:lynn.wee@lchlockton.com.sg">lynn Wee &lt; lynn.wee@lchlockton.com.sg</a> ; Insurance Dept < <a href="mailto:grp.lnsurance@samwoh.com.sg">grp.lnsurance@samwoh.com.sg</a> Subject: Accident involving WC4796Y at Woodland Avenue 5 on 15 December 2017 (hit onto tree) (17075)
Dear Ms. Adeline Lee,
Attached please find our idac report and police report.
Kindly inform MSIG that we are pending for repair quotation.
Best regards,
Donald
DID 63652639
On Mon, Dec 18, 2017 at 10:41 AM, Adeline Lee <a deline.lee@lchlockton.com.sg=""> wrote:</a>
Dear Donald
We refer to the above accident.
Please note MSIG reply which is self-explanatory for your necessary action.
Best Regards
Adeline Lee LCH Lockton Pte Ltd
Insurance Brokers and Consultants
No. 6 Raffles Quay #22-00 Singapore 048580
DID: (+65) 6439 4166
Tel: (+65) 6221 3366 , Fax: (+65) 6220 9497 Email: adeline.lee@lchlockton.com.sg

From: Eng Huey Ni [mailto: <u>HueyNi Eng@sg.msig-asia.com</u> ]  Sent: Monday, 18 December 2017 10:19 AM  To: Adeline Lee < <u>adeline.lee@lchlockton.com.sg</u> >  Cc: Vimmala D/O Raja Singam < <u>vimmala rajasingam@sg.msig-asia.com</u> >  Subject: RE: Accident involving WC4796Y at Woodland Avenue 5 on 15 December 2017 (hit onto tree) (17075)
Subject: RE: Accident involving WC4/96Y at Woodland Avenue 3
Hi Adeline,
Thanks for taking my call just. Some amendment on the email below.
We will still require the accident report to be filed at IDAC so that there is a record of this accident and the accident report in the Merimen Database.
Strictly on a special case basis, we will allow the reporting at IDAC without the vehicle. Please request your driver to bring along the necessary documents (e.g. police report, driving license, certificate of insurance). If he/she encounter any problem during reporting, please get the IDAC personnel to call me or Mala for approval to do reporting w/o vehicle.
We await the IDAC report + police report and the estimate before we assign the case to our surveyor. We note your request to get the appointed surveyor to liase with Donald at his DID 63652639 or HP 93819627 on the survey.
Thank you.
Huey Ni
From: Vimmala D/O Raja Singam Sent: Monday, 18 December 2017 10:06 AM To: Adeline Lee <a href="mailto:adeline.lee@lchlockton.com.sg">adeline.lee@lchlockton.com.sg</a> Cc: Eng Huey Ni <a href="mailto:HueyNi Eng@sg.msig-asia.com">HueyNi Eng@sg.msig-asia.com</a> Subject: RE: Accident involving WC4796Y at Woodland Avenue 5 on 15 December 2017 (hit onto tree) (17075)
Hi Adeline,
Thank you for the email.

# MEGASTONE

## HOLDINGS PTE LTD

REPAIR & REGISTER FORM

AMM-	PR: 13288	
100	PR: /730	
1-	PR:	
	PR:	

108RT 42A WORKSHOP

Project/ Cost Centre: w(4796 Vehicle/ Machinery No.:

Date/Time In: 4/2/17

Engine System/ Transmission System/ Gear Box System/ PTO System/ Clutch System/ Brake System Electrical Systeme / Wire System/ Fuel System/ Steering System/ Undercarriage System/ Air System

Aircon System Servicing Oil Cabin/ Bucket/ Bodywork/ Paintwork/ Speed Limiter/ LTA Inspection Accident Repair/ Insurance Claim/ Claim Third Party/ Hit to Third Party Vehicle Check Check Remarks Replace Replace 0 /fpx Center Hub Bolt/ Oil Seal/ Air Front/ 2nd/ King Pin/ Oil Overhaul Engine/ Oil Leak/ Hose Seal/ Hub Bolt/ Air Hose Excretive Engine Oil Consumption/ Overheat Brake Pump/ Lining/ Drum/ Brake Pump/ Lining/ Drum/ Top-Overhaul Engine/ No Brg Outer/ Inner/ LH/RH Brg Outer/ Inner/ LH/ RH Power/ Overheat Rear Hub Bolt/ Oil Seal/ Air Overhaul Center Gear Box/ Engine Mounting/ Gear Box Rear Gear Box/ Speed Box/ Mounting/ Bracket Support Diff Seal/ PTO Gear Box/ Brake Pump/ Lining/ Drum/ Fuel Pump/ Injector/ Turbo-Hi/Low Wiring Brg Outer/Inner/LH/RH Charge/ Fuel Hose Rear Leaf Spring/ U Bolt/ Front/ 2nd/ Absorrber/ Leaf Timing Belt/ Idle Bearing/ Air Center Bolt/ Torque Bush/ Spring/ U Balt/ Center Balt/ Con Pulley/ Water Pump Trunnion Shast/ Bush/ Bolt/ Pin/ Bush LH/RH LH/MH) Gearshuft Gear Lever/ Cable/ Drag Link/ 2nd/ Tie Rod End/ Top-Fan Clutch Oil/ Fan Ball Joint Ball Joint Plate/ Fan/ Air Con Belt Mixer Drum/ Cable/ Roller/ Pro Shaft/ PTO Shaft/ Radiator Core/ Flushing/ PTO Shaft/ Coupling Coupling/ Front/ Rear Spare Water Tank Battery/ Batter Water/ Brake 16 Wiring System/ Lighting Up/ Lower/ Bottom/ Pass/ L/ System/ Wind Motor Hose/ Pipe / Coolant Battery Charging Condition Air System/ Air valve/ Air Dryer/ Pedal Valve/ Kit Cabin Absorber/ Absorber Air Spring Mounting/ Coil Spring/ Actuator Valve/ Stopper/ Cylinder Kit/ Driver Seat/ Seat Fuel Tank/ Bleed Air Out of Fuel System/ Clean Fuel Line System/ Washer (Lack of Fuel, Top Fuel/ Fuel With Water Clogged/ Fuel Dirty) Clutch Disc( ) Cover( ) Bearing( ) Grease Hose( ) Flywheel/ Seal( ) Shaft/ Bush( Clutch Master Pump( ) Clutch Booster Pump( ) (Used IMPROPER/ WEAR, TEAR) Servicing/ Engine Oii(36L) Speed Box Oil(40L) Gear Oil(40L) Hyd Motor Oil(5L) Air Filter( | ) Oil Filter( 1 ) Gas Filter( ) T/M Gear Oil( | ) Fuel Filter( ) Hyd Filter( | ) Ad-blue Filter( ) LTA[ ] STA[ ] VICOM( ) JIC( ) IU( ) Black Smoke( ) Inspection( ) Wiring System( Light System( ) Wheel Alignment( ) General Services( Remark: Borrich \$ pcs/\$ ) Grease Nipple( | Greasing(S) Top Up: Bearing Grease:(5 \$ ) Fuse( pcs/5 pcs/S pcs/\$ Bulb( ) H3/H7( Supply Materials: H4( pcs/\$ \$ ) Mudguard Rubber/Bolt( Set/5 Air Tubel ) Connector( pcs/\$ \$ ) Battery Cable( FT/S pcs/S ) Hose Clip( FT/8 Fuel Hose( 5 ) Fire Extinguisher ABC DRY 1KG( ) Wirel Battery Clampl pcs/\$ 5 ) Green Sticker( No Smoking Sticker( ) Max 60km/ 30km/H Sticker( TRANSPORATION TRIP: Date/ Time In, Out: 7/2 ŝ Price Hour Man WORKING HOUR (On Site) Date/ Time In, Out: y S Price 2 Hour WORKING HOUR (42A) Date/ Time In, Out: (74) Total: \$ Serviced By Person in-Charge Name: Kiat, BC, Hock, Das, Shiang, Diao, Ng, SYK Contact Number: Murugesan, Prasath, Rana, Jwule, BACK CHARGE: DRIVER MUST WAIT AT RESTING AREA, NO LOITERING ALLOW IN WORKSHOP AREA.

司机必须在休息区等待,禁止在车间僻离。

# MEGASTONE

HOLDINGS PTE LTD

3	ᆫ	D	1	N	ы	0		_	,	_	_	•		
F	RΕ	P	A	IR	&	R	E	G	IS	TE	R	F	ORM	

10	PR:	
FIL	PR:	14668
	PR:	

108RT 42A WORKSHO	A WORKS	101
-------------------	---------	-----

Date / Time In: 3/ 710 Project / Cost Centre Km/h : / 7 7 58 W 4196 Vehicle / Machinery No :

Engine System / Transmission System / Gear Box System / PTO System / Clutch System / Brake System Electrical Systeme / Wire System / Fuel System / Steering System / Under Carriage System / Air System

	Adj/ Check/	rplace	Remarks	Claim Third Party / H	Ady/ Check/ Repair	Prplace	Remarks		Adj/ Check/	Prplace	Remarks
erhaul Engine / Oil Leak / cretive Engine Oil		4	<u>~</u>	Front / 2nd / King Pin / Oil Seal / Hub Bolt / Air Hose				Center Hub Bolt / Oil Seal / Air Hose			
onsumption / Overheat op-Overhaul Engine / No	Ď			Brake Pump / Lining / Drum / Brg Outer / Inner /	1			Brake Pump / Lining / Drum / Brg Outer / Inner / LH/RH			
wer / Oveheat gine Mounting / Goar Box ounting / Bracket Support el Pump / Injector / Torbo	V			Overhaul Center Gear Box / Rear Gear Box / Speed / Diff Seal / Pto Gear Box / HI / Low Wireing			×	Rear Hub Bolt / Oil Seal / Air Hose Brake Pump / Lining Drum / Brg Outer / Inner (LHRH			
Fuel Hose  G Bet / Mile Bearing / Con Puby / Water Pump Fan clutch oil / Fan	/			Front / 2nd /Absorber / Leaf Spring / U Bolt / / Pin / Bush LH/RH	V			Rear Leaf Spring (D Bolt / Center Bolt / Corque Bush / Trunnion Shast / Bush / Bolt / LH/RH			
Fam / Air Con Belt Same Core / Flushing /	V		1	Drag Link / 2nd / Tie Rod End / Ball Joint				Gearshift Gear Lever / Cable / Ball Joint	V		_
p / Lower / Bottom / Pass	1			Pro Shaft / Pto Shaft / Coupling / Front / Rear	V			Mixer Drum / Cable / Roller / PTO Shaft / Coupling	1		_
I Hose ! Pipe / Coolant ir System /Air Valve / Air ryer / Pedal Valve / Kit	1	1		Wireing System / Lighting System / Wing Motor g / Coil Spring / Actuator Va	M			Battery / Battery Water / Brake Fluid		$\vee$	4L
existing / Engine Oil /	35 L	Spee	d Box	h Booster Pump ( ) ( Oil ( L ) Gear Oil ( ( ) T/M Gear Oil (	L) Fuel F	lyd Mo ilter (	2,11	Hyd Filter ( )	-	V	ok
ervicing / Engine Oil ( ir Filter ( ) Oil Filte	35 L)	Spee ) Gas JIC(	d Box Filter	Oil () Gear Oil () T/M Gear Oil () Black Smoke () ins) General Services (	L) Fuel F	lyd Mo ilter (	2,11	Hyd Filter ( )		V	ok
tir Filter ( ) Oil Filte TA( ) STA( ) VICOI htting System ( )	Besi H4 Air Ba	Spee ) Gas JIC( Aligni aring ( Tube of Hos	Grease ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( )	Oil () Gear Oil () T/M Gear Oil () Black Smoke () Ins. ) General Services (	L) Fuel F pection )  Bulb ( ) Mudgu cs /\$ ) Fire E	Great ,pcs ,ard Ri ) Ba	wiring se Nip se Nip ttery (	Hyd Filter ( ) g System ( )	\$ \$ \$ \$ \$		ok.
revising / Engine Oil () ir Filter ( ) Oil Filte TA( ) STA( ) VICON htting System ( ) ixs:  Y ] - 5  Top-Up: Supply Materials:	Besi H4 Air Ba	Spee ) Gas JIC( Aligni aring ( Tube of Hos	Grease ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( )	Oil () Gear Oil ()  (	L) Fuel F pection )  Bulb ( ) Mudgu cs /\$ ) Fire E km/h St	Great .pcs / ard R: ) Ba ktingu	wiring se Nip se Nip stery ( disher	Hyd Filter ( )  System ( )  Ple ( pcs /\$ )  Fuse ( pcs /\$ )  / Bolt ( Set /\$ )  Cable ( FT/\$ )  ABC DRY 1KG ( )  Green Sticker ( )	\$ \$ \$ \$ \$		ok.
revising / Engine Oil () in Filter ( ) Oil Filte TA( ) STA( ) VICON htting System ( ) in State   Y ] - S  Top-Up: Supply Materials:	Bea H4 Air Fui Ba	Spee ) Gas JIC( Aligni ( po Tube of Hos Smol	Grease ( ) se ( Clamp	Oil () Gear Oil () T/M Gear Oil ()  Black Smoke () Ins. ) General Services (	L) Fuel F pection )  Bulb (   Mudgu cs /\$ ) Fire E km/h St TRIP:	Great ,pcs ( and Ri ) Ba ktinguicker (	wiring se Nip se Nip stery ( disher	Hyd Filter ( )  System ( )  Ple ( pcs /\$ )  Fuse ( pcs /\$ )  / Bolt ( Set /\$ )  Cable ( FT/\$ )  ABC DRY 1KG ( )  Green Sticker ( )	\$ \$ \$ \$ \$ \$		ok.
revicing / Engine Oil (, ir Filter ( ) Oil Filter TA( ) STA( ) VICON (htting System ( )) ks :  Y ] - 5	Best H4 Air Full Bar	Spee ) Gas JIC( Aligni  Aligni  Tube titery ( Smol	Grease ( ) se ( Clamp	Oil () Gear Oil () T/M Gear Oil ()  Black Smoke () Ins. ) General Services (	L) Fuel F pection ) Bulb ( ) Mudgu cs /\$ ) Fire E km/h St TRIP: On Site	Great ,pcs and Ri ) Ba ktinguicker (	wiring se Nip se Nip subber ttery ( sisher )	Hyd Filter ( )  System ( )  Ple ( pcs /\$ )  Fuse ( pcs /\$ )  / Bolt ( Set /\$ )  Cable ( FT/\$ )  ABC DRY 1KG ( )  Green Sticker ( )  Hour Price	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$		ok.
revising / Engine Oil () in Filter ( ) Oil Filte TA( ) STA( ) VICON htting System ( ) in State   Y ] - S  Top-Up: Supply Materials:  Date/Time In,Out: //3	Bear H4 Air Full Bar No	Spee ) Gas JIC( Aligni  Aligni  Tube titery ( Smol	Grease ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( )	Oil () Gear Oil () T/M Gear Oil ()  Black Smoke () Ins. ) General Services (	L) Fuel F pection )  Bulb ( ) Mudgu cs /\$ ) Fire E km/h St TRIP: On Site 42A)	Great .pcs and Ri ) Ba ktinguicker (	wiring se Nip se Nip subber ttery ( sisher )	Hyd Filter ( )  System ( )  Ple ( pcs /\$ )  Fuse ( pcs /\$ )  / Bolt ( Set /\$ )  Cable ( FT/\$ )  ABC DRY 1KG ( )  Green Sticker ( )  Hour Price	s tal s	iao	ok.


# MEGASTONE HOLDINGS PTE LTD

# Megastone Holdings Pte Ltd









26th January 2018

MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way, #21-01, SGX Centre 2 Singapore 068807

MSIG claim reference: 541659

Attention: Motor Claims Department

Dear Sir/ Madam,

Quotation to supply labour, parts, necessary equipment and tools for the repair of WC4796Y.

Description	Qty	U/Price	Total Price
Front panel	1 pc		
Front windscreen glass	1 pc		
Front windscreen rubber	1 pc		
Front panel lock	2 pcs		
Front panel grille	1 pc		
Front wiper panel	1 pc		
Front wiper arm	1 pc		
Front wiper blade	1 pc		
Front bumper	1 pc		
Front bumper bracket	1 pc		
Front headlamp LH	1 pc		
Front side lamp	1 pc		
Front fog lamp front bumper grille	1 pc		
Air con coil	1 pc		
Air con blower	1 pc		
Front cabin bracket	1 pc		
Front cabin cross member	1 pc		
Front radiator	1 pc		
Inter cooler	1 pc		
Fan blade	1 pc		
Fan cover	1 pc		
Fan bracket	1 pc		
Front center panel	1 pc		
Labour Charge			
To remove & refix engine and gear box	1 job		-
To R&R air con system, top up air con gas	1 job		+
To repair & remove front cabin damaged parts	1 job		
To remove & refix front radiator and inter cooler	1 job		
To remove & refix front axle	1 job		
To putty & spray painting	1 job		

To remove & refix front windscreen glass	1 job		
To remove a remaind it will assist gross		Total cost:	\$35,000.00
		7% GST	\$2,450.00
		Grand Total	\$ 37'450.00

Thanks,

Jou Chung Fat Workshop In-charge We will approve for not reporting at the IDAC centre since the vehicle is badly damage.

Please inform our insured to forward us a copy of the police report and the estimate before we arrange for survey.

Thank you.

### Mala (Ms)

Senior Admin Officer, Claims Services (Motor)

Direct line +65 6594 2471 | Direct fax +65 6225 7402 | vimmala\_rajasingam@sg.msig-asia.com





MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | http://www.msig.com.sg/ | Follow us

A member of MS&AD INSURANCE GROUP

This message, and any associated files, is intended only for use of the individual or entity to whom it is addressed and contain information that is privileged and confidential, subject to copyright or constitutes a trade secret. If you are not the intended recipient you are hereby notified that any dissemination, copying or distribution of this message, or files associated with this message, is strictly prohibited. If you have received this message in error, please notify us immediately by return e-mail and delete the original message.

If you are providing us with Personal Information and Data, or for more information about how we handle Personal Information and Data, please see our Privacy Policy and Notice at http://www.lchlockton.com.sg/privacypolicy-and-notice

Best Regards,

Donald Go

Administrator

DID 63652639

HP 93819627

This message, and any associated files, is intended only for use of the individual or entity to whom it is addressed and contain information that is privileged and confidential, subject to copyright or constitutes a trade secret. If you are not the intended recipient you are hereby notified that any dissemination, copying or distribution of this message, or files associated with this message, is strictly prohibited. If you have received this message in error, please notify us immediately by return e-mail and delete the original message.

If you are providing us with Personal Information and Data, or for more information about how we handle Personal Information and Data, please see our Privacy Policy and Notice at http://www.lchlockton.com.sg/privacy-policyand-notice

Best Regards, Donald Go Administrator DID 63652639 HP 93819627

This message, and any associated files, is intended only for use of the individual or entity to whom it is addressed and contain information that is privileged and confidential, subject to copyright or constitutes a trade secret. If you are not the intended recipient you are hereby notified that any dissemination, copying or distribution of this message, or files associated with this message, is strictly prohibited. If you have received this message in error, please notify us immediately by return e-mail and delete the original message.

If you are providing us with Personal Information and Data, or for more information about how we handle Personal Information and Data, please see our Privacy Policy and Notice at http://www.lchlockton.com.sg/privacy-policy-and-notice

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a warver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

This message, and any associated files, is intended only for use of the individual or entity to whom it is addressed and contain information that is privileged and confidential, subject to copyright or constitutes a trade secret. If you are not the intended recipient you are hereby notified that any dissemination, copying or distribution of this message, or files associated with this message, is strictly prohibited. If you have received this message in error, please notify us immediately by return e-mail and delete the original message.

If you are providing us with Personal Information and Data, or for more information about how we handle

Personal Information and Data, please see our Privacy Policy and Notice at http://www.lchlockton.com.sg/privacy-policy-and-notice

From:

Donald Jesus Molina Go <donald.go@samwoh.com.sg>

Sent:

Thursday, 12 July 2018 2:36 PM

To:

Shiau Chan (LKKAuto)

Cc:

Insurance Dept; Wong Kok Fu; SUR

Subject:

Re: Request for document (WC4796Y) Service record

Dear Shiau Chan,

Kindly inform MSIG that we will accept the lump sum settlement. We will issue invoice as follows:

 Being Lump Sum Repair Cost
 \$ 21,100.00

 Less: Policy Excess
 \$ 2,000.00

 Sub Total
 \$ 19,100.00

 Plus: 7% GST
 \$ 1,337.00

 Grand Total
 \$ 20,437.00

Kindly request cheque to MEGASTONE HOLDINGS PTE LTD

Best regards, Donald

On Fri, Jun 29, 2018 at 12:09 PM, Shiau Chan (LKKAuto) <siewsc@lkkauto.com> wrote:

Dear Donald,

Can we confirm repair cost at Lump Sum \$21,100.00 before excess \$2,000.00 & GST?

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)

Sent: Monday, 4 June 2018 4:06 PM

To: Donald Jesus Molina Go <donald.go@samwoh.com.sg>

-				
ъ.	rn	m	٠.	

Donald Jesus Molina Go <donald.go@samwoh.com.sg>

Sent:

Monday, 7 May 2018 1:37 PM

To:

Shiau Chan (LKKAuto)

Cc:

Sebastian Yeang (LKK Auto); Insurance Dept; Wong Kok Fu; SUR

Subject:

Re: Request for document (WC4796Y) Service record

Attachments:

20180116\_133940.jpg; 20180116\_133958.jpg; SAM\_3409.JPG

Dear Shiau Chan,

We wish to highlight with you the cost we incur which is not included in your first offer.

1. Aircon Blower	. \$501.00
2. Fan Blade	\$ 800.00
3. Fan Cover	
4 Fan Bracket	\$ 150.00

I attached some of the photographs.

Kindly let us have your breakdown for parts and labour.

Thanks, Donald DID 63652639

On Mon, May 7, 2018 at 11:44 AM, Shiau Chan (LKKAuto) < siewsc@lkkauto.com > wrote:

Dear Donald,

Offer Lump Sum \$19,900.00 before excess \$2,000.00 & GST.

Kindly confirm.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

From:

Shiau Chan (LKKAuto)

Sent:

Thursday, 8 March 2018 9:17 AM

To:

Donald Jesus Molina Go; Sebastian Yeang (LKK Auto)

Ce

Insurance Dept; Wong Kok Fu; SUR

Subject:

RE: Request for document (WC4796Y) Service record

Dear Donald,

As instructed by our client MSIG Insurance, please proceed to repair the insured vehicle WC4796Y (excess \$2,000/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

#### LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)

Sent: Wednesday, 7 March 2018 11:30 AM

To: Donald Jesus Molina Go <donald.go@samwoh.com.sg>; Sebastian Yeang (LKK Auto)

<SebastianYeang@lkkauto.com>

Cc: Insurance Dept <grp.Insurance@samwoh.com.sg>; Wong Kok Fu <kokfu.wong@megastone.com.sg>; SUR

<sur@lkkauto.com>

Subject: RE: Request for document (WC4796Y) Service record

Dear Donald,

Please find the attached of our surveyor's marking estimate.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Donald Jesus Molina Go [mailto:donald.go@samwoh.com.sg]

Sent: Thursday, 1 March 2018 5:37 PM

To: Shiau Chan (LKKAuto) < siewsc@lkkauto.com >; Sebastian Yeang (LKK Auto) < Sebastian Yeang@lkkauto.com >

Cc: Insurance Dept <grp.Insurance@samwoh.com.sg>; Wong Kok Fu <kokfu.wong@megastone.com.sg>; SUR

<sur@lkkauto.com>

Subject: Re: Request for document (WC4796Y) Service record

Dear Shiau and Sebastian,

## Claim Audit

-	On	Audit	Remarks	Ву
No.		Cim Veh Model		[I] Pang Xio
1	20 Dec 2017 14:25	Changed Changed	(201615) ISUZU CYH52S 15.7 D (M).	Shi
2	20 Dec 2017 14:25	Clm Created	Reg No: WC4796Y. Policy No: B28626097MKC. Acct Date: 2017/12/15. Claim T ype: SC. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Ins.Status => N otification. Created from SAS:MVA117166176	[I] Pang Xii Shi
3	08 Jan 2018 10:19	Notification Status Changed	Ins.Status => Incoming Claim	[I] Vimmali D/Ö Raja Singam
4	08 Jan 2018 10:19	Clm Registration Modified	Seti.Type:3->0. Rep:1137->200544. Claim Type:SC->OD. Init.Est.:->20,000 - 25,000.	[I] Vimmal D/O Raja Singam
5	08 Jan 2018 10:20	Clm Registration Modified	Excess: -> 2000.00.	[I] Vimmal D/O Raja Singam
6	08 Jan 2018 10:25	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor): Please revert first. S urveyor, please check on the market value and rebates to determine whether t he vehicle is economical to repair. Thank you.	[1] Vimmal D/O Raja Singam
7	08 Jan 2018 10:25	Adj Next Rpt Changed	Next Rpt:Im. Advice,Due Date:2018/01/09	[I] Vimmal D/O Raja Singam
8	08 Jan 2018 10:25	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Vimmal D/O Raja Singam
9	08 Jan 2018 10:31	Assignment 1st Accessed		[A] Ho Pei Fang
10	08 Jan 2018 10:33	Adj Assignment Cancelled	IHS APPT FULL	[I] Vimmali D/O Raja Singam
11	08 Jan 2018 10:33	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	<ul><li>[I] Vimmal</li><li>D/O Raja</li><li>Singam</li></ul>
12	08 Jan 2018 10:39	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Please revert and survey by today. Surveyo r, please check on the market value and rebates to determine whether the vehi cle is economical to repair. Please also check brake system, tyres conditions and also the steering wh	[I] Vimmali D/O Raja Singam
13	08 Jan 2018 10:39	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/01/09	[I] Vimmal D/O Raja Singam
14	08 Jan 2018 10:39	Adj Mandate Set	Approved:25000.00.Reinsp:AdJ decides.	[I] Vimmal D/O Raja Singam
15	08 Jan 2018 10:41	Assignment 1st Accessed		[A] CATHERINI CHONG KA LING
16	14:18	Adj Adjuster Assigned	[None] -> Sebastian Yeang Wal Keen	[A] Nivitha Govindasam
17	11 Jan 2018 09:58	Adj Rpt Initiated		[A] SHIAU CHAN
18	11 Jan 2018 10:07	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/02/07	[A] SHIAU CHAN
19	11 Jan 2018 10:07	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/07	[A] SHIAU CHAN
20	11 Jan 2018 10:32	Adj Mandate Request	Cur.Req:0.00:After undergoing the on site check, it is found that the steering d o not have any issue in turning. (please refer to the video DSCN2168). Howeve r, the brake is not functioning during the on site test. This is because the air ho se (air	[A] SHIAU CHAN
21	14 Feb 2018 09:20	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/07. Mandate Remarks: KIV update on re pair assessment	[I] NG CHE HOW
22	14 Feb 2018 09:20	Adj Mandate Set	Approved:0.00:KIV update on repair assessment	[I] NG CHE HOW
23	07 Mar 2018 11:31	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/02/07	[A] SHIAU CHAN
24	07 Mar 2019	Adj Mandate Request	Cur.Req:27553.60:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
25	07 Mar 2018 15:44	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/07. Mandate Remarks: check items (\$16 51) to be verified	[I] Eng Hue Ni
26	07 Mar 2018 15:44	Adj Mandate Set	Approved:25902.60:check items (\$1651) to be verified	[I] Eng Hue Ni

ACTIVITY

No record

1	Bill Rof No	11/01/2018	Acc Type	Acc Name  LKK Auto	Co Name (Branch) LKK Auto	Ref 1	100000	10.70
	1691762	09:58	Motor	Consultants Pte	Consultants Pte Ltd (HQ)	WC4796Y		10.70

#### Note: This document has not been finalised.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Vimmala D/O Raja Singam

Date: 07 Mar 2018

## Preliminary Advice

Vehicle No.

: WC4796Y

Accident Date

: 15/12/2017

Make

: ISUZU CYH52S

Policy No.

: B28626097MKC

Assignment Date

: 08/01/2018

Excess

:S\$

: \$\$2,000.00

Date of Inspection

: 08/01/2018

Est. Duration of Repair

: 12

Inspection At

: SAMWOH CORPORATION PTE LTD (HQ)

25E SUNGEI KADUT STREET 1

SINGAPORE 729333

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	36,303.60
Revised Amount	:S\$	25,902.60
Check Items (Estimated)	:S\$	1,651.00
Total	:S\$	27,553,60

Lump Sum Repair

#### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	60,000.00
COE / PARF Rebate	:S\$	14,259.00
Salvage Value	:S\$	
Margin for Repair	:S\$	45,741.00

#### Remarks

- ( X ) The vehicle is economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis. WE HAVE NOT AUTHORISE REPAIR.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Catherine Thia Shi Yi

Date: 11 Jan 2018

## Preliminary Advice

Vehicle No

: WC4796Y

Accident Date

: 15/12/2017

Make

: ISUZU CYH52S

Policy No. Excess

: B28626097MKC

Assignment Date

: 08/01/2018

: S\$2,000.00

Date of Inspection

: 08/01/2018

Est. Duration of Repair

: 0.00

Inspection At

: SAMWOH CORPORATION PTE LTD (HQ)

25E SUNGEI KADUT STREET 1

SINGAPORE 729333

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	NOT READY
Revised Amount	:S\$	0.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
(414)		

:S\$ Lump Sum Repair

### Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	60,000.00
COE / PARF Rebate	:S\$	14,259.00
Salvage Value	:S\$	
Margin for Repair	:S\$	45,741.00

### Remarks

The vehicle is economical/not economical for repair.

The above survey was conducted on a 'without prejudice' basis. (X)

> After undergoing the on site check, it is found that the steering do not have any issue in turning. (please refer to the video DSCN2168).

> However, the brake is not functioning during the on site test. This is because the air hose (air-brake) leaked and air is coming out. The leak high possibility is due to the collision with the tree. The leak can be seen at video "DSCN2173".

> The condition of the tyres were also in serviceable condition with a remaining tread depth of approximately 5mm each.

PENDING FOR ESTIMATE BREAKDOWN AND SERVICING RECORD FROM REPAIRER.

WE HAVE NOT AUTHORISE REPAIR.

From:

Shiau Chan (LKKAuto)

Sent:

Thursday, 11 January, 2018 10:29 AM

To:

Catherine Thia

Cc:

SUR

Subject:

RE: VEHICLE WC 4796Y (YOUR REF: 541659)

Attachments:

DSCN2173.mp4

Dear Catherine,

Attached with 2<sup>nd</sup> video.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)

Sent: Thursday, 11 January, 2018 10:26 AM

To: Catherine Thia <catherine\_thia@sg.msig-asia.com>

Cc: SUR <sur@lkkauto.com>

Subject: VEHICLE WC 4796Y (YOUR REF: 541659)

Dear Catherine Thia,

After undergoing the on site check, it is found that the steering do not have any issue in turning. (please refer to the video DSCN2168).

However, the brake is not functioning during the on site test. This is because the air hose (air-brake) leaked and air is coming out. The leak high possibility is due to the collision with the tree. The leak can be seen at video "DSCN2173".

The condition of the tyres were also in serviceable condition with a remaining tread depth of approximately 5mm each.

2<sup>nd</sup> email will follow up with 2<sup>nd</sup> video "DSCN2173".

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Dear

After undergoing the on site cleck, it is found that the steering to not have any issue in turning. (As shown in the viteo) "DSCAUZI68"

However, the brake is not functioning the during the on site text.

This is because the air hose (air brake) leaked and air is coming out. The leak to high possibility is due to the collision with the tree.

The leak can be seen at video DSCN2173"

# Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	9069N
Vehicle Details	
Vehicle No.:	WC4796Y
Vehicle to be Exported:	No
Intended De-registration Date:	09 Jan 2018
Vehicle Make:	ISUZU
Vehicle Model:	CYH52S
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	6WG1415487
Chassis No.:	JALCYH52SB7000178
Maximum Power Output:	
Open Market Value:	\$146,975.00
Original Registration Date:	17 Nov 2011
First Registration Date:	17 Nov 2011
Transfer Count:	0
Actual ARF Paid:	\$7,349.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	

16 Nov 2021
C - Goods Vehicle & Bus
10
\$37,011.00
\$14,259.00
\$14,259.00

The information contained herein is correct as at 09 Jan 2018

OK

1/8/2018 E-FILE

MVA117166176 / VAC - Bukit Batok ENTRY DATE & TIME: 18/12/2017 15:47

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation,
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

ACCIDENT STATEMENT

Date Of Report 18/12/2017 15:47 Date Of Accident 15/12/2017 10:15

Exact Location Of Accident WOODLANDS AVE 5 TO WOODLANDS AVE 12

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number WC4796Y

Insured/Policyholder

Name Of Registered Owner SAMWOH READY MIX PTE LTD

Co Reg No 20040906AN Email Address NOEMAIL

Mobile Phone No. (LOCAL) +65-93709330

Alternative Phone No. Office-93709330

Vehicle Particulars

Manufacturer VOLVO Model TRUCK

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken REPORTING ONLY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number B 28626097 MKC

Cover Note Number

Driver

Name of Driver RENGAN KARUPPAIAH

Work Permit No G6731692X Date Of Birth 15/07/1983 Occupation OUTDOOR Date Of Driving Pass 13/02/2015

Driving Experience 2 YEARS AND 10 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-93709330 1/8/2018 E-FILE

Fax Number

OFFICE-93709330 Contact Number

**EMail Address** NOFMAIL

51 KRANJI CRESCENT Address

#02-200 NORTH COAST LODGE

YES

Postcode S728661

Was driver an employee of the Insured's Company

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLIDED INTO PROPERTY

Weather Conditions CLEAR Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

Police Station Name WOODLANDS EAST N.P.C

ROAD: 3 WOODLANDS DRIVE 63, POSTCODE: 737890, COUNTRY: Police Station Address

SINGAPORE

NO

YES

NO

Police Station Contact TEL NO: - FAX NO:

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

PLEASE SEE ATTACHED POLICE REPORT. ATTENDED BY : SUSAN

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera? NO Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties TREE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**Details of Witness** 

Name

Phone Number

Email Address

### Sketch Plan

SKETCH PLAN	ACH -	NC 4796	У	D + Tic	r E
		12	-	_	
		0 10 111		011	1/3
				>	WOOD SLANDS
	<u></u> D				AUE + TOWARDS WODELAND AVE IL
					10190 100
			-	-	
DESCRIBE CIRCUMSTANCE	S OF THE ACCIDENT				
			-/-		
			/	-	
				/	
		-/-	19/		
		/	101		
	)	1	+		
		DIVO			
	/	20			
	/				
DECLARATION  VWe declare the foregoing par	siculars are true in every r	1 8 DEC 2	017 IDA	C BUKIT B	ATOK (VAC)
	R. Ka.	laint	Tel: Ema	Singapore 6560 3312 F ill vachb@si	ATOK (VAC) 9k Street 23 659545 9ax: 6569 0722 ngnet.com.sg

Policyholder's Signature Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time

Reporting Centre Personnel's Signature Name

NRIC/FIN No.

#### SKETCH PLAN

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, arknowledge, agree and consent that.

- My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
  - [1] processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claurs;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me:
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me. which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes"
- all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) any Personal Information will also be collected and used to compile claims history for the purpose of freud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (ii) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

1 8 DEC 2017

Policyholder's Signature Date & Time

Driver's Signature

If driver is not the policyholder)

Date & Time:

IDAC BUKIT BATOK (VAC) 511 Bukit Batok Street 23 Singapore 659545 Tel: 6560 3312 Fax: 6569 0722 Email: vacbb@singnet.com.sg

Reporting Centre Personnel's Signature

Name NURSE / FIN NO.





Police Station Of Origin: Woodlands East N.P.C. 3 Woodlands Drive 63 SINGAPORE 737890 Tel No: 1800-7679999

Report No. T/20171215/2117

REPORT	OF A	TRAFFIC	ACCIDENT
--------	------	---------	----------

Date/Time Report Made: 15/12/2017 17:12		Made:	Vide Report No.:	Station Diary No.:	
Intoletta	1000年2月1日	ulary 74 all of the	OF BUILDING SPECIAL PROPERTY OF THE PERSON NAMED IN SPECIAL PROPERTY OF THE PERSON NAM	NEW COLUMN TO THE PARTY OF THE	
Name of RENGA	Informant N KARUPP		Address:	200 NORTH COAST LODGE	
ID Type / ID No.: FIN NO / G6731692X			Contact No.: Hame/Office:	Mobile: 93709330	
National INDIAN	ity:		Email:		
Sex: Male	Age: 34	Date of Birth: 15/07/1983	Type of Informant:		
Race: Indian			Language: English	Institution / School Name:	
Occupation: Lorry driver			Driving Licence Information: Class: 2B,3,4 Date of Expiry:		

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 15/12/2017 10:	Type of Location: Straight Road	
WOODLAND WOODLAND Lamp Post N	Traveling Toward Road S AVENUE 5 S AVENUE 12 umber: 113	2			
01		Road Surface: Dry		Road Speed Limit:	
		Traffic Control: Traffic Light - Wo	orking •	Traffic Volume: No Traffic	
Type of Collis Moving Vehic	sion: de Against - Road Divide	r/Kerb/Railings		Anyone conveyed by ambulance: No	

	men nyews			
WC4796Y	Lorry		Slightly Damaged	0 -

Détalle : 1 Parson 6- pieter :	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA





Police Station Of Origin: Woodlands East N.P.C. 3 Woodlands Drive 63 SINGAPORE 737890 Tel No: 1800-7679999

2 of 3 Report No. T/20171215/2117

CONTINUATION OF REPORT

Name	RENGAN KARUPPAIAH		ID No.		G6731692X	
Related Vehicle	WC4796Y (Lorry)		1	Conta	ct No.	93709330
Hospital/Clinic	NIL .			Class Drivin Licens Expiry	g	Class: 2B,3,4 Date of Expiry: NIL
Date Treatment	NIL		Date Disc	harge	NIL	
No. of Days granted Medical Leave NIL			Degree of		NIL	

#### Brief Details.

On 15/12/2017 at about 1015hrs, I was driving my mixer Truck bearing registration number WC4796Y from Woodlands Avenue 5 towards Woodlands Avenue 12. It was a 3 lane road so I was on the middle lane. I know I am driving a heavy vehicle so I wanted to change lane to the left lane which was the slower

While I change lane, I discovered that my mixer truck steering wheel was lock and I can't shift to the right side, my mixer truck then went straight to hit a big tree and the tree fell on the grass patch. My vehicle also damages, the damages was Windscreen crack and my whole front part of the vehicle was dented.

After hitting the tree, I came down of my vehicle to take a look at the damages and called my office which was located at 51 Kranji crescent to informed regards of the accident. My manager namely: Gary, Hp:96759252 then came down to take a look on my √hicles damages.

At about 1054hrs, Two traffic Police officers then arrived at my scene and they straight away checked for my injuries. They then interviewed me regarding the accident and they also took down my particular. After which they left. No ambulance was at scene.

I wish to informed that the police did not give me any report number. My mixer truck have an inbuild camera. I lodged this report for my insurance claims. This is the first time such incident have happened to me.





Police Station Of Origin: Woodlands East N.P.C. 3 Woodlands Drive 63 SI Tel No: 1800-7679999

VGAPORE 737890

Report No. T/20171215/2117

CONTINUATION OF REPORT

Sketch Plan		
Informant is not able to provide	-vatch plan	9
	100 m	,
		1000
		1
	1	
	1	
	Α.	
	1	
900		

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you r<sub>low, please</sub> fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  J /  Sgt 1 GLENN SEET YONG SHENG	R. Kamblarell
Signature Of Interpreter: Not applicable	Date/Time: 15/12/2017 17:12
Officeron Charge Of Case: SN 130	Classification Of Case:
Authorizada Berre Police Force	Ti .



# Megastone Holdings Pte Ltd

(A Member of Samwon Group)
Company Bardstration No.: 199504015N, GST Registration No.: 19-9504015A









05th Jan 2018

LCH Lockton Pte Ltd Insurance Brokers and Consultants No. 6 Raffles Quay #22-00 Singapore 048580 Tel: (+65) 6221 3366, Fax: (+65) 6220 9497

Attention: Motor Claims Department

Dear Sir/ Madam,

#### Estimated quotation for the repair of WC4796Y

Base on the present condition of the truck, we are providing the estimated quotation (Exclude engine & transmission gearbox damage, due to unable to assess) for the repair of WC4796Y as follow.

To supply workmanship to repair and replacement of damaged parts including intercooler, radiator, air conditioner, wiring, painting and all external damage parts.

Total lump sum: \$\$25,000.00

 Note: Final quote will be based on another assessment after we are able to remove away those damaged parts.

Thanks,

Innovate

Wong Kok Fu

Workshop Asst. Manager

# HOLDINGS PTE LTD

# Megastone Holdings Pte Ltd







O bistate bistate

01ST March 2018

MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way, #21-01, SGX Centre 2 Singapore 068807

MSIG claim reference: 541659

Attention: Motor Claims Department

Dear Sir/ Madam,

hous checked parks preces than

12 days.

Quotation to supply labour, parts, necessary equipment and tools for the repair of WC4796Y.

Description	Qty	U/Price	Total Price
Front panel V CKA	1 pc	\$ 1,136.00	\$ 1,136.00
Front windscreen glass JORA	1 pc	\$ 1,629.00	\$ 1,629.00
Front windscreen rubber INEC	1 pc	\$ 405.00	\$ 405.00
Front panel lock V DNG	2 pcs	\$ 90.00	\$ 180.00
Front panel grille VIII	1 pc	\$ 1,067.00	\$ 1,067.00
Front wiper panel 🗸 📆	1 pc	\$ 500.00	\$ 500.00
Front wiper arm 🗸 07	1 pc	\$ 124.38	\$ 124.38
Front wiper blade / Mc	1 pc	\$ 48.22	\$ 48.22
Front bumper V DT	1 pc	\$ 1,290.00	\$ 1,290.00
Front bumper bracket   Ør	1 pc	\$ 320.00	\$ 320.00
Front headlamp LH V CSA	1 pc	\$ 351.00	\$ 351.00
Front side lamp	1 pc	\$ 56.00	\$ 56.00
Front fog lamp front bumper grille Van	1 pc	\$ 250.00	\$ 250.00
Air con coil V GT	1 pc	\$ 550.00	\$ 550.00
Air con blower 7 JCRK	1 pc	\$ 501.00	\$ 501.00
Front cabin bracket v pmg	1 pc	\$ 1,874.00	\$ 1,874.00
Front cabin cross member V ST	1 pc	\$ 794.00	\$ 794.00
Front radiator Sr	1 pc	\$ 6,064.00	\$ 6,064.00
Inter cooler JOT	1 pc	\$ 4,631.00	\$ 4,631.00
Fan blade 2 CCA	1 pc	\$ 800.00	\$ 800.00
Fan cover ? V Difom	1 pc	\$ 200.00	\$ 200.00
Fan bracket ? \square 87	1 pc	\$ 150.00	\$ 150.00
Front center panel	1 pc	\$ 1,533.00	\$ 1,533.00
		Sub-total:	\$ 24,453.60
Labour Charge			
To remove & refix engine and gear box	1 job	\$ 2,500.00	\$ 2,500.00
To R&R air con system, top up air con gas	1 job	\$ 1,500.00	\$ 1,500.00
To repair & remove front cabin damaged parts	1 job	\$ 3,000.00	\$ 3,000.00
To remove & refix front radiator and inter cooler	1 job	\$ 500.00	\$ 500.00
To remove & refix front axle	1 job	\$ 3,000.00	\$ 3,000.00
To putty & spray painting	1 Job	\$ 1,000.00	\$ 1,000.00

800

300 do

To remove & refix front windscreen glass	1 job	\$ 350.00	\$ 350.00
To remove a remaind windsorcem glass	1,100	Sub-total: \$ 11,850.0	\$ 11,850.00
		Total cost:	\$36,303.60
		7% GST	\$2,541.25
		Grand Total	\$ 38'844.85

Thanks,

Wong Kok Fu

Workshop Asst.Manager

- Lup Su Repair.

- Question Morte Itan Plate
- Photo After Paint

LIGK Auto Consultants hence notify

- the Repairer of the following: . To resurvey before latter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from trisurance Company

Acknowledged by Repairer

Signature:

Date:

# Claim Audit

2 A	UDIT TRAIL			By:
No.	On	Audit	Remarks	[I] Pang Xiu
	20 Dec 2017 14:25		(201615) ISUZU CYH52S 15.7 D (M).	Shi
	20 Dec 2017 14:25	Clm Created	Reg No: WC4796Y, Policy No: B28626097MKC, Acct Date: 2017/12/15, Claim Type: SC, Insurer: MSIG Insurance (Singapore) Pts. Ltd. (HQ), Ins.Status => Notification, Created from SAS:MVA117166176	[1] Pang Xiu Shi
	08 Jan 2018 10:19	Notification Status Changed	Ins.Status => Incoming Claim	[1] Vimmala D/O Raja Singam
	05 Jan 2018 10:19	Clm Registration Modified	Setl.Type:3->0. Rep:1137->200544. Claim Type:SC->OD, Init.Est.:->20,000 - 25,000.	[1] Vimmala D/O Raja Singam
	08 Jan 2018 10:20	Cim Registration Modified	Excess: -> 2000.00.	[I] Vimmala D/O Raja Singam
6	08 Jan 2018 10:25	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor): Please revert first. Surveyor, plea se check on the market value and rebates to determine whether the vehicle is economical to repair. Thank you.	Singam
7	08 Jan 2018 10:25	Adj Next Rpt Changed	Next Rpt:lm. Advice.Due Date:2018/01/09	[I] Vimmala D/O Raja Singam
8	08 Jan 2018 10:25	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Vimmala D/O Raja Singam
9	08 Jan 2018 10:31	Assignment 1st Accessed		[A] Ho Pei Fang [I] Vimmala
10	08 Jan 2018 10:33	Adj Assignment Cancelled	IHS APPT FULL	D/O Raja Singam
11	06 Jan 2018 10:33	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Vimmala D/O Raja Singam
12	08 Jan 2018 10:39	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Please revert and survey by today. Surveyor, please che ck on the market value and rebates to determine whether the vehicle is economical to repai r. Please also check brake system, tyres conditions and also the steering wh	[I] Vimmale D/O Raja Singam [I] Vimmale
13	08 Jan 2018 10:39	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/01/09	D/O Raja Singam
14	08 Jan 2018 10:39	Adj Mandate Set	Approved: 25000.00. Reinsp: Adj decides.	[I] Vimmala D/O Raja Singam [A]
15	08 Jan 2018 10:41	Assignment 1st Accessed		CATHERINE CHONG KA LING
16	14:18	Adj Adjuster Assigned	[None] -> Sebastian Yeang Wai Keen	[A] Nivitha Govindasam [A] SHIAU
17	11 Jan 2018 09:58	Adj Rpt Initiated		CHAN (A) SHIAU
18	11 Jan 2018 10:07	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/02/07	CHAN [A] SHIAU
19	11 Jan 2018 10:07	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/07	CHAN
20	11 Jan 2018 10:32	Adj Mandate Request	Cur.Req: 0.00: After undergoing the on site check, it is found that the steering do not have a ny issue in turning. (please refer to the video DSCN2168). However, the brake is not functioning during the on site test. This is because the air hose (air	
21	14 Feb 2018 09:20	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/07. Mandate Remarks: KIV update on repair assessment	HOW
22	14 Feb 2018 09:20	Adj Mandate Set	Approved:0.00:KIV update on repair assessment	[I] NG CHE

#### ACTIVITY

No record

Merimen Billing for this case - Transaction History								
681 Ref No	BIII Date	Acc Type	Acc Name:	Co Name (Branch)	Ref 1	R61 2	Amount	
1691762	11/01/2018 09:58	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	WC4796Y		10.70	

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

	OLDER TRA	CKING							
Case	Votified	Est Submitted	Adj Assigned	Adj Rpt	Ad	Submitted	Ins Auth'ed	Status	
Main	18 Dec 2017		08 Jan 2018 10:39 Edit Adj Rpt	5\$21,100. Edit Estima	7.70 W	21,100.00 /iew Rpt		Pending for Se Report Cancel Case	
,	tain	) R	eference	Clai	m Details		Documents		Show All
CLAIM SUI	SFOLDER DE	TAILS				[Created	by insurer]		
Insured:	SAMWOH	READY MIX PTE	LTD, Co. Reg. No	.: 200409069	N				
Vehicle Reg. No.:	WC4796	Y		D	ate of Loss		7 10:00 - :59 s and <b>28</b> Days From :	LTA Reg Date	(Man Yr)]
Claim Type:	OD / 54	659			olicy/Cover ate No.:		MKC (Comprehensiv 17/11/2017 - 16/11/		
				E	coess	S\$2,000.00	)		
Repairer:	Samwoh	Corporation Pte	Ltd (HQ) 25E Sung	ei Kadut Stree	rt 1, 72933	3 Sungei Kad	ut - Tel: 6269 7288		
Handling Insurer:	MSIG Ins	urance (Singapo	re) Pte. Ltd. (HQ)	- Tel: +65 68	27 7888	. [Handled by	Vimmala D/O Raja	Singam - 6	5942471]
Adjuster:	D7/02/20	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561 [H	landled by	Sebastian Y	eang Wai Keen]	Final Rpt	due
Driver/Custo	RENGAN K	COLUMN SECTION DESIGNATION OF	Male), NRIC: G67	CHARASSON, NO	: +659370	2000000			
dian:			today, Surveyor, pic	ease check on	the marke	nd also the ste	bates to determine w	if they are in	ehicle is
F. 50 HI 6-00	economica	to repair. Please as our insured inc	also check brake sy	ring wheel wa	s locked ar	nd unable to s	hift to right. Also req	uest for the s	efficient ervicing
Adj Asg. Remarks:	conditions	I to repair. Please as our insured inc nank you	also check brake sy	ring wheel wa	s locked ar	nd unable to s	hift to right. Also req	uest for the s	efficient ervicing se Case Mail
Adj Asg. Remarks: ASSOCIAT • M5IG_56 • M5IG S6	economica conditions records. Ti ED MAIL RE 5 (18/07/2018 5 (07/03/2018	to repair. Please as our insured inc tank you CEIVED ): WC4796Y (54) ): Alert - Adi Ma	also check brake sy licated that the stee (1659) Indate Approved (	ring wheel wa	s locked ar	od unable to s	hift to right. Also req	Uest for the s	ervicing
Adj Asg. Remarks: ASSOCIAT • M5IG_50 • M5IG_50	economica conditions records. Ti ED MAIL RE 5 (18/07/2018 5 (07/03/2018	I to repair. Please as our insured inclank you CEIVED 1): WC4796Y (54): Alert - Adj Ma (): Alert - Adj Ma	also check brake sy licated that the stee (1659) Indate Approved (	ring wheel wa	s locked ar	6Y - Claim H	View A andler: Vimmala D/O Ra	Uest for the s	ervicing

#### Claim Documents


\*WC4796Y (541659) OD Dec 15 2017 10:00AM
[SAMWOH READY MIX PTE LTD]
Samwoh Corporation Pte Ltd

Ass	essment Reports		1 per p	age. V	8
No	Finalized On	VAC (Bukit Batok)		Thumbnail	_
1	18/12/17 15:53	Accident Statement	0	Load HTM	
Vo.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	11/01/18 10:07	Adjuster Immediate Advice	0	Load HTM	-
2	07/03/18 11:31	Adjuster Immediate Advice		Load Him	-
Pho	itos/Images		3 per p	age: 💟	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	April and April
1	11/01/18 09:52	General View	0	Load JPG	V
2	11/01/18 09:52	General View	0	Load JPG	V
3	11/01/18 09:52	General View	0	Load JPG	2
4	11/01/18 09:52	General View	0	Load JPG	2
5	11/01/18 09:52	General View	0	Load JPG	<b>V</b>
6	11/01/18 09:52	General View	0	Load JPG	V
7	11/01/18 09:52	General View	0	Load JPG	V
8	11/01/18 09:52	General View	0	Load JPG	V
9	11/01/18 09:52	General View	0	Load JPG	V
10	11/01/18 09:52	General View	0	Load JPG	2
11	11/01/18 09:52	General View	0	Load JPG	V
12	11/01/18 09:52	General View	0	Load JPG	<b>V</b>
13	11/01/18 09:52	General View	0	Load JPG	V
14	11/01/18 09:52	General View	0	Load JPG	V
15	11/01/18 09:52	General View	0	Load JPG	V
16	11/01/18 09:52	General View	0	Load JPG	V
17	11/01/18 09:52	General View	0	Load 3PG	V
18	11/01/18 09:52	General View	0	Load JPG	V
19	11/01/18 09:52	General View	0	Load JPG	V
20	11/01/18 09:52	General View	0	Load JPG	V
21	11/01/18 09:52	General View	0	Load JPG	V
22	11/01/18 09:52	General View	0	Load JPG	1
23	11/01/18 09:52	General View	0	Load JPG	V
24	11/01/18 09:52	General View	0	Load JPG	V
25	11/01/18 09:52	General View	0	Load JPG	V
26	11/01/18 09:52	General View	0	Load JPG	V
27	11/01/18 09:52	General View	0	Load JPG	V
		General View	0	Load JPG	V
28	11/01/18 09:52	General View	0	Load JPG	V
29	11/01/18 09:52	General View	0	Load JPG	V
30	11/01/18 09:52	PERMINISTRAL	0	Load JPG	V
31	11/01/18 09:52	General View	0	Load JPG	N
32 33	11/01/18 09:52	General View General View	0	Load JPG	100.0

Ass	essment Reports		1 per page	
Vα	Finalized On	VAC (Bukit Batok)	Thumbna	and a figure on the con-
			0 1000	
14	11/01/18 09:52	General View	O Load JPG	
15	11/01/18 09:52	General View	1 Load JPG	_
16	11/01/18 09:52	General View	1 Load JPG	
17	11/01/18 09:52	General View	1 Load JPC	_
38	11/01/18 09:52	General View	1 Load JPC	-
39	11/01/18 09:52	General View	8 Load JPS	-
40	11/01/18 09:52	General View	O Load JPC	
41	11/01/18 09:52	General View	■ Load JPC	_
42	11/01/18 09:52	General View	Load JPG	_
43	11/01/18 09:52	General View	1 Load JPG	
44	11/01/18 09:52	General View	1 Load 3PG	-
45	11/01/18 09:52	General View	Load JPC	-
46:	11/01/18 09:52	General View	1 Load JPC	
47	11/01/18 09:52	General View	■ Load 3PG	
84	11/01/18 09:52	General View	Load 3PC	
49	11/01/18 09:52	General View	Load JPC	
50	11/01/18 09:52	General View	■ Load JP6	5 5
51	11/01/18 09:52	General View	Load JPC	5 5
52	11/01/18 09:52	General View	■ Load JPC	5 5
53	11/01/18 09:52	General View	■ Load 3PC	5 5
54	11/01/18 09:52	General View	Load 3PG	5
55	11/01/18 09:52	General View	■ Load JPC	S 5
56	11/01/18 09:52	General View	■ Load JPC	5 5
57	11/01/18 09:52	General View	■ Load 3PC	
58	11/01/18 09:52	General View	■ Load JPC	5 5
59.	11/01/18 09:52	General View	■ Load JPC	5 5
50	11/01/18 09:52	General View	Example 190	. 5
51	11/01/18 09:52	General View	■ Load 3PG	E 5
52	11/01/18 09:52	General View	E Load JPG	
63	11/01/18 09:52	General View	1 Load JPC	5 5
64	11/01/18 09:52	General View	■ Load 3PG	
55	11/01/18 09:52	General View	1 Load JPG	5 5
56	11/01/18 09:52	General View	■ Load JPC	
57	11/01/18 09:52	General View	1 Load JPG	
58	11/01/18 09:52	General View	■ Load 3PC	. 5
59	11/01/18 09:52	General View	1 Load JPG	
70	11/01/18 09:52	General View	■ Load JPC	. L
71	11/01/18 09:52	General View	D Load JPG	5 5
72	11/01/18 09:52	General View	Load JPG	-
73	11/01/18 09:52	General View	■ Load JPC	
74	11/01/18 09:52	General View	Load 3PG	
75	11/01/18 09:52	General View	O Load JPC	
76	13/07/18 11:18	Reinspection Photo	Load JPC	
77	13/07/18 11:18	Reinspection Photo	■ Load JPC	-
78	13/07/18 11:18	Reinspection Photo	O Load JPC	
79	13/07/18 11:18	Reinspection Photo	O Load JPC	-
		Reinspection Photo	O Load JPC	
80	13/07/18 11:23		O Load JPC	
81	13/07/18 11:23	Reinspection Photo Reinspection Photo	O Load JPC	

Asse	ssment Reports		1 per	The state of the s	V
No	Finalized On	VAC (Bukit Batok)		Thumbnail	Springer Street
83	13/07/18 11:23	Reinspection Photo	0	Load JPG	~
84	13/07/18 11:23	Reinspection Photo	Ð	Load JPG	8
85	13/07/18 11:23	Reinspection Photo	0	Load JPG	V
86	13/07/18 11:23	Reinspection Photo	0	Load JPG	V
87	13/07/18 11:23	Reinspection Photo	0	Load JPG	V
88	13/07/18 11:23	Reinspection Photo	0	Load JPG	V
89	13/07/18 11:23	Reinspection Photo	0	Load JPG	V
90	13/07/18 11:23	Reinspection Photo	0	Load 3PG	V
91	13/07/18 11:23	Reinspection Photo	0	Load JPG	V
		Reinspection Photo	0	Load JPG	V
92	13/07/18 11:23	Printed Andrews Company	0	Load JPG	V
93	13/07/18 11:23	Reinspection Photo	0	110000000000000000000000000000000000000	2
94	13/07/18 11:23	Reinspection Photo		Load JPG	-
95	13/07/18 11:23	Reinspection Photo	0	Load JPG	V
96	13/07/18 11:23	Reinspection Photo	0	Load JPG	V
97	13/07/18 11:23	Reinspection Photo	0	Load JPG	Z
98	13/07/18 11:23	Reinspection Photo	0	Load JPG	₹.
99	13/07/18 11:23	Reinspection Photo	0	Load JPG	V
100	13/07/18 11:23	Reinspection Photo	0	Load JPG	V
101	13/07/18 11:23	Reinspection Photo	0	Load JPG	V
102	13/07/18 11:23	Reinspection Photo	0	Load JPG	V
103	13/07/18 11:23	Reinspection Photo	0	Load JPG	V
-51			0	Load JPG	2
104	13/07/18 11:23	Reinspection Photo	0		V
105	13/07/18 11:23	Reinspection Photo		Load JPG	_
106	13/07/18 11:23	Reinspection Photo	0	Load JPG	V
107	13/07/18 11:23	Reinspection Photo	0	Load JPG	V
108	13/07/18 11:23	Reinspection Photo	0	Load JPG	8
109	13/07/18 11:23	Reinspection Photo	0	Load JPG	V
110	13/07/18 11:23	Reinspection Photo	0	Load JPG	~
111	13/07/18 11:23	Reinspection Photo	0	Load JPG	V
112	13/07/18 11:23	Reinspection Photo	0	Load JPG	~
113	13/07/18 11:23	Reinspection Photo	0	Load JPG	V
114	13/07/18 11:23	Reinspection Photo	0	Load JPG	V
	13/07/18 11:23	Reinspection Photo	0	Load JPG	S.
***************************************		The transfer of the transfer o			
Docu	umentation		1 per	page 🗸	V
No	Finalized On	HSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	22/12/17 09:28	LCH will submit estimate	0	Load TXT	
2	08/01/18 10:27	Estimate from Samwoh	0	Load PDF	-
3	08/01/18 10:27	Email from broker to arrange for survey today	0	Load PDF	
4 No	20/07/18 11:13 Finalized On	Signed DV VAC (Bukit Batok)		Load PDF Thumbnail	Print
		Sketch Plan	0	Load TIF	1.1111
1	18/12/17 15:52	[Linked Accident Report Documents]		LUBU TIP	
2	18/12/17 15:52	Sketch Plan #2 [Linked Accident Report Documents]	0	Load TIF	
3	18/12/17 15:52	PR [Limked Accident Report Documents]	0	Load TIF	
4	18/12/17 15:52	PR [Linked Accident Report Documents]	0	Load TIF	
5	18/12/17 15:52	PR	0	Load TIF	
No:	Relabel/Reorder	[Linked Accident Report Documents]  LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	20/02/18 16:46	SERVICING RECORD	0	Load PDF	
2	07/03/18 11:31	ESTIMATE	0	Load PDF	
3.	18/07/18 09:57	PHOTO	0	Load PDF	

#### **Linked Accident Report Documents**



#### **Documents Checklist**

DOCUMENTS CHECKLIST	Reset   Save   Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

#### LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607 198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way, #21-01 SGX Centre 2

Singapore 068807

Our File No:

CS/MSG18000391/SQD3E2

6WG1415487

0 km

Date:

30/07/2018

REFERENCE

Date of Loss:

Insured/Claimant:

SAMWOH READY MIX PTE LTD

15/12/2017

Policy No:

Nature of Claim:

B28626097MKC

Engine No:

Chassis No:

Odometer:

OD

Claim No: 541659

JALCYH52SB7000178

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

Reg. Date:

Colour

WC4796Y

Make & Model:

ISUZU CYH52S, 15.7 D (M)

17/11/2011 (Man. Year. 2011)

Engine Capacity:

15681 cc Market Value/New Car Price: S\$60,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Footbrake (Serviceable): Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: Front Left Side:

295/80 R22.5 Distance 5 mm

Rear Tyre Size: Rear Left Side:

Rear Right Side:

295/80 R22.5 Distance 5 mm

D-Master 5 mm

Front Right Side: Distance 5 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,453.60	20,785.56	3,668.04	15.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,850.00	5,650.00	6,200.00	52.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,303.60	26,435.56	9,868.04	27.18
Approved Total (Overridden) (S\$)		21,100.00		
- Excess (S\$)	2,000.00	2,000.00	0.00	0.00
(S\$)	34,303.60	19,100.00	15,203.60	44.32
+ GST 7.00/7.00% (S\$)	2,401.25	1,337.00	1,064.25	44.32
Nett Amount (S\$)	36,704.85	20,437.00	16,267.85	44.32

INSPECTION

Date of Assignment:

08/01/2018

Date Inspected:

08/01/2018 Inspected At:

42A SUNGAI KADUT STREET 1 Repairer: Samwoh Corporation Pte Ltd

(HQ)

Estimated Period of Repair

12.0 days

Adjuster Report Page 2 of 4

Adjuster: Sebastian Yeang Wai Keen Manager: SHIAU CHAN

NOTE. This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 30 Jul 2018)

Parts: N/A ISUZU CYH52S 15.7 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for WC4796Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

# Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Cracked	1,136.00 F	*1,136.00 FL
2	1		*FRONT WINDSCREEN GLASS	Cracked	1,629.00 F	*1,629.00 FL
3	1		*FRONT WINDSCREEN RUBBER	Necessary	405.00 F	*405.00 FL
4	2		*FRONT PANEL LOCK	Damaged	180.00 F	*180.00 FL
5	1		*FRONT PANEL GRILLE	Cracked	1,067.00 F	*1,067.00 FL
6	1		*FRONT WIPER PANEL	Dented	500.00 F	*500.00 FL
7	1		*FRONT WIPER ARM	Bent	124.38 F	*124.38 FL
8	1		*FRONT WIPER BLADE	Necessary	48.22 F	*48.22 FL
9	1		*FRONT BUMPER	Dented	1,290.00 F	*1,290.00 FL
10	1		*FRONT BUMPER BRACKET	Bent	320.00 F	*320.00 FL
11	1		*FRONT HEADLAMP LH	Cracked	351.00 F	*351.00 FL
12	1		*FRONT SIDE LAMP	Cracked	56.00 F	*56.00 FL
13	1		*FRONT FOG LAMP FRONT BUMPER GRILLE	Cracked	250.00 F	*250.00 FL
14	1		*AIR CON COIL	Bent	550.00 F	*550.00 FL
15	1		*AIR CON BLOWER	Cracked	501.00 F	*501.00 FL
16	1		*FRONT CABIN BRACKET	Damaged	1,874.00 F	*1,874.00 FL
17	1		*FRONT CABIN CROSS MEMBER	Bent	794.00 F	*794.00 FL
18	1		*FRONT RADIATOR	Bent	6,064.00 F	*6,064.00 FL
19	1		*INTER COOLER	Bent	4,631.00 F	*4,631.00 FL
20	1		*FAN BLADE	Cracked	800.00 F	*800.00 FL
21	1		*FAN COVER	Deformed	200.00 F	*200.00 FL
22	1		*FAN BRACKET	Bent	150.00 F	*150.00 FL
23	1		*FRONT CENTER PANEL	Cracked	1,533.00 F	*1,533.00 FL
F=Fn	anchise	part. L=ListIt	emDisc.	17 - MARTINE MARTINE	20100-0000	
				Sub Total (S\$)	24,453.60	24,453.60
			- List Item Discount on L Item	s 0.00/15.00% (S\$)	0.00	3,668.04
				Total Parts (S\$)	24,453.60	20,785.56

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items		SUMMAN PRO	
1	TO REMOVE & REFIX ENGINE AND GEAR BOX	New	2,500.00	900.00
2	TO R&R AIR CON SYSTEM, TOP UP AIR CON GAS	New	1,500.00	800.00
3	TO REPAIR & REMOVE FRONT CABIN DAMAGED PARTS	New	3,000.00	2,000.00
4	TO REMOVE & REFIX FRONT RADIATOR AND INTER COOLER	New	500.00	300.00
5	TO REMOVE AND REFIX FRONT AXLE	New	3,000.00	600.00
6	TO PUTTY & SPRAY PAINTING	New	1,000.00	800.00
7	TO REMOVE & REFIX FRONT WINDSCREEN GLASS	New	350.00	250.00
	Gross Labo	our Cost (S\$)	11,850.00	5,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >