

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18000420/UKS3Q2

Date: 12/08/2020

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100490064-00000
Claimant Vehicle No :	GBG466D	Insured Vehicle No :	SLH9471E
Date of Loss:	03/01/2018	Nature of Claim:	TP
		Claim No:	6153378303SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG466D		
Make & Model:	NISSAN URVAN, 3.0 5MT ABS AB 5DR LWB PANEL (A)	Engine No:	ZD30204032K
Reg. Date:	27/12/2008 (Man. Year: 2008)	Chassis No:	JN1MG4E25Z0792130
Colour:	Silver	Odometer:	362036 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/80 R15	Rear Tyre Size:	195/80 R15
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	88.74	88.74	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	350.00	280.00	70.00	20.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	438.74	368.74	70.00	15.95
+ GST 7.00/7.00% (\$\$)	30.71	25.81	4.90	15.96
Nett Amount (\$\$)	469.45	394.55	74.90	15.95
+ Loss of Use (2.0 x S\$60.00/day) (\$\$)		120.00		
(\$\$)		514.55		
Liabe Amount (50.00%) (\$\$)		257.28		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		264.73		
Global Sum Settlement (\$\$)		257.00		

INSPECTION

Date of Assignment:	08/01/2018	
Date Inspected:	08/01/2018	Inspected At:

Vfix Auto Service Pte Ltd (HQ)
26 Chia Ping Road
Singapore 619977

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE LAMP LH	Broken	98.60 FN	*98.60 FN
					Sub Total (S\$)	98.60
					- Nett Item Discount on N Items 10.00/10.00% (S\$)	9.86
					Total Parts (S\$)	88.74

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE DAMAGED PART	New	150.00	100.00
2	TO SPRAY PAINT REPLACED /REPAIRED BODY PANELS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS	New	200.00	180.00
Gross Labour Cost (\$\$)			350.00	280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >